

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
PART 4 OF 6
BOOKS 32 OF 43

11001	INSTALLED LH SEAT BELT BUCKLE. NEEDED TO REMOVE FRONT SEAT TO INSTALL NEW PART AND PUT ALL BACK	
12001	REPLACE SEAT BELT	
11001	SEAT BELT DEFECTIVE REPLACED SEAT BELT BUCKLES	
11001	CHECKED OUT, CONFIRMED INTERMITTANT CONCERN. REPLACE DRIVERS SEATBELT ASSY. RETESTS OK	
11001	FOUND SEAT BELT BUCKLE DEFECTIVE REPLACED THE DRIVERS SIDE SEAT BELT	
11001	VERIFIED CONCERN, SEAT BELT WILL NOT HOLD. NEC TO REPLACE BUCKLE ASSY.	
11001	14 7861203 REPLACE LEFT FRONT SEATBELT	
11001	REPLACE DRIVERS SEAT BELT BUCKLE ASSY THAT WOULD NOT LATCH PROPERLY	
11001	SEATBELT ASSEMBLY FRONT REPLACE	
11001	ROAD TEST, UNABLE TO VERIFY CONCERN, REPLACE SEAT BELT BUCKLE PER HOTLINE	
11001	REMOVE DRIVERS SEAT TO REPLACE SEATBELT BUCKLE	
11001	REPLACE BUCKLES	
12001	REPLACED THE BELT	

11001	SEATBELT WONT LATCH SEATBELT ASSEMBLY FRONT REPLACE	
12001	DOES NOT OPERATE PROPERLY REPLACE RT FRT SEAT BELT BUCKLE	
11001	THE ORIGINAL SEAT BELT BUCKLE IS COMING UNLATCHED WHILE THE CUSTOMER WAS DRIVING I REPLACED IT WITH A NEW ONE.	
11001	REPLACE DRIVERS SEAT BELT BUCKLE	
11001	12220 W TECH 599,VERIFIED CONCERN,R I DR SEAT TO GAIN ACCESS,RR BAD DR SIDE SEAT BELT BUCKLE,RETEST,ALL OPER OK AT THIS TIME	
11001	14881 W 302 VERIFIED CONCERN.REPLACE DRIVER SEATBELT RECIEVER DUE TO INOP.RETEST,OK AT THIS TIME. QUALITY INSPECTED BY 302. 14881.	
11001	INOP SEATBELT ASSEMBLY FRONT REPLACE	
11001	INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	
11001	BUCKLE PASSED, 01S21 COMES UNDONE INTERMITTENTLY REPLACED BUCKLE	
11001	INOP LATCH DIAG & VERIFY CONCERN.REPLACE DRIVERS SEAT BELT	
11001	INOP SEATBELT ASSEMBLY FRONT REPLACE	
11001	WOULD NOT HOLD REPLACE DRIVERS SIDE BUCKLE	

RODA-011 12883

11001	SEATBELT ASSEMBLY FRONT REPLACE	
11001	INSPECTED, LF SEAT BUCKLE WILL NOT LATCH, R&R REPLACED LF SEAT BELT BUCKLE ASSY. VERIFY REPAIR.	
11001	B L F SEAT BELT BUCKLE DOES NOT LATCH ALL THE TIME, REPL BUCKLE	
11001	12013 SAME REPLACE DRIVERS SEAT BELT BUCKLE RELEASES WHILE DRIVING JH	
11001	14937 42 W RR LT FT SEAT TO REPLACE SEAT BELT BUCKLE SOP	
11001	20885 42 1L7Z7861203CAA R&I DRIVERS SEAT & R&R DRIVERS SEAT BELT BUCKLE	
11001	11857 42 INOP WARR 6310 REPLACE LT FRT SEAT BELT BUCKLE ASSY GA	
11001	REMOVE SEAT ASSY. AND REPLACE SEATBELT ASSY.	
11001	SEATBELT ASSEMBLY FRONT REPLACE	

11001	DRIVERS SEAT BELT FAILED SEATBELT ASSEMBLY FRONT REPLACE	
11001	A REPLACED R SEAT BELT BNUCKLE	
11001	R&R DRIVER SEAT,REPL BROKEN SEAT BELT BUCKLE,RETEST.	
11001	LEFT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE	
11001	BUCKLE INOP REPLACED BOTH FRONT SEATBELT BUCKLES	
12001	DEFECTIVE SEAT BELT BUCKLE REPLACE D S SEAT BELT BUCKLE	
11001	DRIVER SIDE SEAT BUCKEL WOULD NOT HOLD REPLACE DRIVER SIDE SEAT BUCKLE	
11001	REPLACED DRIVER SIDE BUCKLE; WAS NOT LATCHING PROPERLY	
11001	ACCESS AND REPLACED SEAT BELT TO CORRECT	
11001	SEAT BELT FAILURE SEATBELT ASSEMBLY FRONT REPLACE	
11001	VERIFIED, REPLACED LEFT FRONT SEAT BELT LATCH, RIGHT SIDE OK	
11001	REMOVE AND REPLACE DRIVERS FRONT SEAT BELT BUCKLE	

11001	1974 42 42 THE CUSTOMER STATES THE DRIVERS SIDE FRONT SEAT BELT INTERMINTELY WILL UNLATCH VERIFIED THE PROBLEM I REPLACED THE DRIVERS SIDE FRONT SEAT BELT BUCKLE AS NEEDED MILES OUT 1974 FAILED PA	RT 1L7Z 7881203 CAA
12001	INSPECT, REPLACE DRIVERS SIDE AND PASSENGER SIDE FRONT SEAT BELT BUCKLES	
12001	REPLACE RT FRT BUCKLE INOP	
12001	REPLACE 2 SEAT BELT BUCKLES	
11001	VERIFIED REPLACED PASSENGER FRONT SEATBELT RECEPICLE. VERIFIED REPAIR. BUCKLE NOT OPERATING PROPERLY. REQUEST M TIME BECAUSE OF NO LABOR OP	
11001	11408 REPLACE DRIVE SIDE SEAT BUCKLED	
11001	CK & RPL DRIVERS SEAT BELT, DOES NOT WORK, RECK OK	
11001	REPLACED DRIVERS SEATBELT LATCH FOR NOT LOCKING CC01 FP7881203	
11001	13057 REPLACED DRIVER SIDE SEAT BELT BUCKLE ORDERED DRIVER SEAT BELT LATCH ASSY	
11001	B780 DEFECTIVE SEAT BUCKLE 42 R AND R SEAT IN ORDER TO ACCESS SEAT BUCKLE. REPLACED SEAT BUCKLE AND TESTED. WORKS FINE.	
11001	D SIDE FRONT SEATBELT WILL NOT LATCH... VERIFIED CONCERN..DIAG AND REPLACED D SIDE FRONT SEATBELT...	

11001	REPLACE ONE SEAT BELT BUCKLE	
11001	01S21 RECALL PERFORMED 01S21 RECALL PERFORMED	
11001	6133 BUCKLE LATCH 42 WARR VERIFIED CONCERN. REMOVED LT FR SEAT FROM VEHICLE FOR ACCESS TO REPLACE LT FR SEAT BELT BUCKLE LATCH ASSY. REINSTALLED ALL TEST ALL OK.	
11001	REPLACE BUCKLE INOP	
11001	REMOVED AND REPLACED SEAT BELT BUCKLE TESTED OK	
11001	VERIFY AND REPLACE BUCKLE 8620	
11001	1 REPLACED SEAT BELT BUCKLE DRIVERS SEAT	
11001	D S SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE	
11001	CHECK AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE	
11001	REPLACED BOTH FRONT SEATBELT BUCKLES	

11001	19500 BASIC 7861203 CONDITION 42 REPLACED LEFT FRONT SEATBELT BUCKLE THAT WOULD NOT STAY LATCHED. OK NOW.	
12001	REPLACE RIGHT AND LEFT FRONT SEAT BELT BUCKLES PER OLD ONES WOULD NOT STAY LATCHED	
11001	1671 REPLACE DRIVERS SIDE BELT BUCKLE WILL NOT STAY BUCKLED	
11001	REPLACE LF. SEAT BELT LATCH AND CHECKS OK FW.	
11001	REPLACED LEFT FRONT SEAT BELT BUCKEL BN 7861203 CG 42 TECH 173	
11001	INSTALLED SOP DRIVERS SEAT BUCKLE RECEIVER VERIFIED REPAIR	
11001	TESTED AND FOUND BAD LATCH, REPLACED LATCH ASSEMBLY.	
11001	7861203 42 VERIFIED CONCERN INSPECT AND TEST SEAT BELT LATCH FOUND LATCH NOT LATCHING PROPERLY R&R DRIVERS SEAT REPLACED	
11001	61203 42 VERIFY CONCERN, REPLACE LH FR SEATBELT BUCKLE.	

11001	R&R SEATBELT BUCKLE DR. FRONT TESTED FAULTY	
12001	INSTALLED SO SEAT BELT BUCKLE. RETESTED OK.	
11001	8995 7861203 BUCKLE, 42 DNOP CONFIRMED CUST CONCERN OF DRIVER SIDE SEAT BELT BUCKLE NOT HOLDING. REPLACED LF BUCKET SEAT BUCKLE ASSEMBLY. RETEST, WORKING PROPERLY AFTER REPAIR.	
11001	REPLACE DR SEATBELT BUCKLE	
11001	INSPECTED SEAT BELT ASSEMBLY, UNABLE TO VERIFY CONCERN, INSPECTED SEAT BELT LATCH ASSEMBLY, NO FOREIGN MATERIAL IN LATCH, ORDERED LATCH.	
11001	16512 R&I BAD DRIVERS FT SEAT BELT 42 7861203	
11001	FOUND LATCH TO BE FAULTY, REPLACED LATCH ASSEMBLY	
11001	CK OUT R&R DRIVER SEAT BELT BUCKLE	
11001	CHECKED OUT, R AND R DRIVERS SEAT AND REPLACED SEAT BELT BUCKLE	
11001	BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE	

11001	BUCKLE MALFUNCTION	SEATBELT ASSEMBLY FRONT	REPLACE	
12001	SEATBELT	REPLACED LEFT FRONT BELT		
11001	BUCKLE MALFUNCTIONS	SEATBELT ASSEMBLY FRONT	REPLACE	
11001	REPLACED SEAT BELT LATCH			
12001	SEAT BELT LATCH	REPLACED SEAT BELT LATCH		
11001	REPLACED FRONT SEAT BUCKLE			
11001	REPLACED DRIVERS SIDE SEAT BELT BUCKLE			
11001	INSTALLED SEAT BELT BUCKLE ASSEMBLY WOULDNT LATCH			
12001	INOP	SEATBELT ASSEMBLY R FRONT	REPLACE	
11001	1 1 CHECK AND REPLACE SEATBELT			
11001	19859 INSTALL SOPS REMOVED AND INSTALLED SEAT BELT BUCKLE FRONT SEATS BOTH SIDES.			
11001	SEATBELT FAILED	SEATBELT ASSEMBLY FRONT	REPLACE	

11001	1 REPLACED DRIVERS SEAT BELT BUCKLE	
11001	SEAT BELT NOT WORKING PROPERLY CK SEAT BELT BUCKLE NOT LOCKING IN ALL TIMES REPLACE SEAT BELT BUC	
11001	REPLACE DRIVERS SIDE SEAT BELT REPLACE SEAT BELT	
11001	CONFIRMED. REMOVED AND REPLACED DRIVERS SEAT BELT LATCH TO CORRECT	
11001	. VERIFIED CUST CONCERN, INSTALLED NEW SEAT BELT BUCKLE.	
11001	1 NEC TO REPLACE SEAT BUCKLES	
11001	SEAT BELT NOT LOCKING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	
11001	INOP SEATBELT ASSEMBLY FRONT REPLACE	
11001	UNLATCH SEATBELT ASSEMBLY FRONT REPLACE	
11001	3321 REPLACED DRIVER SIDE SEAT BELT BUCKLE.	
11001	4266 REPLACED BELT Y	

12001	REPLACED BOTH FRT SEAT BELT BUCKLES CHECKED OPERATION OK	
12001	CHECKED AND REPLACED BOTH PASS AND DRIVERS SEAT BELT BUCKLE	
11001	R AND R DRIVER SEAT, REPLACE SEAT BELT WITH NEW, RAND R PASSENGER SEAT, REPLACE SEATBELT.	
11001	1472 O1 REPLACED DRIVERS SEAT BELT BUCKLE WOULD NOT STAY LATCHED TECH 2825 M.D	
11001	NECESSARY TO REPLACE LEFT FRONT SEAT BELT BUCKLE.	
11001	3133 REPLACE DRIVERS SEAT BELT BUCKLE	
11001	SEATBELT ASSEMBLY FRONT REPLACE (611A72 611A73) 61203,S25,42	
11001	REPLACE DRIVERS SIDE SEAT BELT BUCKLE	
11001	REPLACED DRIVER SIDE SEAT BELT BUCKLE	

11001		
11001	SEAT BELT LATCH NOT HOLDING R AND I DRIVERS SEAT TO REPL SEAT BELT LATCH	
12001	REPLACED THE BUCKLE ASSY	
11001	REPLACE D S SEAT BELT BUCKLE	
12001	REPLACE SEAT BELT ASSY	
11001	VERIFY CONCERN LEFT SEAT BELT UNLATCHES INTERMITTENT, R&R LEFT SEAT BELT BUCKLE	
11001	REPLACE BOTH FRONT SEATBELT BUCLEREPLACE BOTH FRONT SEATBELT BUCKLES	
11001	CHECK FOR LEFT FRONT SEAT BELT FOR NOT LATCHING PROPERLY. CONCERN VERIFIED.REPALCED LEFT FRONT SEAT BELT. POST TEST	
11001	VERIFY CONERN AND CK. SEAT BELT ON LEFT FRONT SEAT BELT FAILED TO LATCH, REPLACE SEAT BELT LATCH. VERIFY REPAIR,OK.	
11001	REPL LEFT SEATBELT BUCKLE DUE TO COMING APART	
11001	SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	

11001	INSTALL NEW SEATBELT IN DRIVERS SEAT NOT LATCHING PROPERLY RETEST OK C C42	
11001	VERIFIED CONCERN RETEST BUCKLES WITH RECALL TEST BOTH BUCKLES PASS BUT DRIVERS WILL UNHOOK APPROX 1 OUT OF 10 TIMES	
12001	MO 16608 CC 42 61202 VERIFIED CUSTOMER CONCERN. REPLACED PASSENGER FRONT SEAT BELT BUCKLE. BUCKET SEATS, REMOVE SEAT TO ACCESS	
11001	5709 FOUND DRIVERS SEAT BELT BUCKLE TO BE COMING APART INTERNALLY. REPLACED DRIVERS SEAT BELT BUCKLE + TEST. *** QUALITY CONTROL BY JOHN MEDROW ***	
11001	3500 1.0 REPLACED SEAT BELT LOCK	
11001	8226 LOOSE REPLACE LOOSE LF SEAT BELT BUCKEL	
11001	1 TESTED SEAT BELTS AND FOUND BOTH FRONT BUCKLES FAILED REPLACED BOTH BUCKLES, POWER SEATS BUCKETS	
11001	COMES UNLATCHED SEATBELT ASSEMBLY FRONT REPLACE	
11001	DRVS SEAT BELT WOULD NOT LATCH AT TIMES I REPLACED THE DRVS SEATBELT AT THIS TRIME IT LATCHES AS INTENDED	
11001	REPLACED LATCH ASSY	
11001	VERIFIED CUSTOMERS CONCERN, PERFORMED INSPECTION. FOUND BUCKLE SPRING BROKEN, REPLACED BUCKLE, RETEST OK...	
11001	1 R&R SEAT BELT BUCKLE.	

11001	TESTED; DRIVER SIDE FAILED	
11001	REPLACE LEFT FRONT SEATBELT FEMALE INOP	
11001	REPLACED SEATBELT ASSY	
11001	SEATBELT BUCKLE CAME APART	
11001	BUCKLE BINDING	
11001	REPLACED DRIVERS SEAT BELT	
11001	REPLACED DRIVERS SIDE BUCKLE	
11001	RAN DIAG FOUND SEAT BELT WOULD NOT LATCH REPLACE SEAT BELT ASSY	
11001	5821 WARR REPLACE DRIVERS SIDE SEATBELT BUCKEL.	
11001	BELT BUCKLE BELT BUCKLE BROKEN REPLACED, EXTRA TIME TO REMOVE SEAT TO GAIN ACCESS	
11001	DEFECTIVE REPLACED LF SEAT BELT BUCKLE	
11001	DIAGNOSED AND TESTED TO VERIFY COMPLAINT,R*R DR IVER SIDE SEAT BUCKET TO REMOVE AND REPLACE SEA T BELT BUCKLE	
11001	FOUND SEAT BELT RECIVER NOT HOLDING REPLACED AND RECHECKED OPERATION	

11001	REPLACED FRONT 2 SEAT BELT BUCKES	
11001	REPLACED DRICER SIDE BUCKLE	
12001	CHECK SEAT BELT LATCHES THEY FAILED SO REPLACED WITH NEW ONES TESTED OUT OK	
11001	25555 SEAT BELT WOULD COME LOOSE (NOT RECALL) 42 WR VERIFIED CUSTOMERS CONCERN AND ROAD TESTED VEHICLE. FOUND THAT SEAT BELT BUCKLE WOULD NOT HOLD SEAT BELT AND WOULD BECOME LOOSE AT A SUDDEN STOP.	REMOVED SEAT IN ORDER TO REMOVE SEAT BELT BUCKLE. R R SEAT BELT BUCKLE ON DRIVER SIDE. ROAD TESTED AND FOUND BELT BUCKLE WORKING NORMALLY.
11001	33327 61203,42 DOES NOT OPERATE PROPERLY R R DRIVER SEAT REPLACED SEAT BELT BUCKLE TEST,OK	
11001	19901 BOTH FRONT SEAT BELT BUCKLES WILL NOT STAY LATCHED. REPLACED BOTH FRONT SEAT BELT BUCKLES. CC 42 QUALITY CHECKED BY MJM	
11001	4954 CC 42, DRIVERS SEATBELT BUCKLE NOT WORKING PROPERLY, REPLACED DRIVERS SEATBELT BUCKLE, SYSTEM OK, QUALITY CHECKED BY A RANDEL	
11001	REPLACED DRIVER SIDE SEAT BELT BUCKLE CAME UNLATCH WHEN DRIVING.	
11001	INOP SEATBELT ASSEMBLY FRONT REPLACE	
11001	42 REPLACE DRIVERS SEAT BELT BUCKLE WONT LATCH	
11001	TEST DRIVER SEATBELT BUCKLE NOT LATCHING PROPERLY, REPLACE.	

11001	6122 TEST AND REPLACE DRIVER SIDE SEATBELT CC 42	
12001	32691 VERIFIED CUSTOMER CONCERN BOTH FRT SEAT BELT BIKLES INOP REPLACED BOTH FRT BUCKLES	
11001	INSPECT SEAT BELTS AND REPLACE ONE SEAT BELT	
11001	RR DRIVERS SEAT TO REPLACE SEAT BELT BUCKLE WOULD NOT LATCH AT TIMES	
11001	REPLACED SEATBELT BUCKLES.	
11001	ACCESS AND REPLACE SEATBELT BUCKLE.	
11001	REPLACED SEAT BELT BUCKLE	
11001	ACCESS AND REPLACE SEATBELT BUCKLE.	
11001	SEAT BELT BUCKLE INOP REPLACE DRIVER SEAT BELT BUCKLE	
11001	LEFT FRONT SEAT BELT WILL NOT LOCK, REPLACE BUCKLE	
11001	1 REPLACED LEFT FRONT SEAT BELT BUCKLE	

11001	CONFIRM SEATBELTS UNBUCKLE. REPLACE BOTH FRONT SEAT BELT FEMALE ENDS. CONFIRM REPAIR. 41 61202	
12001	CHECKED BOTH FRONT SEAT BELT OPP FOUND THAT AT TIMES WHEN SEAT BELTS ARE PULLED HARD BUCKLES WILL INT RELEASE	
11001	33 61203 VERIFY CUSTOMERS CONCERN.REPLACE DRIVERS SEAT BELT BUCKLE. LOOSE	
11001	640 DRIVER SEAT BELT BUCKLE NOT LATCHING BELT REPLACE BUCKLE AND RETEST WORKING PROPERLY NOW	
11001	12242 VERIFIED SEATBELT BUCKLE REALES EB REMOVED AND REPLACED WITH NEW ONE RETESTED NEW ONE WORKS OK	
12001	R & R RF SEAT AND REPLACED SEAT BUCKLE DUE TO NO LOCK	
12001	DIAGNOSE AND REPLACE FRONT SEAT BELT BUCKLE, RETEST O.K.	
11001	REPLACE SEAT BELT BUCKLE	
12001	REPLACE PASS. SIDE SEAT BELT BUCKLE	
11001	REPLACED SEAT BELT BUCKLE	
11001	VERIFIED BELT COMES UNHOOKED WAS REPLACED 10 26 01.....RO #44848 INSTALL NEW SEAT BELT, RETEST, OK	
12001	TESTED ALL SEAT BELT BUCKLES BOTH FRONT FAILED TEST. ORDERED PRIORITY REPLACED BOTH FRONT SEAT BUCKELS, WITH NEW.	
11001	REPLACED LEFT FRONT SEAT BELT BUCKLE	

NOV-011 12128

TBL2001 ExpedLF_CUST_TXT	TBL2001 ExpedLF_A REA_CD	TBL2001 ExpedLF_C OUNTRY_CD	TBL2001 ExpedLF_S LS_DLR_CD	TBL2001 ExpedLF_T XN_CD	TBL2001 ExpedLF_C NTRY_SOL D	TBL2001 ExpedLF_Q RT_CD	TBL2001 ExpedLF_V FG_CD
CUST. STATES DRIVER FRONT SEAT BELT COMES OUT OF BUCKLE WHILE DRIVING PARTS IN	205	USA	121406	1	USA	Q21	V05
CK DRIVERS SEATBELT KEEPS COMING UNBUCKLED	258	USA	121707	E84	USA	Q21	V05
CUSTOMER STATES DRIVERS SEAT BELT COMES LOOSE AFTER BUCKLING TRIM KH	205	USA	326330	2	USA	Q21	V05
CUSTOMER STATES CHECK DRIVER SEAT BELT RELEASES ON ITS OWN AT TIMES	870	USA	123001	2	USA	Q21	V05
DRIVERSIDE SEATBELT WILL NOT STAY BUCKLED	501	USA	123590	1	USA	Q21	V06
C S THAT LEFT FRONT SEAT KEEPS COMING LOOSE CHECK AND ADVISE	480	USA	354289	E84	USA	Q21	V03
DRIVERS SEAT BELT COMES LOOSE WHEN DRIVING INSTALL SOP	480	USA	354289	1	USA	Q21	V05
CUST STATES DRIVERS SEAT BELT BUCKLE RED KNOB WILL NOT COME ALL THE WAY OUT AT TIMES, AND THE SEAT BELT WILL NOT STAY IN BUCKLE	602	USA	171171	E84	USA	Q21	V05
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE WILL COME UN DONE AT TIMES AND SOMETIMES YOU WILL HAVE TO PLAY WITH RED BUTTON TO	602	USA	158582	E84	USA	Q21	V05

CS DRIVERS SEAT BELT COMES UNDONE WHEN DRIVING	802	USA	171178	1	USA	Q21	V05
CUST STATES THAT DRIVER SEAT BELT COMES UNDONE SOMETIMES WHILE DRIVING	802	USA	171178	E84	USA	Q21	V05
CUSTOMER STATES: FRONT DRIVER SIDE SEAT BELT DOES NOT STAY LATCHED ALL THE TIME. CHECK ALL SEAT BELTS	780	USA	171079	2	USA	Q21	V05
CHECK DRIVERS SEAT BELT WILL NOT STAY LATCHED INTERMITTENT	909	USA	171153	1	USA	Q21	V05
CHECK DRIVER SIDE SEAT BELT BUCKLE UNHOOKS WHILE DRIVING	909	USA	171153	1	USA	Q21	V05
CUST STATES THE DRIVERS SEAT BELT IS INOP	310	USA	171040	E84	USA	Q21	V05
CUSTOMER REPORTS DRIVERS SIDE SEAT BELT COMES OUT OF RECEPTICLE WHILE DRIVING, CHECK AND ADVISE	925	USA	172023	1	USA	Q21	V05
CK DRIVER SEAT BELT BUCKET NOT HOLDING	828	USA	171037	1	USA	Q21	V05
CUSTOMER STATES WHILE DRIVING THE LEFT FRONT SEAT BELT WILL POP OUT OF THEBUCKLE ASY.	909	USA	171150	1	USA	Q21	V05
CUSTOMER STATES LEFT FORNT SEAT BELT UNBUCKLES AT TIMES WHILE DRIVING	582	USA	171055	1	USA	Q21	V05
CUSTOMER STTAAES RIGHT FRONT SEAT BELT BUCKLE DOES NOT LATCH	582	USA	171047	E84	USA	Q21	V05
LEFT FRONT SEAR BELT WONT LATCH	582	USA	171011	E84	USA	Q21	V05
CUSTOMER STATES THAT LEFT FRONT SEAT BELT KEEPS COMING UNLATCHED WHILE DRIVING	714	USA	171052	1	USA	Q21	V05
CUSTOOOMER STATES THAT LEFT FRONT SEAT BELT COMES UNDONE	714	USA	171052	E84	USA	Q21	V05
D S SEAT BELT INOP DOES NOT BUCKLE AT TIMES	780	USA	171427	E84	USA	Q21	V17

CUST SAYS DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING	582	USA	171047	1	USA	Q21	V05
CUST STATES RT FRONT SEAT BELT WILL NOT STAY LATCHED COMES LOOSE	819	USA	171078	1	USA	Q21	V05
CUST STATES RT FRONT SEAT BELT WILL NOT STAY LATCHED COMES LOOSE	619	USA	171078	1	USA	Q21	V05
CUST STATES LEFT FRONT SEAT BELT WILL NOT NOT STAY LATCH IN THE BUCKLE COMES LOOSE	819	USA	171078	1	USA	Q21	V05
CUST STATES LEFT FRONT SEAT BELT WILL NOT NOT STAY LATCH IN THE BUCKLE COMES LOOSE	819	USA	171078	1	USA	Q21	V05
DRIVERS SEAT BELT WONT LATCH	780	USA	171102	E84	USA	Q21	V05
S28 CUST. REPORTS DRIVERS SIDE SEAT BUCKLE WONT LATCH	819	USA	171088	1	USA	Q21	V05
CUST REPROTS THAT WHEN DRIVING AND DRIVERS SEATBELT IS LOCKED IN PLACE,WILL AUTOMATICALLY UNLOCK,DOES CLICK WHEN	626	USA	171015	E84	USA	Q21	V05
CUSTOMER STATES WHILE DRIVING SEAT BELT COMES APART.	310	USA	171025	1	USA	Q21	V05
CUST STATESW DRIVER SIDE SEAT BELT INOP WILL NOT BUCKEL	818	USA	171040	1	USA	Q21	V05
S28 CUSTOMER STATES THAT DRIVERS FRONT SEAT BELT BUCKLE UNLOCKS BY ITSELF WHILE	818	USA	171040	E84	USA	Q21	V05
DRVRS SIDE SEAT BELT KEEPS POPPING OUT AT TIMES WILL NOT STAY LATCHED	826	USA	171098	1	USA	Q21	V05
CLIENT STATES BOTH FRONT SEATBELTS AFTER 5 MINUTES OF DRIVING POP OFF ON THEIR OWN.		USA	171154	E84	USA	Q21	V05
CUSTOMER STATES: THE DRIVER S SEAT BELT WILL NOT STAY LATCHED, SOP IN	310	USA	171015	1	USA	Q21	V05

CUSTOMER STATES THAT THE DRIVERS SEAT BELT BUCKLE IS NOT HOLDING BELT. REFER TO LINE A	619	USA	171076	1	USA	Q21	V05
CS FRT PASS SEAT BELT UNLATCHES BY ITSELF	818	USA	171227	E84	USA	Q21	V05
SPECIAL ORDER PARTS IN MIDDLE SEAT MIDDLE SEAT BELT RECEPTICLE AND REAR BENT LEFT OUT	510	USA	172013	1	USA	Q21	V05
CUSTOMER REPORTS DRIVERS SEATBELT WILL NOT HOLD AT TIMES	209	USA	172402	E84	USA	Q21	V05
D S FRONT SEAT BELT WILL NOT STAY LATCHED	510	USA	172008	1	USA	Q21	V05
CUSTOMER STATES THE DRIVER SIDE BELT WILL NOT STAY LATCHED...SOP HERE	209	USA	158011	2	USA	Q21	V05
CUST STATES DR SIDE SEAT BELT WONT LATCH	818	USA	171029	E84	USA	Q21	V05
DRIVER SEAT BELT POPS OUT	780	USA	354198	2	USA	Q21	V05
CUST STATES RIGHT FRONT SEAT BELT FEMALE WILL NOT ALWAYS LOCK INTO CLIP	818	USA	354280	E84	USA	Q21	V05
ADVISE CUST STATES DRIVERS SEAT BELT OPENS WHILE JUST SITTING IN SEAT	562	USA	354081	E84	USA	Q21	V05
SAYS DRIVER SEAT BELT WONT STAY LATCHED POPS OUT WHILE DRIVING	303	USA	355299	2	USA	Q21	V05
CUSTOMER STATES VEHICLE SEAT BELT LATCHES RELEASE BY THEM SELVS BOTH FRONT SEATS.	303	USA	355115	1	USA	Q21	V05
CHECK FRONT SEATBELT BUCKLES WONT HOLD	*	USA	158823	E84	USA	Q21	V05

DRIVERS SEAT BELT WONT LATCH	860	USA	111407	E84	USA	Q21	V05
RT FRT SEAT BELT WILL NOT STAY BUCKLED	302	USA	18901L	E84	USA	Q21	V05
CUST STATES D S FT SEATBELT WILL COME UNLATCHED WHEN DRMING	813	USA	124449	1	USA	Q21	V05
STS DR SEATBELT WONT STAY LATCHED	407	USA	124228	1	USA	Q21	V05
S40 CHECK CUST CONCERN FOR DRIVER SIDE SEAT BELT BUCKLE WILL NOT LATCH.	954	USA	124015	E84	USA	Q21	V05
S40 DRIVERS SEAT BELT WONT LATCH, ALL TIMES, CUST STATES.	954	USA	124015	E90	USA	Q21	V05
O R DRIVERS SEATBELT CAN BE PULLED OUT, OR WHEN IT IS PUT UNDER PRESSURE IT WILL COME OUT OF BUCKLE.	407	USA	124224	1	USA	Q21	V05
CS BOTH SEAT BELT BUCKLES KEEP COMING UNDONE WHEN DRIVING?	407	USA	141448	E84	USA	Q21	V05
CUST STATES DRIVERS SEAT BELT COMES UNLATCHED AFTER DRIVING A WHILE	904	USA	124455	E84	USA	Q21	V05
CUST STATES THE DRIVERS SEAT BELT POPS OPEN WHILE DRIVING	407	USA	124214	E84	USA	Q21	V71
CUST STATES DRIVERSIDE SEAT BELT COMES OUT AFTER YOU CLICK IT IN BY ITSELF	813	USA	124208	2	USA	Q21	V05
CUST TBS DRIVER SIDE SEAT BELT WHEN BUCKLED IT DELATCHES	954	USA	124010	1	USA	Q21	V05

CUST STATES BOTH FRT SEAT BELTS DONT LATCH	813	USA	124521	E84	USA	Q21	V05
LEFT FRONT SEAT BELT WONT STAY LATCHED	407	USA	325189	2	USA	Q21	V05
C 8 LEFT FRONT SEATBELT DOES NOT LATCH AT TIMES. INT TRIM CODE KH	407	USA	325189	E84	USA	Q21	V05
W40 S25 DRIVERS SEAT BELT RELEASES WHEN LOCKED	305	USA	318309	E84	USA	Q21	V05
S40,LEFT FRT SEAT BELT WONT LATCH,,	305	USA	325256	E84	USA	Q21	V05
S40 DRIVERS SIDE SEAT BELT COMES UNDONE WHILE DRIVING SOP #295827	305	USA	325256	E84	USA	Q21	V05
S25 LEFT FRONT SEAT BELT FEMALE END NOT WORKING PROPERLY WILL NOT LATCH W	306	USA	325118	2	USA	Q21	V05
CUSTOMER STATES THE DRIVERS SEAT BELT COME UNLATCHED	770	USA	121003	E84	USA	Q21	V05
DRIVERS SEAT BELT COMES UNLATCHED AT TIMES PART IN	476	USA	121500	2	USA	Q21	V05

CK FOR DRIVER SIDE FRT SEATBELT DOES NOT LATCH AT TIMES	770	USA	121480	E84	USA	Q21	V05
CK DR SIDE BELT WONT LOCK	708	USA	121205	2	USA	Q21	V05
CUSOTMER STATES DRIVERS SEAT BELT WILL COME LOOSE WHEN DRIVING SPO PARTS IN	770	USA	121023	E84	USA	Q21	V74
LEFT SEAT BELT WONT STAY LATCHED PART HERE WAIT	770	USA	121059	1	USA	Q21	V05
DRIVERS SIDE FRONT SEAT BELT WILL NOT STAY LATCHED	770	USA	141293	E84	USA	Q21	V06
CUST STATES DRIVER SEAT BELT RELEASES BY ITSELF	770	USA	121025	2	USA	Q21	V74
SEAT BELT WONT BUCKLE	770	USA	121025	2	USA	Q21	V74
CUSTOMER STATES DRIVER S SIDE BUCKLE BECOMES UNLATCHED FROM TIME TO TIME	912	USA	121209	1	USA	Q21	V06
CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED S40	770	USA	328057	1	USA	Q21	V05
CUST. STATES DRIVER SEAT BELT COMES UNBUCKLED AT TIMES WHILE DRIVING (SOP) TECH 128	770	USA	328233	2	USA	Q21	V05
CHECK TWO FRT SEAT BELT LATCH AT TIMES DOESNT LATCH	808	USA	172203	E84	USA	Q21	V05
SEAT BELT FOR DRIVER WILL NOT LATCH	208	USA	355488	2	USA	Q21	V05

T90 C S THE DVS FRONT SEAT BELT INTERMIT WILL UNLATCH	208	USA	355575	1	USA	Q21	V74
DRIVERS SEAT BELT COMES UNBUCKLED	847	USA	141415	1	USA	Q21	V05
PSSGR FRT SEATBELT COMES UNLATCHED PARTS ORDERED ONE MONTH AGO	217	USA	141105	E84	USA	Q21	V05
RT FRT SEAT BELT WONT LATCH INTO BUCKLE MIDDLE SEAT BELT CAME APART	217	USA	141141	E81	USA	Q21	V05
SEATBELT RECEPTICLE DOES NOT HOLD AT TIMES PASSENGER SIDE FRONT	812	USA	348140	1	USA	Q21	V05
CUST. STATES THAT THE DRIVERS SEAT BELT COMES UNBUCKLED S.O.P IS IN	859	USA	147011	2	USA	Q21	V05
S25 DRIVERS SEAT BELT COMES OPEN WHEN DRIVING AT TIMES	806	USA	171104	E84	USA	Q21	V05
S28 DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED WHILE DRIVING.INSTALL SOP 1L7Z7861203BAA	859	USA	147301	1	USA	Q21	V05
CUST STATES DRIVER SEAT BELT LATCH WILL NOT HOLD AT TIMES(REFER TO RO #95200)	225	USA	123148	E84	USA	Q21	V05
CHECK L F SEATBELT ERRATIC COMES UNLOCKED WHILE DRIVING S40	604	USA	123027	1	USA	Q21	V05
CUSTOMER SAYS THAT DRIVERS SIDE SEATBELT INOP...	337	USA	123208	E84	USA	Q21	V05

SEAT BUCKLE WOULD NOT LATCH	225	USA	123145	E84	USA	Q21	V05
CK THE DRIVER SIDE SEAT BELT LATCHES THEN WHEN DRIVING COMES LOOSE OR PULLS OUT OF LATCH	337	USA	123271	1	USA	Q21	V03
S40 O R LEFT FRONT SEAT BELT BUCKLE COMES UNDONE WHEN DRIVING	504	USA	123020	1	USA	Q21	V05
CUSTOMER STATES DR SEAT BELT DOES NOT BUCKLE ALL THE TIME	337	USA	123264	2	USA	Q21	V05
DRIVERS SEATBELT WILL POP LOOSE INSTALL PARTS..	337	USA	123248	1	USA	Q21	V05
CUSTOMER STATES DRIVER SEAT BELT COMES UNFASTENED ON IT OWN..	617	USA	121213	2	USA	Q21	V05
DRIVERS SEAT BELT BUCKLE IS NOT HOLDING PART IN STOCK	508	USA	312145	2	USA	Q21	V05
CUSTOMER STATES DRIVER SEAT BELT UNFASTENS WHILE DRIVING	410	USA	127558	1	USA	Q21	V05
DRIVERS SEAT BELT DOES NOT STAY BUCKLED	207	USA	111558	E84	USA	Q21	V05
DRIVERS SIDE SEAT BELT BUCKLE RELEASES ON IT S OWN INTERMITANTLY	207	USA	111212	1	USA	Q21	V05

LEFT FRT SEAT BELT AT TIMES RELEASES FROM BUCKLE FOR NO REASON	810	USA	345275	E84	USA	Q21	V05
THE SEAT BELT BUCKLE IS NOT STAYING LATCHED PARTS IN	734	USA	148439	1	USA	Q21	V05
S25 CK DRIVERS SEAT BELT SHOULDER HARNESS FEMALE PART WILL NOT STAY BUCKLE COMES UNBUCKLED AFTER LOCKED WHILE DRIVING DIAG \$36.00	313	USA	148020	1	USA	Q21	V05
DRIVERS SEAT BELT WONT LATCH	517	USA	148517	2	USA	Q21	V05
LEFT FRONT SEAT BELT WILL NOT STAY LATCHED	989	USA	148525	1	USA	Q21	V05
S26 INSTALL SPECIAL ORDERED DRIVERS SEAT BELT RECIEVER INTERMITTANT CONCERN COMES UNLATCHED WHILE DRIVING	616	USA	148072	1	USA	Q21	V05
INT DR SEAT BELT DONT LATCH, CANT HEAR IT CLICK	889	USA	148595	2	USA	Q21	V05
CK ADVISE DRIVERS SEAT BELT INOP PARTS NOW IN STOCK	810	USA	345335	2	USA	Q21	V05
DRIVERS SEAT BELT WILL INTERMITTENTLY COME UNLATCHED	810	USA	345335	E84	USA	Q21	V05

DR FRT SEATBELT DOES NOT STAY LATCHED	734	USA	345352	1	USA	Q21	V05
CUST STATES THE DR SIDE BUCKLE WILL RELEASE SEAT BELT AT TIMES, INSTALL SOP 1LZ.7861202.AAB	651	USA	158486	E84	USA	Q21	V05
C S DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING . .	417	USA	153480	1	USA	Q21	V05
CHECK LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING	573	USA	123230	2	USA	Q21	V05
S28 CUST SAYS L F SEAT BELT KEEPS POPPING OFF	314	USA	363604	2	USA	Q21	V05
S25 DRIVERS SEAT BELT WONT LATCH, PART IN	601	USA	123309	E84	USA	Q21	V05
DRIVERS SIDE SEATBELT DOESNT LATCH AT TIMES	408	USA	36403R	2	USA	Q21	V05
CUSTOMER STATES DRMER SEAT BELT KEEPS COMING LOOSE WHILE DRIVING	704	USA	171095	E84	USA	Q21	V05
DR. SEATBELT COMES UNFASTENED AT TIMES	338	USA	121819	2	USA	Q21	V05
C S LF SEATBELT KEEPS COMING LOOSE AT LATCH	704	USA	121213	1	USA	Q21	V05

C S LEFT FRONT SEAT BELT BUCKLE WONT LATCH	704	USA	121213	1	USA	Q21	V05
L F SEAT BELT COMES UNHOOKED. PLS R R (PARTS SHOULD HAVE BEEN ORDERED	704	USA	121213	1	USA	Q21	V05
C S LEFT FRONT SEAT BELT BUCKLE COMES UNLATCHED WHILE DRIVING INT.	704	USA	121213	E84	USA	Q21	V05
CUSTOMER STATES DRIVERS SEATBELT BUCKLE RELEASES	252	USA	121620	E84	USA	Q21	V05
PASSENGER SEATBELT WILL NOT LATCH (PARTS IN)	910	USA	121026	E84	USA	Q21	V05
LH FRT SEAT BELT BUCKLE IS NOT HOLDING ALL THE TIME	252	USA	121641	2	USA	Q21	V03
CUSTOMER STATES THE DRIVERS SIDE SEAT BELT WILL NOT HOLD (SOP)	402	USA	153024	2	USA	Q21	V05
CUST SATES LEFT FRONT SEAT BELT BUCKLE DOESNT STAY LATCHED	973	USA	113510	1	USA	Q21	V05
CUS ST CK SEAT BELTS FT PASS DISCONNECTS WHILE DRIVING	732	USA	113058	E84	USA	Q21	V05
OWNER STATES LEFT FRONT SEATBELT RELEASES ON OWN	.	USA	314474	E84	USA	Q21	V05
CUST STS BOTH FRONT SEATBELT BUCKLES DONT HOLD PROPERLY, STICK CCC S40	732	USA		E84	USA	Q21	V05
CK DR SEATBELT POPS OUT WHILE DRIVING	702	USA	171169	E84	USA	Q21	V05

CUST SAYS THGE LF SEATBELT BUCKLE COMES UNLATCHED SOP TECH 502	702	USA	172404	1	USA	Q21	V05
RECALL ON SEATBELT WAS DONE BUT SEATBELT IS NOT LATCHING LEFT FRONT SEAT BELT CK	702	USA	171189	1	USA	Q21	V05
CUSTOMER STATES DRIVERS SEAT BELT DONT LOCK ALL THE TIME	518	USA	113082	1	USA	Q21	V05
C S DRIVERS SEAT BELT COMES UNLATCHED SOP IS IN	631	USA	113103	1	USA	Q21	V05
CUST STATES THAT DRIVERS SIDE SEAT BELT UNHOOKS ON ITS OWN.	814	USA	314541	1	USA	Q21	V05
CS SEAT BELT BUCKLES NOT HOLDING	71B	USA	314032	1	USA	Q21	V05
C STATES DRIVES SIDE SEAT BELT DONT LOCK.	71B	USA	314061	2	USA	Q21	V03
C S DRIVERS SEAT BELT NOT LOCKING (SOP)	518	USA	314017	2	USA	Q21	V05
CUSTOMER STATES CK BOTH FRONT SEAT BELTS UNLATCH AT TIMES FOR NO REASON	618	USA	314150	2	USA	Q21	V05
REP. DRIVERS SEAT BELT WILL NOT LATCH	614	USA	147018	1	USA	Q21	V05
CUST STATES THE DRIVERS SEAT BELT CONSTANTLY COMES LOOSE AFTER IT HAS BEEN FASTENED.	614	USA	147312	1	USA	Q21	V05

DRIVERS SEATBELT COMES UNDONE REPLACE BOTH FRONT	216	USA	144043	1	USA	Q21	V05
DIAG DRIVERS SEAT BELT BUCKLE COME UNDONE WHILE DRIVING AND CHECK ALL THE OTHER BELTS	405	USA	152603	1	USA	Q21	V05
CK BOTH FRONT SEAT BELT BUCKLES COMING UNLATCH	918	USA	152535	1	USA	Q21	V05
CUST STATES THAT DRIVERS SEAT BELT WILL NOT STAY LATCHED	405	USA	152568	2	USA	Q21	V05
LEFT FRONT SEAT BELT BUCKLE WILL NOT STAY LATCHED.	405	USA	367331	E84	USA	Q21	V05
DRIVERS SEATBELT BUCKLE COMES UNLATCHED SOMETIMES	503	USA	174022	1	USA	Q21	V05
CUST STATES DRIVER SEAT BELT BUCKLE RELEASE CLIP DOES NOT COME ALL THE UP WHEN ENGAUGED	215	USA	315071	1	USA	Q21	V05
DRIVERS SIDE SEAT BELT WONT LATCH	610	USA	315062	E84	USA	Q21	V05
DRIVER SIDE SEAT BELT UNLATCHES WHEN DRIVING.	610	USA	116402	1	USA	Q21	V05

DRIVERS SIDE SEAT BELT WONT LATCH	843	USA	121688	2	USA	Q21	V06
CK FOR DRIVERS SEATELT KEEPS COMING UNHOOKED	843	USA	326355	E84	USA	Q21	V06
FRONT SEAT BELT BUCKLES WONT HOLD	*	USA	116802	E84	USA	Q21	V05
OWNER REPORTS D S FRONT SEAT BELT COMES UNHOOKED BY SELF CK ALL BELTS S26		USA	121420	EB4	USA	Q21	V05
CUST STATES PASS SIDE SEAT BELT IS POPPING LOOSE WHEN IN USE	*	USA	121218	E84	USA	Q21	V05
DRIVERS SIDE SEATBELT WILL COME LOOSE BY ITSELF	901	USA	123008	EB4	USA	Q21	V05
SEAT BELTS COMING UNLATCHED. PART HERE	901	USA	123002	E84	USA	Q21	V05
LEFT FT. SEAT BELT COMES UNHOOKED WHILE DRIVING SOP HERE.	903	USA	152707	1	USA	Q21	V05
CUST. REQUEST CK. FOR LF SEAT BELT WILL NOT LATCH AT TIMES	903	USA	152707	2	USA	Q21	V05
CUSTOMER STATES SEATBELT WONT LATCH	915	USA	152540	1	USA	Q21	V05
DRIVERS SEAT BELT COMES UNBUCKLED	936	USA	152518	2	USA	Q21	V05

SOP SEAT BELT INOP S40	281	USA	152032	E84	USA	Q21	V05
S40 CUSTOMER STATES LEFT SEAT BELT BUCKLE POPS OUT DOES NOT RETAIN SEAT BELT.	281	USA	152032	1	USA	Q21	V05
S40 CUSTOMER STATES RT FT SEAT BELT BUCKLE RELEASES WHILE DRIVING	214	USA	156623	E84	USA	Q21	V05
DRIVERS SEAT BELT BUCKLE POPS OUT OF RECEPTACLE OFTEN	817	USA	152016	1	USA	Q21	V05
DRIVER SIDE SEAT BELT WONT STAY ATTACHED	817	USA	152016	1	USA	Q21	V05
D SIDE SEAT BELT KEEPS COMING OFF	817	USA	152016	1	USA	Q21	V05
CUST STATES DRIVERS SEAT BELT COMES UNDONE WHEN DRIVING	254	USA	152481	1	USA	Q21	V05
SEATBELT BUCKLE COMES UNLATCHED WHILE DRIVING, SOP HERE SEE 89397 TECH 351	940	USA	152406	E84	USA	Q21	V05
INSPECT FOR SEAT BELT NOT LATCHING SOP HERE	817	USA	152019	E84	USA	Q21	V05
DRIVER SEAT BELT WONT STAY BUCKLED.	903	USA	152440	2	USA	Q21	V05
CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT STAY LATCHED	972	USA	152013	1	USA	Q21	V05
DRIVERS SEAT BELT BUCKLE RELEASES WHILE DRIVING..NO WARNING	972	USA	152017	E84	USA	Q21	V05

CUST REPORTS DRIVERS SEAT BELT WILL NOT STAY LATCHED AT TIMES...POPS OUT	972	USA	152013	1	USA	Q21	V05
C S DRIVERS SEATBELT COMES OFF DRIVING DOWN THE ROAD	915	USA	152498	1	USA	Q21	V05
L.F. SEAT BELT BUCKLE COMES LOOSE AT TIMES SOP IN	512	USA	152303	1	USA	Q21	V05
C S DRIVERS SEAT BELT POPS LOSE WHILE DRIVING	512	USA	152303	1	USA	Q21	V05
C S DRIVERS SEAT BELT DOES NOT BUCKEL SEE TOM IN PARTS	512	USA	152020	E84	USA	Q21	V05
S28 THE DRIVERS SEAT BELT BUBKLE COMES UNLATCHED.	512	USA	152740	E84	USA	Q21	V05
DRIVERS SIDE SEAT BELT WONT LATCH	713	USA	152168	2	USA	Q21	V05
CUSTOMER STATES SEAT BELT ON DRIVER SIDE DOES NOT WORK	361	USA	152098	2	USA	Q21	V05
DRIVERS SIDE SEAT BELT IS RELEAEING BY ITSELF	512	USA	152067	2	USA	Q21	V05
DRIVER SIDE SEAT BELT LATCH WONT HOLD	512	USA	152303	E84	USA	Q21	V05
S25 L F SEAT BELT COMES UNFASTENED	512	USA	152302	E84	USA	Q21	V05
DRIVERS SIDE SEATBELT WONT STAY BUCKLED	281	USA	152052	1	USA	Q21	V05
DRIVER SIDE SEATBELT RECIVER DOES NOT HOLD	409	USA	152753	E84	USA	Q21	V05

BOTH FRONT SEAT BELT BUCKLES DONT LATCH	713	USA	152044	2	USA	Q21	V05
CHECK DRIVER FRONT SEAT BUCKLE COMES LOOSE WHILE DRIVING	713	USA	152024	E84	USA	Q21	V05
CHECK DRIVERS SAFETY BELT LATCH HAS RELEASED A FEW TIMES	512	USA	152300	E84	USA	Q21	V05
S39 CUSTOMER STATES SEAT BELT BUCKLE LOOSE	956	USA	124125	E84	USA	Q21	V05
T90 DRIVER SEAT BELT UNBUKLE ST TIMES BY IT SELF	713	USA	152031	E84	USA	Q21	V74
S26 BOTH FRT. SEAT BELT BUCKLES HAVE POPPED OPEN AT TIMES WHEN DRIVING	713	USA	152049	E84	USA	Q21	V05
S26 DRIVERS SEAT BELT BUCKLE COMES UNBUCKLED WHILE DRIVING	713	USA	152049	1	USA	Q21	V05
DRIVERS SEAT BELT KEEPS COMING UNLATCHED WHEN DRIVING	830	USA	152752	1	USA	Q21	V74
DRIVER SEAT BELT COMES UNLATCHED WHILE DRIVING	281	USA	152024	E84	USA	Q21	V05
DR SEAT BELT BUCKLE COMES UNBUCKLED WHEN DRIVING	281	USA	152024	2	USA	Q21	V03
DRIVERS SEAT BELT BUCKLE NOT LATCHING PROP	281	USA	152037	E84	USA	Q21	V05

DRIVER SIDE SEATBELT RELEASE WHEN STOPPING...SOP PARTS..	972	USA	162002	1	USA	Q21	V05
BOTH FT SEAT BELTS UNBUCKLE WHILE DRIVING	872	USA	171206	E84	USA	Q21	V05
SEAT BELT WILL NOT STAY LATCHED	903	USA	152446	2	USA	Q21	V05
CUSTOMER STATES INSPECT FOR DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY ADVISE	915	USA	162211	1	USA	Q21	V05
CHECKED IGH FRONT SEAT BELTT LATCH WONT WORK	281	USA	152032	E84	USA	Q21	V05
LEFT FRONT SEAT BELT COMES UNLATCHED	281	USA	152029	E84	USA	Q21	V05
CK DRIVERS SEAT BELT POPS LOOS DRIVING	281	USA	152241	2	USA	Q21	V05
LEFT FRONT SEAT BELT COMES UNLATCHED	281	USA	152029	E84	USA	Q21	V05
THE DRIVERS SIDE SEAT BELT COMES UNLATCH WHILE DRIVING 328 CK AND SAYS THEY ARE OK	972	USA	152007	1	USA	Q21	V05
DRIVERS SEAT BELT KEEPS COMING UNBUCKLED	281	USA	367032	2	USA	Q21	V05
CUSTOMER STATES THE LEFT FORNT SEATBELT BUCKLE INTERMITTENTLY COMES LOOSE	903	USA	367311	2	USA	Q21	V05

CUST STATES THE FRONT SEATBELTS ARE UNBUCKLING. WE PERFORMED RECALL TEST 8 28 01	972	USA	152012	2	USA	Q21	V05
FRONT SEAT BELTS WILL NOT STAY ATTACHED	972	USA	152012	2	USA	Q21	V05
CUST STATES THE DRIVERS SEATBELT BUCKLE KEEPS POPPING LOOSE	972	USA	367365	E84	USA	Q21	V05
C S DRIVER SEAT BELT BUCKLE NOT LATCHING	915	USA	152210	1	USA	Q21	V05
C S DRIVERS SEATBELT BUCLE REALESES	915	USA	152210	E84	USA	Q21	V05
RF SEAT BELT BUCKLE POPS LOOSE	801	USA	156559	1	USA	Q21	V05
SEAT BELT BUCKLE INOP, SOP IN PASS FRONT SEAT BELT BUCKLE RELEASES BY ITSELF	703	USA	127012	1	USA	Q21	V05
CHECK FOR SEAT BELT NOT LATCHING AT TIMES	757	USA	124018	E84	USA	Q21	V05
SEAT BELT ON PASS. SIDE COMES UNBUCKLED RECALL??	804	USA	127072	E84	USA	Q21	V05
LEFT FRONT SEAT BELT DISCONNECTS BY ITSELF	*	USA	345834	E84	USA	Q21	V05
SERVICE PART WARR. SEAT BELT COMES UNHOOKED. REPLACED ON RO 44808	360	USA	174011	E93	USA	Q21	V05
SEAT BELT COMING UNSNAPED CHECK AND ADVISE	208	USA	174205	1	USA	Q21	V05
DRIVERS SEAT BELT BUCKLE UNCOUPLES WHILE IN USE	208	USA	354708	E84	USA	Q21	V05

TBL2001 ExpedLF_A WS_VL_CD	TBL2001 ExpedLF_V RT_CD	TBL2001 ExpedLF_TI S_FLAG	TBL2001 ExpedLF_VIN_CD	TBL2001 ExpedLF_V EH_LINE_C D	TBL2001 ExpedLF_M KT_DERIVE D	TBL2001 ExpedLF_B OD_CAB_S TL	TBL2001 ExpedLF_V ER_SERIES _CD	TBL2001 ExpedLF_D RIVE_CD
B3	S08		1FMRU15WX1	T/B3	*	TWD	T/EF	T/B
B3	S08		1FMRU16L11L	T/B3	*	TWD	T/EF	T/B
B4	S08		5LMEU27R91L	T/B4	*	TWB	T/EL	T/B
B3	S08		1FMRU15W81L	T/B3	*	TWD	T/EF	T/B
B3	S08		1FMPU18L21L	T/B3	*	TVA	T/EF	T/E
B4	S08		5LMFU28R41L	T/B4	*	TWD	T/EL	T/E
B4	S08		5LMFU28R81L	T/B4	*	TWD	T/EL	T/E
B3	S08	@	1FMPU18L51L	T/B3	*	TVA	T/EF	T/E
B3	S08		1FMPU18L11L	T/B3	*	TVA	T/EF	T/E

B3	S08		1FMRU17WX1	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W41	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W81	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W31	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W31	T/B3	*	T/WD	T/EF	T/B
B3	S08	Ⓢ	1FMRU15L21L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W61	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W01	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L11L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W51	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17W51	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMPU18L91L	T/B3	*	T/VA	T/EF	T/E
B3	S08		1FMRU15LX1L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L71L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15L81L	T/B3	*	T/WD	T/EF	T/B

MOA-811 12132

B3	S08		1FMRU15WX1	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15L41L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15L41L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU16L41L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU16L41L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W11	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W81	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15L81L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17L71L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU16L61L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15L01L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15WX1	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W91	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W51	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B

B3	S08		1FMRU15W21L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMPU16L41L		T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU17W41L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W11L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W21L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMPU18L41L		T/B3	*	T/NA	T/EF	T/E
B3	S08	⊙	1FMRU15W81L		T/B3	*	T/WD	T/EF	T/B
B4	S08		5LMEU27R11L		T/B4	*	T/WB	T/EL	T/B
B4	S08		5LMEU27R41L		T/B4	*	T/WB	T/EL	T/B
B4	S08		5LMEU27R51L		T/B4	*	T/WB	T/EL	T/B
B4	S08		5LMFU28R41L		T/B4	*	T/WD	T/EL	T/E
B4	S08		5LMFU28R11L		T/B4	*	T/WD	T/EL	T/E
B3	S08		1FMPU16L11L		T/B3	*	T/WD	T/EF	T/E

B3	S08	@	1FMRU18W91L	T/B3	*	T/W/D	T/EF	T/E
B3	S08		1FMRU18W71L	T/B3	*	T/W/D	T/EF	T/E
B3	S08		1FMRU17L41LE	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W41L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W21L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W21L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU16W41L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W31L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17W11L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W51L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W91L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17L41LE	T/B3	*	T/W/D	T/EF	T/B

B3	S08		1FMRU17W61	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B4	S08		6LMEU27RX1L	[REDACTED]	T/B4	*	T/W/B	T/EL	T/B
B4	S08		5LMFU28R91L	[REDACTED]	T/B4	*	T/W/D	T/EL	T/E
B4	S08		5LMFU28A11L	[REDACTED]	T/B4	*	T/W/D	T/EL	T/E
B4	S08		5LMEU27R91L	[REDACTED]	T/B4	*	T/W/B	T/EL	T/B
B4	S08		5LMEU27R11L	[REDACTED]	T/B4	*	T/W/B	T/EL	T/B
B4	S08		5LMEU27R41L	[REDACTED]	T/B4	*	T/W/B	T/EL	T/B
B3	S08		1FMRU15W11	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17L81L	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B

B3	S08		1FMRU15LX1L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W71	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W61	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15L31L	T/B3	*	T/WD	T/EF	T/B
B3	S08	②	1FMRU16WX1	T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU15L11L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15L41L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15L41L	T/B3	*	T/WD	T/EF	T/B
B4	S08		5LMEU27RX1	T/B4	*	T/WB	T/EL	T/B
B4	S08		5LMEU27R41	T/B4	*	T/WB	T/EL	T/B
B3	S08		1FMRU16W71	T/B3	*	T/WD	T/EF	T/B
B4	S08		6LMFU28R21L	T/B4	*	T/WD	T/EL	T/E

R004-011 12137

B4	S08		5LMFU28R21	T/B4	*	T/WD	T/EL	T/E
B3	S08		1FMFU16LX1	T/B3	*	T/WD	T/EF	T/E
B3	S08	@	1FMFU16L31	T/B3	*	T/VA	T/EF	T/E
B3	S08	@	1FMFU16L81	T/B3	*	T/WD	T/EF	T/E
B4	S08		5LMFU28RX1	T/B4	*	T/WD	T/EL	T/E
B3	S08		1FMRU16W9	T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU15W1	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU16W6	T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU15W2	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17LX1	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W8	T/B3	*	T/WD	T/EF	T/B

R000-011 12138

B3	S08		1FMRU15L01	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W2	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L71	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU16L61	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L01	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W9	T/B3	*	T/WD	T/EF	T/B
B4	S08		6LMFU28R91	T/B4	*	T/WD	T/EL	T/E
B3	S08	@	1FMRU16W0	T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU16WX	T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU16W8	T/B3	*	T/WD	T/EF	T/E

B4	S08		5LMFU28R31L		T/B4	*	T/WD	T/EL	T/E
B3	S08		1FMRU16W61		T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU16W51		T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMPU18L91L		T/B3	*	T/VA	T/EF	T/E
B3	S08		1FMPU18L51L		T/B3	*	T/VA	T/EF	T/E
B3	S08		1FMRU16W91		T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU16W11		T/B3	*	T/WD	T/EF	T/E
B4	S08		5LMFU28R91L		T/B4	*	T/WD	T/EL	T/E
B4	S08		5LMFU28R51L		T/B4	*	T/WD	T/EL	T/E

NOV-011 12148

B4	S08		5LMFU28R11	[REDACTED]	T/B4	*	T/W/D	T/EL	T/E
B3	S08		1FMFU18LX1	[REDACTED]	T/B3	*	T/W/D	T/EF	T/E
B3	S08		1FMRU16W1	[REDACTED]	T/B3	*	T/W/D	T/EF	T/E
B3	S08		1FMFU18L61	[REDACTED]	T/B3	*	T/A	T/EF	T/E
B4	S08		5LMFU28R91	[REDACTED]	T/B4	*	T/W/D	T/EL	T/E
B3	S08		1FMRU15W2	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B4	S08		5LMFU28R91	[REDACTED]	T/B4	*	T/W/D	T/EL	T/E
B3	S08		1FMRU16WX	[REDACTED]	T/B3	*	T/W/D	T/EF	T/E
B3	S08		1FMRU15W4	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17L51	[REDACTED]	T/B3	*	T/W/D	T/EF	T/B

B3	S08		1FMRU15W21L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15WX1L	T/B3	*	T/WD	T/EF	T/B
B3	S08	@	1FMRU15W51L	T/B3	*	T/WD	T/EF	T/B
B3	S08	@	1FMRU15L51L	T/B3	*	T/WD	T/EF	T/B
B3	S08	@	1FMRU15W41L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15LX1L	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU16WX1L	T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMPU18LX1L	T/B3	*	T/VA	T/EF	T/E
B3	S08		1FMRU16W81L	T/B3	*	T/WD	T/EF	T/E
B4	S08		5LMFU28R51L	T/B4	*	T/WD	T/EL	T/E
B3	S08		1FMPU18L71L	T/B3	*	T/VA	T/EF	T/E
B3	S08		1FMRU15W21L	T/B3	*	T/WD	T/EF	T/B

B3	S08		1FMPU16L11L		T/B3	*	TVA	T/EF	T/E
B3	S08		1FMRU15W51		T/B3	*	TWD	T/EF	T/B
B3	S08		1FMRU16W31		T/B3	*	TWD	T/EF	T/E
B3	S08		1FMPU18L61L		T/B3	*	TVA	T/EF	T/E
B4	S08		5LMFU28R91L		T/B4	*	TWD	T/EL	T/E
B4	S08		6LMFU28R91L		T/B4	*	TWD	T/EL	T/E
B4	S08		5LMFU28R91L		T/B4	*	TWD	T/EL	T/E
B4	S08		5LMFU28R31L		T/B4	*	TWD	T/EL	T/E
B4	S08	②	5LMFU28R91L		T/B4	*	TWD	T/EL	T/E
B3	S08		1FMRU15W51		T/B3	*	TWD	T/EF	T/B
B3	S08		1FMRU15W31		T/B3	*	TWD	T/EF	T/B

B3	S08		1FMPU18L81L		T/B3	*	T/VA	T/EF	T/E
B3	S08		1FMRU17L81L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15LX1L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L81L		T/B3	*	T/WD	T/EF	T/B
B4	S08		5LMEU27RX1L		T/B4	*	T/WB	T/EL	T/B
B3	S08		1FMPU18L11L		T/B3	*	T/VA	T/EF	T/E
B4	S08		5LMFU28R61L		T/B4	*	T/WD	T/EL	T/E
B4	S08		5LMFU28R71L		T/B4	*	T/WD	T/EL	T/E
B3	S08		1FMRU18W21L		T/B3	*	T/WD	T/EF	T/E

B3	S08		1FMRU17L21	T/B3	*	TWD	T/EF	T/B
B4	S08		5LMEU27R31	T/B4	*	TWB	T/EL	T/B
B3	S08	Ⓢ	1FMPU18L91	T/B3	*	TWD	T/EF	T/E
B3	S08		1FMRU17LB1	T/B3	*	TWD	T/EF	T/B
B3	S08		1FMRU15W1	T/B3	*	TWD	T/EF	T/B
B3	S08		1FMPU18L61	T/B3	*	TVA	T/EF	T/E
B3	S08		1FMRU15W9	T/B3	*	TWD	T/EF	T/B
B3	S08		1FMRU15W9	T/B3	*	TWD	T/EF	T/B
B3	S08		1FMPU18L91	T/B3	*	TVA	T/EF	T/E
B3	S08		1FMRU17W3	T/B3	*	TWD	T/EF	T/B
B3	S08		1FMRU17LX1	T/B3	*	TWD	T/EF	T/B

ROSA-011 12148

B3	S08		1FMRU15W81L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17W21L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMPU16L01L		T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU15W71L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU16L41LE		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17WX1L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L01LE		T/B3	*	T/WD	T/EF	T/B
B3	S08	Q	1FMRU17L11LE		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W61L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W91L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17W41L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17W51L		T/B3	*	T/WD	T/EF	T/B

ROD-011 12146

B3	S08	@	1FMRU15WX1L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15WX1L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17W91L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W11L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17L01LA	T/B3	*	T/W/D	T/EF	T/B
B3	S08	@	1FMRU15W21L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W31L	T/B3	*	T/W/D	T/EF	T/B
B3	S08	@	1FMRU15WX1L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W81L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17L81LA	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W01L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU17W71L	T/B3	*	T/W/D	T/EF	T/B
B3	S08		1FMRU15W01L	T/B3	*	T/W/D	T/EF	T/B

B3	S08		1FMRU17L21	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W1	T/B3	*	T/WD	T/EF	T/B
B3	S08	⊙	1FMRU17W5	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15L71	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17W5	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17W1	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W9	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15WX	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L81	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17W1	T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L01	T/B3	*	T/WD	T/EF	T/B

B3	S08		1FMRU17WX1L		T/B3	*	T/WD	T/EF	T/B
B3	S08	@	1FMRU15W71L		T/B3	*	T/WD	T/EF	T/B
B3	S08	@	1FMRU17L11L		T/B3	*	T/WD	T/EF	T/B
B3	S08	@	1FMRU15W71L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU17L01L		T/B3	*	T/WD	T/EF	T/B
B3	S08	@	1FMRU15W61L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15L61L		T/B3	*	T/WD	T/EF	T/B
B3	S08	@	1FMRU15W61L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15WX1L		T/B3	*	T/WD	T/EF	T/B
B4	S08		5LMEU27R31L		T/B4	*	T/WB	T/EL	T/B
B4	S08	@	5LMEU27R41L		T/B4	*	T/WB	T/EL	T/B

RODA-911 12149

B3	S08		1FMRU15W21L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMPU18L81LE		T/B3	*	T/A	T/EF	T/E
B4	S08		5LMFU28R81L		T/B4	*	T/WD	T/EL	T/E
B3	S08		1FMRU17L51LA		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMRU15W21L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMFU16L91LE		T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMPU18L81LE		T/B3	*	T/A	T/EF	T/E
B3	S08		1FMRU15WX1L		T/B3	*	T/WD	T/EF	T/B
B3	S08		1FMFU18L71LA		T/B3	*	T/A	T/EF	T/E
B4	S08		5LMFU28RX1L		T/B4	*	T/WD	T/EL	T/E
B3	S08		1FMRU16W21L		T/B3	*	T/WD	T/EF	T/E
B3	S08		1FMRU16W81L		T/B3	*	T/WD	T/EF	T/E
B4	S08		5LMFU28R31L		T/B4	*	T/WD	T/EL	T/E

FORM-011 12150

TBL2001 ExpedLF_E NG_CD	TBL01Expe d- Navafterrec all_ID	TBL01Expe d- Navafterrec all_MDL_YR	TBL01Expe d- Navafterrec all_SORT_I NDEX	TBL01Expe d- Navafterrec all_TRANS_ CD	TBL01Expe d- Navafterrec all_PLANT_ CD	TBL01Exped- Navafterrecall_PRO DN_DT	TBL01Exped- Navafterrecall_WRT Y_START_DT	TBL01Expe d- Navafterrec all_NAME	TBL01Expe d- Navafterrec all_DOC_N UM
TVN	94	2001	28	T/DU	AP	2/2/2001	3/17/2001	SUNNY KING FORD	15801901
TVZ	213	2001	19	T/DE	AP	4/27/2001	5/22/2001	WOODY ANDERSON FORD	6187451
TWC	282	2001	43	T/DE	AP	1/5/2001	5/17/2001	RAY PEARMAN LINCOLN MERCURY,	2192501
TVN	106	2001	40	T/DU	AP	4/24/2001	8/6/2001	LEWIS FORD	341940A
TVZ	238	2001	42	T/DE	AP	3/14/2001	9/14/2001	W & W FORD SALES, INC.	4641850
TWC	282	2001	23	T/DE	AP	3/7/2001	3/28/2001	FIESTA LINCOLN- MERCURY	3198201
TWC	251	2001	12	T/DE	AP	3/3/2001	9/8/2001	FIESTA LINCOLN- MERCURY	2490201
TVZ	320	2001	28	T/DE	AP	10/23/2000	11/9/2000	DON SANDERSO N FORD, INC.	63722201
TVZ	237	2001	43	T/DE	AP	4/27/2001	5/15/2001	LOU GRUBB FORD	2688351

TVN	4	2001	4	T/DU	AP	4/14/2001	6/25/2001	LOU GRUBB FORD	2556151
TVN	140	2001	11	T/DU	AP	4/18/2001	5/26/2001	LOU GRUBB FORD	3123151
TVN	128	2001	62	T/DU	AP	2/1/2001	3/31/2001	NORTH COUNTY FORD	230724A
TVN	153	2001	24	T/DU	AP	3/16/2001	6/12/2001	REDLANDS FORD	7188451
TVN	162	2001	23	T/DU	AP	3/31/2001	10/10/2001	REDLANDS FORD	7095751
TVZ	212	2001	18	T/DE	AP	11/20/2000	1/29/2001	BEVERLY HILLS FORD	13801002
TVN	123	2001	57	T/DU	AP	4/23/2001	5/29/2001	LITHIA FORD OF CONCORD	331888A
TVN	181	2001	52	T/DU	AP	4/23/2001	6/30/2001	PASADENA FORD, INC.	3093240
TVZ	51	2001	19	T/DE	AP	4/24/2001	7/17/2001	MOSS BROS. FORD	1549050
TVN	134	2001	5	T/DU	AP	4/14/2001	7/7/2001	CERRITOS FORD	25390105
TVN	13	2001	13	T/DU	AP	9/30/2000	12/23/2000	FORD WEST	3797252
TVZ	224	2001	30	T/DE	AP	8/21/2000	11/21/2000	CERRITOS FORD	26218705
TVZ	188	2001	59	T/DE	AP	2/3/2001	3/20/2001	PACIFIC FORD	9758551
TVZ	33	2001	1	T/DE	AP	5/14/2001	7/6/2001	PACIFIC FORD	9379852
TVZ	192	2001	63	T/DE	AP	9/24/2000	1/9/2001	FIESTA FORD, INC.	4645252

TVN	89	2001	23	T/DU	AP	4/8/2001	8/25/2001	STAR FORD	55373701
TVZ	204	2001	10	T/DE	AP	4/4/2001	8/8/2001	EL CAJON FORD	5886550
TVZ	314	2001	20	T/DE	AP	4/4/2001	8/8/2001	EL CAJON FORD	5886550
TVZ	204	2001	10	T/DE	AP	4/4/2001	8/8/2001	EL CAJON FORD	5886550
TVZ	314	2001	20	T/DE	AP	4/4/2001	8/8/2001	EL CAJON FORD	5886550
TVN	177	2001	48	T/DU	AP	8/22/2000	11/1/2000	KEN GRODY FORD - CARLSBAD	4888952
TVN	107	2001	41	T/DU	AP	2/27/2001	7/31/2001	BOB BAKER FORD - MISSION VALLEY	373354F
TVZ	191	2001	82	T/DE	AP	10/17/2000	11/13/2000	BOB WONDRIES FORD	240046B
TVZ	37	2001	5	T/DE	AP	2/9/2001	4/30/2001	PEYTON CRAMER FORD	4888462
TVZ	202	2001	8	T/DE	AP	10/14/2000	3/15/2001	GALPIN FORD	5888892
TVZ	216	2001	22	T/DE	AP	4/7/2001	8/9/2001	GALPIN FORD	8070431
TVN	83	2001	27	T/DU	AP	1/31/2001	5/12/2001	ED BUTTS FORD	6208348
TVN	103	2001	37	T/DU	AP	1/20/2001	3/2/2001	RACEWAY FORD	441281C
TVN	136	2001	7	T/DU	AP	3/30/2001	4/22/2001	AIRPORT MARINA FORD	24354401

T/VN	162	2001	33	T/DU	AP	4/23/2001	7/26/2001	FULLER FORD	172091A
T/VZ	327	2001	33	T/DE	AP	12/19/2000	1/5/2001	FOLSOM LAKE FORD INC	31617701
T/VN	15	2001	15	T/DU	AP	3/9/2001	8/11/2001	HAYWARD FORD	35616201
T/VN	175	2001	46	T/DU	AP	2/6/2001	3/6/2001	BIG VALLEY FORD	42367902
T/VN	159	2001	30	T/DU	AP	4/22/2001	6/23/2001	MELROSE FORD	6914401
T/VZ	233	2001	39	T/DE	AP	4/19/2001	7/16/2001	GEWEKE FORD	12747101
T/VN	112	2001	46	T/DU	AP	8/11/2000	10/24/2000	VISTA FORD	6149752
T/WC	292	2001	53	T/DE	AP	1/4/2001	8/27/2001	ADVANTAG E LINCOLN- MERCURY	3306801
T/WC	300	2001	6	T/DE	AP	10/26/2000	2/3/2001	SANTA MONICA LINCOLN- MERCURY	20970502
T/WC	285	2001	46	T/DE	AP	10/22/2000	11/22/2000	DOWNEY LINCOLN MERCURY	077883B
T/WC	263	2001	24	T/DE	AP	2/3/2001	5/23/2001	MIKE NAUGHTO N FORD INC	12881904
T/WC	298	2001	4	T/DE	AP	4/19/2001	11/27/2001	KUMPF LINCOLN MERCURY, INC.	127912A
T/VZ	326	2001	34	T/DE	AP	4/18/2001	5/3/2001	HERTZ RAC - DENVER	39571501

T/VN	68	2001	2	T/DU	AP	11/11/2000	3/13/2001	RAY SERAPHIN FORD INC	4281152
T/VN	305	2001	11	T/DU	AP	2/12/2001	2/15/2001	FORD MOTOR COMPANY P&A	10282601
T/VZ	48	2001	14	T/DE	AP	4/20/2001	10/22/2001	JARRETT- BODIFORD FORD	8877101
T/VN	144	2001	15	T/DU	AP	10/28/2000	3/17/2001	DON REID FORD, INC.	9821752
T/VN	171	2001	42	T/DU	AP	9/20/2000	2/22/2001	MAROONE FORD	504365A
T/VN	171	2001	42	T/DU	AP	9/20/2000	2/22/2001	MAROONE FORD	504365A
T/VN	143	2001	14	T/DU	AP	4/23/2001	9/3/2001	GREENWA Y FORD, INC.	6890452
T/VN	147	2001	18	T/DU	AP	4/17/2001	4/25/2001	GREENWA Y FORD, INC.	5632751
T/VN	22	2001	22	T/DU	AP	10/21/2000	3/2/2001	GARBER FORD- MERCURY, INC.	089421B
T/VN	135	2001	6	T/DU	AP	4/12/2001	8/16/2001	DON REID FORD, INC.	853852
T/VN	102	2001	36	T/DU	AP	3/2/2001	7/20/2001	ERNIE HAIRE FORD, INC.	5129051
T/VZ	46	2001	13	T/DE	AP	4/30/2001	5/25/2001	PLANTATIO N FORD	8888551

T/VN	10	2001	10	T/DU	AP	3/16/2001	5/26/2001	ERNIE HAIRE FORD, INC.	6028651
T/WC	278	2001	39	T/DE	AP	1/16/2001	7/26/2001	CENTRAL FLORIDA LINCOLN MERCUR	3476824
T/WC	245	2001	6	T/DE	AP	2/11/2001	7/10/2001	CENTRAL FLORIDA LINCOLN MERCUR	3886652
T/WC	299	2001	5	T/DE	AP	9/26/2000	11/4/2000	PREMIER LINCOLN MERCURY	3675404
T/WC	281	2001	42	T/DE	AP	2/12/2001	6/24/2001	MARGATE LINCOLN- MERCURY INC	283868B
T/WC	291	2001	52	T/DE	AP	2/5/2001	2/26/2001	MARGATE LINCOLN- MERCURY INC	281775D
T/WC	288	2001	49	T/DE	AP	10/30/2000	7/20/2001	MARGATE LINCOLN- MERCURY INC	281534F
T/VN	178	2001	49	T/DU	AP	9/21/2000	5/18/2001	TEAM FORD OF MARIETTA	7676654
T/VZ	40	2001	8	T/DE	AP	3/8/2001	9/3/2001	WARNER ROBINS FORD LINCOLN- MER	7296851

TVZ	189	2001	60	T/DE	AP	1/19/2001	2/16/2001	AKINS FORD CORPORAT ION	8978740
T/VN	115	2001	49	T/DU	AP	4/7/2001	8/30/2001	FREEWAY FORD INC	8992381
T/VN	129	2001	63	T/DU	AP	12/8/2000	2/25/2001	JIM TIDWELL'S WORLD FORD	8521840
TVZ	209	2001	15	T/DE	AP	2/5/2001	6/7/2001	JOHN BLEAKLEY FORD INC	8380751
T/VN	63	2001	31	T/DU	AP	10/15/2000	10/31/2000	ALLAN VIGIL FORD	1028851
TVZ	215	2001	21	T/DE	AP	4/24/2001	8/4/2001	GWINNETT PLACE FORD	8875651
TVZ	205	2001	11	T/DE	AP	2/1/2001	8/17/2001	GWINNETT PLACE FORD	8229052
TVZ	208	2001	12	T/DE	AP	10/28/2000	9/18/2001	J.C. LEWIS MOTOR CO., INC.	28914801
T/WC	276	2001	37	T/DE	AP	4/17/2001	8/18/2001	BARANCO LINCOLN- MERCURY INC	2273702
T/WC	287	2001	48	T/DE	AP	3/13/2001	10/15/2001	PUGMIRE LINCOLN- MERCURY INC	8081252
T/VN	118	2001	50	T/DU	AP	2/5/2001	3/14/2001	WINDWAR D FORD	8957752
T/WC	270	2001	31	T/DE	AP	3/17/2001	4/18/2001	THEISEN MOTORS INC	9836802

T/WC	269	2001	30	T/DE	AP	4/19/2001	9/28/2001	LITHIA LINCOLN MERCURY OF BOIS	347556A
T/NZ	323	2001	29	T/DE	AP	4/22/2001	11/2/2001	FOX LAKE FORD MERCURY, INC.	496501
T/NZ	321	2001	27	T/DE	AP	12/20/2000	8/20/2001	LANDMARK FORD, INC.	9648603
T/NZ	337	2001	43	T/DE	AP	3/1/2001	4/2/2001	KEN DIEPHOLZ FORD L-M INC	041673C
T/WC	295	2001	1	T/DE	AP	10/14/2000	8/7/2001	LINDSAY LINCOLN- MERCURY, INC.	686440
T/VN	67	2001	1	T/DU	AP	2/8/2001	8/1/2001	AIRPORT FORD	1265201
T/VN	172	2001	43	T/DU	AP	4/25/2001	7/14/2001	CHINO HILLS FORD SALES INC	248386A
T/VN	71	2001	5	T/DU	AP	3/9/2001	10/31/2001	PAUL MILLER FORD, INC.	11677201
T/VN	158	2001	29	T/DU	AP	6/8/2001	5/31/2001	DIXIE LINCOLN MERCURY	642565A
T/NZ	25	2001	25	T/DE	AP	1/17/2001	8/22/2001	ADVANTAG E FORD	012421C
T/VN	111	2001	45	T/DU	AP	10/23/2000	11/7/2000	GRAY FORD MERCURY	13340402

TVZ	217	2001	23	T/DE	AP	11/8/2000	4/17/2001	ALL STAR FORD LINCOLN MERCURY,	238812A
TVN	183	2001	34	T/DU	AP	4/18/2001	5/9/2001	HUB CITY FORD, INC.	5118351
TVZ	34	2001	2	T/DE	AP	4/30/2001	5/24/2001	LAMARQUE FORD INC	171372C
TVZ	197	2001	3	T/DE	AP	12/8/2000	8/8/2001	BORDELON MOTORS, INC.	4010801
TVZ	56	2001	24	T/DE	AP	10/12/2000	6/9/2001	LEESVILLE FORD LINCOLN MERCURY	8254101
TVN	89	2001	33	T/DU	AP	4/10/2001	11/9/2001	HARRELSON FORD, INC.	4225140
TWC	242	2001	3	T/DE	AP	4/21/2001	8/9/2001	BAY STATE LINCOLN- MERCURY	4414402
TVN	83	2001	17	T/DU	AP	4/20/2001	12/4/2001	NORRIS FORD OF EASTON, LLC	2034950
TVN	64	2001	32	T/DU	AP	8/10/2000	10/12/2000	ROCKLAND FORD LINCOLN- MERCURY	8195803
TVN	69	2001	3	T/DU	AP	4/20/2001	5/7/2001	ROWE FORD SALES	21809601

T/WC	267	2001	28	T/DE	AP	2/2/2001	8/16/2001	MEL FARR LINCOLN- MERCURY INC	258954B
T/VN	307	2001	13	T/DU	AP	3/3/2001	8/20/2001	GENE BLITMAN FORD SLS INC	2773301
T/VN	72	2001	6	T/DU	AP	4/25/2001	8/20/2001	FAIRLANE FORD SALES, INC.	104938B
T/VZ	223	2001	28	T/DE	AP	1/4/2001	8/28/2001	VICTORY FORD MERCURY, INC.	575540Z
T/VZ	232	2001	38	T/DE	AP	4/19/2001	5/29/2001	SIGNATUR E FORD LINCOLN- MERCURY	073883A
T/VN	85	2001	33	T/DU	AP	4/22/2001	10/9/2001	DUTHLER FORD SALES, INC.	5208101
T/VN	80	2001	14	T/DU	AP	4/26/2001	11/20/2001	SCOTT MCNAMAR A FORD MERCURY OF	043714B
T/WC	250	2001	11	T/DE	AP	12/21/2000	9/4/2001	VARSITY LINCOLN- MERCURY INC	8543604
T/WC	258	2001	19	T/DE	AP	1/26/2001	3/8/2001	VARSITY LINCOLN- MERCURY INC	8579002

T/WC	271	2001	32	T/DE	AP	3/16/2001	8/15/2001	MOMENTUM LINCOLN MERCURY, INC.	7210351
T/VZ	325	2001	31	T/DE	AP	3/11/2001	3/31/2001	INVER GROVE FORD	28546401
T/VN	81	2001	15	T/DU	AP	3/9/2001	5/18/2001	FRIENDLY FORD, INC.	207883B
T/VZ	228	2001	34	T/DE	AP	5/1/2001	8/8/2001	LUTESVILLE MOTOR COMPANY	2762301
T/WC	243	2001	4	T/DE	AP	4/13/2001	9/5/2001	PAUL CERAME LINC-MERC INC	213506E
T/VN	170	2001	41	T/DU	AP	9/27/2000	6/3/2001	GRAY- DANIELS FORD	183418B
T/WC	246	2001	7	T/DE	AP	1/29/2001	1/31/2001	HAYRE FORD LINCOLN MERCURY	078450C
T/VN	59	2001	27	T/DU	AP	4/17/2001	4/30/2001	HILBISH MOTOR CO	5163001
T/VN	141	2001	12	T/DU	AP	4/21/2001	5/31/2001	PLAZA FORD, LINCOLN- MERCURY, I	129034B
T/VZ	42	2001	10	T/DE	AP	4/30/2001	9/28/2001	HARRELSON FORD, INC.	4013540

T/VN	160	2001	31	T/DU	AP	4/24/2001	6/16/2001	HARRELSON FORD, INC.	3876040
T/VN	65	2001	19	T/DU	AP	4/23/2001	6/3/2001	HARRELSON FORD, INC.	3578240
T/VN	131	2001	2	T/DU	AP	4/23/2001	5/17/2001	HARRELSON FORD, INC.	3673840
T/VZ	198	2001	4	T/DE	AP	3/11/2001	3/30/2001	PECHELES FORD MERCURY	10367002
T/VN	311	2001	17	T/DU	AP	9/16/2000	3/10/2001	CROWN FORD	14861004
T/VZ	185	2001	68	T/DE	AP	4/24/2001	8/29/2001	HASTINGS FORD, INC.	048852A
T/VN	60	2001	28	T/DU	AP	4/22/2001	6/29/2001	JOHN MARKEL, INC.	238600B
T/VZ	219	2001	25	T/DE	AP	10/26/2000	8/8/2001	MAGARINO FORD-MERCURY, INC.	3225501
T/VN	304	2001	10	T/DU	AP	1/2/2001	1/27/2001	OASIS FORD	8885652
T/WC	259	2001	20	T/DE	AP	1/2/2001	3/24/2001	MAPLECREST LINCOLN-MERCURY, IN	8473005
T/VZ	227	2001	33	T/DE	AP	2/26/2001	3/7/2001	TOMS FORD, INC.	202014A
T/VN	164	2001	35	T/DU	AP	4/14/2001	6/14/2001	FORD COUNTRY	8344251