

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
BOOK 43
PART 2 OF 4

20402*	NA	AZ	12001	b	FACTORY WARRANTY CUSTOMER STATES DRIVERS SIDE SEAT BELT WONT STAY LATCHED	1 REPLACE BUCKLE	802 USA	171206
1865*	NA	CA	11001	d	DRIVER SEAT BELT POPS OUT WHILE DRIVING	INTERNAL FAULT TEST SYSTEM, FOUND INTERNAL FAULT, REPLACE SEAT BELT BUCKLE	909 USA	171153
7725*	NA	CA	12001	b	CUSTOMER STATES DRIVERS SEAT BELT KEEPS COMING LOOSE FROM SEAT BELT BUCKLE.	VERIFIED CONCERN, DRIVERS SEAT BELT BUCKLE NOT HOLDING BELT REPLACED DRIVERS SIDE SEAT BELT BUCKLE RE TEST OK.	707 USA	172413
4443*	NA	TX	12001	a	CK PASS SIDE FRONT SEAT BELT DOES NOT LATCH	R&R PASSENGER SEAT ASSEMBLY TO REPLACE PASSENGER FRONT SEAT BELT BUCKLE.	291 USA	152052
7784*	NA	CA	12001	e	OTHER RESTRAINT TROUBLES.. CUSTOMER REPORTS.. DRIVERS SEATBELT LOOSE	FAILED SEAT BELT REPLACED DRIVERS SEAT BELT BUCKLE.	631 USA	172401

2001_FSD_Seat_Belt_Query

8473*	NA	TN	11001	b	828 STATES THAT THE PASS SEATBELT WILL NOT STAY LATCHED SEE DARWIN	CHECKED AND FOUND SEAT BELT TO BE RELEASING PREMATURELY. REPLACED SEAT BELT BUCKLE ASSEMBLY.	423 USA	147441
3168*	NA	CO	11001	e	REPLACE RT. SIDE SEAT BELT BUCKLE	NOT LATCHING REPL RT FRT SEATBELT BUCKLE	719 USA	156474
5958*	NA	KY	12001	b	CUSTOMER STATES THE DRIVERS SIDE SEAT BELT COMES UNBUCKLED	BUCKLE FAILED REPLACE BUCKLE ON THE DRIVERS SEAT	270 USA	147081
2797*	NA	IN	11001	e	BOTH SEATBELT BUCKLES IN THE FRONT DO NOT RELEASE FULLY	REPLACED BOTH FRONT SEATBELT BUCKLES, WOULD NOT RELEASE PROPERLY.	219 USA	148025
815*	NA	AL	11001	e	C 8 THAT THE LEFT FRONT SEAT BELT COMES UNLATCHED AT TIMES ADVISE CODE 840	6117 TESTED SEAT BELT BUCKLE. VERIFIED CUST CONCERN, REPLACED BUCKLE. RETESTED, CK OK.	258 USA	121408
8578*	NA	NC	11001	e	PASSENGER SEAT BELT BUCKLE IS INOP ..	R/R PASSENGER SEAT AND REPLACED SEAT BELT ASSY.	252 USA	121630

2001_FSD_Seat_Belt_Query

7735*	NA	CA	11001	b	DRIVERS SIDE SEAT BELT WILL NOT STAY BUCKLED	BELT WILL NOT STAY BUCKLED REPLACE LEFT BUCKLE	630	USA	172436
5450*	NA	CA	11001	d	DRIVERS SEAT BELT POPS OUT WHILE DRIVING	REPLACED DRIVER SIDE SEAT BELT	760	USA	171440
4143*	NA	TN	11001	b	CUSTOMER STATES P 8 FRONT SEAT BLET BUCKLE INOP AT TIMES	REPLACED RIGHT FRONT SEAT BLET BUCKLE	365	USA	121897
1172*	NA	FL	12001	d	CUST STATES SEAT BELT UNBUCKLES WHILE DRIVING	BUCKLES INOP REPLACE BOTH FT SEAT BELT BUCKLES	407	USA	124213
6671*	NA	MA	11001	a	RIGHT SIDE SEAT BELT DOES NO WORK	REPLACE RIGHT SIDE SEAT BELT.	508	USA	111643
8516*	NA	OR	12001	b	RECALL 01521 PASS SEATBELT DOES NOT HOLD	CHECK AND REPLACE BUCKLES	603	USA	171431
1389*	NA	WA	11001	b	CUST STATES THE RP SEAT BELT WILL NOT STAY BUCKLED,REPORT	CONFIRM SEATBELT WILL NOT BUCKLE. REPLACE PASSENGER SIDE SEATBELT. M TIME TO DO REPAIR. CHECK, OK	380	USA	174494

R004-011 17424

2815*	NA	NJ	11001	e	CUSTOMER STATES THE DRIVERS SIDE SEAT BELT IS INOP	VERIFIED DRIVERS SEAT BELT BUCKLE INOP. REPLACED DRIVERS SIDE SEAT BELT BUCKLE. RECHECK OK.	908 USA	118510
4924*	NA	FL	11001	e	GNN CUS STATES D S SEAT BELT LATCH IS INOP AT TIMES,SOP IN SEE DEAL	3003 REMOVED AND REPLACED SOP DRIVERS FRT. SEATBELT BUCKLE.	407 USA	124214
5301*	NA	ID	11001	e	CUST STATES DRIVERS SEATBELT NOT ATTACHED	FOUND SEATBELT BUCKLE LOOSE FROM SENSOR WIRES AND UNATTACHED TO SEAT REPLACE BUCKLE ASSY RECHECK OK	208 USA	172205
3588*	NA	TX	11001	a	CK FOR RH FRONT SEAT BELT NOT LATCHING S25 01821 SEAT BELT	SEAT BELT NOT LATCHING REPLACED BUCKLE.	808 USA	162144
4483*	NA	TX	11001	e	DSIDE SEATBELT INOP S25	11435 42 2861203 R&R L H SEAT BELT BUCKLE, 40 20 40 SEATING, FRT	979 USA	132781
1470*	NA	OH	11001	e	CHECK SEATBELTS	CHECK AND REPLACE SEAT BELTS	814 USA	147030

20238*	NA	IA	11001	b	PASSENGER FRONT SEAT BELT NOT STAYING LATCHED	INSPECT FRONT SEAT BELT BUCKLE REPLACE RIGHT SIDE SEAT BELT BUCKLE FAILED SOP PART	319	USA	141200
5100*	NA	MO	11001	b	DRIVERS SEAT BELT WONT STAY LATCHED. PART HERE TO CORRECT.	REMOVE SEAT ANC REPLACE BUCKLE	518	USA	153115
7945*	NA	OR	11001	a	CUSTOMER STATES DRIVERS SEAT BELT IS BROKE	1 REPLACED SEAT BELT	541	USA	172455
6541*	NA	LA	12001	a	CUSTOMER STATES THE PASSENGER SIDE SEATBELT DOES NOT WORK	REPLACED THE PASSENGER SIDE SEATBELT BUCKLE	318	USA	123371
2232*	NA	OH	11001	d	DRIVERS SEAT BELT WONT STAY LATCHED WHILE DRIVING	DIAG DRIVERS SIDE FRONT SEAT BELT NOT OPERATING PROPERLY WONT LATCH REPLACED SEAT BELT ASY	814	USA	147312
7887*	NA	CA	11001	d	INSTALL SOP FOR PASS FRONT SEAT BELT UNBUCKLES WHILE DRIVING	72: VERIFY PASSENGER SEATBELT UNFASTENS. PART ORDERED, R&R SEAT TRIM COVER AND SEAT TO ACCESS, REPLACED SEATBELT BUCKLE ASSEMBLY, RECHECK OK AT THIS TIME	559	USA	172440

K004-011 17428

	3188*	NA	CO	12001	e	CUST STATES PASSENGER SIDE FRONT SEAT BELT FEMALE END BUTTON IS HARD TO RELEASE	BUCKLE IS BINDING REPLACED RIGHT FRONT SEAT BELT BUCKLE.			303 USA		158001
	1894*	NA	L	11001	b	CUSTOMER STATES L FRT SHOULDER BELT WONT STAY BUCKLED	1 R AND R INNER SEAT BELT BUCKLE ASSEMBLY TO REPLACE			847 USA		141057
	1394*	NA	PA	11001	b	CUSTOMER STATES DR SIDE BELT WILL NOT STAY CLIPPED	TECH VER CONCERN FOUND DR SIDE BELT BROKEN, REPLACED RETESTED ALL OK			570 USA		115302

R094-911 17428

2001_FBD_Seat_Belt_Query

2088*	NA	OH	11001	a	REPAIR SEAT BELT BUCKLE	REPLACE FAULTY RIGHT SEAT BELT BUCKLE	937 USA	147422
831*	NA	NC	12001	a	RIGHT FRONT SEAT BELT NOT CONNECTING	REPLACED SEAT BELT BUCKLE	704 USA	121404
8586*	NA	OR	11001	a	DRIVERS SEAT BELT SOMETIMES UNLATCHES BY ITSELF	FAULTY BUCKLE CHECKED SEAT BELT LATCH, ORDERED AND REPLACED BUCKLE	541 USA	174417
7022*	NA	CA	11001	a	CUST STATES FRONT PASS SEATBELT KEEPS POPPING LOOSE	RECALL REPAIRED AS PER RECALL	805 USA	171447

2001_FSD_Seat_Belt_Query

9508*	NA	MI	11001	e	DRIVERS SEAT BELT RECPT CAME APART	BUCKLE DEFECTIVE REPLACE SEAT BELT BUCKLE ASSEMBLY	517 USA	148431
1402*	NA	DE	11001	b	LEFT SEAT BELT WILL NOT STAY BUCKLED	DOES NOT OPERATE PROPERLY REPLACE LEFT BUCKLE TEST LEFT AND RT SEATBELT BUCKLES	302 USA	118213
8502*	NA	OR	12001	d	CUSTOMER REPORTS LEFT FRONT SEAT BELT UNATTACHES WHILE DRIVING SPECIAL ORDER PARTS IN	VERIFIED CUSTOMER CONCERN AND REPLACED LEFT HAND BUCKLE ASSEMBLY OK AFTER REPAIRS	608 USA	174013
2058*	NA	OH	11001	a	CK FOR DRIVERS BIDE SEAT BELT RANDOMLY DECIDES NOT TO LATCH CUST DID HAVE RECALL PREFORMED AND SAID SEATBELTS WERE FINE AT THAT TIME	20099 CHECKED FOR DRIVERS SEAT BUCKLE NOT WORKING ALL THE TIME. REPLACED DRIVERS SEAT BUCKLE	613 USA	147004

ROSA-011 17430

2001_FSD_Seat_Belt_Query

5674*	NA	CA	11001	e	PASSENGER SIDE FRONT SEAT BELT BUCKLE IS INOPERATIVE, DIAGNOSE AND REPORT.	REPLACE INOP R FRONT SEAT BELT BUCKLE ASSY	780	USA	172220
1155*	NA	OK	11001	e	SEAT BELT INOP	VERIFIED FOUND SEAT BELT BUCKLE NOT BOLTED IN BUCKLE ASSEMBLY PULLED LOOSE OF COVER AND BROKEN WARNING WIRES R AND R DRIVERS SEAT REPLACED SE AT BELT BUCKLE PROBLEM SOLVED	580	USA	162200
9420*	NA	MN	11001	b	CHECK SEAT BELTS....DR SEAT BELT WILL NOT HOLD... CUST REQUEST CHECK ALL BELTS....	840 42 81203 INSPECT AND REPLACE SEAT BELT BUCKLE	652	USA	121718
7727*	NA	CA	12001	e	DRIVERS SIDE SEAT BELT KEEPS POPPING LOOSE	1 REPLACED SEAT BELT, RECHECKED OK.	816	USA	127636
7818*	NA	GA	12001	b	SEAT BELT ON PASS FRONT COMES UNBUCKLED	REPLACED RIGHT SEAT BELT BUCKLE	706	USA	121450

R004-011 17431

2001_FSD_Seat_Belt_Query

8854 *	NA	OK	11001	a	CS DRIVER SEAT BELT WILL COME UNBUCKLED BY ITSELF WHEN DRIVING ON ROUGH ROADS INT TRIM 22	42 SEATBELT ASSEMBLY FRONT REPLACE	405 USA	118068
4824 *	NA	FL	11001	b	CHECK BOTH FRONT SEAT BELT BUCKLES DO NOT HOLD PROPERLY	REPLACE BOTH FRONT SEAT BELTS PER RECALL	853 USA	124475
7884 *	NA	CA	11001	a	01S21 SOP SEAT BELT BUCKLE IS HERE....	REPLACED RIGTH SIDE SEAT BELT BUCKLE, FAILED.	915 USA	172205
7768 *	NA	CA	11001	d	PASSENGER SEATBELT BUCKLE WILL NOT STAY BUCKLED COMES APART WHILE DRIVING PER CUSTOMER	1 COULD NOT VERIFY CONCERN BUT REPLACED FOR SAFTEY REASONS	707 USA	172208
1808 *	NA	PA	11001	a	CUSTOMER STATES SEAT BELT WONT LATCH	REPLACED BOTH FRONT SEAT BELT BUCKLES	814 USA	144421
4373 *	NA	TX	12001	c	C S PASSENGER SIDE FRONT SEAT BELT INOP, SUDDENLY UNLOCKS FROM BUCKLE.....	INSPECTED AND FOUND FAULTY SEAT BELT BUCKLE..... REMOVED AND REPLACED SEAT BELT BUCKLE TO CORRECT.....	830 USA	152719

2001_FSD_Seat_Belt_Query

4502*	NA	TX	11001	d	SEAT BELT COMES OUT WHILE DRIVING	REPLACED LEFT SEAT BELT BUCKLE	408 USA	152708
9030*	NA	UT	11001	e	INSTALL SOP SEATBELT IS PROP	SEAT BELT REPLACE RIGHT FRONT SEAT BELT END 77 STEVE QUALITY CHECK	801 USA	158026
7068*	NA	UT	12001	e		REPL BOTH FRT SEATBELT LATCHES	435 USA	158571
97*	NA	MD	11001	e	INSTALL SOP SEATBELT	CAUBAL 2851203 CC 42 C0C 825 REPLACED SEAT BELT	410 USA	127038
1061*	NA	NC	11001	e		TECH FOUND DRIVERS SEATBELT BUCKLE LATCH FAILING. REPLACED BELT BUCKLE AND RETESTED OK	704 USA	121400
5218*	NA	MI	11001	b	PASS SIDE SEAT BELT WILL NOT LATCH ALL THE TIME.	REPLACED PASS SEATBELT BUCKLE ASSY.	906 USA	141615
5491*	NA	LA	11001	b	PLEASE CK THE SEAT BELT LATCH PASSENGER SIDE COMES UNSNAPPED	DOESNT OPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE	337 USA	129271

R084-011 17433

2001_FSD_Seat_Belt_Query

	3827*	NA	ID	11001	a	INSTALL ORDERED SEAT BELT FOR RECALL	4811 WARR INSTALL SEATBELT LATCH.		208 USA	174437
	8666*	NA	MI	12001	a	PASS. SIDE SEAT BELT WILL NOT LATCH	REPLACED PASS SIDE SEATBELT BUCKLE.M TIME DUE TO NO APPLICABLE LABAOR OP		231 USA	146844
	20337*	NA	AZ	11001	d	BASE DRIVERSIDE SEATBELT COMES UNLATCHED WHILE DRIVING ITT 848	BUCKLE BECOMES UNLATCHED DURING OPERATION R AND R RIGHT CAPTAINS CHAIR AND REPLACE SEAT BELT ASSEMBLY BELT RETRACTOR HAD BEEN REPLACED BUT NOT BUCKLE		520 USA	171178
	3130*	NA	CO	11001	a	CUS STATES THE DRIVERS SIDE SEAT BELT WONT LATCH S.O P	REPLACED SEAT BELT BUCKLE 4121		303 USA	156002
	2061*	NA	WV	11001	b	CHECK DR SEATBELT WONT HOLD	REPLACE STICKING LEFT FRONT BUCKLE		304 USA	147545

ROSA-811 17434

2001_FSD_Seat_Belt_Query

	7761*	NA	HI	12001	e	PASS FRONT SEAT BELT BUCKLE IS INOP	INOP REPL PASS SEAT BELT BUCKLE		808 USA	172414
	9014*	NA	RI	11001	e	CHECK SEAT BELT WILL NOT LOCK	12031 370 CHECKED OPERATION OF SEAT BELT BUCKLE, WOULD NOT LOCK. REPLACED WITH ANOTHER BUCKLE, GOOD TO GO.		401 USA	111553
	3408*	NA	IA	11001	e	SEAT BELTS WONT HOLD WPI	REPLACE BELT TENSIONERS COMPLETED 5 28 02 WONT HOLD		641 USA	141263

RC04-011 17435

8420*	NA	UT	11001	b	CUSTOMER STATES THAT THE DRIVERS SEAT BELT KEEPS COMING UN DONE PLEASE CHECK	CHECKED CUSTOMERS CONCERN WITH THE SEAT BELT CONFIRMED CUSTOMERS CONCERN REMOVED AND REPLACED DRIVERS SEAT BELT	801 USA	158558
1331*	NA	PA	11001	c	CUSTOMER STATES THAT THE DR SEAT BELT COMES LOOSE AT TIMES SOP PARTS HERE TECH 208	CHECK AND DIAG CONCERN REPL DR SIDE SEATBELT	717 USA	116225
8518*	NA	OR	11001	■	DRIVER REPORTS LEFT FRONT SEATBELT WILL NOT LATCH	LFT FRT SEATBELT WONT LATCH REPLACED SEAT BELT BUCKLE OK AT THIS TIME	341 USA	174023
136*	NA	VA	11001	c	DRIVER AND PASS SIDE SEAT BELTSD COME UN LATCHED	REMOVE AND REPLACE BOTH FRONT SEATBELTS, RETEST OK	703 USA	127012

2001_PSD_Seat_Belt_Query

4586*	NA	TX	11001	b	CUSTOMER STATES LEFT SIDE SEATBELT WILL NOT LATCH	REPLACE SEATBELT TO LATCH BINDING.		210 USA	162721
8677*	NA	MD	11001	g	CUST STATES R F SEAT BELT BUCKLE COMES UNCLASPED INTERMITT WHEN BRAKING	BINDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE		301 USA	127047
4902*	NA	FL	12001	e	DRIVER SEAT BELT BROKE, AND COVERS TO THE SEAT TRAC REAR BOLTS MISSING	61203 01 REPLACE L F SEAT BELT BUCKLE.		661 USA	124220
7787*	NA	CA	11001	d	CUSTOMER REPORTS RIGHT AND LEFT FRONT SEAT BELT WILL UNCLASP ITSELF WHEN DRIVING.	INSPECT TEST BOTH SEAT BELTS, VERIFY COMPLAINT, BUCKLES ARE FAULTY. REPLACE BOTH LEFT AND RIGHT FRONT SEAT BELT BUCKLES, RETEST OPERATION PASS, OK AT THIS TIME. M TIME DUE TO NO AVAILABLE LABOR OP COD	E	209 USA	172518
4790*	NA	FL	12001	e	840 CUST STS DRIVER SIDE SEAT BELT KEEPS POPPING LOOSE PLEASE INSTALL SOP	INOP 81203 42 REPLACE DRIVERS SEAT BELT BELT		386 USA	124481
8886*	NA	MI	11001	s	CUSTOMER STATES DRIVER AND PASSENGER SIDE SEATBELTS DON T LATCH 825 ROY M148953	REPLACED BOTH THE DRIVER SIDE AND PASSENGER SIDE PRE TENSIONERS		818 USA	148618

RO04-011 17A37

2001_FSD_Seat_Belt_Query

8530*	NA	OR	11001	d	*** FORD WARRANTY *** REPAIR DRIVERS SEAT BELT DISCONNECTS WHILE DRIVING.	INTERNAL FAILURE SEATBELT ASSEMBLY FRONT REPLACE	503 USA	174411
20118*	NA	IA	11001	b	SEAT BELT WILL NOT STAY LATCHED OWNER REPLACED BUCKLE	SUPPLIED CUSTOMER WITH SEAT BELT LATCH UNDER WARRANTY. CUSTOMER INSTALLED	318 USA	141528
3775*	NA	AZ	12001	e	BOTH FRT SEAT BELT BUCKLES STICK.	RR FRT SEAT BELT BUCKLE ASSYS AND REPLACE	928 USA	171468
881*	NA	NY	11001	e	CHECK SEAT BELT BUCKLE	DRIVER SEAT BELT BUCKLE STICKING REPLACED DRIVER SIDE SEAT BELT BUCKLE	807 USA	113619
3943*	NA	FL	12001	b	CUSTOMER STATES THE PASS SEAT BELT DOES NOT STAY SOP HERE	DOES NOT OPERATE PROPERLY R&I PS SEAT REPLACE SEAT BELT BUCKLE REASSEMBEL RETEST	352 USA	124402

MOB-011 17438

4498*	NA	TX	11001	a	840 CUSTOMER STATE DRIVER SIDE BELT BUCKLE INOP.	8152 SEAT BELT WR PERFOR MDIAG ON DRIVER SIDE SETBELT FOUND INOP. REMOVE AND REPLACE RECHECK PASS	858	USA	152772
3415*	NA	IA	11001	b	OWNER STATES DRIVERS SEAT BELT WONT STAY LATCHED	DRIVERS SEAT BELT BUCKLE WILL NOT STAY LATCHED.CHECK AND REPLACE LEFT SEAT BELT BUCKLE.RECHECK OPERATION OK	615	USA	153548
2335*	NA	OH	11001	b	PASSENGER SIDE SEAT BELT NOT STAYING BUCKLED	VERIFIED CONCERN AND REPLACED BELT	418	USA	144305
2777*	NA	MI	12001	e	DRIVERS SEATBELT BUCKLE COMING APART 825	1 FOUND DRIVERS SEAT BELT BUCKLE BROKEN, REMOVED SEAT AND REPLACED. OK NOW. BASE#81203	734	USA	148431
8404*	NA	UT	12001	e	CUST. STATES PASS. SIDE SEATBELT DOES NOT LATCH. CHECK AND CORRECT.	INSPECT: SEAT BELT NOT LATCHING: R AND R SEAT BELT BUCKLE: RETEST: DOEN: DOEN:	601	USA	174810

2001_FSD_Seat_Belt_Query

1840*	NA	KY	12001	b	CUSTOMER STATES THE PASS SIDE SEAT BELT WILL NOT STAY LATCHED	REMOVED THE RIGHT FRONT SEAT FOR ACCESS TO REMOVE AND REPLACE THE SEAT BELT BUCKLE AND REINSTALLED THE SEAT.	608	USA	147409
8053*	NA	ME	11001	b	CUSTOMER SAYS SEAT BELTS DO NOT ALWAYS STAY BUCKLED	CHECK AND REPLACE SEAT BELT BUCKLES	207	USA	111044
803*	NA	NC	11001	b	R SEAT BELT WONT BUCKLE	REPL SEAT BELT BUCKLE ASSY	335	USA	121617
4513*	NA	TX	12001	e	OK DRIVER SEATBELT BUCKLE INOP	MTS1203 TO REMOVE SEAT TO INSTALL THE BUCKLE CONFIRMED SEATBELT BUCKLE NOT WORKING REMOVED SEAT AND REMOVED AND REPLACED DRIVER SEATBELT BUCKLE RECHECK WORKING OK AT	955	USA	162084
1782*	NA	PA	11001	b	CUSTOMER STATES THAT THE DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED	DID VERIFY CUSTOMERS CONCERN ORDER AND INSTALL A NEW RT FRONT SEAT BELT BUCKLE ASSY RECHECK ALL OK NOW HAD TO R AND R RT FRONT SEAT TO REPLACE.	724	USA	144028
8873*	NA	MA	11001	e	REPLACE THE ORDERED SEATBELT	REPLACED ORDERED SEATBELT	875	USA	111044

K004-011 17449

2001_FSD_Seat_Belt_Query

1158*	NA	SC	12001	e	CUSTOMER STATES PASSENGER SEAT BELT WONT RELEASE AT TIMES.	FOUND PASS SIDE SEAT BELT WILL NOT LATCH AT TIMES REPLACE SEAT BELT ASSY	843 USA	121728
5401*	NA	CA	12001	b	CUSTOMER STATES THAT THE PASSENGER AND DRIVERS SIDE SEAT BELT BUCKLES ARE FAILING NOT SECURE CHECK AND ADVISE.	BOTH BUCKLES NOT HOLDING. TEST BOTH FRONT SEAT BELT BUCKLES. BOTH FAILED TEST. REPLACE BOTH SEAT BUCKLES. RETEST OK.	582 USA	171056
4558*	NA	TX	11001	b	INTERIOR TRIM REPAIR CUST STATES R.F SEAT BELT KEEPS COMING LOOSE FROM RECEIVER	REMOVE REPLACE RIGHT FRONT SEATBELT ASSEMBLY	830 USA	152806

ROSA-011 17441

2001_FSD_Seat_Belt_Query

9180*	NA	MA	11001	b	THE CUSTOMER STATES THE DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED.	REPLACE THE SEAT BELT ASSEMBLY VERIFY THE SEAT BELT IS WORKING NORMALLY	413 USA	116052
8710*	NA	OR	11001	d	RIGHT SIDE SEAT BELT POPS OUT AT TIMES	VERIFIED, SEAT BELT DOES NOT OPERATE PROPERLY, R&R SEAT BELT ASSY ALL OK	503 USA	174426
1081*	NA	NC	12001	e		REPLACE DRIVER SIDE SEAT BELT TEST OK	704 USA	121162
5425*	NA	CA	12001	e	CUSTOMER STATES PASSENGER SEATBELT DOES NOT LATCH	REPALCED PASSENGER SIDE SEATBELT, SEATBELT WOULD NOT LATCH	805 USA	144032
7802*	NA	CA	11001	d	CUST. STATES L FRT. SEAT BELT WONT STAY LATCHED WILL COME UNLOCKED AT TIMES WHILE DRIVING.	INOP, REPLACED L FRT. SEAT BELT	408 USA	172031

R084-011 17A42

5079*	NA	MO	11001	●	X09 INSTALL SOP SEAT BELTS	8704 REPLACE LEFT FRONT SEAT BELT BUCKLE 7784	816	USA	183007
20101*	NA	IA	11001	●	LEFT FRONT SEATBELT WONT BUCKEL	REPLACED LEFT FRONT SEATBELT BUCKEL	319	USA	141774
7263*	NA	SD	12001	■	SEAT BELT INOP	R&R SEATBELT ASSY SPW 90236	605	USA	158430
7003*	NA	TX	11001	■	DRIVERS SEAT BELT BUCKLE COMING UNLATCHED ADVISE	WONT STAY LATCHED REPLACE SEAT BELT BUCKLE	606	USA	152100
20577*	NA	NY	11001	■	INNER SEAT BELTS BOTH SIDES WONT LATCH PROPERLY	SEAT BELTS INOP REPLACE BOTH INNER SEAT BELTS	518	USA	113477

8742*	NA	WA	11001	e	CUSTOMER STATES: RT. SEAT BELT BUCKLE STICKS.	NEED TO REPLACE RT. SEAT BELT BUCKLE ASSEMBLY. CHECK OPERATION OK	380	USA	174518
8876*	NA	MA	11001	b	CK PASS SEAT BELT WONT LATCH AND POP OUT WHEN LATCH	VERIFIED CONCERN FOUND SEAT BELT ASSEMBLY AND RETRACTOR (NO P R AND R SEAT BELT ASSEMBLY AND RETRACTOR B TIME USE TO ACCESS INTERIOR PANEL TO REPLACE	508	USA	111847
4928*	NA	FL	12001	d	CUSTOMER STATES THE DRV SEATBELT IS RELEASING WHILE BUCKLED AND TRUCK IS MOVING	TEST DRIVE AND CONFIRM CONCERN. REMOVE DRIVER'S SEAT FOR ACCESS. REPLACE SEAT BELT BUCKLE. TEST DRIVE AND CONFIRM	541	USA	124512

2001_FSD_Seat_Belt_Query

	3897	NA	ID	12001	e	W CUST STATES SEAT BELT WILL NOT LATCH	6703 SEAT BELT WILL NOT LATCH WARR DIAG THAT RIGHT SIDE SEAT BELT WONT LATCH, R&R SEAT BELT.		200 USA	156559
	7789	NA	CA	11001	e	CUST SAYS LF SEAT BELTBUCKLE INOP HAB TO JIGGLE IT TO WORK INSTALL SOP USE SPO 01288004	R&R LF SEAT REPLACED SEAT BELT BUCKLE ASSEMBLY VERIFIED		828 USA	172455

Root 011 17449

88*	NA	MD	11001	a	LEFT FRONT SEAT BELT WILL NOT BUCKLE	5132 BUCKLE INOP WF REMOVED DRIVERS SEAT,REPLACED DRIVERS SEAT BELT BUCKLE	410	USA	127410
1076*	NA	IL	11001	b	RIGHT FRONT SEAT BELT WILL NOT CLASP AT ALL TIMES.	SEAT BELT CLASP, INOP. SEATBELT ASSEMBLY FRONT REPLACE	830	USA	141442
4235*	NA	ND	11001	c	SEAT BELT NOT WORKING	CK OUT TEST SYSTEMS REPLACE SEAT BELT	701	USA	159541
6347*	NA	ID	12001	e	DRIVER SIDE SEAT BELT INOP	REPALCED LP BELT	208	USA	106804

	5143*	NA	MO	11001	b	C & THE DRIVER FRONT SEAT BELT WILL SOMETIMES NOT STAY BUCKLED	SEATBELT WONT STAY BUCKLED SEATBELT ASSEMBLY FRONT REPLACE		417	USA	153482
	636*	NA	NY	11001	b	CUSTOMER STATES:PASS SEAT BELT WILL NOT STAY BUCKLED	REPLACED RT FT SEAT BELT BUCKLE WONT LATCH		607	USA	113629
	7620*	NA	CA	11001	e	CUSTOMER STATES RT SEAT BELT FRONT COMES UNLATCHED BY ITSELF	11408 VERIFIED RT FRONT SEATBELT BUCKLE UNLATCHES BY ITSELF AT TIMES,REPLACED FRONT BUCKLE AND PRETENSIONER ASSEMBLY,OK NOW		925	USA	172429

2001_FSD_Seat_Belt_Query

	2623 *	NA	TX	11001	e	REPLACE SEAT BELT BINDING	REPLACED BINDING BELT		903 USA	152515
	2394 *	NA	TX	12001	e	P.O. FOR PASS SIDE BUCKLE WAS LOOSE NOT SURE IF PARTS STILL HERE	LOOSE REPLACED PASS SIDE SEAT BUCKLE		903 USA	152012
	4884 *	NA	FL	11001	b	CUSTOMER STATES DRIVERS SEAT BELT KEEPS UNLOCKING BY ITSELF.	REPLACED FAULTY SEATBELT.		804 USA	124209

NOB-011 17448

2001_FSD_Seat_Belt_Query

	3281*	NA	GA	11001	e	PASS SIDE SEAT BELT BUCKLE WILL NOT LATCH SEE PARTS	BUCKLE REPALCED BUCKLE ASSEMBLY		478 USA	121488
	8488*	NA	LA	12001	d	DRIVERS SEAT BELT COMES UNHOOKED SOMETIMES WHILE DRIVING	REPLACE SEATBELT DRIVER SIDE		226 USA	129145
	4223*	NA	CA	11001	b	STATES DRIVER SEAT BELT BUCKLE VAME LOOSE	INSPECT SEAT BELT BUCKLE CAME APRT RR DRIVER SEAT TO REDONE BUCKLE		828 USA	172623

RCM-811 17449

2001_F8D_Seat_Belt_Query

5417*	NA	CA	11001	b	INSTALL SOP SEAT BELTS CUST STATES WONT HOLD	51 SEATBELT ASSEMBLY FRONT REPLACE	818 USA	171040
5981*	NA	TN	11001	b	CHECK DR SEATBELT RELEASING AT TIMES	REPLACE LEFT SEATBELT	931 USA	123348
4808*	NA	FL	11001	c	CUST STATES DRIVERS SEATBELT KEEPS POPPING OPEN	REPLACE BOTH FRONT SEAT BELT BUCKLES	681 USA	124220
2874*	NA	TX	12001	a	CUST STATES FRONT LEFT SEAT BELT WONT LATCH SOP HERE	VERIFY CONCERN INSPECTED SEAT BELT AND HAD TO REMOVE SEAT AND REMOVE AND REPLACE DRIVERS SIDE SEAT BELT,CHECKED TO VERIFY REPAIR	916 USA	152578
2591*	NA	TX	12001	a	540PASS. SIDE SEAT BELT BUCKLE WONT LATCH	REPLACE RT SEAT BELT BUCKLE ASSY,CAME APART INTERNALLY	916 USA	162674
8828*	NA	WA	11001	d	CUST STATES LEFT FRONT SEAT BELT COMES UNDONE WHILE DRIVING CHECK AND ADVISE	INOP SEATBELT ASSEMBLY FRONT REPLACE	350 USA	174622

2001_FSD_Seat_Belt_Query

2625*	NA	TX	12001	a	RT FRT SEAT BELT WILL NOT LATCH	REPLACE BELT	972	USA	162016
2380*	NA	OH	11001	a	INSTALL SO SEAT BELT	REPLACE PASS. FRONT SIAT BULB	216	USA	144088
487*	NA	GA	12001	a	BOTH FRONT SEAT BELTS INOP PARTS HERE	FRONT SEAT BELTS INOP TRACK ASSEMBLY FRONT SEAT REPLACE	770	USA	121681
5814*	NA	MS	11001	a	CHECK RIGHT FRONT BUCKLE NOT WORKING	REPLACE RIGHT FRONT SEAT BELT BUCKLE	652	USA	123492
8375*	NA	ID	12001	b	CHECK FOR LEFT FRONT SEAT BELT WILL COME UNBUCKLED AT TIMES	X REPLACED LEFT FRONT SEAT BELT BUCKLE	208	USA	158805
9815*	NA	MN	12001	b	DRIVERS SIDE SEAT BELT BUCKLE DOES NOT STAY BUCKLED SEAT BELTS	CC 42,CCC S40 INSTALLED SEAT BELT BUCKLE DRIVERS SIDE 605	507	USA	158621
877*	NA	SC	12001	a	DRIVER SIDE SEAT BUCKLE INOP	REPLACED LEFT SEATBELT BUCKLE. RECHECKED	864	USA	121228

4285*	NA	TX	11001	e	DRIVERS SIDE BUCKLE WILL NOT LATCH	CHECK SEAT BELTS ON 08,08,01 WAS OK DRIVE SEAT BELT WOULD NOT LATCH REPLACE DRIVE SEAT BELT BUCKLE	512	USA	152783
529*	NA	GA	11001	d	DRIVERS SEAT BELT BUCKLE COMES UNLATCHED WHILE DRIVING SOP	SEATBELT SEATBELT ASSEMBLY FRONT REPLACE	770	USA	121024
1771*	NA	OK	11001	a	DIAG DRIVERS SEAT BELT BUCKLE WONT LATCH	DIAGNOSED AND REPLACED THE DR SIDE SEAT BELT BUCKLE, AND REMOVED THE SEAT FOR ACCESS, VEH OK AT THISTIME	408	USA	152603
2652*	NA	MI	11001	e	RT FRNT SEAT BELT INOP	INSTALLED SEAT BELT BUCKLE ON THE RIGHT FRONTSEAT AND REINSTALLED THE SEAT ASSEMBLY	734	USA	148544

2001_F8D_Seat_Belt_Query

	3318*	NA	UT	11001	a	INSPECT FOR SEATBELT BUCKLE WILL NOT LATCH (SOP PART)	1 INSTALLED SOP SEAT BELT. PERFORMED QUALITY REPAIR CHECK. 6108		801 USA	158800
	7735*	NA	CA	11001	b	DRIVERS SIDE AND PASSENGER SIDE SEATBELTS IN OP (\$ O PARTS HERE)	BUCKLES NOT LOCKING REPLACE BOTH FRONT FEMALE ENDS OF BUCKLES		530 USA	171173
	3218*	NA	CO	11001	c	DRIVERS SIDE SEAT BELT WOULD NOT LATCH ONE TIME	ORDER AND REPLACE BELT		970 USA	158282
	1860*	NA	OH	11001	b	PASS. SEAT BELT DISCONNECTS.	COULD NOT VERIFY PROBLEM ON ROAD TEST RMR RT FRT SEAT CHECK BUCKLE AND CIRCUITS REPLACED RT SEAT BELT BUCKLE OK		837 USA	147213

ROD-011 17463

2001_F8D_Seat_Belt_Query

	7301*	NA	PA	11001	e	<p>CB RECALL 01821 SEATBELT PART WAS ORDERED AND HERE.</p>	<p>VERIFIED CONCERN R.R. DRIVER SIDE SEATBELT BUCKLE AND BELT WITH NEW OK</p>		814 USA	144565
	4583*	NA	TX	11001	b	<p>840 CUST STATES THAT THE DRIVERS SEAT BELT WONT STAY LATCHED SOP PARTS ARE IN SEE R084854</p>	<p>SEAT BELT BINDING. SOP RO 48884 10 08 01 W 18008 MILES REPLACED D S SEAT BELT BUCKLE. RO 48108 10 17 01 W 18384 MILES</p>		210 USA	162718
	10828*	NA	MI	11001	d	<p>REPAIR FOR FRT SEAT BELTS COME ON DONE WHILE DRIVING</p>	<p>REPLACED BOTH FRONT SEAT BELT BUCKLES FOR SAFETY</p>		618 USA	148508

RO84-811 17454

2001_F8D_Seal_Belt_Query

348*	NA	GA	11001	a	SEAT BELT BUCKLE INOP	SEATBELT ASSEMBLY FRONT REPLACE	478 USA	121210
553*	NA	OR	12001	e	DRIVERS SIDE SEAT BELT FEMALE END FELL APART	REMOVED AND REPLACED SEAT BELT	546 USA	172472
4862*	NA	TX	12001	e	REPAIR LH SEAT BELT INOP	REPLACED SEATBELT	210 USA	152900
5542*	NA	TX	11001	b	REPLACE DRIVERS SEAT BELT BUCKLE PER ROW231578	18189 REPLACED DRIVERS SEATBELT PER ROW231578. TESTED.WORKS FINE AT THIS TIME	261 USA	152055
1783*	NA	IL	11001	d	DRIVERS SEAT BELT WILL POP OUT WHILE DRIVING	1170 VERIFIED CONCERN ORDERED SEAT BELT BUCKLE REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE OK AT THIS TIME	708 USA	141001

NOVA-911 17405

2001_FBD_Seat_Belt_Query

2381*	NA	MN	11001	e	FRONT SEATBELT INOPERABLE	CCC S25 CC24 INSPECT AND REPLACE SEAT BELT BUCKLE	962 USA	158017
7781*	NA	HI	12001	b	BEAT BELTS DO NOT STAY COUPLED	DOES NOT OPERATE PROPER SEATBELT ASSEMBLY FRONT REPLACE	808 USA	172414
8821*	NA	CT	11001	■	CUST STATES BOTH FRONT SEAT BELT BUCKLES AND NOT LATCHING PROPERLY	DX VERIFIED SEAT BELTS NOT LATCHING CORRECTLY REPLACED BOTH FRONT SEATBELT BUCKLES RECHECKED ALL OK AT TIME	650 USA	111401
20341*	NA	NM	11001	■	DRIVERS SEAT BELT WONT LATCH PARTS IN	R & R DRIVERS SEAT BELT LATCH (NOPI)	506 USA	158478
5038*	NA	MO	11001	■	CHECK FRONT SEATBELTS NOT LATCHING PROPERLY	CHECKED AND REPLACED DRIVERS SEAT BELT BUCKLE	818 USA	153423
9443*	NA	MN	11001	■	INSTALL SEAT BELT ASSY RIGHT SHIDE	INSTALLED PASS FRT SEAT BELT BUCKLE PRETENSIONER ASSY	218 USA	158498
1487*	NA	NM	12001	■	RECALL 01521 NPF BUT SEATBELTS ARE NOT LATCHING CORECTLY	TEST SEATBELTS,R&I BOTH FT SEATS,REPLACE SEATBELT BUCKLES.	505 USA	123078

R004-811 17495

2001_FSD_Seat_Belt_Query

4589*	NA	TX	12001	a	C/S THER RIGHT FRONT BUCKLE WILL NOT LATCH PROPERLY.	VERIFIED CONCERN. FOUND RIGHT SIDE SEAT BUCKLE WILL NOT LATCH PROPERLYDIAG. AND REPLACE WITH NEW LATCH ASY. ALL OKAY AFTER REPAIRS.	210	USA	162721
6720*	NA	IN	11007	b	DRIVER AND PASSENGER SEAT BELT BUCKLE WILL COME LOOSE FROM RESTARAIT	REPLACED DRIVER AND PASSENGER SIDE BELT BUCKLE	612	USA	147427
4514*	NA	FL	11001	d	RIGHT FRONT SEAT BELT BUCKLE RELEASES WHILE DRIVING AT TIMES	BINDING INSPECT SEAT DELT AND BUCKLE REPLACE FRT PASS SEAT BELT BUCKLE	941	USA	124414
1029*	NA	OH	11001	b	INSTALL SPECIAL ORDER DRIVER SEAT BELT UNLATCHES BY ITSELF	REPLACE FRT SEATBELT ASSY X	519	USA	147001
6660*	NA	VA	11001	b	CUSTOMER STATES PASSENGER SIDE SEAT BELT KEEP8 UNFASTENING	WONT LATCH MTIME TO REPLACE L SEAT BELT BUCKLEWOULD RELEASE AFTER BEING PROPE	804	USA	127072
389*	NA	TN	11001	e	RECALL SEAT BELT BUCKLES	6632 RECALL INSPECT & REPLACE FRONT SEAT BELT BUCKLES.	423	USA	121203

3278*	NA	CO	11001	e	CUSTOMER STATES DRIVER SEAT BELT BUCKLE INOP	DRIVERS SEAT BELT BUCKLE NOT WORKING REMOVED DRIVERS SEAT FROM VEHICLE, REMOVED AND INSTALLED NEW BUCKLE, REINSTALLED SEAT IN VEHICLE	303	USA	156008
9012*	NA	MO	11001	a	SOP DRIVERS SEAT BELT BUCKLE FOR WILL NOT LATCH INTERMITTENTLY VERIFIED BY FOREMAN	1734S REMOVE SEAT REPLACE SEAT BELT BUCKLE PRETENSIONER ASSEMBLY	638	USA	163076
1765*	NA	IL	11001	c	CUSTOMER STATES SEAT BELT COMES UNDONE AT TIMES COULD NOT VERIFY IN DRIVE	383S VERIFIED SEAT BELT DID NOT WORK WITH TOOL FROM RECALL ORDERED SEAT BELT WAITING ON PARTS REMOVED COMPLETE SET DEABLED PRETENSIONER REINSTALLED NEW REATTACHED SEAT RETESTED OK	708	USA	141001

2838*	NA	FL	11001	e	L15 CUSTOMER STATES VEHICLE RIGHT FRONT SEATBELT DID NOT PASS SEAT BELT RECALL.SOP.	1 REPLACE SEAT BELT BUCKLE ASSEMBLY	321 USA	124487
4982*	NA	FL	12001	e	C STATES PARTS IN FOR SEAT BELT BUCKLES PERFORMED RECALL,BOTH FAIL	INSPECT AND REPLACE TWO SEAT BELT BUCKLES.	850 USA	121481
20305*	NA	AZ	12001	e	CUST CAME IN TO HAVE SEAT BELT RECALL DONE. CHECKED BELTS ON THE DRIVE AND THE LF SEAT BELT FAILED THE TEST. CHECKED HISTORY AND DISCOVERED THE RECALL HAD BEEN DONE 6 02 01 ON RO# 124332	WF 42 01203 CCG 840 VERIFIED CONCERN, REPLACED L.F. SEAT BELT BUCKLE, DOES NOT OPERATE PROPERLY	480 USA	171175
5895*	NA	KY	11001	d	CUSTOMER STATES RIGHT FRONT SEAT BELT BUCKLE COMES UNDONE WHILE DRIVING	REPLACE RIGHT BELT	502 USA	147024
5547*	NA	CA	12001	e	PERFORM SEAT BELT RECALL 01921	CHECK AND REPLACE OPERATIVE DRIVERS SEATBELT BUCKLE 40 20 40 CREW CAB E	714 USA	171083

2001_F30_Seat_Belt_Query

678*	NA	NY	11001	a	BUCKLE NO WORKING DRIVERS SIDE	REPLACE AS NECESSARY	718 USA	144809
2500*	NA	OH	11001	b	BELT WON'T STAY LATCHED	CHECK, REPLACE RIGHT SIDE PRETENSIONER AS PER RECALL	419 USA	148223
2594*	NA	TX	12001	a	CK DRIVER SIDE SEATBELT WILL NOT LATCH PROPERLY	INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	806 USA	152100
5113*	NA	MO	12001	a	CHECK DRIVERS SEAT BELT FEMALE BUCKLE WILL NOT LATCH. SOP HERE.	CHECK & REPLACE DRIVERS SEAT BELT	816 USA	153408
7262*	NA	IA	11001	a	LEFT FRT SEATBELT INOP	SEATBELT ASSEMBLY FRONT REPLACE	712 USA	153556

800-911-1749

	2788 *	NA	MO	11001	a	SEAT BELT INOP INSTALL SOP BELT PER NIGHT DROP	INSTALLED NEW FRONT SEAT BELT RECEPTICLES, BOTH WERE BINDING AT TIMES			314	USA	163080
	8803 *	NA	ID	11001	d	C S DRIVERS SEAT BELT POPS OUT WHILE DRIVING, PARTS HERE	REPLACED DEFECTIVE SEAT BELT			208	USA	174432

RCM-011 17401

2001_F8D_Seat_Belt_Query

	3643 *	NA	FL	12001	b	CUSTOMER STATES SEAT BELT BUCKEL CAME OUT AFTER HITTING BUMP	DOES NOT OPERATE PROPERLY REPLACE DRIVERS SIDE SEATBELT BUCKLE		352 USA	124621
	6998 *	NA	NJ	11001	b	CUSTOMER STATES CHECK SEAT BELTS ONE WONT HOLD JUST HAD RECALL BY AANOTHER DEALER	CHECK BELT WITH TOOL DRIVER SIDE FRONT NO GOOD MT TIME IS TO REMOVE ADD ON CONSOLE		973 USA	113452
	2805 *	NA	MN	11001	e	CUSTOMER STATES INSTALL SEAT BELT.	X REPLACED FRONT PASSENGER SEATBELT LATCH		507 USA	158822
	6503 *	NA	MN	12001	c	PASSENGER SIDE SEAT BELT POPPS OPEN, WONT LATCH CORRECTLY	2005 I REPLACED THE PASSENGER FRONT SEAT BELT BUCKLE WITH SIR AND BUCKET SEATS. 4X4		812 USA	158003
	7742 *	NA	CA	12001	a	DRIVERF SIDE SEAT BELT WILL NOT LATCH. FSA 01821 PERF AND PASSED AT ANOTHER DEALER	FOUND SEAT BELT LATCH NOT OPERATION PROPERLY. REPL SEAT BELT LATCH PER SHOP MANUAL.		209 USA	172402
	3729 *	NA	NY	11001	d	CUST STATES PASS SEAT BELT UNBUCKLES WHEN DRIVING	REPL SAT BELT BUCKLE AND REPAIR OTHER SEAT BELT		518 USA	113538

R004-011 17482

2001_FSD_Seat_Belt_Query

	382*	NA	GA	11001	a	CHECK LEFT HAND SEAT BELT WILL NOT LATCH	R AND R LH SEAT BELT RETEST OK		478	USA	121515
	3144*	NA	CO	11001	a	CUSTOMER STATES THAT INSTALL SOP LEFT FT SEAT BELT	REPLACED DRIVER & SEAT RETAINER BUCKLE ASSY		303	USA	155461
	9838*	NA	MI	11001	a	CUSTOMER STATES BOTH FRONT SEATBELTS DO NOT LATCH.	VERIFIED CONCERN, REPLACED BOTH FRONT BUCKLES.		959	USA	148426
	20341*	NA	NM	11001	a	DRIVERS SEAT BELT WONT LATCH PARTS IN	R & R DRIVERS SEAT BELT LATCH (INQP)		506	USA	156478
	4168*	NA	LA	11001	a	C & THE DRIVERS SEATBELT WILL NOT LATCH AT TIMES	CP 2551203, CC 42 VERIFIED CONCERN, REPLACED DRIVERS SIDE SEAT BELT BUCKLE.		318	USA	123223
	7828*	NA	CA	11001	b	CUSTOMER REPORTS L F SEAT BELT WILL NOT STAY LATCHED WILL COME OUT OF BUCKLE	DEFECTIVE VERIFY CONCERN. INSTALL SPECIAL ORDERED SEAT BELT BUCKLES (BOTH)		610	USA	172007

RODA 011 17483

2001_FSD_Seat_Belt_Query

7713*	NA	CA	12001	e	SEAT BELT RECALL	REPLACE FRONT SEAT BELT & BUCKLE REPLACE FRONT SEAT BELT & BUCKLE ASSEMBLY	707	USA	172527
8025*	NA	CT	12001	c	CUSTOMER STATES THE DRIVER SIDE SEATBELT COME UNLATCHED WITHOUT DEPRESSING THE BUTTON	VERIFIED LATCHING CONCERN REMOVED AND REPLACED DRIVERS SIDE FRONT SEAT BELT LATCH AS NEEDED	203	USA	124451
7749*	NA	CA	12001	b	DRIVER SEAT BELT WILL NOT STAY CONNECTED TO BUCKLE	REPLACED DRIVER SIDE SEAT BELT	916	USA	172207
8585*	NA	WA	11001	e	CUSTOMER STATES THAT THE DRIVER SIDE SEAT BELT CATCHES AND WONT RELEASE AT TIMES	919 ORDER NEW SEAT BELT BUCKEL WILL NOT CATCH AT TIMES HAD TO REORDER BELT	208	USA	174208
3808*	NA	NY	11001	c	CUSTOMER STATES PASS SIDE SEATBELT OPENS WHEN LOCKED	TESTED PASSENGER SIDE SEATBELT. SEATBELT FAILED TEST, NEEDS REPLACEMENT OF SEATBELT LATCH ASSEMBLY. ORDERED ASSEMBLY REPLACED PASSENGER SIDE SEATBELT AND LATCH ASSEMBLY. FUNCTIONING AS DESIGNED	518	USA	113180

	828*	NA	SC	11001	e	SEAT BELT ON PASS SIDE INOP	SEATBELT INOP SEATBELT ASBY FRONT		884 USA	121628
	2331*	NA	OH	12001	b	DRIVERS SEATBELT WONT STAY LATCHED SOP IN	CK OUT AND R R LEFT FRT SEAT REPLACE SEAT BELT BUCKLE END		418 USA	147128
	4755*	NA	IN	11001	n	CUSTOMER STATES DRIVERS SIDE SEAT BUCKLE WILL NOT BUCKLE CORRECTLY. WILL NOT LATCH.	TESTED THE BUCKLE ASSEMBLY AND RETRACTOR. BUCKLE IS DEF. REPLACED THE SEAT BELT BUCKLE ASSEMBLY.		812 USA	147515

	8318 *	NA	MT	11001	b	SEAT BELT BUCKLE WOULD NOT STAY BUCKLED NEEDS REPAIRED/RPLCD	SEAT BELT WOULD NOT STAYED BUCKLED REPLACED BUCKLE		406 USA	148403
	8678 *	NA	OR	11001	e	REPLACE LEFT FRONT SEAT BELT	REPLACED LEFT SEATBELT BUCKLE. R&R SEAT FOR ACCESS		503 USA	174540
	8889 *	NA	MD	11001	e	DRIVERS SEAT BELT LOOSE	REPLACED THE DRIVERS SEATBELT.		818 USA	163404

2014*	NA	KY	11001	d	CUSTOMER STATES THAT VEHICLE SEAT BELTS RELEASE WHILE DRIVING, EVEN AFTER PASSING RECALL 01821 FOR SEAT BELT BUCKLE INSPECTION	SEAT BELT ASSY LATCHES FRONT INSTALLED NEW SEAT BELT LATCH ASSYS TO CORRECT CONCERN	502	USA	147487
5035*	NA	FL	11001	e	SEAT BELT UNLATCHING	5071 2ND VISIT , SEAT BELT UNLATCHING. 3 INSPECTED SEAT BELT, DUPLICATED AND ORDERED NEW SEAT BELT BUCKLE.INSTALLED PARTS.	407	USA	124900
600*	NA	NY	11001	a	R FRT. SEATBELT WONT BUCKLE B	REPLACE BELT	716	USA	144011
1108*	NA	NC	12001	e	CUSTOMER STATES DRIVER SEAT BELT LATCH WONT LATCH	SEAT BELT LT FT SEAT BELT REPLACE WILL NOT LATCH	910	USA	121788
9704*	NA	MI	11001	b	CUSTOMER STATES THAT HE WAS INSTALLING HIS CHILD SEAT AND SEAT BELT WOULD NOT STAY LATCHED	10008 W CHECK OUT PASSENGER FRONT SEAT BELT BUCKLE WILL NOT LATCH.REMOVE SEAT AND REPLACE CHARGED SEAT BELT BUCKLE.INSTALL PASSENGER FRONT SEAT AND TEST SEAT BELT BUCKLE.O.K.	517	USA	148580
832*	NA	NC	11001	b	PASSENGER SIDE SEAT BELT JUMPS OUT OF LATCH	TEST SEAT BELT RR SEAT TO GAIN ACCESS TO REPLACE BUCKLE	704	USA	121208

2001_F9D_Seat_Belt_Query

3658*	NA	CT	12001	e	R R SEAT BELT BUCKLE RELEASES BY ITSELF,SEE PRIOR RO.	REPLACE RIGHT SEAT BELT BUCKLE ASSY.	203	USA	141278
3374*	NA	PA	11001	f	R F OUTER SEATBELT RECEIVER BUCKLE UNLATCHES WHILE DRIVING ORDER NEW BUCKLE	R AND I THE SEAT TRIM AND R AND R THE RF SEAT BELTPRENSIONER AND RECHKECK OK	717	USA	116517
4893*	NA	FL	11001	e	CUSTOMER STATES FT CENTER SEAT BELT BUCKLE INOP	R&R LEFT FRONT SEAT BELT BUCKLE	305	USA	183000
2634*	NA	TX	11001	e	SEATBELT INOP RH FRONT PSGR	REPLACE SEAT BELT ASSY	805	USA	162551
2518*	NA	TX	12001	b	D SIDE FRT SEAT BELT BUCKLE COMES LOOSE HAS HAD RECALL DONE SEE PRE REPAIR	BINDING SEATBELT ASSEMBLY FRONT REPLACE		USA	162018
7752*	NA	CA	12001	a	CUSTOMER STATES SEAT BELT IS NOT LATCHING CHECK AND REPORT.	DUPLICATED CONCERN DRIVERS SEAT BELT BUCKLE FAILED REPLACED SEAT BELT BUCKLE RECHECKS OK NOW	818	USA	172205

ROD-011 17988

5733*	NA	TN	12001	b	SEAT BELT RECALL 01621 (SEAT BELT ON DRIVERS SIDE WHEN YOU HOOK INTO RELEASES WITHOUT WARNING)	REPLACE LF SEAT BELT BUCKLE RECALL ALREADY INSPECTED BUT THIS BUCKLE WOULD COME LOOSE FROM TIME TO TIME	865	USA	121278
7914*	NA	CA	12001	a	INSTALL SOP SEAT BELT. RECALL 01521	INSTALL SOP SEAT BELT ASSEMBLY	707	USA	172405
7800*	NA	CA	12001	b	CUSTOMER STATES 1 SEAT BELT WILL NOT HOLD RIGHT SIDE	CONFIRMED CUSTOMER CONCERN. FOUND SEAT BELT NOT LATCHING NEC TO REMOVE AND REPLACE SEAT BELT BUCKLE OK NOW	209	USA	172425

2001_FSD_Seat_Belt_Query

1304*	NA	PA	11001	b	CUSTOMER REQUEST CHECK OPERATION OF FRONT SEATBELTS WONT STAY LATCHED	INSPECTED BELTS WILL NOT LOCK ALL THE TIME. REP LACED BOTH BELT ASSY	570 USA	116302
4357*	NA	TN	11001	a	CUST STATES DRIVER SIDE SEAT BELT WANT LOCK.	REPLACE LF SEATBELT BUCKLE REPLACE FRONT SEATBELT BUCKLE	801 USA	128008
3781*	NA	FL	11001	b	DRIVER S SEAT BELT WILL NOT STAY LOCKED	BUCKEL JAMED REPLACED WITH NEW BELT	863 USA	124425
2027*	NA	OH	11001	a	CK PASS SEAT BELT LODSE.	CK NAD REPLACE SEAT BELT.	814 USA	147048
8042*	NA	TX	11001	b	825 DRIVERS SEAT BELT BUCKLE WONT HOLD PROPERLY SOP HERE	3463 REPL LFRT SEAT BELT BUCKLE	281 USA	152055

8084-911 17478

2001_F80_Seat_Belt_Query

7282*	NA	IA	11001	■	CHECK FRONT SEAT BELT BUCKEL WONT LATCH	SEATBELT ASSEMBLY FRONT REPLACE	712	USA	153558
6530*	NA	NH	11001	●	PERFORM RECALL 01821 FOR FRONT SEAT BELT CHECK SOP PART PASSENGER SIDE SEAT BELT	COMPLETED 018211 REPLACED PASSENGER SEAT BELT BUCKLE	603	USA	111858
6285*	NA	CO	11001	●	PASS SEAT BELT INOP	PASS SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE	970	USA	169490
2014*	NA	KY	11001	●	PASSENGER SEAT BELT DOES NOT OPERATE PROPERLY	SEAT BELT LATCH INOP SEATBELT ASSEMBLY FRONT REPLACE	502	USA	147425

R084-811 17471

2001_FSD_Seat_Belt_Query

4615*	NA	TX	12001	a	INOPERATIVE SEAT BELT	INOPERATIVE REPLACED SEAT BELTS	656 USA	152997
214*	NA	GA	12001	b	CHECK DR. SEAT BELT KEEPS COMING LOOSE	SEATBELT ASSEMBLY FRONT REPLACE	706 USA	121081
6382*	NA	IN	11001	c	SEAT BELT COME UNBUCKLED	REPLACED THE DRIVERS SIDE SEAT BELT 1	219 USA	148435
2183*	NA	OH	11001	b	CUSTOMER STATES THAT THE PASSENGER FRONT SEATBELT COMES UNHOOKED FROM THE BUCKLE FRONT SEAT 1840	CAUS 1861202 CCC 540 CC 33 CK AND PERFORMED SEAT BELT RETENTION TOOL PER RECALL CK. BELT, BAD. DEACTIVATED AIR BAGS REMOVED AND REPLACED PASS.	330 USA	144083

RO04-011 1747Z

2001_F80_Seat_Belt_Query

20050*	NA	IL	11001	e	REPLACE SOP SEAT BELT	REPLACE DRIVERS SEATBELT LATCH	815	USA	152512
3021*	NA	CA	11001	d	CLIENT STATES DRIVER SEAT BELT UNBUCKLES WHILE DRIVING. SOP HERE TO REPAIR.	1 REPLACED DRIVERS SEAT BELT BUCKLE. REF PREVIOUS RO NO PROBLEM FOUND.	405	USA	172038
17*	NA	MD	11001	e	PASSENGER FRONT SEAT BELT INOP SEAT BELT IN STOCK B40	REPLACE SEAT BELT	410	USA	127418
2800*	NA	OH	11001	b	CHECK SEAT BELT LATCH. WILL NOT STAY LATCHED	CHECK, REPLACE BUCKLE ASSY, RECHECK, OK	419	USA	148223

NOA-012 17473

4155*	NA	IN	11001	•	DRIVERS SEATBELT BUCKLE	WILL NOT FASTEN CORRECTLY/R AND R DRIVERS SIDE BUCKLE ASSY	219	USA	141629
7798*	NA	CA	12001	•	PERFORM SEAT BELT RECALL SPECIAL ORDERED PARTS HERE	RECALL REPALCED RIGHT SIDE SERAT BELT BUCKLE ASSY	850	USA	172429
2827*	NA	TX	12001	•	SEAT BELT RECALL 01821	RECALL 01821 DRIVER & PASSENGER SEAT BELT FAILED BUCKETS ELECTRIC	254	USA	152504
3081*	NA	GA	12001	•	CUST STATES PASSENGER SIDE SEATBELT IS NOT LOCKING	FOUND PASSENGERS SIDE SEAT BELT BUCKLE WILL NOT LATCH REPLACED SEAT BELT BUCKLE FOR PASS SEAT RR SEAT TO REPLACE	708	USA	121439
2858*	NA	PA	12001	•	PERFORM RECALL	REPLACE SEAT BELT	814	USA	144487

R004-811 17474

2001_FSD_Seat_Belt_Query

6058*	NA	VT	12001	e	OWNER NOTIFICATION PROGRAM	REPLACED SEAT BELT	802 USA	111516
5636*	NA	CA	11001	d	S26 CHECK AND REPAIR CUSTOMER STATES DRIVERS SEAT BELT KEEPS POPPING OFF WHILE DRIVING AFTER RECALL WAS PERFORM REINSPECT	CC121 PERFORMED RECALL MS21D	818 USA	171802
8547*	NA	WA	12001	b	INSTALL SOP SEATBELT RECIEVERS BELTS WONT STAY BUCKLED	8503 81203 DRIVERS SEAT BELT BUCKLE INTERMITTENT 42 REPLACED DRIVERS SEAT BELT BUCKLE. FAILS ON CU STOMER.	360 USA	174021
3688*	NA	AL	11001	d	CUSTOMER STATES DRIVER SEATBELT COMES UNDONE WHILE DRIVING	REPLACED DRIVER SIDE SEATBELT BUCKLE CHKD OK	206 USA	121418
8883*	NA	MA	11001	e	INSTALL S O SEAT BELT	6538 REPLACED LEFT AND RIGHT FRONT SEATBELT BUCKLES	781 USA	111032
3680*	NA	NY	11001	b	CUST STATES PASS SIDE SEATBELT RELEASES (SOP)	REPLACED SEATBELT ASSEMBLY	518 USA	113815
6398*	NA	MT	11001	a	SEATBELT WILL NOT LATCH	M TIME TO REPLACE SEAT BELT,NO TIME LISTED IN SLTS	408 USA	174816

NOB4-011 17478

2001_FSD_Seat_Belt_Quary

1758*	NA	MI	11001	c	CHECK FOR SEAT BELT NOT LATCHING AT TIMES D. SIDE	166 VERIFIED CONCERN R&I DRIVERS SEAT REPLACE SEAT BELT BUCKLE ASSY RE CK OK LOOSE 33 7921 MILES AT 165	517	USA	148513
181*	NA	MI	11001	b	RIGHT SEAT BELT DOES NOT STAYED LATCHED.	INSTALLED SEAT BELT RF LATCH	618	USA	148689
6649*	NA	MS	12001	e	SEAT BELT BUCKLES INOP	INSPECTED SEAT BELTS AND FOUND SEAT BELT BUCKLES INOP. REMOVED AND INSTALLED NEW SEAT BELT BUCKLES AND CHECKED OPERATION	601	USA	123548
4180*	NA	NC	12001	d	CHECK FRONT SEAT BELT BUCKLES, KEEP RELEASING WHILE DRIVING	SEATBELT SEATBELT ASSEMBLY FRONT REPLACE	704	USA	
1783*	NA	WI	12001	b	CUSTOMER STATES THAT FRONT SEATBELTS DONT BUCKLE SOMETIMES	MT EQUALS TIME TO REPLACE BOTH FRONT SEATBELT BUCKLES.	414	USA	141033

ROB-911 17478

2001_F60_Seat_Belt_Query

3168*	NA	CO	12001	d	CUSTOMER STATES LEFT FRONT SEAT BELT BUCKLE WONT LATCH AT TIMES AND AT TIMES BELT COMES OUT OFF BUCKLE WHILE DRIVING	REPLACED BOTH FRONT SEAT BELT RECEIVERS VERIFY CUSTOMER CONCERN THAT DRIVER SEAT BELT WILL NOT ALWAYS LATCH PROPERLY NOTED THAT PASSENGER FRONT SEAT BELT RECEIVER WILL NOT ALWAYS LATCH PROPERLY. R	EPLACE DRIVER AND PASSENGER FRONT SEAT BELT RECEIVERS	309	USA	156501
20403*	NA	NM	11001	a	DRIVER SIDE FRONT SEAT BELT WILL NOT LATCH	SEATBELT LATCH INSPECT FOR DRIVERS SEATBELT LATCH NOT LOCKING VERIFY CONCERN,R&R		505	USA	158487
5895*	NA	TN	11001	b	CUSTOMER STATES DRIVER SEATBELT FAILS WILL NOT STAY BUCKLED.	BUCKLE HAS INTERNAL FAILURE S40 42 INSPECT REMOVE REPLACE DRIVER SEATBELT BUCKLE.		615	USA	123198
4280*	NA	CT	11001	a	INSTALL SEAT BELT BUCKLE THAT FAILED INSPECTION 01821 CENTER BUCKLE	42 CENTER SEAT BELT BUCKLE.REMOVE RIGHT SIDE SEAT FOR ACCES		850	USA	111408

RO04-013 17477

6412*	NA	CA	11001	d	CUSTOMER STATES DRIVER SEAT BELT COMES UNLATCHED WHILE DRIVING SOP IS IN UBE SPO 01227003	NA REMOVED AND REINSTALLED SEAT TO REPLACE BUCKLE ASSEMBLY.	714	USA	171166
1899*	NA	IN	11001	b	REPAIR PASS SEAT BELT WONT HOLD	REPLACED RT FRONT SEAT BELT	766	USA	147420
17*	NA	MD	11001	e	RECALL SEAT BELTS	REPLACE SEAT BELT	410	USA	127419
4475*	NA	TX	11001	e	CHECK OUT DRIVERS SEAT BELT SEAMS TO COME UNBUCKLED	SEAT SEAT BELTS RETESTED OKVERIFIED CONCERN REMOVED AND REPLACED BOTH FRONT S	408	USA	162151
348*	NA	GA	12001	e	RECALL # 01821 SEAT BELT RETENTION (SEE PARTS DEPT FOR THE LEFT SIDE BELT)	SEATBELT ASSEMBLY FRONT REPLACE	478	USA	121210
7781*	NA	HI	11001	b	DRIVERS SEAT BELT WILL NOT LATCH AT TIMES	REPLACE DRIVER SEAT BELT BUCKLE	806	USA	172414

1450*	NA	AR	11001	e	SOP RT FT SEAT BELT ASSEM WONT HOLD S40	REPLACED SEAT BELT LATCHES	501	USA	123204
6803*	NA	ME	12001	a	Q CHK FOR PASS SEAT BELT POPS OPEN	3893 CHECKED FOR SOP PART, FOUND PASSENGERS SIDE SEAT BELT BUCKLE ORDERD. R+R PASSENGERS SIDE SEAT BELT BUCKLE. VERIFIED OPERATION.	207	USA	111547
3860*	NA	NY	11001	e	RECALL SEATBELT PASS SIDE	REPLACED SEAT BELT	518	USA	113480

34*	NA	MD	11001	e	INSTALL SOP REC.	INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	410	USA	127035
1758*	NA	AZ	11001	e	RECALL #01821 SOP HERE	PERFORMED RECALL 1821 REPLACED BOTH SEAT BELT BUCKLES RECALL WAS CLOSED OUT BY BRETTE FORD SEATBELTS WERE NOT REPLACED	520	USA	127042
20809*	NA	NY	11001	e	RECALL 01821 2001 SEAT BELT BUCKLE RETENTION	01821 PERFORMED RECALL	518	USA	113160
5538*	NA	KY	11001	e	INSTALL SOP FOR SEAT BELT RECALL	8147 GC 42 WARR REPLACE DRIVER SIDE SEAT BELT FOR WORKING ON RECALL 677 4718	502	USA	147011
5734*	NA	TN	12001	e	INSTALL SOP L F SEAT BELT BUCKLED FAILED INSPECTION, SEE FILE	INOP SEATBELT ASSEMBLY FRONT REPLACE	615	USA	147020

5535*	NA	CA	12001	a	INSTALL SOP SEAT BELT RECALL SEE RO 175897 LINE A	INSTALL SOP SEAT BELT PER RECALL	908	USA	171108
8301*	NA	ID	12001	a	W REPLACE R F BUCKLE 01621 TECH115	FOUND SEAT BELT BUCKLE DEFECTIVE REPLACE BUCKLE ASSY	208	USA	156563
5536*	NA	CA	11001	b	CUST STATES DR SIDE SEAT BELT COMES UNBUCKLE BY ITSELF/640	CCG66 REPLACED DRIVERS SEAT BELT BUCKLE	818	USA	171040
1474*	NA	PA	11001	b	DRIVERS SEAT BELT KEEPS COMING UNHOOKED	CHECK OUT SEAT BELT OPERATION,ORDER AND INSTALLED NEW DRIVERS SEAT BELT BUCKLE,COULD NOT VERIFY COMPLAINT	717	USA	118532
8512*	NA	WA	12001	b	PER CUSTOMER, DRIVERS SEAT BELT IS HARD TO LATCH AND RELEASE AT TIMES	CND REPLACED BUCKLE PER CUSTOMER REQUEST	253	USA	174205
2444*	NA	TX	11001	a	CHECK DRIVER SIDE SEAT BELT BUCKLE	1 REPALCED LEFT FRT SEAT BELT BUCKLE NOT LATCHING 1	815	USA	152587

20872*	NA	NJ	11001	●	SEATBELT BUCKLES DO NOT WORK PROPERLY	CHECK SEATBELT BUCKLES WILL NOT RELEASE PROPERLY HAD TO REPLACE SEATBELT BUCKLE	809	USA	116008
2153*	NA	OH	12001	●	SAFETY RECALL 01S21: SEAT BELT BUCKLE RETENTION INSPECTION ON EXCURSION, EXPEDITION, F SERIES, RANGE	01S21A 3 4 INCLUDING THE ADMIN LOTS OF OTHER LOTS FOR REPLACEMENT; BY VEHICLE INSPECT SEATBELT BUCKLE RETENTION USING SPECIAL SERVICE TOOL. REPLACE LH BELT BUCKLE ASSEMBLY.	330	USA	144083
6481*	NA	LA	11001	●	CUST STATES THE RIGHT FRONT SEAT BELT DOES NOT LATCH	01S21 RECALL PERFORMED 01S21 RECALL PERFORMED	337	USA	116216

MO04-011 17482

2001_FSD_Seat_Belt_Query

1788 *	NA	WI	11001	a	INSTALL SOP SEATBELT FOR PASS SIDE	ACCESS AND REPLACE SEATBELT TO COSEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	414	USA	141109
3383 *	NA	IA	11001	e	CUST STATES THAT BOTH FRONT SEAT BELT CASING ARE FALLING OFF	REPLACED DRIVERS AND PASSENGERS SEAT BELT LATCH	712	USA	163411
1505 *	NA	IL	11001	e	SAFETY BELT LOOSE SOP	REPLACE LOOSE SEAT BELT BUCKLE WHEN INSPECTED FOR RECALL WAS ALRIG	847	USA	141408
3579 *	NA	NJ	11001	e	CUSTOMER STATES CHECK DRIVER SIDE SEAT BELT DOESNT WORK CORRECTLY	CHECK DRIVER SIDE SEAT BELT BUCKLE DOESNT LOCK CHECK AND REPLACE DRIVER SIDE SEAT BELT BUCKLE	973	USA	113451
5458 *	NA	CA	12001	a	CUST STATES RT FRONT SEAT BELT WILL NOT LATCH	BUCKLE REPLACE RIGHT FRONT SEATBELT BUCKLE ASSEMBLY	819	USA	171034

ROSA-011 17483

	4883*	NA	FL	12001	d	CLUS SAYS DR SIDE SEATBELT IS COMING LOOSE WHEN DRIVING.	CHK OUT, FOUND THAT THE DRIVER SEAT BELT BUCKLE WAS BROKEN. REMOVE THE DRIVER SIDE SEAT AND REPLACE THE BUCKLE, PUT TOGETHER AND RETEST AND OPERATING NORMALLY. MILES OUT 3051		904 USA	124223
--	-------	----	----	-------	---	---	--	--	---------	--------

RC04-011 17484

20884*	NA	NJ	11001	c	BOTH FRONT SEAT BELT BUCKLES NOT WORKING THEY RELEASE THE BELTS AT TIMES	VERIFIED CUSTOMER CONCERN REORDERED SEAT BELT BUCKLES NUMEROUS WRONG ASSEMBLIES WERE SENT FROM FCSD; INSTALLED FINAL CORRECT BUCKLES ON FOLLOWUP VISIT PERFORMED 12 28 01.	873 USA	113044
9640*	NA	MI	11001	b	LEFT SEATBELT WONT HOLD SOP	REMOVE AND INSTALL LEFT FRONT SEAT TO REPLACE INNER SEAT BELT BUCKLE ASSEMBLY	618 USA	148684
3182*	NA	CO	11001	a	CUSTOMER STATES THAT THE L F SEATBELT WILL NOT LATCH INTO BUCKLE	REPLACE SEAT BELT	870 USA	156490
7424*	NA	PA	11001	a	SEAT BELT ON PASSENGER SIDE WILL NOT LOCK	REMOVED AND REPLACED PASSENGER SIDE SEAT BELT DUE TO NOT LATCHING	724 USA	144410

2001_F8D_Seat_Belt_Query

3423*	NA	NE	11001	a	PASS SIDE SEATBELT UNBUCKLES AT TIMES	REMOVE AND REPLACE RIGHT SIDE SEAT BELT BUCKLES	402	USA	153507
8801*	NA	WA	11001	a	SEATBELT WONT CATCH	REPL STICKING BUCKLE ASSY	208	USA	174527
5043*	NA	MO	12001	b	THE CUSTOMER STATES THE FRONT SEAT BELTS WILL NOT LATCH AT TIMES, THE LATCHES PASS ON RECALL 01821	SEAT BELTS STICKING	818	USA	153417
2200*	NA	OH	11001	c	PASSENGER SIDE SEAT BELT UNLATCHES	VERIFIED COMPLAINT REPLACED PASSENGER FRONT SEAT BELT BUCKLE	216	USA	144069
9252*	NA	TX	12001	d	S40 CC THE PASSENGER SIDE SEAT BELT COMES UNDONE WHILE DRIVING	CC 42 BPN 7861202 PASSENGER SIDE BUCKLE INOP. REMOVED PASSENGER SEAT AND REPLACED BUCKLE. REINSTALLED SEAT AND RETEST PROVED OK.	978	USA	152158
3150*	NA	CO	11001	e	INSTAL SOP SEAT BELT BUCKLE FOR RECALL	REPLACED SEAT BELT ASSY	303	USA	155009
4909*	NA	FL	11001	e	PER CUST WE NEED TO INSTALL SOP SEATBELT.	REPLACED SEATBELT	551	USA	124220

K084-911 17488

4532 *	NA	TX	11001	b	CUST STATES FRT SEAT BELTS WILL NOT STAY LATCHED	CHECK OUT BOTH FRT SEAT BELT BUCKLES NOT STAYING LATCHED, REPLACE BOTH FRT SEAT BELT BUCKLES (NOT OPERATING PROPERLY)	409	USA	152092
369 *	NA	TN	12001	b	DRIVER NEW SEAT BELT BUCKLE NOT HOLD;INSTALL NEW ONE SOP	6665 INSTALLED NEW SEATBELT BUCKLE	423	USA	121201
5503 *	NA	CA	11001	a	CUSTOMER STATES THE PASSANGER SIDE BUCKLE LOOSE. SOP HERE	REPLCED PASSANGER SIDE SEAT BELT BUCKLE	661	USA	171446
6360 *	NA	WI	11001	a	CHECK FOR RIGHT FRONT SEATBELT WONT HOLD	CHECK AND REPLACE RIGTH FORTN SEAGBELT	292	USA	141343
9824 *	NA	MI	11001	a	I C PASS SEATBELT WILL NOT LATCH	REPLACE PASS FRONT SEAT BELT BUCKLE INOP	517	USA	148662
3284 *	NA	CO	11001	a	SEAT BELT STUCK	REPLACED BOTH SEATBELT BUCKLES, BOTH FAILED INSPECTIONT BUCKLE . BOTH FAILED INSPECTION.	303	USA	127836

2001_F&D_Seat_Belt_Query

5668*	NA	KY	12001	e	SEATBELT LATCH PROBLEM	REPLACE SEATBELT AND BUCKLE ASSY	270	USA	147627
4483*	NA	TX	11001	b	THE SEAT BELT BUCKLES DO NOT ALWAYS LOCK THE SEAT BELT.	R 1 DRIVE SIDE FRONT SEAT (BRACKET) REPLACE SEAT BELT BUCKLE	512	USA	152904
4218*	NA	NJ	11001	d	CUST STATES WHEN DRIVING THE PASS SIDE FRONT SEATBELT UNHOOKS FROM FEMALE PART.	7132 INSTALL NEW PS FRONT SEAT BELT ASSY	908	USA	113480
8601*	NA	WA	12001	a	SEAT BELT WONT LATCH	INSP AND REPL LATCH ASSY BINDS	206	USA	174527
3660*	NA	CT	11001	d	C 8 LEFT SEAT BELT BUCKLE KEEPS POPPING OUT WHILE DRIVING	BROKEN MTIME TO R&R LEFT FRONT SEAT BELT BUCKLE	860	USA	113241

ROD-012 17406

2001_FBD_Seat_Belt_Query

1281*	NA	PA	11001	c	LF SEAT BELT BUCKLE DOES NOT LATCH ALL THE TIME.	REPLACED LF SEATBELT BUCKLE ASSY.	610	USA	116488
9818*	NA	MI	11001	a	RECALL 01S21. SEAT BELT BUCKLES.	RECALL PERFORMED RECALL REPLACED RIGHT FRONT BUCKLE	231	USA	148802
2415*	NA	TX	12001	b	LEFT SEAT BELT WON'T STAY LATCHED	RREPLACED SEAT BELT	972	USA	152012
2415*	NA	TX	11001	b	SEAT BELTS COME UNBUCKLED BY THEMSELVES	REPLACED SEAT BELT BUCKLES 1	972	USA	152012
5508*	NA	GA	12001	a	SPO SEAT BELT	SEAT BELT BUCKLE BROKEN NECESSARY TO REPLACE	948	USA	171095
2173*	NA	OH	11001	e	INSTALL ORDERED SEAT BELT ASSEMBLY	REPALCE LEFT FRT SEAT BELT BUCKLE	218	USA	144130

R004-011 17489

2001_FSD_Seat_Belt_Query

5355*	NA	CA	11001	e	INSTALL SOP RECALL 01621 SEE RO 183544 LINE A	REPLACE SEAT BELTS	808	USA	148017
3140*	NA	CO	12001	e	CUSTOMER STATES LEFT FRONT SEAT BELT LATCH BUTTON WILL STICK DOWN AT TIMES	888A TIME TO CHECK AND REPLACE LEFT FRONT SEAT BELT LATCH BUCKLE	718	USA	132168
8143*	NA	WI	11001	e	REPAIR SEAT BELT BUCKLES	11081 04 05 02. GIVEV A SOP PART & NOT KNOWING IF IT WAS R OR L. I TESTED THE L 7 IT FAILED. REMOVED & FOUND I HAD A R. TTESTED THE R & IT FAILED. REPOLACED BOTH BELT BUCKLES.	820	USA	141880
4283*	NA	TX	11001	b	SEAT BELT ON DRIVER SIDE KEEPS UNBUCKLING PLEASE CK AND REPORT	DEACTIVATE AIRBAG SYSTEM. REPLACED LEFT HAND PR EXTENSIONER BUCKLE. RETEST.	979	USA	152768
2415*	NA	TX	11001	e	PASS SIDE SEATBELT TROUBLED	REPL PASS SIDE SEAT BELT BUCKLE	872	USA	152003

RO04-011 17489

2001_F80_Seat_Belt_Query

6850*	NA	OK	11001	e	WF ADD ON F.S.A. 01821 SEAT BELT BUCKLES.	8762 TESTED DRIVER PASSED. PASSENGER FAILED. REPLACED PASSENGER BELT PER RECALL 0.5 BUCKET NONPOWER	405	USA	162634
5428*	NA	CA	12001	e	CUST STATES SEAT BELT INOP	INOP REPLACED PASSENGER SEAT BELT	805	USA	171469
5428*	NA	CA	12001	e	CUST STATES SEAT BELT INOP	INOP REPLACED SEAT BELT PASSENGER SIDE	805	USA	171458
402*	NA	GA	12001	b	CHECK PASS FRONT SEATBELT HARD TO LATCH UNLATCH	SEAT BELT BINDING SEATBELT ASSEMBLY PASSENGER FRONT REPLACE	770	USA	121480
5428*	NA	CA	12001	e	CUST STATES SEAT BELT INOP	INOP REPLACED DRIVERS SEAT BELT	805	USA	171469
4605*	NA	TX	11001	e	CUSTOMER STATES FRONT SEAT BELT BUCKLES NOT CLOSING PROPERLY	CUSTOMER STATES FRONT SEAT BELT BUCKLES NOT CLOSING PROPERLY. VERIFIED CONCERN RETESTED BUCKLES FOUND BOTH FRONT BUCKLES FAILED NEEDED MT TIME TO REPLACE BUCKLES DUE TO NO LABOR CP AVAILABLE	856	USA	162492
4605*	NA	TX	11001	e	CUSTOMER STATES DRIVER SEAT BELT BUCKLE NOT LATCHING PROPERLY	CUSTOMER STATES DRIVER SEAT BELT BUCKLE NOT LATCHING PROPERLY. NEEDED MT TIME TO REPLACE BUCKLE DUE TO NO LABOR CP AVAILABLE	856	USA	152759

R084-011 17491

	3177*	NA	CO	11001	.		REPLACED FRONT SEATBELT ASSY		303 USA	158439
--	-------	----	----	-------	---	--	---------------------------------	--	---------	--------

5965 *	NA	AR	12001	g	SEAT BELT INOP SERVICE INSTALL RD 149384	18250 REMOVED SEAT ASSY FOR ACCESS REPLACED SEAT BUCKLE ASSY REINSTALLED SEAT ASSY	479	USA	123570
553 *	NA	OR	12001	■	DRIVERS SEAT BELT WILL NOT HOLD	VERIFIED COMPLAINT REMOVED AND REPLACED SEAT BELT. RETEST OK	541	USA	172472
3153 *	NA	NM	11001	●	01821 SEAT BELT RECALL	VERIFIED CONCERN TEST SEAT BUCKLES RIGHT SIDE OK DRIVERS SIDE FAILED ORDER DRIVERS SIDE BUCKLE	605	USA	166537

RO04-011 17403

903*	NA	NC	11001	a	CK RT SEAT BELT BROKE	REPL RT FRT BUCKEL HAD TO R R SEAT TO REPL	336	USA	121617
7283*	NA	OR	12001	b	RH FRONT SEATBELT WILL NOT STAY BUCKLED	R&R BELT AS NEEDED	641	USA	174468
8613*	NA	MA	11001	b	PS BUCKLE DISCONNECTS REPLACE BUCKLE	RF SEATBUCKLE DISCONNECTS SEATBELT ASSEMBLY FRONT REPLACE	978	USA	111300
5325*	NA	ID	12001	d	CUSTOMER STATES THAT PASS SIDE WILL NOT EVEN STAY BUCKLED WHILE DRIVING DOWN THE ROAD	IMPROPER OPERATION SEATBELT ASSEMBLY FRONT REPLACE	208	USA	166598
1884*	NA	CA	12001	b	CUST STATES DRIVERS SEATBELT BUCKLE DISCONNECTS BY ITSELF AT TIMES	LF SEATBELT COMES UNBUCKLED SEATBELT ASSEMBLY FRONT REPLACE	861	USA	171040
20307*	NA	NM	12001	e	CUSTOMER STATES THAT DRIVERS SIDE SEAT BELT INOP CHECK AND ADVISE CHECK AND ADVISE SOP	1 REPLACED SEAT BELT IN UNIT	505	USA	156302

2001_FSD_Seat_Belt_Query

2707*	NA	MI	12001	a	CENTER SEATBELT BUCKLE INOP PARTS ARE IN	5832 REPLACED CENTER SEAT BELT BUCKLE, BUCKLE DID NOT WORK PROPERLY, OK NOW, 611880 CC 42 ADD JOB	610	USA	148428
5627*	NA	TN	12001	b	CHECK CENTER SEAT BELT WILL NOT STAY LATCHED	CHECK AND REPLACE CENTER SEAT BELT ASSY INOP SEE MT TIME FOR ACTUAL NO LABOR OPERATION GIVEN	615	USA	121444
3590*	NA	NY	11001	b	CUSTOMER STATES DRIVERS SIDE SEAT BELT UNBUCKLES.	14861 BUCKLE INOP WILL NOT LOCK CHECK SEAT BELT REMOVE SEAT REPLACE BUCKLE WOULD NOT LOCK	914	USA	113489
5476*	NA	CA	11001	d	LEFT SEAT BELT WONT STAY LATCHED POPS OPEN WHILE DRIVING		714	USA	171166
1412*	NA	CA	11001	d	CUSTOMER STATES CHECK DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING, CHECK AND ADVISE	INSPECTED AND REPLACED DEFECTIVE SEAT BELT LATCH ASSY, RE TESTED, OK.	209	USA	172916
6249*	NA	WI	11001	a		ORDERED PART. REPLACED SEAT BELT ASSEMBLY	820	USA	141353

R004-011 17495

4945*	NA	FL	11001	a	SEAT BELT LATCH NOT WORKING	REPLACE SEAT BELT		813 USA	124547
2980*	NA	NY	11001	a	INSTALL INSTALL SOP SEATBELT	16233 INSTALL SOP SEATBELT REPL DRIVER SIDE RECIEVER CHECKS OK		718 USA	144117
2732*	NA	MI	11001	b	C C PASSENGER FRONT SEAT BELT WILL NOT STAY LATCHED			517 USA	148018

NOV-911 17498

6541	NA	ID	11001	a	SEAT BELT BUCKLE HARD TO SNAP IN	REPLACED PASS SIDE AND R/R PASS SIDE BUCKLE	200	USA	174447
4482	NA	TX	12001	a	RT SEAT BELT WONT BUCKLE	SEAT BELT WONT LOCK REPLACE SEAT BELT	830	USA	152148
61	NA	VA	11001	b	RT AND LT SEATBELT BUCKLES WILL NOT STAY LATCH INTO BELT	RIGHT AND LEFT FRONT SEATBELT BUCKLES INOP REPLACE RIGHT AND LEFT SEATBELT BUCKLES	640	USA	127440
1681	NA	OR	12001	a	REPLACE SEAT BELT		541	USA	174457
8185	NA	IL	11001	a	SEAT BELT BUCKLES	REPLACE BOTH SEAT BELT BUCKLES	618	USA	127838
4280	NA	CT	11001	a	REPLACE DRIVERS BUCKLE AND MIDDLE SEAT BUCKLE PARTS ARE HERE	42 REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE	860	USA	113548

R004-011 17487

2001_FSD_Seat_Belt_Query

10431*	NA	PA	11001	a	REPLACE 2 SEATBELT BUCKLES IN AN F250	REPLACED BOTH SEATBELT ASY	717 USA	118456
6778*	NA	NC	12001	b	SEAT BELT WONT ENGAGE PROPERLY PASS SIDE	SEAT BELT WILL NOT ENGAUGE PROPERADDITIONAL MISC. REPAIRS	252 USA	121644
4194*	NA	MT	11001	b	BUCKLE COMES UNDONE	REPLACE BUCKLE	408 USA	174694
3586*	NA	OH	11001	b	CK SEAT BELT WONT HOLD	REPLACE PASS SIDE SEAT BELT	740 USA	147045
1827*	NA	MA	12001	a	TECH Z3 INSTALL PASSENGER SEAT BELT AND COVER	REPLACED BELT AND COVERS	608 USA	111083

NR04-011 17498

2001_FSD_Seat_Belt_Query

	2183 *	NA	OH	12001	c	CUSTOMER STATES THAT THE FRONT SEATBELT ON THE PASSENGER SIDE POPS OUT OF THE BUCKLE 840	CAUS 7881202 CCC 840 CC 30 REPLACED SEAT BELT BUCKEL ON PASS SIDE FRONT SEAT OLD ONE WOULD NOT LATCH		330	USA	144058
	4219 *	NA	NJ	11001	e	INSTALL ORDERED SEAT BELTS	8102 SEAT BUCKLE INSTALL FRONT L& R SEAT BUCKLE SEAT BULK		600	USA	113824
	2155 *	NA	OH	11001	e	REPLACE THE RIGHT SIDE SEAT BELT ASSEMBLY AS PER PREVIOUS DIAGNOSIS.	REPLACE THE RIGHT SIDE SEAT BELT ASSEMBLY.		330	USA	144098
	3544 *	NA	IA	12001	a	PASSENGER SIDE SEAT BELT WONT LATCH.	PASS FRONT SEAT BELT LATCH WONT ALWAYS LATCH. REMOVE SEAT AND REPLACE BELT BUCKLE.		712	USA	158857

ROSA-011 17488

7892*	NA	NV	11001	#	INSTALL SOP RT SEAT BELT RECEPTACLE	10655 REPLACED PASS SEAT BELT RECEPTACLE(DEACTIVAT	702	USA	172404
144*	NA	MD	11001	e	RECHECK SEAT BELTS	SEAT BELT ASSEMBLY SEATBELT ASSEMBLY FRONT REPLACE	410	USA	127087
225*	NA	AL	12001	b	825 PASS SEAT BELT VIBRATES LOOSE (2ND TRIP) 1ST TIME WRONG PART WONT STAY LOCKED.	9842 R R R FRT SEAT ASSY, REPLACED RIGHT SEAT BELT BUCKLE BUCKLE PRETENSIONER ASSY, CK OK CC42	206	USA	121015
3182*	NA	CO	11001	d	AFTER INTERIOR OF CAB IS HOT DRIVERS SEATBELT DOES NOT ALWAYS BUCKLE WILL POP OUT WHILE DRIVING	REPLACE LF SEAT BELT BUCKLE	870	USA	153875
20400*	NA	AZ	11001	b	LF SEAT BELT COMES UNBUCKLED PART ON ORDER STEVE KRELL R #1 BUCKLE FROM STOCK UNIT 12223 TAG 3046	REMOVED DRV. SEATBELT BUCKLE AND REPLACED WITH BUCKLE FROM BTK. UNIT, NECESSARY TO REMOVE DRV. SEAT FOR ACCESS. R#1 CLAIM ZONE APPROVAL #P71LW	602	USA	171172

2001_FSD_Seat_Belt_Query

3921*	NA	CA	12001	e	BOTH SEAT BELT BUCKLES ARE BAD	1 REPLACED LFT AND RT FRT SEAT BELT BUCKLES	408 USA	172039
4107*	NA	ND	11001	e	SEAT BELTS IN VEHICLE STICK AND HARD TO REMOVE	REPLACED BELTS AND LOCKS TRYED TO CLEAN BTILL DIDNT WORK	701 USA	116008
699*	NA	NC	11001	e	CS DRIVERS SEATBELT BUCKLE MISSING	REMOVE DRIVERS SEAT INSTALL SEAT BLET AND BUCKLE ASEMBLY	252 USA	124008
755*	NA	CA	12001	e	CUST STATES VEH SEAT BELT INOP	CHECK AND REPLACE BOTH FRONT SEAT BELT BUCKLES BOTH FRONT BUCKLES JAMMING UP	780 USA	171428
7841*	NA	CA	11001	e	INSTALL SPO SEAT BELT USE SPO D1254008	INSTALLED LT SEAT BELT	209 USA	172300

RC04-911 17501