



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: EA 05-002
Prompted By: Consumer Complaints
Date Opened: 02/02/2005 Date Closed: 08/31/2006
Principal Investigator: Robert Young
Subject: Sudden, unforeseen transmission lockup

Manufacturer: POLARIS INDUSTRIES, INC.
Products: 1999-2000 Victory Motorcycle Division, Polaris Industries, Inc
Population: 6628

Problem Description: While underway, the transmission will suddenly downshift from 3rd to 2nd gear and/or lockup. Loss of motorcycle control may then occur.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	211	393	604
Crashes/Fires:	3	4	7
Injury Incidents:	1	1	2
# Injuries:	1	1	2
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	0	0	0

*Description of Other:

Action: This engineering analysis is closed.

Engineer: Bob Young

Date: 08/31/2006

Div. Chief: Richard Boyd

Date: 08/31/2006

Office Dir.: Kathleen C. DeMeter

Date: 08/31/2006

Summary: This investigation determined that the subject motorcycle transmissions are prone to shifting performance issues that occur well before the transmissions have reached the end of the manufacturer's stated intended design life (30,000 miles). Polaris has taken actions including carrying out two safety recalls to address issues in some of the subject vehicles, conducting a special policy, and formally communicating with its dealers and subject owners to address these issues. In light of the nature and circumstances of the reported problems and these activities by Polaris, further use of agency resources does not appear to be warranted.

See the attached technical report for full details.

ENGINEERING ANALYSIS CLOSING REPORT

SUBJECT: False neutraling, spontaneous downshifting, and transmission lockup.

EA No.: 05-002

Date Opened: 2-Feb-05

Date Closed: 30-Aug-06

BASIS: This engineering analysis was opened on February 2, 2005 based on information gathered during Preliminary Evaluation (PE), PE04-057. The PE was opened on August 3, 2004, to investigate allegations of spontaneous downshifting and/or lockup of the transmission of MY 1999 and 2000 Victory brand motorcycles produced by Polaris Industries (the subject vehicles).

THE SUBJECT VEHICLES: Model Year (MY) 1999-2000 V92 model (and derivatives) Victory brand motorcycles produced by Polaris Industries and assembled in Spirit Lake, Iowa.

THE ALLEGED DEFECT: While the motorcycle is underway, its transmission may spontaneously downshift or lock-up, causing a rider to lose control of the vehicle.

DESCRIPTION OF COMPONENT OR VEHICLE SYSTEM: The subject vehicles are produced with a typical motorcycle transmission, i.e., a 5-speed, constant mesh, sequential shift, non-synchronized power transfer system. A diagram of the transmission used in the subject vehicles follows:




Figure 1. Subject Vehicle Internal Transmission Components, 1999 V92C Service Manual

HOW THE TRANSMISSION WORKS:

The gears are arranged so that the drive gear is coupled to the engine through the clutch. The driven gear is coupled to the rear wheel. Power is transferred from the engine, through the clutch, to the mainshaft, which rotates at engine speed. Gears on the main shaft rotate those arranged on the countershaft, which then rotate the freewheeling driven gear at a speed determined by the selected gear ratio. The following photo shows these components and, directionally, how the power is transferred from the engine, through the transmission, to the rear wheel. In this instance, the transmission is in "3rd" gear.




Figure 2. Gearsets and Power transfer

Shifting gears is accomplished by moving sliding cogs so that their "dogs" (i.e. engagement points) engage those of the cogs fixed on either the main or counter-shafts. See Figures 3 and 4. These dogs fit snugly into the appropriate slots and allow the transmission to remain in gear. See Figure 4.




Figure 3 – Gear dogs, Disengaged




Figure 4 – Gear dogs, Engaged

The sliding gears are moved across the shaft by “forks” which ride in a radial slot on the gear. See Figure 5.



Figure 5 – Shift Fork

A “shift drum” is rotated when the rider lifts or presses on the motorcycle’s shift lever. This moves the shift forks, which slide the appropriate cogs into position to engage the dogs and select 1st, 2nd, 3rd, 4th, or 5th “gear” or neutral. Through a pin and slot arrangement, the shift drum is designed to select only one gear pair and engagement dog set at a time. See Figures 6 and 7.



Figure 6 – Shift drum and forks

Selecting two or more gear pairs simultaneously would “lockup” the transmission (and rear wheel), which could result in a loss of vehicle control.




Figure 7 – Shift Forks and Drum

CORRESPONDENCE:

NHTSA sent Polaris an information request and Polaris responded and later supplemented the response. Correspondence dates are as follows:

Table 1 - Correspondence

NHTSA to MFR	MFR to NHTSA	MFR to NHTSA Supplement
23-Aug-05	3-Oct-05	7-Oct-05 & 10-Mar-06

A breakdown of incidents reported to NHTSA and Polaris is detailed in Tables 2 through 4, which, collectively, depict the number of reported incidents regarding the alleged defect, the reported number of problems by model year, and the number of reported problems broken out by calendar year along with the type of alleged failure.

Table 2 - Problem Experience

<u>Problem Experience</u>	<u>Cumulative Reports</u>		<u>Total</u>
	<u>ODI</u>	<u>MFR</u>	
Reports	211	393	604
Crashes	3	4	7
Injury Crashes/Injuries	1/1	1/1	2/2
Fatal Incidents/Fatalities	0	0	0

Table 3 - Problem Experience by Model Year (MY)

<u>Model Year</u>	<u>1999</u>	<u>2000</u>	<u>Total</u>
Report Count	342	262	604

Table 4 - Problems by Failure Mode of MY 1999-2000 Victory Motorcycles and Calendar Year


Failure Year	99	00	01	02	03	04	05	06	Unk	Total
Spontaneous Downshift, False Neutral Events	1	13	29	35	55	44	34	1	0	212
Spontaneous Downshift	1	8	15	20	28	38	44	5	0	159
False Neutral	0	0	2	7	3	10	36	1	0	59
Remedy Failure, 3rd gear	0	1	10	18	5	2	6	0	0	42
Unknown	0	0	3	10	9	6	8	0	0	36
Unable to Shift	0	1	8	8	5	4	5	1	1	33
Misc	1	1	4	4	8	3	4	2	0	27
Stripped Gear	0	0	0	2	5	3	2	0	0	12
Cannot Shift into 3rd or 4th gear	0	0	3	2	2	3	1	0	0	11
Sprocket Nut/Lockup	0	0	2	3	1	2	0	0	0	8
Ratcheting	0	1	2	0	0	0	1	0	1	5
Totals	3	25	78	109	121	115	141	10	2	604

VEHICLE POPULATION: Polaris produced 6,628 V92 (and derivative) model motorcycles for the 1999 and 2000 model years.

SERVICE BULLETINS: Polaris released no bulletins related to engagement dog wear prior to August 1, 2006.

WARRANTY: Polaris reports 417 transmission service kits were installed under the basic 12-month warranty. These claims allegedly related to chipped gear teeth, abnormal wear, and improper transmission function.

PART SALES: Polaris sold 1,120 transmission service kits for the 6,628 MY 99-00 subject vehicles:



Of the 1,120 transmission remedy kits sold, 982 (87%) were purchased prior to January 1, 2005.

In addition, Polaris introduced a host of transmission design changes, which ultimately resulted in the use of a new transmission supplier. The transmissions built by the new supplier entered into production in June 2002. These changes are noted in the table below.

DESIGN, MATERIAL, AND/OR PRODUCTION MODIFICATIONS:

P/N	Description	Used On	Kit Status	Additional Kit Info
2201878	2001 Trans Update Kit	MY 99/00	Rel. 8-00. Superseded by 2202148	2001 Trans Design - Major design changes to upgrade transmission
2202148	1999-2000 Kit	MY 99/00	Rel. 7-01. Contains 2002 production components. Superseded by 2202431	2002 Trans Design - Gear ratio change. Changes not intended to improve durability. Vendor problem with heat treat.
2202149	2001 Trans Update Kit	MY 2001	Rel. 7-01. Contains 2002 production components. Superseded by 2202432	2002 Trans Design - Gear ratio change. Changes not intended to improve durability. Vendor problem with heat treat.
2202430	1999-2000 Kit	MY 99/00 SE Models	Rel. 6-02. Contains 2003 production components. Current kit.	2003 Trans Design - New gear supplier. Modified 3rd gear to improve strength and reduce material through hardening.
2202431	2000 Kit	MY 00 except SE	Rel. 6-02. Contains 2003 production components. Current kit.	2003 Trans Design - New gear supplier. Modified 3rd gear to improve strength and reduce material through hardening.
2202432	2001 Kit	MY 2001	Rel. 6-02. Contains 2003 production components. Current kit.	2003 Trans Design - New gear supplier. Modified 3rd gear to improve strength and reduce material through hardening.
2202433	2002 Kit	MY 2002	Rel. 6-02. Contains 2003 production components. Current kit.	2003 Trans Design - New gear supplier. Modified 3rd gear to improve strength and reduce material through hardening.

FAILURE MODES & WARNING SYMPTOMS: Polaris indicates that the transmissions in the subject motorcycles have a design life of 30,000 miles. Owners, however, have reported shifting difficulties that begin with as little as 900 miles. As detailed in Table 4 above, the transmission is subject to a series of problems that affect its performance. Of these, the agency's data indicate that false neutraling often precedes the occurrence of spontaneous downshifting events. Gear shift combinations that have reportedly experienced the most number of complaints involved 3rd gear combinations (2nd to 3rd and 3rd to 4th). In these instances, rather than engaging the next gear, the transmission will be in neutral with no drive being transferred to the rear wheel. This condition often precedes the occurrence of spontaneous downshifting. For example, a rider may shift from 2nd to 3rd but the transmission will suddenly downshift back to 2nd. The transmission's design does not permit a downshift of more than one gear at a time and there are no reports of a spontaneous downshift beyond an adjacent gear. The incidence of problems is tabulated in Table 4 above.

MANUFACTURER'S EVALUATION OF THE ALLEGED DEFECT: During this investigation, Polaris provided the following assessment of the current risk posed by the subject condition:

"Polaris firmly concludes that the issues related to the Victory transmissions are durability-based and are not the result of a transmission design defect. The subject transmission condition results from gradual wear of transmission components, with cues being provided to the operator, and not an unexpected and sudden transmission failure without warning. Since this failure mode is progressive, the operator has ample time to service the vehicle."

ODI ANALYSIS:

The alleged performance issues relate to mechanical problems. When the transmission's dogs do not fully engage, it can permit "false neutrals" during gear shifts. Without dog engagement, the transmission is in "neutral" whether "neutral" was selected or not. If these events increase in frequency, parts may wear and further degrade shift quality. When this occurs, the dogs and shift forks are usually damaged first, resulting in more frequent false-neutralling. This condition may lead to 1) a bent or worn shift fork and/or 2) "rounded" dogs, either of which can cause the transmission to "jump" out of gear. If the fork(s) are worn/bent, the gear cog may not be moved far enough to fully engage the dogs. Likewise, if the dogs are sufficiently rounded, they will not be fully engaged and the transferred torque will force them apart, causing spontaneous downshifts. Figures 8 through 11 show examples of normal and abnormal shift fork and dog wear.



Figure 8 – Normal shift fork wear – 13,153 miles



Figure 9 – Worn shift fork – 5,163 miles




Figure 10 – Engagement Dogs – New




Figure 11 – Worn Engagement Dogs
– 13,153 miles

During the investigation, other potentially-related problems were discovered with certain replacement transmissions installed by Polaris dealers to address consumer shifting concerns. These include problems stemming from: 1) a loss of clamp load of the front sprocket retaining nut in MY 2000 motorcycles, which can lead to transmission lockup; and 2) a gear ratio set in certain replacement transmissions used in MY 1999-2000 motorcycles that creates an abnormal overload condition resulting in a 3rd gear failure.


More recently manufactured transmissions that have been installed as replacements, however, have not encountered any of the problems noted above.

Among the reported crashes, none of them could be verified as linked to the alleged defect. Two injuries were reported. ODI could not confirm that these injuries were related to the alleged defect.

MANUFACTURER'S ACTIONS: Polaris has decided to take three actions to address the problems discussed above. First, Polaris will conduct a safety recall (06V-303) to install a new hardened drive sprocket, (creating a tighter spline fit) and a wider sprocket nut with a thread locking patch lock in MY 2000 V92-series motorcycles. Second, Polaris will recall (06V-298) all MY 1999-2000 motorcycles that received transmission kits that were built during MY 2001 and install a "rear sprocket hub damper assembly." This will reduce the shock loads seen by the motorcycle and reduce the risk of a third gear failure. Third, Polaris is conducting a special policy on those remaining motorcycles equipped with the original transmission that have not yet reached 30,000 miles. Copies of all three documents may be found in the public file for EA05-002.

REASON FOR CLOSING: This investigation determined that the subject vehicle transmissions are prone to shifting performance issues that occur well before the transmissions have reached the end of the manufacturer's stated intended design life (30,000 miles). Polaris has taken actions, including carrying out two safety recalls to address issues in some of the subject vehicles, conducting a special policy, and formally communicating with its dealers and subject vehicle owners to address these issues. In light of the nature and circumstances of the reported problems and these activities by Polaris, further use of agency resources does not appear to be warranted. The closing of this investigation does not constitute a finding by NHTSA that no safety-related defect exists with regard to the false neutralling/spontaneous downshifting events and the agency reserves the right to take further action on this issue if warranted by the circumstances.


Bob Young


Safety Defects Investigator

30-Aug-06
Date


I Concur:

Richard Boyd


Chief, Vehicle Control Division

Aug 30, 2006
Date

Kathleen DeMeter


Director, Office of Defects Investigation

8/31/06
Date

DEFECT INFORMATION REPORT 06V-303-7 12 25

1. **Manufacturer's name/address:** Polaris Industries, Victory Motorcycle Division, 2100, Highway 55, Medina, MN 55340

2. **Vehicles or Equipment involved in this defect notification:** All MY 2000 Victory Motorcycles produced with a Gates Drive Belt system.

3. **Total number of vehicles or items of equipment:** 2402

4. **Approximate percentage of vehicles or equipment estimated to actually contain the defect:** Victory does not know the percentage of vehicles estimated to actually contain the defect. All MY 2000 Victory motorcycles produced with a Gates Drive Belt system are included in the campaign.

5. **Description of the defect:** Victory has determined that the material used for the original front sprocket and the specified spline fit between the sprocket and transmission output shaft can lead to wear at the joint between the front sprocket and retaining nut. If wear does develop in this area the clamp load of the front sprocket retaining nut is reduced. This reduction in clamping force can lead to more wear and eventually the retaining nut may no longer secure the front sprocket to the output shaft.

Because the front sprocket nut is external to the transmission, Victory did not expect any correlation between front sprocket nut looseness (or failure) and transmission lockup. However, Victory looked at the failure data again recently, and concluded that it is possible, in some rare cases, for the sprocket nut failure to result in a lockup. While Victory believes that the sprocket nut failure is a customer satisfaction, and not a safety, issue, Victory nevertheless wishes to avoid any conflict with the agency and is willing to conduct a campaign as if it were a safety recall to address the issue of sprocket nut failure. Accordingly, Victory decided to conduct this recall.

6. **Chronological summary of events leading to this determination:** See Item 5.

7. **Description of proposed remedy (including schedule for dealer and customer notification):** Victory will replace the front sprocket assembly that is comprised of:

- A. Hardened Drive Sprocket
- B. Tighter spline fit
- C. Hardened spacer behind sprocket
- D. Increase sprocket nut width from 7 mm to 11 mm
- E. Addition of thread-locking patchlock to the sprocket nut.

These design changes eliminate the loss of clamp load on the drive sprocket joint during normal operation.

Customer notification will begin on [TBD] and will conclude on [TBD].

Dealer notification will begin on [TBD] and will conclude on [TBD].

8. Program for remedy campaign (including program for reimbursing any consumer who obtained the remedy at his/her own expense within one year of the opening of the EA, or within one year of this 573 report, whichever is earlier):

Victory will reimburse owners who obtained a replacement sprocket nut assembly at their own expense within one year of this Part 573 report.

Signed: _____

Don L. Good

Product Compliance Specialist

Polaris Industries Inc.

Date: _____

8-4-2006

Attachments

VIN List: Pages: 3-15

Draft of Consumer Letter: TBD

Draft of Dealer Bulletin: TBD

Serial Number	Serial Number	Serial Number	Serial Number
5VPCB15D9Y3000101	5VPCB15D4Y3002354	5VPCB15D9Y3001765	5VPCS15D2Y3000862
5VPCB15D0Y3000102	5VPCB15D6Y3002355	5VPCB15D0Y3001766	5VPCS15D4Y3000863
5VPCB15D2Y3000103	5VPCB15D8Y3002356	5VPCB15D2Y3001767	5VPCS15D6Y3000864
5VPCB15D4Y3000104	5VPCB15DXY3002357	5VPCB15D4Y3001768	5VPCS15D8Y3000865
5VPCB15D6Y3000105	5VPCB15D1Y3002358	5VPCB15D6Y3001769	5VPCS15DXY3000866
5VPCB15D8Y3000106	5VPCB15D3Y3002359	5VPCB15D2Y3001770	5VPCS15D1Y3000867
5VPCB15DXY3000107	5VPCB15DXY3002360	5VPCB15D4Y3001771	5VPCS15D3Y3000868
5VPCB15D1Y3000108	5VPCB15D1Y3002361	5VPCB15D6Y3001772	5VPCS15D5Y3000869
5VPCB15D3Y3000109	5VPCB15D3Y3002362	5VPCB15D8Y3001773	5VPCS15D1Y3000870
5VPCB15DXY3000110	5VPCB15D5Y3002363	5VPCB15DXY3001774	5VPCS15D3Y3000871
5VPCB15D1Y3000111	5VPCB15D7Y3002364	5VPCB15D1Y3001775	5VPCS15D5Y3000872
5VPCB15D3Y3000112	5VPCB15D9Y3002365	5VPCB15D3Y3001776	5VPCS15D7Y3000873
5VPCB15D5Y3000113	5VPCB15D0Y3002366	5VPCB15D5Y3001777	5VPCS15D9Y3000874
5VPCS15D7Y3000114	5VPCB15D2Y3002367	5VPCB15D7Y3001778	5VPCS15D0Y3000875
5VPCS15D9Y3000115	5VPCB15D4Y3002368	5VPCB15D9Y3001779	5VPCS15D2Y3000876
5VPCS15D0Y3000116	5VPCB15D6Y3002369	5VPCB15D5Y3001780	5VPCS15D4Y3000877
5VPCS15D2Y3000117	5VPCB15D2Y3002370	5VPCS15D7Y3001781	5VPCS15D6Y3000878
5VPCS15D4Y3000118	5VPCB15D4Y3002371	5VPCS15D9Y3001782	5VPCS15D8Y3000879
5VPCS15D6Y3000119	5VPCB15D6Y3002372	5VPCS15D0Y3001783	5VPCS15D4Y3000880
5VPCS15D2Y3000120	5VPCB15D8Y3002373	5VPCS15D2Y3001784	5VPCS15D6Y3000881
5VPCS15D4Y3000121	5VPCB15DXY3002374	5VPCS15D4Y3001785	5VPCS15D8Y3000882
5VPCS15D6Y3000122	5VPCB15D1Y3002375	5VPCS15D6Y3001786	5VPCS15DXY3000883
5VPCS15D8Y3000123	5VPCB15D3Y3002376	5VPCS15D8Y3001787	5VPCS15D1Y3000884
5VPCS15DXY3000124	5VPCB15D5Y3002377	5VPCS15DXY3001788	5VPCS15D3Y3000885
5VPCS15D1Y3000125	5VPCB15D7Y3002378	5VPCS15D1Y3001789	5VPCS15D5Y3000886
5VPCS15D3Y3000126	5VPCB15D9Y3002379	5VPCS15D8Y3001790	5VPCS15D7Y3000887
5VPCS15D5Y3000127	5VPCB15D5Y3002380	5VPCS15DXY3001791	5VPCS15D9Y3000888
5VPCS15D2Y3000201	5VPCB15D7Y3002381	5VPCS15D1Y3001792	5VPCS15D1Y3001078
5VPCS15D4Y3000202	5VPCB15D9Y3002382	5VPCS15D3Y3001793	5VPCS15D3Y3001079
5VPCS15D6Y3000203	5VPCB15D0Y3002383	5VPCS15D5Y3001794	5VPCS15DXY3001080
5VPCS15D8Y3000204	5VPCB15D2Y3002384	5VPCS15D7Y3001795	5VPCS15D1Y3001081
5VPCS15DXY3000205	5VPCB15D4Y3002385	5VPCS15D9Y3001796	5VPCS15D3Y3001082
5VPCS15D1Y3000206	5VPCB15D6Y3002386	5VPCS15D0Y3001797	5VPCS15D5Y3001083
5VPCS15D3Y3000207	5VPCB15D8Y3002387	5VPCS15D2Y3001798	5VPCS15D7Y3001084
5VPCS15D5Y3000208	5VPCB15DXY3002388	5VPCS15D4Y3001799	5VPCS15D9Y3001085
5VPCS15D7Y3000209	5VPCB15D1Y3002389	5VPCS15D7Y3001800	5VPCS15D0Y3001086
5VPCS15D3Y3000210	5VPCB15D8Y3002390	5VPCS15D9Y3001801	5VPCS15D2Y3001087
5VPCS15D5Y3000211	5VPCB15DXY3002391	5VPCS15D0Y3001802	5VPCS15D4Y3001088
5VPCS15D7Y3000212	5VPCB15D1Y3002392	5VPCB15D3Y3001910	5VPCS15D6Y3001089
5VPCS15D9Y3000213	5VPCB15D3Y3002393	5VPCB15D5Y3001911	5VPCS15D2Y3001090
5VPCS15D0Y3000214	5VPCB15D4Y3002502	5VPCB15D7Y3001912	5VPCS15D4Y3001091
5VPCS15D2Y3000215	5VPCB15D6Y3002503	5VPCB15D9Y3001913	5VPCS15D6Y3001092
5VPCS15D4Y3000216	5VPCB15D8Y3002504	5VPCB15D0Y3001914	5VPCS15D8Y3001093
5VPCB15D6Y3000217	5VPCB15DXY3002505	5VPCB15D2Y3001915	5VPCS15D2Y3001140
5VPCB15D8Y3000218	5VPCB15D1Y3002506	5VPCB15D4Y3001916	5VPCS15D4Y3001141
5VPCB15DXY3000219	5VPCB15D3Y3002507	5VPCB15D6Y3001917	5VPCS15D6Y3001142
5VPCB15D6Y3000220	5VPCB15D5Y3002508	5VPCB15D8Y3001918	5VPCS15D8Y3001143
5VPCB15D8Y3000221	5VPCB15D7Y3002509	5VPCB15DXY3001919	5VPCS15DXY3001144
5VPCB15DXY3000222	5VPCB15D3Y3002510	5VPCB15D6Y3001920	5VPCS15D1Y3001145

5VPCB15D1Y3000223	5VPCB15D5Y3002511	5VPCB15D8Y3001921	5VPCS15D3Y3001146
5VPCB15D3Y3000224	5VPCB15D7Y3002512	5VPCB15DXY3001922	5VPCS15D5Y3001147
5VPCB15D5Y3000225	5VPCB15D9Y3002513	5VPCB15D1Y3001923	5VPCS15D7Y3001148
5VPCS15D6Y3000332	5VPCB15D0Y3002514	5VPCB15D3Y3001924	5VPCS15D9Y3001149
5VPCS15D8Y3000333	5VPCB15D2Y3002515	5VPCB15D5Y3001925	5VPCS15D5Y3001150
5VPCS15DXY3000334	5VPCB15D4Y3002516	5VPCB15D7Y3001926	5VPCS15D7Y3001151
5VPCS15D1Y3000335	5VPCB15D6Y3002517	5VPCB15D9Y3001927	5VPCS15D9Y3001152
5VPCS15D3Y3000336	5VPCB15D8Y3002518	5VPCB15D0Y3001928	5VPCS15D0Y3001153
5VPCS15D5Y3000337	5VPCB15DXY3002519	5VPCB15D2Y3001929	5VPCS15D2Y3001154
5VPCS15D7Y3000338	5VPCB15D6Y3002520	5VPCB15D9Y3001930	5VPCS15D4Y3001155
5VPCS15D9Y3000339	5VPCB15D8Y3002521	5VPCB15D0Y3001931	5VPCS15D6Y3001156
5VPCS15D5Y3000340	5VPCB15DXY3002522	5VPCB15D2Y3001932	5VPCS15D8Y3001157
5VPCS15D7Y3000341	5VPCB15D1Y3002523	5VPCB15D4Y3001933	5VPCS15DXY3001158
5VPCS15D9Y3000342	5VPCB15D3Y3002524	5VPCB15D6Y3001934	5VPCS15D1Y3001159
5VPCS15D0Y3000343	5VPCB15D5Y3002525	5VPCB15D8Y3001935	5VPCS15D8Y3001160
5VPCS15D2Y3000344	5VPCB15D7Y3002526	5VPCB15DXY3001936	5VPCS15DXY3001161
5VPCS15D4Y3000345	5VPCB15D9Y3002527	5VPCB15D1Y3001937	5VPCS15D1Y3001162
5VPCS15D6Y3000346	5VPCB15D0Y3002528	5VPCB15D3Y3001938	5VPCS15D3Y3001163
5VPCS15D8Y3000347	5VPCB15D2Y3002529	5VPCB15D5Y3001939	5VPCS15D5Y3001164
5VPCS15DXY3000348	5VPCB15D9Y3002530	5VPCB15D1Y3001940	5VPCS15D7Y3001165
5VPCS15D1Y3000349	5VPCB15D0Y3002531	5VPCB15D3Y3001941	5VPCS15D9Y3001166
5VPCS15D8Y3000350	5VPCB15D2Y3002532	5VPCB15D5Y3001942	5VPCS15D0Y3001167
5VPCS15DXY3000351	5VPCB15D4Y3002533	5VPCB15D7Y3001943	5VPCS15D2Y3001168
5VPCS15D1Y3000352	5VPCB15D6Y3002534	5VPCB15D9Y3001944	5VPCS15D4Y3001169
5VPCS15D3Y3000353	5VPCB15D8Y3002535	5VPCB15D0Y3001945	5VPCS15D0Y3001170
5VPCS15D5Y3000354	5VPCB15DXY3002536	5VPCB15D2Y3001946	5VPCS15D2Y3001171
5VPCS15D7Y3000355	5VPCB15D1Y3002537	5VPCB15D4Y3001947	5VPCS15D4Y3001172
5VPCS15D9Y3000356	5VPCB15D3Y3002538	5VPCB15D6Y3001948	5VPCS15D6Y3001173
5VPCS15D0Y3000357	5VPCB15D5Y3002539	5VPCB15D8Y3001949	5VPCS15D8Y3001174
5VPCS15D2Y3000358	5VPCB15D1Y3002540	5VPCB15D4Y3001950	5VPCS15DXY3001175
5VPCS15D4Y3000359	5VPCB15D3Y3002541	5VPCB15D6Y3001951	5VPCS15D1Y3001176
5VPCS15D0Y3000360	5VPCB15D5Y3002542	5VPCS15D8Y3001952	5VPCS15D6Y3001383
5VPCS15D2Y3000361	5VPCB15D7Y3002543	5VPCB15DXY3001953	5VPCS15D8Y3001384
5VPCS15D4Y3000362	5VPCB15D9Y3002544	5VPCB15D1Y3001954	5VPCS15DXY3001385
5VPCS15D6Y3000363	5VPCB15D0Y3002545	5VPCB15D3Y3001955	5VPCS15D1Y3001386
5VPCS15D8Y3000364	5VPCB15D2Y3002546	5VPCB15D5Y3001956	5VPCS15D3Y3001387
5VPCS15DXY3000365	5VPCB15D4Y3002547	5VPCB15D7Y3001957	5VPCS15D5Y3001388
5VPCS15D1Y3000366	5VPCB15D6Y3002548	5VPCB15D9Y3001958	5VPCS15D7Y3001389
5VPCS15D3Y3000367	5VPCB15D8Y3002549	5VPCB15D0Y3001959	5VPCS15D3Y3001390
5VPCS15D5Y3000368	5VPCB15D4Y3002550	5VPCB15D7Y3001960	5VPCS15D5Y3001391
5VPCS15D7Y3000369	5VPCB15D6Y3002551	5VPCB15D9Y3001961	5VPCS15D7Y3001392
5VPCS15D3Y3000370	5VPCB15D8Y3002552	5VPCB15D0Y3001962	5VPCS15D9Y3001393
5VPCS15D5Y3000371	5VPCB15DXY3002553	5VPCB15D1Y3002070	5VPCS15D0Y3001394
5VPCS15D7Y3000372	5VPCB15D1Y3002554	5VPCB15D3Y3002071	5VPCS15D2Y3001395
5VPCS15D9Y3000373	5VPCB15D3Y3002555	5VPCB15D5Y3002072	5VPCS15D4Y3001396
5VPCS15D0Y3000374	5VPCS15D8Y3002664	5VPCB15D7Y3002073	5VPCS15D6Y3001397
5VPCS15D2Y3000375	5VPCS15DXY3002665	5VPCB15D9Y3002074	5VPCS15D8Y3001398
5VPCS15D4Y3000376	5VPCS15D1Y3002666	5VPCB15D0Y3002075	5VPCS15DXY3001399
5VPCS15D6Y3000377	5VPCS15D3Y3002667	5VPCB15D2Y3002076	5VPCS15D2Y3001400
5VPCS15D8Y3000378	5VPCS15D5Y3002668	5VPCB15D4Y3002077	5VPCS15D4Y3001401

5VPCS15DXY3000379	5VPCS15D7Y3002669	5VPCB15D6Y3002078	5VPCS15D6Y3001402
5VPCS15D6Y3000380	5VPCS15D3Y3002670	5VPCB15D8Y3002079	5VPCS15D8Y3001403
5VPCS15D8Y3000381	5VPCS15D5Y3002671	5VPCB15D4Y3002080	5VPCS15DXY3001404
5VPCS15DXY3000382	5VPCS15D7Y3002672	5VPCB15D6Y3002081	5VPCS15D1Y3001405
5VPCS15D1Y3000383	5VPCS15D9Y3002673	5VPCB15D8Y3002082	5VPCS15D3Y3001406
5VPCS15D3Y3000384	5VPCS15D0Y3002674	5VPCB15DXY3002083	5VPCS15D5Y3001407
5VPCS15D4Y3000491	5VPCS15D2Y3002675	5VPCB15D1Y3002084	5VPCS15D7Y3001408
5VPCS15D6Y3000492	5VPCS15D4Y3002676	5VPCB15D3Y3002085	5VPCS15D9Y3001409
5VPCS15D8Y3000493	5VPCS15D8Y3002678	5VPCB15D5Y3002086	5VPCS15D5Y3001410
5VPCS15DXY3000494	5VPCS15DXY3002679	5VPCB15D7Y3002087	5VPCS15D7Y3001411
5VPCS15D1Y3000495	5VPCS15D6Y3002680	5VPCB15D9Y3002088	5VPCS15D9Y3001412
5VPCS15D3Y3000496	5VPCS15D8Y3002681	5VPCB15D0Y3002089	5VPCS15D0Y3001413
5VPCS15D5Y3000497	5VPCS15DXY3002682	5VPCB15D7Y3002090	5VPCS15D2Y3001414
5VPCS15D7Y3000498	5VPCS15D1Y3002683	5VPCB15D9Y3002091	5VPCS15D4Y3001415
5VPCS15D9Y3000499	5VPCS15D3Y3002684	5VPCB15D0Y3002092	5VPCS15D6Y3001416
5VPCS15D1Y3000500	5VPCS15D5Y3002685	5VPCB15D2Y3002093	5VPCS15D8Y3001417
5VPCS15D3Y3000501	5VPCS15D7Y3002686	5VPCB15D4Y3002094	5VPCS15DXY3001418
5VPCS15D5Y3000502	5VPCS15D9Y3002687	5VPCB15D6Y3002095	5VPCS15D1Y3001419
5VPCS15D7Y3000503	5VPCS15D0Y3002688	5VPCB15D8Y3002096	5VPCS15D8Y3001420
5VPCS15D9Y3000504	5VPCS15D2Y3002689	5VPCB15DXY3002097	5VPCS15DXY3001421
5VPCS15D0Y3000505	5VPCS15D9Y3002690	5VPCB15D1Y3002098	5VPCS15D1Y3001422
5VPCS15D2Y3000506	5VPCS15D0Y3002691	5VPCB15D3Y3002099	5VPCS15D3Y3001423
5VPCS15D4Y3000507	5VPCS15L3Y3002692	5VPCB15D6Y3002100	5VPCS15D5Y3001424
5VPCS15D6Y3000508	5VPCS15L5Y3002693	5VPCB15D8Y3002101	5VPCS15D7Y3001425
5VPCS15D8Y3000509	5VPCS15L7Y3002694	5VPCB15DXY3002102	5VPCS15D9Y3001426
5VPCS15D4Y3000510	5VPCS15L9Y3002695	5VPCB15D1Y3002103	5VPCS15D0Y3001427
5VPCS15D6Y3000511	5VPCS15L0Y3002696	5VPCB15D3Y3002104	5VPCS15D2Y3001428
5VPCS15D8Y3000512	5VPCS15L2Y3002697	5VPCB15D5Y3002105	5VPCS15D4Y3001429
5VPCS15DXY3000513	5VPCS15L4Y3002698	5VPCB15D7Y3002106	5VPCS15D0Y3001430
5VPCS15D1Y3000514	5VPCS15L6Y3002699	5VPCB15D9Y3002107	5VPCS15D2Y3001431
5VPCS15D3Y3000515	5VPCS15C9Y3002700	5VPCB15D0Y3002108	5VPCS15D4Y3001432
5VPCS15D5Y3000516	5VPCB15C0Y3002701	5VPCB15D2Y3002109	5VPCS15D6Y3001433
5VPCS15D7Y3000517	5VPCS15L2Y3002702	5VPCB15D9Y3002110	5VPCS15D9Y3001488
5VPCS15D9Y3000518	5VPCS15L4Y3002703	5VPCB15D0Y3002111	5VPCS15D0Y3001489
5VPCS15D0Y3000519	5VPCS15L6Y3002704	5VPCB15D2Y3002112	5VPCS15L8Y3001635
5VPCS15D7Y3000520	5VPCS15L8Y3002705	5VPCB15D4Y3002113	5VPCS15LXY3001636
5VPCS15D9Y3000521	5VPCS15LXY3002706	5VPCB15D6Y3002114	5VPCS15L1Y3001637
5VPCS15D0Y3000522	5VPCS15L1Y3002707	5VPCB15D8Y3002115	5VPCS15L3Y3001638
5VPCS15D2Y3000523	5VPCS15D2Y3002708	5VPCB15DXY3002116	5VPCS15L5Y3001639
5VPCS15D4Y3000524	5VPCS15D4Y3002709	5VPCB15D1Y3002117	5VPCS15L1Y3001640
5VPCS15D6Y3000525	5VPCS15L1Y3002710	5VPCB15D3Y3002118	5VPCS15L3Y3001641
5VPCS15D8Y3000526	5VPCS15D2Y3002711	5VPCB15D5Y3002119	5VPCS15L5Y3001642
5VPCS15DXY3000527	5VPCS15L5Y3002712	5VPCB15D1Y3002120	5VPCS15L7Y3001643
5VPCS15D1Y3000528	5VPCS15L7Y3002713	5VPCB15D3Y3002121	5VPCS15L9Y3001644
5VPCS15D3Y3000529	5VPCS15D8Y3002714	5VPCB15D5Y3002122	5VPCS15L0Y3001645
5VPCS15DXY3000530	5VPCS15DXY3002715	5VPCB15D7Y3002123	5VPCS15L2Y3001646
5VPCS15D1Y3000531	5VPCS15D1Y3002716	5VPCB15D1Y3002232	5VPCS15L4Y3001647
5VPCS15D3Y3000532	5VPCS15D3Y3002717	5VPCB15D3Y3002233	5VPCS15L6Y3001648
5VPCS15D5Y3000533	5VPCS15D8Y3002826	5VPCB15D5Y3002234	5VPCS15L8Y3001649
5VPCS15D7Y3000534	5VPCS15DXY3002827	5VPCB15D7Y3002235	5VPCS15L4Y3001650

5VPCS15D9Y3000535	5VPCS15D1Y3002828	5VPCB15D9Y3002236	5VPCS15L6Y3001651
5VPCS15D0Y3000536	5VPCS15D3Y3002829	5VPCB15D0Y3002237	5VPCS15L8Y3001652
5VPCS15D2Y3000537	5VPCS15C0Y3002830	5VPCB15D2Y3002238	5VPCS15LXY3001653
5VPCS15D6Y3000539	5VPCS15C2Y3002831	5VPCB15D4Y3002239	5VPCS15L1Y3001654
5VPCS15D2Y3000540	5VPCS15C4Y3002832	5VPCB15D0Y3002240	5VPCS15L3Y3001655
5VPCS15D4Y3000541	5VPCS15C6Y3002833	5VPCB15D2Y3002241	5VPCS15L5Y3001656
5VPCS15D6Y3000542	5VPCS15C8Y3002834	5VPCB15D4Y3002242	5VPCS15L7Y3001657
5VPCS15D8Y3000543	5VPCS15CXY3002835	5VPCB15D6Y3002243	5VPCS15L9Y3001658
5VPCS15DXY3000544	5VPCS15C1Y3002836	5VPCB15D8Y3002244	5VPCS15L0Y3001659
5VPCS15D4Y3000653	5VPCS15C3Y3002837	5VPCB15DXY3002245	5VPCS15L7Y3001660
5VPCS15D6Y3000654	5VPCS15C5Y3002838	5VPCB15D1Y3002246	5VPCS15L9Y3001661
5VPCS15D8Y3000655	5VPCS15C7Y3002839	5VPCB15D3Y3002247	5VPCS15L0Y3001662
5VPCS15DXY3000656	5VPCS15C3Y3002840	5VPCB15D5Y3002248	5VPCS15L2Y3001663
5VPCS15D1Y3000657	5VPCS15C5Y3002841	5VPCB15D7Y3002249	5VPCS15L4Y3001664
5VPCS15D3Y3000658	5VPCS15C7Y3002842	5VPCB15D3Y3002250	5VPCS15L6Y3001665
5VPCS15D5Y3000659	5VPCS15C9Y3002843	5VPCB15D5Y3002251	5VPCS15L8Y3001666
5VPCS15D1Y3000660	5VPCS15C0Y3002844	5VPCB15D7Y3002252	5VPCS15LXY3001667
5VPCS15D3Y3000661	5VPCS15C2Y3002845	5VPCB15D9Y3002253	5VPCS15L1Y3001668
5VPCS15D5Y3000662	5VPCS15C4Y3002846	5VPCB15D0Y3002254	5VPCS15L3Y3001669
5VPCS15D7Y3000663	5VPCS15C6Y3002847	5VPCB15D2Y3002255	5VPCS15LXY3001670
5VPCS15D9Y3000664	5VPCS15C8Y3002848	5VPCB15D4Y3002256	5VPCS15L1Y3001671
5VPCS15D0Y3000665	5VPCS15CXY3002849	5VPCB15D6Y3002257	5VPCS15L3Y3001672
5VPCS15D2Y3000666	5VPCS15C6Y3002850	5VPCB15D8Y3002258	5VPCS15L5Y3001673
5VPCS15D4Y3000667	5VPCS15C8Y3002851	5VPCB15DXY3002259	5VPCS15L7Y3001674
5VPCS15D6Y3000668	5VPCS15CXY3002852	5VPCB15D6Y3002260	5VPCS15L9Y3001675
5VPCS15D4Y3000717	5VPCS15C1Y3002853	5VPCB15D8Y3002261	5VPCS15L0Y3001676
5VPCS15D6Y3000718	5VPCS15C3Y3002854	5VPCB15DXY3002262	5VPCS15L2Y3001677
5VPCS15D8Y3000719	5VPCS15C5Y3002855	5VPCB15D1Y3002263	5VPCS15L4Y3001678
5VPCS15D4Y3000720	5VPCS15C7Y3002856	5VPCB15D3Y3002264	5VPCS15L6Y3001679
5VPCS15D6Y3000721	5VPCS15C9Y3002857	5VPCB15D5Y3002265	5VPCS15L2Y3001680
5VPCS15D8Y3000722	5VPCB15C0Y3002858	5VPCB15D7Y3002266	5VPCS15L4Y3001681
5VPCS15DXY3000723	5VPCB15C2Y3002859	5VPCB15D9Y3002267	5VPCS15L6Y3001682
5VPCS15D1Y3000724	5VPCB15C9Y3002860	5VPCB15D0Y3002268	5VPCS15L8Y3001683
5VPCS15D3Y3000725	5VPCB15C0Y3002861	5VPCB15D2Y3002269	5VPCS15LXY3001684
5VPCS15D5Y3000726	5VPCB15C2Y3002862	5VPCB15D9Y3002270	5VPCS15L1Y3001685
5VPCS15D7Y3000727	5VPCB15C4Y3002863	5VPCB15D0Y3002271	5VPCB15DXY3001693
5VPCS15D9Y3000728	5VPCB15C6Y3002864	5VPCB15D2Y3002272	5VPCB15D1Y3001694
5VPCS15D0Y3000729	5VPCB15C8Y3002865	5VPCB15D4Y3002273	5VPCS15D2Y3001803
5VPCS15D7Y3000730	5VPCB15CXY3002866	5VPCB15D6Y3002274	5VPCS15D4Y3001804
5VPCS15D9Y3000731	5VPCB15C1Y3002867	5VPCB15D8Y3002275	5VPCS15D6Y3001805
5VPCS15D0Y3000732	5VPCB15C3Y3002868	5VPCB15DXY3002276	5VPCS15D8Y3001806
5VPCS15D2Y3000733	5VPCB15C5Y3002869	5VPCB15D1Y3002277	5VPCS15DXY3001807
5VPCS15D4Y3000734	5VPCB15C1Y3002870	5VPCB15D3Y3002278	5VPCS15D1Y3001808
5VPCS15D6Y3000735	5VPCB15C3Y3002871	5VPCB15D5Y3002279	5VPCS15D3Y3001809
5VPCS15D8Y3000736	5VPCB15C5Y3002872	5VPCB15D1Y3002280	5VPCS15DXY3001810
5VPCS15DXY3000737	5VPCB15C7Y3002873	5VPCB15D3Y3002281	5VPCS15D1Y3001811
5VPCS15D1Y3000738	5VPCB15C9Y3002874	5VPCB15D5Y3002282	5VPCS15D3Y3001812
5VPCS15D3Y3000739	5VPCB15C0Y3002875	5VPCB15D7Y3002283	5VPCS15D5Y3001813
5VPCS15DXY3000740	5VPCB15C2Y3002876	5VPCB15D9Y3002284	5VPCS15D7Y3001814
5VPCS15D1Y3000741	5VPCB15C4Y3002877	5VPCB15D0Y3002285	5VPCS15D9Y3001815

5VPCS15D3Y3000742	5VPCB15C6Y3002878	5VPCB15D5Y3002394	5VPCS15D0Y3001816
5VPCS15D5Y3000743	5VPCB15C8Y3002879	5VPCB15D7Y3002395	5VPCS15D2Y3001817
5VPCS15D7Y3000744	5VPCS15LXY3003094	5VPCB15D9Y3002396	5VPCS15D4Y3001818
5VPCS15D9Y3000745	5VPCS15L1Y3003095	5VPCB15D0Y3002397	5VPCS15D6Y3001819
5VPCS15D0Y3000746	5VPCS15L3Y3003096	5VPCB15D2Y3002398	5VPCS15D2Y3001820
5VPCS15D2Y3000747	5VPCS15L5Y3003097	5VPCB15D4Y3002399	5VPCS15D4Y3001821
5VPCS15D4Y3000748	5VPCS15D5Y3003111	5VPCB15D7Y3002400	5VPCS15D6Y3001822
5VPCS15D6Y3000749	5VPCS15D6Y3003151	5VPCB15D9Y3002401	5VPCS15D8Y3001823
5VPCS15D2Y3000750	5VPCS15D7Y3003188	5VPCB15D0Y3002402	5VPCS15DXY3001824
5VPCS15D4Y3000751	5VPCS15D9Y3003189	5VPCB15D2Y3002403	5VPCS15D1Y3001825
5VPCS15D6Y3000752	5VPCS15D7Y3003191	5VPCB15D4Y3002404	5VPCS15D3Y3001826
5VPCS15D8Y3000753	5VPCS15D9Y3003192	5VPCB15D6Y3002405	5VPCS15D5Y3001827
5VPCS15D0Y3000889	5VPCS15D0Y3003193	5VPCB15D8Y3002406	5VPCS15D7Y3001828
5VPCS15D7Y3000890	5VPCB15D7Y3000226	5VPCB15DXY3002407	5VPCS15D9Y3001829
5VPCS15D9Y3000891	5VPCB15D9Y3000227	5VPCB15D1Y3002408	5VPCS15D5Y3001830
5VPCS15D0Y3000892	5VPCB15D0Y3000228	5VPCB15D3Y3002409	5VPCS15D7Y3001831
5VPCS15D2Y3000893	5VPCB15D2Y3000229	5VPCB15DXY3002410	5VPCS15D9Y3001832
5VPCS15D4Y3000894	5VPCB15D9Y3000230	5VPCB15D1Y3002411	5VPCS15D0Y3001833
5VPCS15D6Y3000895	5VPCB15D0Y3000231	5VPCB15D3Y3002412	5VPCS15D2Y3001834
5VPCS15D8Y3000896	5VPCB15D2Y3000232	5VPCB15D5Y3002413	5VPCS15D4Y3001835
5VPCS15DXY3000897	5VPCB15D4Y3000233	5VPCB15D7Y3002414	5VPCS15D6Y3001836
5VPCS15D1Y3000898	5VPCB15D6Y3000234	5VPCB15D9Y3002415	5VPCS15D8Y3001837
5VPCS15D3Y3000899	5VPCB15D8Y3000235	5VPCB15D0Y3002416	5VPCS15DXY3001838
5VPCS15D6Y3000900	5VPCB15DXY3000236	5VPCB15D2Y3002417	5VPCS15D1Y3001839
5VPCS15D8Y3000901	5VPCB15D1Y3000237	5VPCB15D4Y3002418	5VPCS15D8Y3001840
5VPCS15DXY3000902	5VPCB15D3Y3000238	5VPCB15D6Y3002419	5VPCS15DXY3001841
5VPCS15D1Y3000903	5VPCB15D5Y3000239	5VPCB15D2Y3002420	5VPCS15D1Y3001842
5VPCS15D3Y3000904	5VPCB15D1Y3000240	5VPCB15D4Y3002421	5VPCS15D3Y3001843
5VPCS15D5Y3000905	5VPCB15D3Y3000241	5VPCB15D6Y3002422	5VPCS15D5Y3001844
5VPCS15D7Y3000906	5VPCB15D5Y3000242	5VPCB15D8Y3002423	5VPCS15D7Y3001845
5VPCS15D9Y3000907	5VPCB15D7Y3000243	5VPCB15DXY3002424	5VPCS15D9Y3001846
5VPCS15D0Y3000908	5VPCB15D9Y3000244	5VPCB15D1Y3002425	5VPCS15D0Y3001847
5VPCS15D2Y3000909	5VPCB15D0Y3000245	5VPCB15D3Y3002426	5VPCS15D4Y3001849
5VPCS15D9Y3000910	5VPCB15D2Y3000246	5VPCB15D5Y3002427	5VPCS15D0Y3001850
5VPCS15D0Y3000911	5VPCB15D4Y3000247	5VPCB15D7Y3002428	5VPCS15D2Y3001851
5VPCS15D2Y3000912	5VPCB15D6Y3000248	5VPCB15D9Y3002429	5VPCS15D4Y3001852
5VPCS15D4Y3000913	5VPCB15D8Y3000249	5VPCB15D5Y3002430	5VPCS15D6Y3001853
5VPCS15D6Y3000914	5VPCB15D4Y3000250	5VPCB15D7Y3002431	5VPCS15D8Y3001854
5VPCS15D8Y3000915	5VPCB15D6Y3000251	5VPCB15D9Y3002432	5VPCB15DXY3001855
5VPCS15DXY3000916	5VPCB15D8Y3000252	5VPCB15D0Y3002433	5VPCB15D1Y3001856
5VPCS15D1Y3000917	5VPCB15DXY3000253	5VPCB15D2Y3002434	5VPCB15D2Y3001863
5VPCS15D3Y3000918	5VPCB15D1Y3000254	5VPCB15D4Y3002435	5VPCB15D4Y3001864
5VPCS15D5Y3000919	5VPCB15D3Y3000255	5VPCB15D6Y3002436	5VPCB15D6Y3001865
5VPCS15D1Y3000920	5VPCB15D5Y3000256	5VPCB15D8Y3002437	5VPCB15D8Y3001866
5VPCS15D3Y3000921	5VPCB15D7Y3000257	5VPCB15DXY3002438	5VPCB15DXY3001867
5VPCS15D5Y3000922	5VPCB15D9Y3000258	5VPCB15D1Y3002439	5VPCB15D1Y3001868
5VPCS15D7Y3000923	5VPCB15D0Y3000259	5VPCB15D8Y3002440	5VPCB15D3Y3001869
5VPCS15D9Y3000924	5VPCB15D7Y3000260	5VPCB15DXY3002441	5VPCB15DXY3001870
5VPCS15D0Y3000925	5VPCB15D9Y3000261	5VPCB15D1Y3002442	5VPCB15D1Y3001871
5VPCS15D2Y3000926	5VPCB15D0Y3000262	5VPCB15D3Y3002443	5VPCB15D3Y3001872

5VPCS15D4Y3000927	5VPCB15D2Y3000263	5VPCB15D5Y3002444	5VPCB15D5Y3001973
5VPCS15D6Y3000928	5VPCB15D4Y3000264	5VPCB15D7Y3002445	5VPCB15D7Y3001974
5VPCS15D8Y3000929	5VPCB15D6Y3000265	5VPCB15D9Y3002446	5VPCB15D9Y3001975
5VPCS15D4Y3000930	5VPCB15D8Y3000266	5VPCB15D0Y3002447	5VPCB15D0Y3001976
5VPCS15D6Y3000931	5VPCB15DXY3000267	5VPCB15D5Y3002556	5VPCB15D2Y3001977
5VPCS15D8Y3000932	5VPCB15D1Y3000268	5VPCB15D7Y3002557	5VPCB15D4Y3001978
5VPCS15DXY3000933	5VPCB15D3Y3000269	5VPCB15D9Y3002558	5VPCB15D6Y3001979
5VPCS15D1Y3000934	5VPCB15DXY3000270	5VPCB15D0Y3002559	5VPCB15D2Y3001980
5VPCS15D3Y3000935	5VPCB15D1Y3000271	5VPCB15D7Y3002560	5VPCB15D4Y3001981
5VPCS15D5Y3000936	5VPCB15D3Y3000272	5VPCB15D9Y3002561	5VPCB15D6Y3001982
5VPCS15D7Y3000937	5VPCS15D5Y3000273	5VPCB15D0Y3002562	5VPCB15D8Y3001983
5VPCS15D9Y3000938	5VPCS15D7Y3000274	5VPCB15D2Y3002563	5VPCB15DXY3001984
5VPCS15D0Y3000939	5VPCS15D9Y3000275	5VPCB15D4Y3002564	5VPCB15D1Y3001985
5VPCS15D7Y3000940	5VPCS15D0Y3000276	5VPCB15D6Y3002565	5VPCB15D3Y3001986
5VPCS15D9Y3000941	5VPCS15D2Y3000277	5VPCB15D8Y3002566	5VPCB15D5Y3001987
5VPCS15D0Y3000942	5VPCS15D4Y3000278	5VPCB15DXY3002567	5VPCB15D7Y3001988
5VPCS15D3Y3001177	5VPCS15D5Y3000385	5VPCB15D1Y3002568	5VPCB15D9Y3001989
5VPCS15D5Y3001178	5VPCS15D7Y3000386	5VPCB15D3Y3002569	5VPCB15D5Y3001990
5VPCS15D7Y3001179	5VPCS15D9Y3000387	5VPCB15DXY3002570	5VPCB15D7Y3001991
5VPCS15D3Y3001180	5VPCS15D0Y3000388	5VPCB15D1Y3002571	5VPCB15D9Y3001992
5VPCS15D5Y3001181	5VPCS15D2Y3000389	5VPCB15D3Y3002572	5VPCB15D0Y3001993
5VPCS15D7Y3001182	5VPCS15D9Y3000390	5VPCB15D5Y3002573	5VPCB15D2Y3001994
5VPCS15D9Y3001183	5VPCS15D0Y3000391	5VPCB15D7Y3002574	5VPCB15D4Y3001995
5VPCS15D0Y3001184	5VPCS15D2Y3000392	5VPCB15D9Y3002575	5VPCB15D6Y3001996
5VPCS15D2Y3001185	5VPCS15D4Y3000393	5VPCB15D0Y3002576	5VPCB15D8Y3001997
5VPCS15D4Y3001186	5VPCS15D6Y3000394	5VPCB15D2Y3002577	5VPCB15DXY3001998
5VPCS15D6Y3001187	5VPCS15D8Y3000395	5VPCB15D4Y3002578	5VPCB15D1Y3001999
5VPCS15D8Y3001188	5VPCS15DXY3000396	5VPCB15D6Y3002579	5VPCB15D2Y3002000
5VPCS15DXY3001189	5VPCS15D1Y3000397	5VPCB15D2Y3002580	5VPCB15D4Y3002001
5VPCS15D6Y3001190	5VPCS15D3Y3000398	5VPCB15D4Y3002581	5VPCB15D6Y3002002
5VPCS15D8Y3001191	5VPCS15D5Y3000399	5VPCB15D6Y3002582	5VPCB15D8Y3002003
5VPCS15DXY3001192	5VPCS15D8Y3000400	5VPCB15D8Y3002583	5VPCB15DXY3002004
5VPCS15D1Y3001193	5VPCS15DXY3000401	5VPCB15DXY3002584	5VPCB15D1Y3002005
5VPCS15D3Y3001194	5VPCS15D1Y3000402	5VPCB15D1Y3002585	5VPCB15D3Y3002006
5VPCS15D5Y3001195	5VPCS15D3Y3000403	5VPCB15D3Y3002586	5VPCB15D5Y3002007
5VPCS15D7Y3001196	5VPCS15D5Y3000404	5VPCB15D5Y3002587	5VPCB15D7Y3002008
5VPCS15D9Y3001197	5VPCS15D7Y3000405	5VPCB15D7Y3002588	5VPCB15D9Y3002009
5VPCS15D0Y3001198	5VPCS15D9Y3000406	5VPCB15D9Y3002589	5VPCB15D5Y3002010
5VPCS15D2Y3001199	5VPCS15D0Y3000407	5VPCB15D5Y3002590	5VPCB15D7Y3002011
5VPCS15D5Y3001200	5VPCS15D2Y3000408	5VPCB15D7Y3002591	5VPCB15D9Y3002012
5VPCS15D7Y3001201	5VPCS15D4Y3000409	5VPCB15D9Y3002592	5VPCB15D0Y3002013
5VPCS15D9Y3001202	5VPCS15D0Y3000410	5VPCB15D0Y3002593	5VPCB15D2Y3002014
5VPCS15D0Y3001203	5VPCS15D2Y3000411	5VPCB15D2Y3002594	5VPCB15D4Y3002015
5VPCS15D2Y3001204	5VPCS15D4Y3000412	5VPCB15D4Y3002595	5VPCB15D9Y3002124
5VPCS15D4Y3001205	5VPCS15D6Y3000413	5VPCB15D6Y3002596	5VPCB15D0Y3002125
5VPCS15D6Y3001206	5VPCS15D8Y3000414	5VPCB15D8Y3002597	5VPCB15D2Y3002126
5VPCS15D8Y3001207	5VPCS15DXY3000415	5VPCB15DXY3002598	5VPCB15D4Y3002127
5VPCS15DXY3001208	5VPCS15D1Y3000416	5VPCB15D1Y3002599	5VPCB15D6Y3002128
5VPCS15D1Y3001209	5VPCS15D3Y3000417	5VPCB15D4Y3002600	5VPCB15D8Y3002129
5VPCS15D8Y3001210	5VPCS15D5Y3000418	5VPCB15D6Y3002601	5VPCB15D4Y3002130

5VPCS15DXY3001211	5VPCS15D7Y3000419	5VPCB15D8Y3002602	5VPCB15D6Y3002131
5VPCS15D1Y3001212	5VPCS15D3Y3000420	5VPCB15DXY3002603	5VPCB15D8Y3002132
5VPCS15D3Y3001213	5VPCS15D5Y3000421	5VPCB15D1Y3002604	5VPCB15DXY3002133
5VPCS15D5Y3001214	5VPCS15D7Y3000422	5VPCB15D3Y3002605	5VPCB15D1Y3002134
5VPCS15D7Y3001215	5VPCS15D9Y3000423	5VPCB15D5Y3002606	5VPCB15D3Y3002135
5VPCS15D9Y3001216	5VPCS15D0Y3000424	5VPCB15D7Y3002607	5VPCB15D5Y3002136
5VPCS15D0Y3001217	5VPCS15D2Y3000425	5VPCB15D9Y3002608	5VPCB15D7Y3002137
5VPCS15D2Y3001218	5VPCS15D4Y3000426	5VPCB15D0Y3002609	5VPCB15D9Y3002138
5VPCS15D4Y3001219	5VPCS15D6Y3000427	5VPCS15D5Y3002718	5VPCB15D0Y3002139
5VPCS15D0Y3001220	5VPCS15D8Y3000428	5VPCS15D7Y3002719	5VPCB15D7Y3002140
5VPCS15D2Y3001221	5VPCS15DXY3000429	5VPCS15L4Y3002720	5VPCB15D9Y3002141
5VPCS15D4Y3001222	5VPCS15D6Y3000430	5VPCS15L6Y3002721	5VPCB15D0Y3002142
5VPCS15D6Y3001268	5VPCS15D8Y3000431	5VPCS15L8Y3002722	5VPCB15D2Y3002143
5VPCS15D8Y3001269	5VPCS15DXY3000432	5VPCS15LXY3002723	5VPCB15D4Y3002144
5VPCS15D4Y3001270	5VPCS15D1Y3000433	5VPCS15L1Y3002724	5VPCB15D6Y3002145
5VPCS15D6Y3001271	5VPCS15D3Y3000434	5VPCS15L3Y3002725	5VPCB15D8Y3002146
5VPCS15D8Y3001272	5VPCS15D5Y3000435	5VPCB15D4Y3002726	5VPCB15DXY3002147
5VPCS15DXY3001273	5VPCS15D7Y3000436	5VPCB15L7Y3002727	5VPCB15D1Y3002148
5VPCS15D0Y3001279	5VPCS15D9Y3000437	5VPCB15L9Y3002728	5VPCB15D3Y3002149
5VPCS15D7Y3001490	5VPCS15D1Y3000545	5VPCB15L0Y3002729	5VPCB15DXY3002150
5VPCS15D9Y3001491	5VPCS15D3Y3000546	5VPCB15L7Y3002730	5VPCB15D1Y3002151
5VPCS15D0Y3001492	5VPCS15D5Y3000547	5VPCB15L9Y3002731	5VPCB15D3Y3002152
5VPCS15D2Y3001493	5VPCS15D7Y3000548	5VPCB15L0Y3002732	5VPCB15D5Y3002153
5VPCS15D4Y3001494	5VPCS15D9Y3000549	5VPCB15L2Y3002733	5VPCB15D7Y3002154
5VPCS15D6Y3001495	5VPCS15D5Y3000550	5VPCB15L4Y3002734	5VPCB15D9Y3002155
5VPCS15D8Y3001496	5VPCS15D7Y3000551	5VPCB15L6Y3002735	5VPCB15D0Y3002156
5VPCS15DXY3001497	5VPCS15D9Y3000552	5VPCS15L8Y3002736	5VPCB15D2Y3002157
5VPCS15D1Y3001498	5VPCS15D0Y3000553	5VPCS15LXY3002737	5VPCB15D4Y3002158
5VPCS15D3Y3001499	5VPCS15D2Y3000554	5VPCS15L1Y3002738	5VPCB15D6Y3002159
5VPCS15D6Y3001500	5VPCS15D4Y3000555	5VPCS15L3Y3002739	5VPCB15D2Y3002160
5VPCS15D8Y3001501	5VPCS15D6Y3000556	5VPCS15LXY3002740	5VPCB15D4Y3002161
5VPCS15DXY3001502	5VPCS15D8Y3000557	5VPCS15D0Y3002741	5VPCB15D6Y3002162
5VPCS15D1Y3001503	5VPCS15DXY3000558	5VPCS15L3Y3002742	5VPCB15D8Y3002163
5VPCS15D3Y3001504	5VPCS15D1Y3000559	5VPCS15L5Y3002743	5VPCB15DXY3002164
5VPCS15D5Y3001505	5VPCS15D8Y3000560	5VPCS15L7Y3002744	5VPCB15D1Y3002165
5VPCS15D7Y3001506	5VPCS15DXY3000561	5VPCS15L9Y3002745	5VPCB15D3Y3002166
5VPCS15D9Y3001507	5VPCS15D1Y3000562	5VPCS15L0Y3002746	5VPCB15D5Y3002167
5VPCS15D0Y3001508	5VPCS15D3Y3000563	5VPCS15L2Y3002747	5VPCB15D7Y3002168
5VPCS15D2Y3001509	5VPCS15D5Y3000564	5VPCB15L4Y3002748	5VPCB15D9Y3002169
5VPCS15D9Y3001510	5VPCS15D7Y3000565	5VPCS15L6Y3002749	5VPCB15D5Y3002170
5VPCS15D0Y3001511	5VPCS15D9Y3000566	5VPCS15L2Y3002750	5VPCB15D7Y3002171
5VPCS15D2Y3001512	5VPCS15D0Y3000567	5VPCS15L4Y3002751	5VPCB15D9Y3002172
5VPCS15D4Y3001513	5VPCS15D2Y3000568	5VPCS15L6Y3002752	5VPCB15D0Y3002173
5VPCS15D6Y3001514	5VPCS15D4Y3000569	5VPCS15L8Y3002753	5VPCB15D2Y3002174
5VPCS15D8Y3001515	5VPCS15D0Y3000570	5VPCS15LXY3002754	5VPCB15D4Y3002175
5VPCS15DXY3001516	5VPCS15D2Y3000571	5VPCS15L1Y3002755	5VPCB15D6Y3002176
5VPCS15D1Y3001517	5VPCS15D4Y3000572	5VPCS15L3Y3002756	5VPCB15D8Y3002177
5VPCS15D3Y3001518	5VPCS15D6Y3000573	5VPCS15L5Y3002757	5VPCB15D2Y3002286
5VPCS15D5Y3001519	5VPCS15D8Y3000574	5VPCS15L7Y3002758	5VPCB15D4Y3002287
5VPCS15D1Y3001520	5VPCS15DXY3000575	5VPCS15L9Y3002759	5VPCB15D6Y3002288

5VPCS15D3Y3001521	5VPCS15D1Y3000576	5VPCS15L5Y3002760	5VPCB15D8Y3002289
5VPCS15D5Y3001522	5VPCS15D3Y3000577	5VPCS15L7Y3002761	5VPCB15D4Y3002290
5VPCS15D7Y3001523	5VPCS15D5Y3000578	5VPCS15L9Y3002762	5VPCB15D6Y3002291
5VPCS15D9Y3001524	5VPCS15D7Y3000579	5VPCS15L0Y3002763	5VPCB15D8Y3002292
5VPCS15D0Y3001525	5VPCS15D3Y3000580	5VPCS15L2Y3002764	5VPCB15DXY3002293
5VPCS15D2Y3001526	5VPCS15D5Y3000581	5VPCS15L4Y3002765	5VPCB15D1Y3002294
5VPCS15D4Y3001527	5VPCS15D7Y3000582	5VPCS15L6Y3002766	5VPCB15D3Y3002295
5VPCS15D6Y3001528	5VPCS15D9Y3000583	5VPCS15L8Y3002767	5VPCB15D5Y3002296
5VPCS15D8Y3001529	5VPCS15D0Y3000584	5VPCS15LXY3002768	5VPCB15D7Y3002297
5VPCS15D4Y3001530	5VPCS15D2Y3000585	5VPCS15L1Y3002769	5VPCB15D9Y3002298
5VPCS15D6Y3001531	5VPCS15D4Y3000586	5VPCS15L8Y3002770	5VPCB15D0Y3002299
5VPCS15D8Y3001532	5VPCS15D6Y3000587	5VPCB15LXY3002771	5VPCB15D3Y3002300
5VPCS15DXY3001533	5VPCS15D8Y3000588	5VPCB15C4Y3002880	5VPCB15D5Y3002301
5VPCS15D1Y3001534	5VPCS15DXY3000589	5VPCB15C6Y3002881	5VPCB15D7Y3002302
5VPCS15D3Y3001535	5VPCS15D6Y3000590	5VPCB15C8Y3002882	5VPCB15D9Y3002303
5VPCS15D5Y3001536	5VPCS15D8Y3000591	5VPCB15CXY3002883	5VPCB15D0Y3002304
5VPCS15D7Y3001537	5VPCS15DXY3000592	5VPCB15C1Y3002884	5VPCB15D2Y3002305
5VPCS15D9Y3001538	5VPCS15D1Y3000593	5VPCB15C3Y3002885	5VPCB15D4Y3002306
5VPCS15D0Y3001539	5VPCS15D3Y3000594	5VPCB15C5Y3002886	5VPCB15D6Y3002307
5VPCS15D7Y3001540	5VPCS15D5Y3000595	5VPCB15C7Y3002887	5VPCB15D8Y3002308
5VPCS15D9Y3001541	5VPCS15D7Y3000596	5VPCB15C9Y3002888	5VPCB15DXY3002309
5VPCS15D0Y3001542	5VPCS15D9Y3000597	5VPCB15C0Y3002889	5VPCB15D6Y3002310
5VPCS15D2Y3001543	5VPCS15D0Y3000598	5VPCB15C7Y3002890	5VPCB15D8Y3002311
5VPCB15D3Y3001695	5VPCS15DXY3000754	5VPCB15C9Y3002891	5VPCB15DXY3002312
5VPCB15D5Y3001696	5VPCS15D1Y3000755	5VPCB15C0Y3002892	5VPCB15D1Y3002313
5VPCB15D7Y3001697	5VPCS15D3Y3000756	5VPCB15C2Y3002893	5VPCB15D3Y3002314
5VPCB15D9Y3001698	5VPCS15D5Y3000757	5VPCB15C4Y3002894	5VPCB15D5Y3002315
5VPCB15D0Y3001699	5VPCS15D7Y3000758	5VPCB15C6Y3002895	5VPCB15D7Y3002316
5VPCB15D3Y3001700	5VPCS15D9Y3000759	5VPCB15C8Y3002896	5VPCB15D9Y3002317
5VPCB15D5Y3001701	5VPCS15D5Y3000760	5VPCB15CXY3002897	5VPCB15D0Y3002318
5VPCB15D7Y3001702	5VPCS15D7Y3000761	5VPCB15C1Y3002898	5VPCB15D2Y3002319
5VPCB15D9Y3001703	5VPCS15D9Y3000762	5VPCB15C3Y3002899	5VPCB15D9Y3002320
5VPCB15D0Y3001704	5VPCS15D0Y3000763	5VPCB15C6Y3002900	5VPCB15D0Y3002321
5VPCB15D2Y3001705	5VPCS15D2Y3000764	5VPCB15C8Y3002901	5VPCB15D2Y3002322
5VPCB15D4Y3001706	5VPCS15D4Y3000765	5VPCB15CXY3002902	5VPCB15D4Y3002323
5VPCB15D6Y3001707	5VPCS15D6Y3000766	5VPCB15C1Y3002903	5VPCB15D6Y3002324
5VPCB15L9Y3001708	5VPCS15D8Y3000767	5VPCB15C3Y3002904	5VPCB15D8Y3002325
5VPCB15L0Y3001709	5VPCS15DXY3000768	5VPCB15C5Y3002905	5VPCB15DXY3002326
5VPCB15L7Y3001710	5VPCS15D1Y3000769	5VPCB15C7Y3002906	5VPCB15D1Y3002327
5VPCB15L9Y3001711	5VPCS15D8Y3000770	5VPCB15C9Y3002907	5VPCB15D3Y3002328
5VPCB15L0Y3001712	5VPCS15DXY3000771	5VPCB15C0Y3002908	5VPCB15D5Y3002329
5VPCB15L2Y3001713	5VPCS15D1Y3000772	5VPCB15C2Y3002909	5VPCB15D1Y3002330
5VPCB15L4Y3001714	5VPCS15D3Y3000773	5VPCS15C9Y3002910	5VPCB15D3Y3002331
5VPCB15L6Y3001715	5VPCS15D5Y3000774	5VPCS15C0Y3002911	5VPCB15D5Y3002332
5VPCB15L8Y3001716	5VPCS15D7Y3000775	5VPCS15C2Y3002912	5VPCB15D7Y3002333
5VPCB15LXY3001717	5VPCS15D9Y3000776	5VPCS15C4Y3002913	5VPCB15D9Y3002334
5VPCB15L1Y3001718	5VPCS15D0Y3000777	5VPCS15C6Y3002914	5VPCB15D0Y3002335
5VPCB15L3Y3001719	5VPCS15D2Y3000778	5VPCS15C8Y3002915	5VPCB15D2Y3002336
5VPCB15LXY3001720	5VPCS15D4Y3000779	5VPCS15CXY3002916	5VPCB15D4Y3002337
5VPCB15L1Y3001721	5VPCS15D0Y3000780	5VPCS15C1Y3002917	5VPCB15D6Y3002338

5VPCB15L3Y3001722	5VPCS15D2Y3000781	5VPCS15C3Y3002918	5VPCB15D8Y3002339
5VPCB15L5Y3001723	5VPCS15D4Y3000782	5VPCS15C5Y3002919	5VPCB15D2Y3002448
5VPCB15L7Y3001724	5VPCS15D6Y3000783	5VPCS15C1Y3002920	5VPCB15D4Y3002449
5VPCB15L9Y3001725	5VPCS15D8Y3000784	5VPCS15C3Y3002921	5VPCB15D0Y3002450
5VPCB15L0Y3001726	5VPCS15DXY3000785	5VPCS15C5Y3002922	5VPCB15D2Y3002451
5VPCB15L2Y3001727	5VPCS15D1Y3000786	5VPCS15C7Y3002923	5VPCB15D4Y3002452
5VPCB15L4Y3001728	5VPCS15D3Y3000787	5VPCS15C9Y3002924	5VPCB15D6Y3002453
5VPCB15L6Y3001729	5VPCS15D5Y3000788	5VPCS15C0Y3002925	5VPCB15D8Y3002454
5VPCB15L2Y3001730	5VPCS15D7Y3000789	5VPCS15C2Y3002926	5VPCB15DXY3002455
5VPCB15L4Y3001731	5VPCS15D3Y3000790	5VPCS15C4Y3002927	5VPCB15D1Y3002456
5VPCB15L6Y3001732	5VPCS15D5Y3000791	5VPCS15C6Y3002928	5VPCB15D3Y3002457
5VPCB15L8Y3001733	5VPCS15D7Y3000792	5VPCS15C8Y3002929	5VPCB15D5Y3002458
5VPCB15LXY3001734	5VPCS15D9Y3000793	5VPCB15D3Y3002930	5VPCB15D7Y3002459
5VPCB15L1Y3001735	5VPCS15D0Y3000794	5VPCB15D5Y3002931	5VPCB15D3Y3002460
5VPCB15L3Y3001736	5VPCS15D2Y3000795	5VPCB15D7Y3002932	5VPCB15D5Y3002461
5VPCB15D4Y3001737	5VPCS15D4Y3000796	5VPCB15D9Y3002933	5VPCB15D7Y3002462
5VPCB15D6Y3001738	5VPCS15D6Y3000797	5VPCS15D6Y3000279	5VPCB15D9Y3002463
5VPCB15D8Y3001739	5VPCS15D8Y3000798	5VPCS15D2Y3000280	5VPCB15D0Y3002464
5VPCB15D4Y3001740	5VPCS15DXY3000799	5VPCS15D4Y3000281	5VPCB15D2Y3002465
5VPCB15D6Y3001741	5VPCS15D2Y3000800	5VPCS15D6Y3000282	5VPCB15D4Y3002466
5VPCB15D8Y3001742	5VPCS15D4Y3000801	5VPCS15D8Y3000283	5VPCB15D6Y3002467
5VPCB15DXY3001743	5VPCS15D6Y3000802	5VPCS15DXY3000284	5VPCB15D8Y3002468
5VPCB15D1Y3001744	5VPCS15D8Y3000803	5VPCS15D1Y3000285	5VPCB15DXY3002469
5VPCB15D3Y3001745	5VPCS15DXY3000804	5VPCS15D3Y3000286	5VPCB15D6Y3002470
5VPCB15D5Y3001746	5VPCS15D1Y3000805	5VPCS15D5Y3000287	5VPCB15D8Y3002471
5VPCB15L8Y3001747	5VPCS15D3Y3000806	5VPCS15D7Y3000288	5VPCB15DXY3002472
5VPCB15LXY3001748	5VPCS15D5Y3000807	5VPCS15D9Y3000289	5VPCB15D1Y3002473
5VPCB15D3Y3001857	5VPCS15D2Y3000943	5VPCS15D5Y3000290	5VPCB15D3Y3002474
5VPCB15D5Y3001858	5VPCS15D4Y3000944	5VPCS15D7Y3000291	5VPCB15D5Y3002475
5VPCB15D7Y3001859	5VPCS15D6Y3000945	5VPCS15D9Y3000292	5VPCB15D7Y3002476
5VPCB15D3Y3001860	5VPCB15D7Y3000985	5VPCS15D0Y3000293	5VPCB15D9Y3002477
5VPCB15D5Y3001861	5VPCS15D6Y3001030	5VPCS15D2Y3000294	5VPCB15D0Y3002478
5VPCB15D7Y3001862	5VPCS15D8Y3001031	5VPCS15D4Y3000295	5VPCB15D2Y3002479
5VPCB15D9Y3001863	5VPCS15DXY3001032	5VPCS15D6Y3000296	5VPCB15D9Y3002480
5VPCB15D0Y3001864	5VPCS15D1Y3001033	5VPCS15D8Y3000297	5VPCB15D0Y3002481
5VPCB15D2Y3001865	5VPCS15D3Y3001034	5VPCS15DXY3000298	5VPCB15D2Y3002482
5VPCB15D4Y3001866	5VPCS15D5Y3001035	5VPCS15D1Y3000299	5VPCB15D4Y3002483
5VPCB15D6Y3001867	5VPCS15D7Y3001036	5VPCS15D4Y3000300	5VPCB15D6Y3002484
5VPCB15D8Y3001868	5VPCS15D9Y3001037	5VPCS15D6Y3000301	5VPCB15D8Y3002485
5VPCB15DXY3001869	5VPCS15D0Y3001038	5VPCS15D8Y3000302	5VPCB15DXY3002486
5VPCB15D6Y3001870	5VPCS15D2Y3001039	5VPCS15DXY3000303	5VPCB15D1Y3002487
5VPCB15D8Y3001871	5VPCS15D9Y3001040	5VPCS15D1Y3000304	5VPCB15D3Y3002488
5VPCB15DXY3001872	5VPCS15D0Y3001041	5VPCS15D3Y3000305	5VPCB15D5Y3002489
5VPCB15D1Y3001873	5VPCS15D2Y3001042	5VPCS15D5Y3000306	5VPCB15D1Y3002490
5VPCB15D3Y3001874	5VPCS15D4Y3001043	5VPCS15D7Y3000307	5VPCB15D3Y3002491
5VPCB15D5Y3001875	5VPCS15D6Y3001044	5VPCS15D9Y3000308	5VPCB15D5Y3002492
5VPCB15D7Y3001876	5VPCS15D8Y3001045	5VPCS15D0Y3000309	5VPCB15D7Y3002493
5VPCB15D9Y3001877	5VPCS15DXY3001046	5VPCS15D7Y3000310	5VPCB15D9Y3002494
5VPCB15D0Y3001878	5VPCS15D1Y3001047	5VPCS15D9Y3000311	5VPCB15D0Y3002495
5VPCB15D2Y3001879	5VPCS15D3Y3001048	5VPCS15D0Y3000312	5VPCB15D2Y3002496


5VPCB15D9Y3001880	5VPCS15D5Y3001049	5VPCS15D2Y3000313	5VPCB15D4Y3002497
5VPCB15D0Y3001881	5VPCS15D1Y3001050	5VPCS15D4Y3000314	5VPCB15D6Y3002498
5VPCB15D2Y3001882	5VPCS15D3Y3001051	5VPCS15D6Y3000315	5VPCB15D8Y3002499
5VPCB15D4Y3001883	5VPCS15D5Y3001052	5VPCS15D8Y3000316	5VPCB15D0Y3002500
5VPCB15D6Y3001884	5VPCS15D7Y3001053	5VPCS15DXY3000317	5VPCB15D2Y3002501
5VPCB15D8Y3001885	5VPCS15D9Y3001054	5VPCS15D1Y3000318	5VPCB15D7Y3002610
5VPCB15DXY3001886	5VPCS15D0Y3001055	5VPCS15D3Y3000319	5VPCB15D9Y3002611
5VPCB15D1Y3001887	5VPCS15D2Y3001056	5VPCS15DXY3000320	5VPCB15D0Y3002612
5VPCB15D3Y3001888	5VPCS15D4Y3001057	5VPCS15D1Y3000321	5VPCB15D2Y3002613
5VPCB15D5Y3001889	5VPCS15D6Y3001058	5VPCS15D3Y3000322	5VPCB15D4Y3002614
5VPCB15D1Y3001890	5VPCS15D8Y3001059	5VPCS15D5Y3000323	5VPCB15D6Y3002615
5VPCB15D3Y3001891	5VPCS15D4Y3001060	5VPCS15D7Y3000324	5VPCB15D8Y3002616
5VPCB15D5Y3001892	5VPCS15D6Y3001061	5VPCS15D9Y3000325	5VPCB15DXY3002617
5VPCB15D7Y3001893	5VPCS15D8Y3001062	5VPCS15D0Y3000326	5VPCB15D1Y3002618
5VPCB15D9Y3001894	5VPCS15DXY3001063	5VPCS15D2Y3000327	5VPCB15D3Y3002619
5VPCB15D0Y3001895	5VPCS15D1Y3001064	5VPCS15D4Y3000328	5VPCB15DXY3002620
5VPCB15D2Y3001896	5VPCS15D3Y3001065	5VPCS15D6Y3000329	5VPCB15D1Y3002621
5VPCB15D4Y3001897	5VPCS15D5Y3001066	5VPCS15D2Y3000330	5VPCB15D3Y3002622
5VPCB15D6Y3001898	5VPCS15D7Y3001067	5VPCS15D4Y3000331	5VPCB15D5Y3002623
5VPCB15D8Y3001899	5VPCS15D9Y3001068	5VPCS15D0Y3000438	5VPCB15D7Y3002624
5VPCB15D0Y3001900	5VPCS15D0Y3001069	5VPCS15D2Y3000439	5VPCB15D9Y3002625
5VPCB15D2Y3001901	5VPCS15D7Y3001070	5VPCS15D9Y3000440	5VPCB15D0Y3002626
5VPCB15D4Y3001902	5VPCS15D9Y3001071	5VPCS15D0Y3000441	5VPCB15D2Y3002627
5VPCB15D6Y3001903	5VPCS15D0Y3001072	5VPCS15D2Y3000442	5VPCB15D4Y3002628
5VPCB15D8Y3001904	5VPCS15D2Y3001073	5VPCS15D4Y3000443	5VPCB15D6Y3002629
5VPCB15DXY3001905	5VPCS15D4Y3001074	5VPCS15D6Y3000444	5VPCB15D2Y3002630
5VPCS15D1Y3001906	5VPCS15D6Y3001075	5VPCS15D8Y3000445	5VPCB15D4Y3002631
5VPCB15D3Y3001907	5VPCS15D8Y3001076	5VPCS15DXY3000446	5VPCB15D6Y3002632
5VPCB15D5Y3001908	5VPCS15DXY3001077	5VPCS15D1Y3000447	5VPCB15D8Y3002633
5VPCB15D7Y3001909	5VPCS15D7Y3001280	5VPCS15D3Y3000448	5VPCB15DXY3002634
5VPCB15D6Y3002016	5VPCS15D9Y3001281	5VPCS15D5Y3000449	5VPCB15D1Y3002635
5VPCB15D8Y3002017	5VPCS15D0Y3001282	5VPCS15D1Y3000450	5VPCB15D3Y3002636
5VPCB15DXY3002018	5VPCS15D2Y3001283	5VPCS15D3Y3000451	5VPCB15D5Y3002637
5VPCB15D1Y3002019	5VPCS15D4Y3001284	5VPCS15D5Y3000452	5VPCB15D7Y3002638
5VPCB15D8Y3002020	5VPCS15D6Y3001285	5VPCS15D7Y3000453	5VPCB15D9Y3002639
5VPCB15DXY3002021	5VPCS15D8Y3001286	5VPCS15D9Y3000454	5VPCB15D5Y3002640
5VPCB15D1Y3002022	5VPCS15DXY3001287	5VPCS15D0Y3000455	5VPCB15D7Y3002641
5VPCB15D3Y3002023	5VPCS15D1Y3001288	5VPCS15D2Y3000456	5VPCB15D9Y3002642
5VPCB15D5Y3002024	5VPCS15D3Y3001289	5VPCS15D4Y3000457	5VPCB15D0Y3002643
5VPCB15D7Y3002025	5VPCS15DXY3001290	5VPCS15D6Y3000458	5VPCB15D2Y3002644
5VPCB15D9Y3002026	5VPCS15D1Y3001291	5VPCS15D8Y3000459	5VPCB15D4Y3002645
5VPCB15D0Y3002027	5VPCS15D3Y3001292	5VPCS15D4Y3000460	5VPCB15D6Y3002646
5VPCB15D2Y3002028	5VPCS15D5Y3001293	5VPCS15D6Y3000461	5VPCB15D8Y3002647
5VPCB15D4Y3002029	5VPCS15D7Y3001294	5VPCS15D8Y3000462	5VPCB15DXY3002648
5VPCB15D0Y3002030	5VPCS15D9Y3001295	5VPCS15DXY3000463	5VPCB15D1Y3002649
5VPCB15D2Y3002031	5VPCS15D0Y3001296	5VPCS15D1Y3000464	5VPCB15D8Y3002650
5VPCB15D4Y3002032	5VPCS15D2Y3001297	5VPCS15D3Y3000465	5VPCB15DXY3002651
5VPCB15D6Y3002033	5VPCS15D4Y3001298	5VPCS15D5Y3000466	5VPCB15D1Y3002652
5VPCB15D8Y3002034	5VPCS15D6Y3001299	5VPCS15D7Y3000467	5VPCB15D3Y3002653
5VPCB15DXY3002035	5VPCS15D9Y3001300	5VPCS15D9Y3000468	5VPCB15D5Y3002654

5VPCB15D1Y3002036	5VPCS15D0Y3001301	5VPCS15D0Y3000469	5VPCB15D7Y3002655
5VPCB15D3Y3002037	5VPCS15D2Y3001302	5VPCS15D7Y3000470	5VPCB15D9Y3002656
5VPCB15D5Y3002038	5VPCS15D4Y3001303	5VPCS15D9Y3000471	5VPCB15D0Y3002657
5VPCB15D7Y3002039	5VPCS15DXY3001354	5VPCS15D0Y3000472	5VPCB15L3Y3002658
5VPCB15D3Y3002040	5VPCS15D1Y3001355	5VPCS15D2Y3000473	5VPCS15L5Y3002659
5VPCB15D5Y3002041	5VPCS15D3Y3001356	5VPCS15D4Y3000474	5VPCS15D0Y3002660
5VPCB15D7Y3002042	5VPCS15D5Y3001357	5VPCS15D6Y3000475	5VPCS15D2Y3002661
5VPCB15D9Y3002043	5VPCS15D7Y3001358	5VPCS15D8Y3000476	5VPCS15D4Y3002662
5VPCB15D0Y3002044	5VPCS15D9Y3001359	5VPCS15DXY3000477	5VPCS15D6Y3002663
5VPCB15D2Y3002045	5VPCS15D5Y3001360	5VPCS15D1Y3000478	5VPCB15L1Y3002772
5VPCB15D4Y3002046	5VPCS15D7Y3001361	5VPCS15D3Y3000479	5VPCB15L3Y3002773
5VPCB15D6Y3002047	5VPCS15D9Y3001362	5VPCS15DXY3000480	5VPCB15L5Y3002774
5VPCB15D8Y3002048	5VPCS15D0Y3001363	5VPCS15D1Y3000481	5VPCB15L7Y3002775
5VPCB15DXY3002049	5VPCS15D2Y3001364	5VPCS15D3Y3000482	5VPCB15L9Y3002776
5VPCB15D6Y3002050	5VPCS15D4Y3001365	5VPCS15D5Y3000483	5VPCB15L0Y3002777
5VPCB15D8Y3002051	5VPCS15D6Y3001366	5VPCS15D7Y3000484	5VPCB15L2Y3002778
5VPCB15DXY3002052	5VPCS15D8Y3001367	5VPCS15D9Y3000485	5VPCB15L4Y3002779
5VPCB15D1Y3002053	5VPCS15DXY3001368	5VPCS15D0Y3000486	5VPCB15L0Y3002780
5VPCB15D3Y3002054	5VPCS15D1Y3001369	5VPCS15D2Y3000487	5VPCB15L2Y3002781
5VPCB15D5Y3002055	5VPCS15D8Y3001370	5VPCS15D4Y3000488	5VPCB15L4Y3002782
5VPCB15D7Y3002056	5VPCS15DXY3001371	5VPCS15D6Y3000489	5VPCB15L6Y3002783
5VPCB15D9Y3002057	5VPCS15D1Y3001372	5VPCS15D2Y3000490	5VPCB15C8Y3002784
5VPCB15D0Y3002058	5VPCS15D3Y3001373	5VPCS15D2Y3000599	5VPCB15CXY3002785
5VPCB15D2Y3002059	5VPCS15D5Y3001374	5VPCS15D5Y3000600	5VPCB15C1Y3002786
5VPCB15D9Y3002060	5VPCS15D7Y3001375	5VPCS15D7Y3000601	5VPCB15C3Y3002787
5VPCB15D0Y3002061	5VPCS15D9Y3001376	5VPCS15D9Y3000602	5VPCB15C5Y3002788
5VPCB15D2Y3002062	5VPCS15D0Y3001377	5VPCS15D0Y3000603	5VPCB15C7Y3002789
5VPCB15D4Y3002063	5VPCS15D2Y3001378	5VPCS15D2Y3000604	5VPCB15C3Y3002790
5VPCB15D6Y3002064	5VPCS15D4Y3001379	5VPCS15D4Y3000605	5VPCB15C5Y3002791
5VPCB15D8Y3002065	5VPCS15D0Y3001380	5VPCS15D6Y3000606	5VPCB15C7Y3002792
5VPCB15DXY3002066	5VPCS15D2Y3001381	5VPCS15D8Y3000607	5VPCB15C9Y3002793
5VPCB15D1Y3002067	5VPCS15D4Y3001382	5VPCS15DXY3000608	5VPCB15C0Y3002794
5VPCB15D3Y3002068	5VPCS15D4Y3001544	5VPCS15D1Y3000609	5VPCB15C2Y3002795
5VPCB15D5Y3002069	5VPCS15D6Y3001545	5VPCS15D8Y3000610	5VPCB15C4Y3002796
5VPCB15DXY3002178	5VPCS15D8Y3001546	5VPCS15DXY3000611	5VPCB15C6Y3002797
5VPCB15D1Y3002179	5VPCS15DXY3001547	5VPCS15D1Y3000612	5VPCB15C8Y3002798
5VPCB15D8Y3002180	5VPCS15D1Y3001548	5VPCS15D3Y3000613	5VPCB15CXY3002799
5VPCB15DXY3002181	5VPCS15D3Y3001549	5VPCS15D5Y3000614	5VPCB15C2Y3002800
5VPCB15D1Y3002182	5VPCS15DXY3001550	5VPCS15D7Y3000615	5VPCB15C4Y3002801
5VPCB15D3Y3002183	5VPCS15D1Y3001551	5VPCS15D9Y3000616	5VPCS15D5Y3002802
5VPCB15D5Y3002184	5VPCS15D3Y3001552	5VPCS15D0Y3000617	5VPCS15D7Y3002803
5VPCB15D7Y3002185	5VPCS15D5Y3001553	5VPCS15D2Y3000618	5VPCS15D9Y3002804
5VPCB15D9Y3002186	5VPCS15D7Y3001554	5VPCS15D4Y3000619	5VPCS15D0Y3002805
5VPCB15D0Y3002187	5VPCS15D9Y3001555	5VPCS15D0Y3000620	5VPCS15D2Y3002806
5VPCB15D2Y3002188	5VPCS15D0Y3001556	5VPCS15D2Y3000621	5VPCS15D4Y3002807
5VPCB15D4Y3002189	5VPCS15D2Y3001557	5VPCS15D4Y3000622	5VPCS15D6Y3002808
5VPCB15D0Y3002190	5VPCS15D4Y3001558	5VPCS15D6Y3000623	5VPCS15D8Y3002809
5VPCB15D2Y3002191	5VPCS15D6Y3001559	5VPCS15D8Y3000624	5VPCS15D4Y3002810
5VPCB15D4Y3002192	5VPCS15D2Y3001560	5VPCS15DXY3000625	5VPCS15D6Y3002811
5VPCB15D6Y3002193	5VPCS15D4Y3001561	5VPCS15D1Y3000626	5VPCS15D8Y3002812

5VPCB15D8Y3002194	5VPCS15D6Y3001562	5VPCS15D3Y3000627	5VPCS15DXY3002813
5VPCB15DXY3002195	5VPCS15D8Y3001563	5VPCS15D5Y3000628	5VPCS15D1Y3002814
5VPCB15D1Y3002196	5VPCS15DXY3001564	5VPCS15D7Y3000629	5VPCS15D3Y3002815
5VPCB15D3Y3002197	5VPCS15D1Y3001565	5VPCS15D3Y3000630	5VPCS15D5Y3002816
5VPCB15D5Y3002198	5VPCS15D3Y3001566	5VPCS15D5Y3000631	5VPCS15D7Y3002817
5VPCB15D7Y3002199	5VPCS15D5Y3001567	5VPCS15D7Y3000632	5VPCS15D9Y3002818
5VPCB15DXY3002200	5VPCS15D7Y3001568	5VPCS15D9Y3000633	5VPCS15D0Y3002819
5VPCB15D1Y3002201	5VPCS15D9Y3001569	5VPCS15D0Y3000634	5VPCS15D7Y3002820
5VPCB15D3Y3002202	5VPCS15D5Y3001570	5VPCS15D2Y3000635	5VPCS15D9Y3002821
5VPCB15D5Y3002203	5VPCS15D7Y3001571	5VPCS15D4Y3000636	5VPCS15D0Y3002822
5VPCB15D7Y3002204	5VPCS15D9Y3001572	5VPCS15D6Y3000637	5VPCS15D2Y3002823
5VPCB15D9Y3002205	5VPCS15D0Y3001573	5VPCS15D8Y3000638	5VPCS15D4Y3002824
5VPCB15D0Y3002206	5VPCS15D2Y3001574	5VPCS15DXY3000639	5VPCS15D6Y3002825
5VPCB15D2Y3002207	5VPCS15D4Y3001575	5VPCS15D6Y3000640	5VPCS15D0Y3002934
5VPCB15D4Y3002208	5VPCS15D6Y3001576	5VPCS15D8Y3000641	5VPCS15C3Y3002935
5VPCB15D6Y3002209	5VPCS15D8Y3001577	5VPCS15DXY3000642	5VPCS15C5Y3002936
5VPCB15D2Y3002210	5VPCS15DXY3001578	5VPCS15D1Y3000643	5VPCB15D6Y3002937
5VPCB15D4Y3002211	5VPCS15D1Y3001579	5VPCS15D3Y3000644	5VPCB15D8Y3002938
5VPCB15D6Y3002212	5VPCS15D8Y3001580	5VPCS15D5Y3000645	5VPCB15DXY3002939
5VPCB15D8Y3002213	5VPCS15DXY3001581	5VPCS15D7Y3000646	5VPCB15D6Y3002940
5VPCB15DXY3002214	5VPCS15D1Y3001582	5VPCS15D9Y3000647	5VPCB15D8Y3002941
5VPCB15D1Y3002215	5VPCS15D3Y3001583	5VPCS15D0Y3000648	5VPCB15DXY3002942
5VPCB15D3Y3002216	5VPCS15D5Y3001584	5VPCS15D2Y3000649	5VPCB15D1Y3002943
5VPCB15D5Y3002217	5VPCS15D7Y3001585	5VPCS15D9Y3000650	5VPCB15D3Y3002944
5VPCB15D7Y3002218	5VPCS15D9Y3001586	5VPCS15D0Y3000651	5VPCB15D5Y3002945
5VPCB15D9Y3002219	5VPCS15D0Y3001587	5VPCS15D2Y3000652	5VPCB15D7Y3002946
5VPCB15D5Y3002220	5VPCS15D2Y3001588	5VPCS15D7Y3000808	5VPCB15D9Y3002947
5VPCB15D7Y3002221	5VPCS15L7Y3001626	5VPCS15D9Y3000809	5VPCB15D0Y3002948
5VPCB15D9Y3002222	5VPCS15L9Y3001627	5VPCS15D5Y3000810	5VPCB15D2Y3002949
5VPCB15D0Y3002223	5VPCS15L0Y3001628	5VPCS15D7Y3000811	5VPCB15D9Y3002950
5VPCB15D2Y3002224	5VPCS15L2Y3001629	5VPCS15D9Y3000812	5VPCB15D0Y3002951
5VPCB15D4Y3002225	5VPCS15L9Y3001630	5VPCS15D0Y3000813	5VPCB15D2Y3002952
5VPCB15D6Y3002226	5VPCS15L0Y3001631	5VPCS15D2Y3000814	5VPCB15D4Y3002953
5VPCB15D8Y3002227	5VPCS15L2Y3001632	5VPCS15D4Y3000815	5VPCB15D6Y3002954
5VPCB15DXY3002228	5VPCS15L4Y3001633	5VPCS15D0Y3000844	5VPCB15D8Y3002955
5VPCB15D1Y3002229	5VPCS15L6Y3001634	5VPCS15D2Y3000845	5VPCB15D3Y3002961
5VPCB15D8Y3002230	5VPCB15L1Y3001749	5VPCS15D4Y3000846	5VPCB15D5Y3002962
5VPCB15DXY3002231	5VPCB15L8Y3001750	5VPCS15D6Y3000847	5VPCB15D7Y3002963
5VPCB15D4Y3002340	5VPCB15LXY3001751	5VPCS15D8Y3000848	5VPCB15D9Y3002964
5VPCB15D6Y3002341	5VPCB15L1Y3001752	5VPCS15DXY3000849	5VPCB15D0Y3002965
5VPCB15D8Y3002342	5VPCB15L3Y3001753	5VPCS15D6Y3000850	5VPCB15D2Y3002966
5VPCB15DXY3002343	5VPCB15L5Y3001754	5VPCS15D8Y3000851	5VPCB15D4Y3002967
5VPCB15D1Y3002344	5VPCB15L7Y3001755	5VPCS15DXY3000852	5VPCB15D6Y3002968
5VPCB15D3Y3002345	5VPCB15L9Y3001756	5VPCS15D1Y3000853	5VPCB15D8Y3002969
5VPCB15D5Y3002346	5VPCB15DXY3001757	5VPCS15D3Y3000854	5VPCB15D4Y3002970
5VPCB15D7Y3002347	5VPCB15D1Y3001758	5VPCS15D5Y3000855	5VPCB15D6Y3002971
5VPCB15D9Y3002348	5VPCB15L4Y3001759	5VPCS15D7Y3000856	5VPCB15D8Y3002972
5VPCB15D0Y3002349	5VPCB15DXY3001760	5VPCS15D9Y3000857	5VPCB15DXY3002973
5VPCB15D7Y3002350	5VPCB15D1Y3001761	5VPCS15D0Y3000858	5VPCB15D1Y3002974
5VPCB15D9Y3002351	5VPCB15D3Y3001762	5VPCS15D2Y3000859	5VPCB15D3Y3002975

5VPCB15D0Y3002352 5VPCB15D5Y3001763 5VPCS15D9Y3000860
5VPCB15D2Y3002353 5VPCB15D7Y3001764 5VPCS15D0Y3000861

06U-298



August 4, 2006

Mayer, Brown, Rowe & Maw LLP
1909 K Street, N.W.
Washington, D.C. 20006-1101

Main Tel (202) 263-3000
Main Fax (202) 263-3300
www.mayerbrownrowe.com

Erika Z. Jones
Direct Tel (202) 263-3232
Direct Fax (202) 263-5232
ejones@mayerbrownrowe.com

Kathleen DeMeter
Director, Office of Defects Investigation
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Re: Victory Motorcycles

Dear Ms. DeMeter:

06U-298
(16 pages)

Enclosed with this letter is a Defect Information Report addressing third gear failures that have been reported in certain MY 2001 Victory motorcycles.

In the subject motorcycles, Victory believes that the loss of third gear is a customer satisfaction concern, not a safety issue. Even if the transmission's third gear is compromised, the transmission's other gears provide the operator with the ability to retain control of the bike and bring it to a stop safely. Nevertheless, to avoid issues with the agency, Victory is willing to conduct this campaign as if it were a safety recall, in voluntary compliance with Parts 573 and 577. The enclosed Defect Information Report contains the information identified in Part 573. The owner notification will contain the information identified in Part 577, and Victory will submit it to your office for review in advance of starting the owner notification, as contemplated by Part 573.

The schedule for starting the campaign is still under development, and will be provided to your office as soon as it is complete.

Please let me know if you have any questions or need any additional information.

Sincerely,

Handwritten signature of Erika Z. Jones in black ink.
Erika Z. Jones

Enclosure

Berlin Brussels Charlotte Chicago Cologne Frankfurt Houston London Los Angeles New York Palo Alto Paris Washington, D.C.
Independent Mexico City Correspondent: Jauregui, Navarrete y Nader S.C.

Mayer, Brown, Rowe & Maw LLP operates in combination with our associated English limited liability partnership in the offices listed above.

DEFECT INFORMATION REPORT

1. **Manufacturer's name/address:** Polaris Industries, Victory Motorcycle Division, 2100 Highway 55, Medina, MN 55340

2. **Vehicles or Equipment involved in this defect notification:** MY 2001 Victory Motorcycles and certain MY 1999-2000 Victory Motorcycles that received transmission replacement kits that were built during MY 2001.

3. **Total number of vehicles or items of equipment:**

A. 2523

a. MY 2001 Victory motorcycles 2350

b. 173 MY 1999 or 2000 Victory motorcycles with transmission replacement kits built during MY 2001

4. **Approximate percentage of vehicles or equipment estimated to actually contain the defect:** Victory does not know the percentage of vehicles estimated to actually contain the defect. All MY 2001 motorcycles and affected MY 1999/2000 motorcycles are included in the campaign.

5. **Description of the defect:** Victory has determined that the subject motorcycles are disproportionately prone to third gear failure if an abnormal overload condition is experienced. Such overload conditions are normally due to shifting the transmission at high rpm (either a down or upshift). While Victory believes that third gear failure is ordinarily a customer satisfaction, and not a safety, issue (due to the consequence of "limping home" in second or fourth gear), Victory nevertheless wishes to avoid any conflict with the agency and is willing to conduct a campaign as if it were a safety recall to address the issue of third gear failure.

6. **Chronological summary of events leading to this determination:** See Item 5.

7. **Description of proposed remedy (including schedule for dealer and customer notification):** Victory will install a "rear sprocket hub damper assembly" in each subject vehicle. The "rear sprocket hub damper assembly" reduces the shock loads seen by the subject vehicles and thus reduces the risk of third-gear failure in the subject vehicles.

8. Program for remedy campaign (including program for reimbursing any consumer who obtained the remedy at his/her own expense within one year of the opening of the EA, or within one year of this 573 report, whichever is earlier):

Victory will execute a Safety Recall campaign whereby the affected machines will have a "rear sprocket damper assembly" installed onto them by Victory Dealers at no charge to the consumers. Victory will reimburse owners who obtained a replacement third gear assembly at their own expense within one year of this Part 573 report.

Signed: Don L. Good Date: 8-4-2006
Don L. Good
Product Compliance Specialist
Polaris Industries Inc.

Attachments

VIN List: 3-15

This VIN list contains all US MY 2001 Victory Motorcycles affected by this issue. Within this list is contained the 122 machines that do not need this repair due to the transmission replacement that has already occurred for them. Those machines will be identified visually and instructions for doing so will be contained in the Safety Recall Bulletin when it is released.

The VIN list does not contain the 173 MY 1999 or 2000 Victory motorcycles with transmission replacement kits built during MY 2001. Those machines will be identified by instructions contained in the Safety Recall Bulletin when it is released.

Draft of Consumer Letter: TBD

Draft of Dealer Bulletin: TBD

MY 2001 VIN	MY 2001 VIN	MY 2001 VIN	MY 2001 VIN
5VPCD15C013002052	5VPCD15D413000832	5VPCS15D613001549	5VPCD15D213002238
5VPCS15C913000371	5VPCD15D413001446	5VPCB15D113002673	5VPCD15D313002815
5VPCB15D013000638	5VPCB15D213000334	5VPCB15D313001606	5VPCD15D413002113
5VPCB15D113000762	5VPCB15D313001735	5VPCB15D413000738	5VPCB15D013002602
5VPCB15D213001953	5VPCB15D313001878	5VPCB15D613001972	5VPCB15D113001555
5VPCB15D413000433	5VPCB15D413001887	5VPCB15D713000460	5VPCB15D113001670
5VPCB15D413000819	5VPCB15D813000693	5VPCB15D813001519	5VPCB15D213002746
5VPCB15D813002590	5VPCB15D813001780	5VPCD15D013001640	5VPCB15D313000486
5VPCB15D913001884	5VPCB15DX13000100	5VPCD15D113002103	5VPCB15D513001672
5VPCD15D013002125	5VPCD15D213001350	5VPCD15D413002306	5VPCB15D813000810
5VPCD15D113000965	5VPCD15D613001867	5VPCD15D613002193	5VPCB15D913000640
5VPCD15D113001338	5VPCD15D713002199	5VPCD15D713001649	5VPCB15D913000671
5VPCD15D113002277	5VPCD15D913001135	5VPCD15D813002101	5VPCB15DX13000601
5VPCD15D213002370	5VPCS15D613000501	5VPCD15D813002258	5VPCD15D013000780
5VPCD15D413002242	5VPCB15DX13000663	5VPCD15D913001328	5VPCD15D013002531
5VPCD15D513001505	5VPCD15D613001349	5VPCD15DX13002181	5VPCD15D113000660
5VPCD15D513002671	5VPCD15DX13002794	5VPCS15D713002788	5VPCD15D213000943
5VPCD15D613000394	5VPCS15D513001588	5VPCD15D413000524	5VPCD15D213001641
5VPCD15D613000654	5VPCB15D413002747	5VPCD15D913000955	5VPCD15D313000787
5VPCD15D613001058	5VPCD15D013002223	5VPCB15D113000910	5VPCD15D313001504
5VPCD15D713001084	5VPCD15D113001999	5VPCB15D513000618	5VPCD15D413001494
5VPCD15D713002381	5VPCD15D213001980	5VPCD15D013001993	5VPCD15D613001691
5VPCD15D813000381	5VPCD15D213002059	5VPCD15D113002229	5VPCD15D813002650
5VPCD15D813001093	5VPCD15D413000782	5VPCD15D713002090	5VPCD15D913001667
5VPCD15D813001949	5VPCD15D613002288	5VPCS15D813000502	5VPCD15D913002530
5VPCD15D913002091	5VPCB15D113000812	5VPCB15D413000884	5VPCD15DX13000964
5VPCD15DX13001936	5VPCB15D513000604	5VPCB15D513002661	5VPCB15D113001877
5VPCD15DX13002259	5VPCB15D613002541	5VPCB15D813000483	5VPCB15D213001600
5VPCS15D413000108	5VPCB15D713001026	5VPCB15D813000614	5VPCB15D613002605
5VPCS15D513000361	5VPCB15D813002539	5VPCB15D813002864	5VPCB15D713000894
5VPCS15D613000546	5VPCB15DX13000890	5VPCD15D013000567	5VPCB15D813000676
5VPCD15D113002151	5VPCD15D013002822	5VPCD15D313000563	5VPCB15DX13002753
5VPCB15D513001607	5VPCD15D313000708	5VPCD15D313002197	5VPCD15D313002636
5VPCB15D813002430	5VPCD15D413001799	5VPCD15D513000774	5VPCD15D413002175
5VPCD15D613002503	5VPCD15D513000936	5VPCD15D913001491	5VPCD15D413002323
5VPCD15D713001036	5VPCD15D713001988	5VPCD15D913002169	5VPCD15D613002582
5VPCD15D713001439	5VPCD15D713002221	5VPCD15DX13001497	5VPCD15D713000789
5VPCD15DX13000849	5VPCD15D813001983	5VPCD15DX13002021	5VPCD15D713001747
5VPCS15D713001544	5VPCD15D913001040	5VPCD15DX13002150	5VPCD15D813000770
5VPCB15D013000686	5VPCD15D913001930	5VPCS15D413001372	5VPCD15D913001619
5VPCB15D013001238	5VPCD15D913002723	5VPCB15DX13002400	5VPCD15DX13001970
5VPCB15D113001782	5VPCD15DX13001662	5VPCD15D613002310	5VPCS15D213001466
5VPCB15D113002835	5VPCB15D213002908	5VPCD15DX13002083	5VPCS15D313001542
5VPCB15D213002830	5VPCB15D713000457	5VPCB15D013000493	5VPCS15D813002783
5VPCB15D313000598	5VPCB15D813002413	5VPCB15D413002912	5VPCS15DX13002784
5VPCB15D413000626	5VPCB15D913001898	5VPCB15D613000689	5VPCB15D013001255
5VPCB15D413002702	5VPCB15D913001903	5VPCB15D713000622	5VPCB15D413000920
5VPCB15D513002417	5VPCD15D013002660	5VPCD15D013001413	5VPCD15D313001096
5VPCB15D713001964	5VPCD15D213002207	5VPCD15D113002358	5VPCD15D413002726

5VPCB15D713002466	5VPCD15D313001311	5VPCD15D413001222	5VPCD15D813002017
5VPCB15D713002600	5VPCD15D513002668	5VPCD15D413001401	5VPCD15D913000518
5VPCB15D713002838	5VPCB15D013001952	5VPCD15D513002167	5VPCD15D913000972
5VPCB15D813002542	5VPCB15D113002897	5VPCD15D713001800	5VPCD15D913002589
5VPCB15D813002704	5VPCB15D813002931	5VPCD15D813000591	5VPCB15D213000608
5VPCB15D913002517	5VPCB15D913001741	5VPCD15D813002065	5VPCB15D913002422
5VPCB15D913002663	5VPCB15DX13002932	5VPCD15D913000857	5VPCB15DX13001957
5VPCB15DX13000484	5VPCD15D013001749	5VPCD15D913001748	5VPCD15D013001251
5VPCB15DX13002834	5VPCD15D113002019	5VPCD15DX13001063	5VPCD15D213001297
5VPCD15D013001086	5VPCD15D413002046	5VPCB15D313002643	5VPCD15D313002152
5VPCD15D013001699	5VPCD15D413002225	5VPCB15D713000491	5VPCD15D413000944
5VPCD15D013002366	5VPCD15D413002581	5VPCB15D813002833	5VPCD15D613002212
5VPCD15D113000514	5VPCD15D713002588	5VPCD15D413000510	5VPCD15DX13002102
5VPCD15D213001106	5VPCS15D413002778	5VPCD15D613001528	5VPCS15D113000535
5VPCD15D213002353	5VPCB15D113000745	5VPCD15D613001626	5VPCS15D213000544
5VPCD15D413002077	5VPCD15D713001912	5VPCD15D713001621	5VPCS15D213001371
5VPCD15D513000631	5VPCD15D813001918	5VPCD15DX13001113	5VPCB15D113000664
5VPCD15D613001044	5VPCB15D013002874	5VPCB15D513000697	5VPCB15D413001419
5VPCD15D713001344	5VPCB15D113000826	5VPCB15D713001740	5VPCB15D413002828
5VPCD15D713002333	5VPCB15D313002433	5VPCD15D213001655	5VPCB15D713002872
5VPCD15D813000557	5VPCB15D513002689	5VPCD15D713001442	5VPCB15D813001875
5VPCB15D413000741	5VPCB15D913002579	5VPCD15D913002804	5VPCB15D813002606
5VPCB15D613000627	5VPCD15D213000828	5VPCB15D013001661	5VPCB15D813002640
5VPCB15D713002645	5VPCD15D513002198	5VPCB15D413000903	5VPCB15D913002923
5VPCB15DX13002879	5VPCD15D513002279	5VPCB15D613001518	5VPCB15DX13001490
5VPCD15D013002352	5VPCD15D813001837	5VPCB15D613002832	5VPCD15D213000750
5VPCD15D313002331	5VPCB15D213002536	5VPCB15D913002842	5VPCD15D213001316
5VPCD15D813002910	5VPCB15D513001395	5VPCD15D013001489	5VPCD15D413002810
5VPCD15D913001507	5VPCB15D513002580	5VPCD15D313001485	5VPCD15DX13002634
5VPCS15D113001362	5VPCB15DX13001778	5VPCD15D313001714	5VPCB15D313002836
5VPCB15D013001904	5VPCD15D013002402	5VPCD15D513001729	5VPCB15D113001734
5VPCB15D213000723	5VPCD15D013002691	5VPCD15D613002632	5VPCB15D213001001
5VPCB15DX13002610	5VPCD15D113001453	5VPCD15D713001330	5VPCB15D613000739
5VPCD15D013002299	5VPCD15D413000930	5VPCD15D913001300	5VPCD15D113001081
5VPCD15D113001811	5VPCD15D513001634	5VPCD15D913001474	5VPCD15D713002347
5VPCD15D113002814	5VPCD15D813002549	5VPCD15D913002656	5VPCD15D813001336
5VPCD15D213002708	5VPCB15D213000642	5VPCD15DX13001290	5VPCD15DX13001919
5VPCD15D313000983	5VPCB15D813002699	5VPCD15DX13001631	5VPCS15D513001364
5VPCD15D613001917	5VPCD15D113002067	5VPCS15D013000106	5VPCS15D713000541
5VPCD15D613002274	5VPCD15D513002329	5VPCS15D013001370	5VPCD15D113000559
5VPCD15D713001845	5VPCD15D713002557	5VPCS15D413001548	5VPCD15D213000523
5VPCD15D813002373	5VPCB15D313000892	5VPCB15D013000882	5VPCD15D813002499
5VPCD15DX13001807	5VPCD15D713002073	5VPCB15D013002664	5VPCD15D913000552
5VPCB15D113001815	5VPCB15D113000468	5VPCB15D113002043	5VPCD15D913002477
5VPCB15D513002594	5VPCB15D313001671	5VPCB15D213000463	5VPCB15D013002731
5VPCB15D513002742	5VPCB15D413000593	5VPCB15D213000883	5VPCB15D313000990
5VPCD15D113002456	5VPCB15D913000623	5VPCB15D213002388	5VPCD15D713001229
5VPCD15D213001848	5VPCD15D013000634	5VPCB15D313000987	5VPCB15D013002695
5VPCD15D213002322	5VPCD15D113001095	5VPCB15D313001234	5VPCD15D413002340
5VPCD15D413002631	5VPCD15D313001728	5VPCB15D413001954	5VPCD15D713000551

5VPCD15D513002573	5VPCD15D813001725	5VPCB15D413002893	5VPCD15D913001653
5VPCD15D713002512	5VPCD15DX13001077	5VPCB15D513000733	5VPCS15D713001589
5VPCD15D913002611	5VPCS15D813001584	5VPCB15D513000747	5VPCB15D113000471
5VPCB15D013002597	5VPCB15D413000478	5VPCB15D513000988	5VPCD15D113002196
5VPCB15D313001945	5VPCB15D713000443	5VPCB15D713001205	5VPCD15D213002000
5VPCD15D013002139	5VPCB15D713000989	5VPCB15D713002869	5VPCD15D613002078
5VPCD15D413002080	5VPCB15D713001608	5VPCB15D813002461	5VPCD15DX13002326
5VPCD15D513002153	5VPCB15D713002841	5VPCB15D813002900	5VPCD15D013001072
5VPCD15D813002633	5VPCB15D813001424	5VPCB15D913001514	5VPCD15D413001057
5VPCD15DX13002231	5VPCB15D913000881	5VPCB15D913001853	5VPCD15D413002709
5VPCS15D213002780	5VPCD15D313000952	5VPCB15D913002534	5VPCD15DX13000527
5VPCB15DX13001716	5VPCD15D413002130	5VPCD15D113000383	5VPCD15DX13000799
5VPCD15D413002452	5VPCD15D713001070	5VPCD15D113001341	5VPCB15D013002387
5VPCD15D613001836	5VPCD15D713002008	5VPCD15D113002246	5VPCB15D013002437
5VPCB15D713000880	5VPCD15DX13001533	5VPCD15D513000838	5VPCB15D113002401
5VPCB15D813002895	5VPCS15D613001468	5VPCD15D513002105	5VPCB15D313002383
5VPCD15D213002613	5VPCB15D213000639	5VPCD15D713000338	5VPCB15D513000490
5VPCD15D313002295	5VPCD15D213002014	5VPCD15D713000971	5VPCB15D713002743
5VPCB15D013001434	5VPCD15D813000784	5VPCD15D813000946	5VPCB15DX13002543
5VPCB15D513001669	5VPCB15D013000865	5VPCD15D813001496	5VPCD15D113002294
5VPCD15D313002247	5VPCD15D013002514	5VPCD15D813002082	5VPCD15D413002063
5VPCD15D413001656	5VPCD15D113002330	5VPCD15D813002647	5VPCD15D413002337
5VPCD15D713002171	5VPCD15D213000859	5VPCD15D913000650	5VPCD15D813000431
5VPCD15D813002504	5VPCD15D413001012	5VPCD15DX13002147	5VPCD15DX13002312
5VPCB15D213002665	5VPCD15D513001083	5VPCS15D013001546	5VPCB15D613000871
5VPCB15D413002876	5VPCD15D513002797	5VPCS15D613001373	5VPCD15D713000792
5VPCB15D713001897	5VPCD15D913002513	5VPCS15D713000538	5VPCB15D113001524
5VPCB15D813000872	5VPCD15DX13002018	5VPCS15D813000340	5VPCB15D213001614
5VPCB15D813002878	5VPCD15D013000858	5VPCD15D213001445	5VPCB15D413000450
5VPCB15D913000735	5VPCD15D813001692	5VPCB15D013002406	5VPCD15D013001248
5VPCD15D013000553	5VPCB15D513002420	5VPCB15D513002384	5VPCD15D513001620
5VPCD15D213002157	5VPCB15D513002563	5VPCB15D713001253	5VPCD15D813001708
5VPCD15D213002658	5VPCB15D613002927	5VPCD15D113002652	5VPCD15DX13001709
5VPCD15D313002068	5VPCD15D113002215	5VPCD15D213001140	5VPCB15D113000454
5VPCD15D813000980	5VPCD15D313002801	5VPCD15D413002368	5VPCB15D213000740
5VPCD15DX13001225	5VPCD15D613002548	5VPCD15D613002372	5VPCB15D313000326
5VPCS15D213000107	5VPCD15DX13001404	5VPCD15D713001246	5VPCB15D613002667
5VPCB15D113001426	5VPCB15D113000700	5VPCD15D913002365	5VPCD15D013000956
5VPCB15D213001676	5VPCB15D113002690	5VPCB15D013000820	5VPCD15D113002618
5VPCB15D213002472	5VPCB15D513001851	5VPCB15D213000687	5VPCD15D213002160
5VPCB15D913000489	5VPCB15D713002595	5VPCB15D213000866	5VPCD15D313000658
5VPCD15D113002764	5VPCB15D913000637	5VPCB15D813000600	5VPCD15D413001091
5VPCD15D313001339	5VPCD15D513002072	5VPCB15D813000662	5VPCD15D513000953
5VPCB15D613000594	5VPCD15D913000759	5VPCB15D913000895	5VPCD15D513001049
5VPCD15D613000511	5VPCD15D913002172	5VPCB15D913002713	5VPCD15D513002637
5VPCD15D913002186	5VPCD15D913002625	5VPCD15D113001503	5VPCD15D713000758
5VPCB15D013002566	5VPCB15D313001900	5VPCD15D413001303	5VPCD15D713002283
5VPCB15D013002891	5VPCB15D713001432	5VPCD15D913000776	5VPCD15D913000843
5VPCB15D113001927	5VPCD15D013001654	5VPCS15D313000536	5VPCD15D913002737
5VPCB15D513001722	5VPCD15D013001931	5VPCS15D513000540	5VPCD15DX13000382

5VPCB15D913000685	5VPCD15D113002327	5VPCS15D913001545	5VPCD15DX13002648
5VPCB15D913001433	5VPCD15D213001638	5VPCD15D013002237	5VPCB15D213000480
5VPCD15D113001632	5VPCD15D213001994	5VPCD15D313000515	5VPCB15D313000455
5VPCD15D213000103	5VPCD15D313001048	5VPCD15D313000580	5VPCD15D313000840
5VPCD15D413002659	5VPCD15D413001415	5VPCD15D913000566	5VPCD15D513000578
5VPCD15D513001407	5VPCB15D013000672	5VPCS15D813001259	5VPCD15D813000509
5VPCD15D513001486	5VPCB15D413001890	5VPCB15D213002732	5VPCD15D913001247
5VPCD15D513002816	5VPCB15D613001888	5VPCB15D613000532	5VPCS15DX13000341
5VPCD15D713001327	5VPCD15D013001637	5VPCD15D113001355	5VPCB15D013000722
5VPCD15D813001448	5VPCD15D013001797	5VPCD15D313001986	5VPCB15D313001668
5VPCD15D813002678	5VPCD15D413002628	5VPCD15D313002202	5VPCB15D513000330
5VPCB15D213002858	5VPCD15D713001313	5VPCD15D513000967	5VPCB15D613000479
5VPCB15D813000628	5VPCD15D913002236	5VPCD15D713000937	5VPCB15D913002386
5VPCB15DX13002445	5VPCD15DX13001354	5VPCD15D813001501	5VPCB15DX13002431
5VPCD15D013002559	5VPCB15D013001241	5VPCD15D813002003	5VPCD15D013002724
5VPCD15D313001843	5VPCB15D013002759	5VPCD15D813002213	5VPCD15D113000707
5VPCD15D413002404	5VPCB15D113000986	5VPCD15D913002298	5VPCD15D113000948
5VPCD15D413002712	5VPCB15D413000500	5VPCB15D913000878	5VPCD15D113000982
5VPCD15D513000841	5VPCB15D513002577	5VPCD15D013000519	5VPCD15D213000554
5VPCD15D613001478	5VPCB15D513002756	5VPCD15D613000556	5VPCD15D213002532
5VPCD15D713000775	5VPCB15D613000692	5VPCD15D613002209	5VPCD15D313001809
5VPCD15D713002770	5VPCB15D613002412	5VPCB15D013000476	5VPCD15D813001207
5VPCD15D813002681	5VPCB15D713002418	5VPCB15D513001431	5VPCB15D413000870
5VPCB15D213001905	5VPCB15D713002564	5VPCB15D713001396	5VPCB15D013002521
5VPCB15D713002421	5VPCB15D813000435	5VPCB15D713001611	5VPCB15D113002740
5VPCB15DX13002624	5VPCB15D813000497	5VPCD15D113000979	5VPCB15D213000916
5VPCD15D013001914	5VPCB15D813002749	5VPCD15D113001713	5VPCB15D613002751
5VPCD15D213002191	5VPCB15D913002758	5VPCD15D213002319	5VPCB15D713000975
5VPCD15D613001948	5VPCD15D013001119	5VPCD15D313001616	5VPCB15D713002399
5VPCD15D613002677	5VPCD15D113000352	5VPCD15D313001695	5VPCB15D813001679
5VPCB15D013002440	5VPCD15D113002795	5VPCD15D413001530	5VPCB15D913001738
5VPCB15D113001880	5VPCD15D113002800	5VPCD15D613001139	5VPCB15D913001786
5VPCB15D213002844	5VPCD15D213000845	5VPCD15D613001450	5VPCB15DX13000985
5VPCB15D313002447	5VPCD15D313000529	5VPCD15D713002574	5VPCD15D313001227
5VPCB15D313002917	5VPCD15D313001356	5VPCD15DX13001712	5VPCD15D313002345
5VPCB15D413000688	5VPCD15D313002524	5VPCB15D413000724	5VPCD15D513001939
5VPCB15D913001612	5VPCD15D413000507	5VPCD15D713001151	5VPCD15D613001299
5VPCB15DX13000873	5VPCD15D413000569	5VPCD15D913000504	5VPCD15D613001920
5VPCD15D013000651	5VPCD15D413002614	5VPCD15DX13000561	5VPCD15D713002025
5VPCD15D013001475	5VPCD15D513001150	5VPCB15D213000625	5VPCB15D213001659
5VPCD15D013001802	5VPCD15D513002394	5VPCB15D313001959	5VPCB15D313000438
5VPCD15D013001847	5VPCD15D513002587	5VPCB15D413002733	5VPCD15D513000516
5VPCD15D013001864	5VPCD15D813000798	5VPCB15D513001901	5VPCD15DX13001287
5VPCD15D113000755	5VPCD15D913001281	5VPCB15D813002041	5VPCB15D113000101
5VPCD15D113002232	5VPCB15DX13001599	5VPCB15D913002730	5VPCB15D413000335
5VPCD15D113002635	5VPCD15D413001317	5VPCD15D113001985	5VPCB15D413002666
5VPCD15D213000716	5VPCD15DX13001628	5VPCD15D313002507	5VPCB15D513001946
5VPCD15D213000778	5VPCB15D613000823	5VPCD15D613002498	5VPCB15D713002483
5VPCD15D213001803	5VPCB15D913002520	5VPCD15D813002261	5VPCB15D913002484
5VPCD15D213002188	5VPCD15D413000104	5VPCB15D213000737	5VPCD15D113002117

5VPCD15D213002806	5VPCD15D413001351	5VPCB15D213002892	5VPCD15D613000833
5VPCD15D313000711	5VPCD15D513001441	5VPCB15D413002487	5VPCD15D613001982
5VPCD15D313001969	5VPCD15D613002131	5VPCB15DX13002607	5VPCD15D713002204
5VPCD15D313002183	5VPCD15D913002351	5VPCD15D213002109	5VPCD15D713002252
5VPCD15D413000653	5VPCS15D013001465	5VPCD15D313002281	5VPCD15D913002222
5VPCD15D513000757	5VPCS15D613002782	5VPCD15D413000636	5VPCD15DX13002309
5VPCD15D513001312	5VPCB15D513002871	5VPCD15D413001768	5VPCB15D213002889
5VPCD15D513002332	5VPCD15D113001873	5VPCS15D313000360	5VPCB15D313000701
5VPCD15D713002218	5VPCD15D313001874	5VPCB15D113000325	5VPCB15D313001881
5VPCD15D813002809	5VPCD15D613000587	5VPCB15D113000485	5VPCB15D513001817
5VPCD15D913002012	5VPCD15D613001951	5VPCB15D213002486	5VPCB15D513001879
5VPCS15D513001462	5VPCD15D813001353	5VPCB15D313000469	5VPCD15D013000942
5VPCB15D013002860	5VPCD15DX13001841	5VPCB15D513002837	5VPCD15D113001291
5VPCB15D313000763	5VPCD15DX13001869	5VPCB15D513002840	5VPCD15D713002798
5VPCB15D313000911	5VPCD15D913002821	5VPCB15D613000899	5VPCD15D913001233
5VPCB15D313001704	5VPCD15DX13002911	5VPCB15DX13001876	5VPCD15D913000941
5VPCB15D413002750	5VPCD15D213002823	5VPCD15D013002156	5VPCB15D313000908
5VPCB15D613001681	5VPCB15D713000863	5VPCD15D313001387	5VPCB15D413001520
5VPCB15D713001818	5VPCD15D513001651	5VPCD15D413002239	5VPCB15D413002537
5VPCB15D813001892	5VPCD15D613002114	5VPCD15D613001724	5VPCB15D713002578
5VPCB15D913000332	5VPCD15D813000848	5VPCD15D613002761	5VPCB15D813001682
5VPCB15D913001707	5VPCB15D713001673	5VPCD15D713000548	5VPCB15D913000976
5VPCB15DX13000498	5VPCB15D813000824	5VPCD15D713000565	5VPCB15DX13002719
5VPCB15DX13000811	5VPCB15DX13000744	5VPCD15D813001689	5VPCD15D013002819
5VPCB15DX13001893	5VPCD15D213001221	5VPCD15D913002107	5VPCD15D113000853
5VPCB15DX13002591	5VPCD15D313001289	5VPCD15D313001082	5VPCD15D113001307
5VPCD15D013001038	5VPCD15D613002615	5VPCS15D513001591	5VPCD15D413000779
5VPCD15D013001279	5VPCD15D713000856	5VPCB15D413000898	5VPCD15D413001477
5VPCD15D013001511	5VPCD15D713002803	5VPCB15D713000717	5VPCD15D413002192
5VPCD15D013002657	5VPCB15D213002715	5VPCB15D713001236	5VPCD15D513001911
5VPCD15D113002649	5VPCB15D513000487	5VPCD15D013002187	5VPCD15D713001487
5VPCD15D213001767	5VPCB15D513001512	5VPCB15D013001739	5VPCD15D713001506
5VPCD15D213002501	5VPCD15D013002321	5VPCB15D113002608	5VPCD15D813001871
5VPCD15D213002692	5VPCD15D813000588	5VPCB15D913002419	5VPCD15D913001412
5VPCD15D313000756	5VPCD15DX13001399	5VPCB15DX13000436	5VPCD15D913001488
5VPCD15D313001051	5VPCD15D213002062	5VPCB15DX13000596	5VPCD15D913002799
5VPCD15D313002071	5VPCD15D413001043	5VPCD15D013002089	5VPCS15D513002787
5VPCD15D413001141	5VPCD15D913002219	5VPCD15D013002285	5VPCS15DX13001540
5VPCD15D413002502	5VPCD15DX13001998	5VPCD15D113002263	5VPCB15D513001736
5VPCD15D513002511	5VPCD15DX13002262	5VPCD15D213001039	5VPCD15D213001137
5VPCD15D613002808	5VPCB15D013001885	5VPCD15D213002286	5VPCB15D013001482
5VPCD15D713002560	5VPCB15D113001605	5VPCD15D313002264	5VPCB15D013002535
5VPCD15D713002669	5VPCB15D613000496	5VPCD15D513000970	5VPCB15D613001857
5VPCD15D713002736	5VPCD15D113001324	5VPCD15D713000582	5VPCB15D713001561
5VPCD15D813000560	5VPCD15D113002392	5VPCD15D713000761	5VPCB15D713002693
5VPCD15D813001868	5VPCD15D313001938	5VPCD15D813002079	5VPCD15D013002108
5VPCD15D813002356	5VPCD15D513001052	5VPCD15D813002129	5VPCD15D013002240
5VPCD15D813002583	5VPCB15D013001398	5VPCD15D913001992	5VPCD15D113001842
5VPCD15D913002396	5VPCB15D113002902	5VPCS15D813001455	5VPCD15D213002711
5VPCD15D913002771	5VPCB15D313001928	5VPCB15D513001557	5VPCD15D313002362

5VPCD15DX13001872	5VPCB15DX13000730	5VPCD15D913002348	5VPCD15D713001120
5VPCD15DX13002617	5VPCD15D113001114	5VPCB15D013000459	5VPCD15D713002364
5VPCB15D313000746	5VPCD15D113002022	5VPCB15D113000602	5VPCB15D613001955
5VPCB15D413001775	5VPCD15D113002506	5VPCB15D113000728	5VPCB15D413001923
5VPCD15D013000570	5VPCD15D413001625	5VPCB15D313000603	5VPCB15D713001902
5VPCD15D013000830	5VPCD15D613002145	5VPCB15D613000451	5VPCB15D713002662
5VPCD15D313001762	5VPCD15D713001537	5VPCB15D813000726	5VPCB15D813002427
5VPCD15D813001756	5VPCD15D913002009	5VPCB15D913002775	5VPCB15D813002718
5VPCD15D913001636	5VPCB15D913001027	5VPCD15D513000709	5VPCB15DX13000629
5VPCB15D113000681	5VPCD15D013002772	5VPCD15D513002248	5VPCD15D413001107
5VPCB15D113002642	5VPCD15D113000951	5VPCD15D513002525	5VPCD15D413002273
5VPCB15D213002925	5VPCD15D613000931	5VPCD15D613001030	5VPCD15D813001319
5VPCB15D313002688	5VPCD15DX13001693	5VPCD15D713000808	5VPCD15D913002334
5VPCB15D413000691	5VPCB15D513002451	5VPCD15D813001644	5VPCD15DX13002214
5VPCB15D613000918	5VPCB15D613002880	5VPCD15D813002115	5VPCS15DX13000534
5VPCB15D713002449	5VPCB15D913000492	5VPCD15D913000793	5VPCB15D313000679
5VPCB15D913001674	5VPCD15D013002612	5VPCS15DX13001473	5VPCB15D113001894
5VPCB15DX13002929	5VPCD15D213000506	5VPCB15D313002884	5VPCB15D813001973
5VPCD15D013002349	5VPCD15D213000571	5VPCB15D613002717	5VPCD15D713002087
5VPCD15D013002528	5VPCD15D213002515	5VPCB15D713000670	5VPCD15D713002137
5VPCD15D113000769	5VPCD15D313002023	5VPCB15D913001240	5VPCD15DX13001645
5VPCD15D113001484	5VPCD15D813002230	5VPCB15D913002727	5VPCD15DX13001838
5VPCD15D213000652	5VPCD15D913000521	5VPCD15D113002179	5VPCB15D013002843
5VPCD15D213001249	5VPCD15D913001054	5VPCD15D313002278	5VPCB15D213002407
5VPCD15D213001476	5VPCB15D213001743	5VPCD15D413000958	5VPCB15D413001677
5VPCD15D413002807	5VPCB15D213002441	5VPCD15D813002289	5VPCB15D513001882
5VPCD15D513000855	5VPCB15DX13002848	5VPCB15D913001481	5VPCB15D513002904
5VPCD15D513002492	5VPCD15D213000781	5VPCB15D913001772	5VPCB15D613000613
5VPCD15D613000752	5VPCD15D313002796	5VPCD15D313002314	5VPCB15D713000698
5VPCD15D613002159	5VPCD15D513002508	5VPCD15D413002287	5VPCB15DX13001523
5VPCD15D713000954	5VPCD15D813001840	5VPCD15D713001067	5VPCB15DX13002672
5VPCD15D713001943	5VPCD15D813002227	5VPCD15DX13002200	5VPCD15D013001492
5VPCD15D913002141	5VPCS15D713001365	5VPCB15D113002916	5VPCD15D113001534
5VPCS15D913002789	5VPCD15D113002683	5VPCB15D413002540	5VPCD15D113002361
5VPCB15D813001777	5VPCB15D413000822	5VPCB15D613000904	5VPCD15D213000585
5VPCD15D413001950	5VPCS15D713001463	5VPCB15D913001237	5VPCD15D313002698
5VPCD15D813000834	5VPCD15DX13002066	5VPCB15D913002436	5VPCD15D513002346
5VPCD15D813002177	5VPCB15D013002924	5VPCB15D913002744	5VPCD15D613000783
5VPCD15D913001913	5VPCB15D813002928	5VPCD15D113001310	5VPCD15D613001321
5VPCB15D513002899	5VPCD15D213002093	5VPCD15D213001493	5VPCD15D613001805
5VPCB15D713000667	5VPCD15D813001143	5VPCD15D313002104	5VPCD15D613002064
5VPCD15D013002738	5VPCD15D813002132	5VPCD15D313002233	5VPCD15D713001991
5VPCD15D613001335	5VPCD15DX13002097	5VPCD15D413002127	5VPCD15D913000633
5VPCD15D613002629	5VPCD15D013001136	5VPCD15D513002136	5VPCD15DX13001080
5VPCB15D013001742	5VPCD15D213001302	5VPCD15D613001934	5VPCD15DX13001340
5VPCB15D013002518	5VPCD15D513001665	5VPCD15D613001979	5VPCS15D313001539
5VPCB15D113001720	5VPCD15D913001622	5VPCD15D713001909	5VPCS15D513001543
5VPCB15D213002410	5VPCS15D313001363	5VPCD15D713002106	5VPCB15D313002416
5VPCB15D313000102	5VPCB15D013001921	5VPCD15D713002266	5VPCB15D613002734
5VPCB15D313002545	5VPCB15D513002045	5VPCD15DX13000978	5VPCD15D313000790

5VPCB15D513001610	5VPCB15D613001924	5VPCD15DX13001323	5VPCD15D313002328
5VPCB15D613000336	5VPCB15D613002040	5VPCD15DX13002133	5VPCD15D513002489
5VPCB15D613001776	5VPCB15D813001889	5VPCD15DX13002682	5VPCB15D113000678
5VPCB15D713000331	5VPCD15D013002707	5VPCS15D113001586	5VPCB15D213002570
5VPCB15D713002547	5VPCD15D313000773	5VPCB15D013002714	5VPCB15D313002450
5VPCB15DX13000324	5VPCD15D613000766	5VPCB15D213000446	5VPCB15D613001907
5VPCD15D013002500	5VPCD15D613001318	5VPCB15D213000902	5VPCB15D813001245
5VPCD15D213002403	5VPCD15D613001769	5VPCB15D413002473	5VPCD15D013002190
5VPCD15D413002497	5VPCD15D613002047	5VPCB15D513001719	5VPCD15D013002206
5VPCD15D513000337	5VPCD15D713002395	5VPCB15D713000605	5VPCD15D113001940
5VPCD15D613002291	5VPCD15DX13002651	5VPCB15D713001429	5VPCD15D413000796
5VPCD15D913000339	5VPCB15D513002773	5VPCB15D913002890	5VPCD15D813000767
5VPCD15DX13001788	5VPCD15D313002572	5VPCD15D013000522	5VPCD15D913002320
5VPCS15D113000342	5VPCB15D313000729	5VPCD15D013001055	5VPCD15DX13002276
5VPCB15D413002411	5VPCD15D113001789	5VPCD15D013001623	5VPCB15D013002471
5VPCB15D713002919	5VPCD15D413001835	5VPCD15D513001388	5VPCD15D313001292
5VPCD15D513002024	5VPCD15D513000581	5VPCD15D613001089	5VPCD15D713001618
5VPCD15D513002086	5VPCD15D713002655	5VPCD15D613001447	5VPCB15D213002469
5VPCD15D913002088	5VPCD15DX13000589	5VPCD15D613001500	5VPCB15D413000643
5VPCS15D213001547	5VPCB15D113001961	5VPCD15D713002767	5VPCB15D813002475
5VPCB15D613002538	5VPCB15D213000706	5VPCD15D813001062	5VPCB15DX13002882
5VPCB15D813001813	5VPCB15D213001922	5VPCD15DX13000558	5VPCD15D213000800
5VPCB15DX13002896	5VPCB15D313000620	5VPCD15DX13001094	5VPCD15D413002211
5VPCD15D313000854	5VPCB15D313000665	5VPCD15DX13001449	5VPCD15D713002316
5VPCD15D313002166	5VPCB15D313001024	5VPCD15DX13002679	5VPCD15D813002275
5VPCD15D513002220	5VPCB15D313002903	5VPCS15D113001359	5VPCD15D813002308
5VPCD15D513002363	5VPCB15D513002546	5VPCB15D013000736	5VPCS15D213002777
5VPCD15D913002138	5VPCB15D613002894	5VPCB15D213002519	5VPCD15D413002015
5VPCD15D913002494	5VPCB15D713001852	5VPCB15D613001678	5VPCD15D513001357
5VPCD15D313002510	5VPCB15D713002905	5VPCB15D713002676	5VPCD15D813002146
5VPCD15D513001293	5VPCB15D813000984	5VPCD15D013002268	5VPCB15D013002745
5VPCB15D013002776	5VPCB15D913000721	5VPCD15D113002201	5VPCB15D113000924
5VPCB15D313000813	5VPCB15D913001075	5VPCD15D513002234	5VPCB15D713002435
5VPCB15D513000666	5VPCB15D913001965	5VPCD15D513002315	5VPCD15D113002120
5VPCB15D813000449	5VPCB15DX13000615	5VPCD15D713001702	5VPCD15D113002490
5VPCB15D913000458	5VPCB15DX13001960	5VPCD15D713002185	5VPCD15D313001793
5VPCB15D913002887	5VPCB15DX13002042	5VPCD15D813001322	5VPCD15D713002459
5VPCD15D113001386	5VPCD15D013000827	5VPCD15D913001698	5VPCS15D113001457
5VPCD15D313001308	5VPCD15D013001332	5VPCS15D413001551	5VPCB15D313000617
5VPCD15D313001633	5VPCD15D013002173	5VPCB15D413000321	5VPCB15D713002757
5VPCD15D413000393	5VPCD15D213002241	5VPCB15D513002918	5VPCD15D113002571
5VPCD15D413000829	5VPCD15D313001079	5VPCB15D513002921	5VPCD15DX13002620
5VPCD15D613001108	5VPCD15D613000850	5VPCB15D713002922	5VPCB15D213000477
5VPCD15D713002638	5VPCD15D613001285	5VPCB15D813000323	5VPCB15D813000886
5VPCD15D813001658	5VPCD15D613001352	5VPCB15D813000466	5VPCD15D113001727
5VPCD15D913000714	5VPCD15D613002081	5VPCB15D813001858	5VPCD15D413000555
5VPCD15D913001345	5VPCD15D613002226	5VPCB15D913002839	5VPCS15D413001369
5VPCS15D113002785	5VPCD15D713002123	5VPCD15D313001034	5VPCB15D013000901
5VPCB15D013002468	5VPCD15D913001331	5VPCD15D713001862	5VPCB15D313002464
5VPCB15D813002444	5VPCS15D613001258	5VPCS15DX13000503	5VPCD15D013002710

5VPCB15D913000606	5VPCS15D813001472	5VPCB15D113000731	5VPCD15D213001347
5VPCD15D013000648	5VPCB15D213001029	5VPCB15D213002875	5VPCB15D013001479
5VPCD15D113002375	5VPCB15D313001721	5VPCB15D413001601	5VPCB15D313000682
5VPCD15D113002909	5VPCB15D413000609	5VPCB15D913000475	5VPCB15D513000702
5VPCD15D213001042	5VPCB15D513000683	5VPCB15D913002470	5VPCB15D613000921
5VPCD15D313002376	5VPCB15D513000909	5VPCB15DX13001926	5VPCB15D613002460
5VPCD15D713001795	5VPCB15D613000868	5VPCD15D113001145	5VPCB15D613002877
5VPCD15D713002297	5VPCB15D813001553	5VPCD15D113001839	5VPCD15D013002805
5VPCD15D813001790	5VPCB15D913001206	5VPCD15D113002134	5VPCD15D313002359
5VPCD15DX13002116	5VPCD15D113000786	5VPCD15D613000959	5VPCD15D413001639
5VPCD15D113001646	5VPCD15D113001033	5VPCD15D813001806	5VPCD15D513001309
5VPCD15D213001624	5VPCD15D413000961	5VPCD15D913000583	5VPCD15D913002558
5VPCD15D513002203	5VPCD15D513000712	5VPCD15D913001068	5VPCD15D913002639
5VPCD15D613002355	5VPCD15D513000760	5VPCB15D013002423	5VPCS15D613001552
5VPCD15D813001403	5VPCD15D513000807	5VPCB15D213000690	5VPCD15D013002626
5VPCB15D113002883	5VPCD15D513001035	5VPCD15D213000635	5VPCD15D213002627
5VPCB15D913001660	5VPCD15D513002119	5VPCD15D513002282	5VPCD15D413001690
5VPCB15DX13000470	5VPCD15D613000802	5VPCD15D813001014	5VPCD15D713000579
5VPCD15D213001915	5VPCD15D813001224	5VPCB15D613000322	5VPCB15D413000917
5VPCD15D213002076	5VPCD15D813001451	5VPCB15D213000592	5VPCB15D413002425
5VPCD15D313001115	5VPCD15D913001510	5VPCB15D613000465	5VPCD15D313002121
5VPCD15D313002670	5VPCD15D913002317	5VPCD15D213001056	5VPCD15D613002128
5VPCD15D413001298	5VPCD15DX13000947	5VPCD15D713000646	5VPCD15D813002339
5VPCD15D713001280	5VPCD15DX13001015	5VPCB15D713000815	5VPCD15DX13002343
5VPCD15D813001529	5VPCD15DX13002391	5VPCB15DX13000923	5VPCB15D013000610
5VPCS15D213001581	5VPCS15D013001367	5VPCD15D613001755	5VPCB15D613000725
5VPCB15D213001886	5VPCB15D113000888	5VPCD15D913001989	5VPCB15D813002914
5VPCB15D713000684	5VPCB15D213001421	5VPCD15DX13001144	5VPCD15D913001121
5VPCB15DX13002476	5VPCD15D113002585	5VPCB15D113000907	5VPCD15D113000710
5VPCB15DX13002641	5VPCD15D213002630	5VPCB15D313000696	5VPCD15D613002646
5VPCD15D313000935	5VPCD15D313000837	5VPCB15D313001430	5VPCS15D213001368
5VPCD15D413001088	5VPCD15D313001065	5VPCB15D713001558	5VPCS15D013000364
5VPCD15D413002094	5VPCD15D413001981	5VPCD15D113001405	5VPCB15D013001076
5VPCD15D413002354	5VPCD15D513001410	5VPCD15D213002529	5VPCB15D113002849
5VPCD15D713002378	5VPCD15D513001536	5VPCD15D513001617	5VPCB15DX13000453
5VPCS15DX13001585	5VPCD15D913001443	5VPCD15D613002405	5VPCD15D313002250
5VPCB15D413000612	5VPCD15D913002253	5VPCD15D713001117	5VPCD15D613000797
5VPCB15D413001856	5VPCD15DX13000804	5VPCD15D713002350	5VPCS15D813001360
5VPCB15D513002644	5VPCD15D113002070	5VPCD15D813000655	5VPCB15D213001967
5VPCB15D813002721	5VPCD15D213000957	5VPCD15D013002495	5VPCB15D313002920
5VPCB15D913002906	5VPCD15D213002224	5VPCB15D013001899	5VPCB15D613002846
5VPCB15DX13001683	5VPCD15D913002110	5VPCB15D513000764	5VPCS15D413001257
5VPCD15D013002335	5VPCB15D413000495	5VPCB15D613000675	5VPCB15D613002930
5VPCD15D313002491	5VPCB15D313001685	5VPCB15D613001891	5VPCD15D513002184
5VPCD15D513001133	5VPCB15D313001962	5VPCB15D713001883	5VPCB15D413002926
5VPCD15D613002338	5VPCB15D813001603	5VPCD15D313002216	5VPCB15D813000595
5VPCD15D913002768	5VPCB15D913001254	5VPCD15D813001532	5VPCB15D913000900
5VPCB15D013000641	5VPCB15D913002596	5VPCD15D913001149	5VPCB15D113002432
5VPCB15DX13001022	5VPCB15DX13000694	5VPCD15DX13002245	5VPCB15D113002463
5VPCD15D013000357	5VPCD15D013002254	5VPCB15D313001895	5VPCB15D313000732

5VPCD15D013000939	5VPCD15D113000531	5VPCB15D313002609	5VPCD15D213002174
5VPCD15D113000397	5VPCD15D513002301	5VPCB15D613001731	5VPCB15D013001563
5VPCD15D113002165	5VPCD15D613002243	5VPCD15D213001865	5VPCB15D313001394
5VPCD15D213000358	5VPCD15D613002257	5VPCD15D313001910	5VPCB15D613001521
5VPCD15D213001333	5VPCD15D713000713	5VPCD15D413001866	5VPCB15D813000922
5VPCD15D213001400	5VPCD15D713000968	5VPCD15D913001846	5VPCB15D013002907
5VPCD15D613000105	5VPCD15D813002244	5VPCD15D913001863	5VPCB15D413001243
5VPCD15D713001294	5VPCD15D913002205	5VPCB15D113001393	5VPCB15L713001566
5VPCD15DX13000785	5VPCS15D613002779	5VPCB15D213000611	5VPCB15L113001126
5VPCD15DX13002357	5VPCB15D213000320	5VPCB15D513000814	5VPCD15LX13002852
5VPCD15DX13002505	5VPCB15D313002593	5VPCB15D513000893	5VPCB15L613001123
5VPCB15D313002741	5VPCB15D413001906	5VPCB15D613000885	5VPCB15L113001577
5VPCD15D813002616	5VPCB15D413002568	5VPCD15D113001064	5VPCS15L613002790
5VPCB15D013002700	5VPCB15D513001896	5VPCD15D313001700	5VPCS15L213001975
5VPCD15D013001282	5VPCB15D813002850	5VPCD15D513001066	5VPCD15LX13000387
5VPCD15D413002533	5VPCD15D113002344	5VPCD15D713000517	5VPCD15L913001157
5VPCD15D913002527	5VPCD15D213002143	5VPCD15D713001408	5VPCD15L813000386
5VPCB15D013000705	5VPCD15D313001941	5VPCD15D813001630	5VPCD15L013001385
5VPCB15D313001556	5VPCD15D413000586	5VPCD15D913002155	5VPCB15LX13000928
5VPCB15D313002674	5VPCD15D913001314	5VPCD15DX13001032	5VPCB15L813000345
5VPCB15D413001565	5VPCD15D913002267	5VPCD15DX13001452	5VPCB15L413001010
5VPCB15D513000991	5VPCD15D713000940	5VPCS15DX13001361	5VPCD15L913000428
5VPCD15D013001444	5VPCD15D013001315	5VPCD15D113001498	5VPCD15L013000379
5VPCD15D113001615	5VPCD15D713002820	5VPCD15D313001499	5VPCB15LX13000346
5VPCD15D313001146	5VPCD15D013002271	5VPCD15D813001627	5VPCS15L913000368
5VPCD15D613001402	5VPCD15D613002095	5VPCB15D513000912	5VPCS15L313000365
5VPCD15D613001688	5VPCD15D813002194	5VPCB15DX13001604	5VPCD15LX13001166
5VPCD15D813001210	5VPCD15DX13002195	5VPCD15D113001288	5VPCD15L913001160
5VPCD15D813001417	5VPCS15D613001454	5VPCD15D213001686	5VPCD15L613001164
5VPCD15DX13000771	5VPCB15D513000442	5VPCD15D613001657	5VPCB15L813001124
5VPCD15DX13002164	5VPCB15DX13002865	5VPCD15D913000938	5VPCB15L613001008
5VPCS15D313001587	5VPCD15D713000632	5VPCB15D213002522	5VPCB15L413001122
5VPCS15D313001590	5VPCB15D113000874	5VPCD15D213002496	5VPCB15L013001019
5VPCS15D813000547	5VPCB15D213001855	5VPCS15D013000543	5VPCB15L813001009
5VPCB15DX13002901	5VPCB15D513001025	5VPCS15D713000362	5VPCD15LX13001376
5VPCB15D113001779	5VPCD15D113000528	5VPCB15D313000889	5VPCD15L513001172
5VPCD15D513001990	5VPCD15D213000649	5VPCB15DX13001781	5VPCD15L213001176
5VPCD15D613002369	5VPCD15D313002135	5VPCD15D013002075	5VPCB15LX13001190
5VPCD15D713001098	5VPCD15D313002765	5VPCD15D313000384	5VPCB15L913001021
5VPCB15D113001958	5VPCD15D513001116	5VPCD15D513000659	5VPCB15L813000927
5VPCB15D113002415	5VPCD15D613000573	5VPCD15D813001031	5VPCB15L413000925
5VPCD15D113002621	5VPCD15D713002168	5VPCS15D113001541	5VPCS15L413001976
5VPCD15D213002255	5VPCD15DX13001337	5VPCB15D313001783	5VPCD15LX13001765
5VPCD15D613001870	5VPCB15D413002523	5VPCB15D413002716	5VPCD15L713001173
5VPCD15D713002526	5VPCB15D613002474	5VPCB15D813001925	5VPCD15L713001156
5VPCD15D813001935	5VPCD15D013002478	5VPCD15D013001041	5VPCD15L013000415
5VPCB15D513001705	5VPCD15D213002479	5VPCD15D113002313	5VPCB15L313001595
5VPCB15D913000444	5VPCD15D313001325	5VPCD15D413000801	5VPCB15L313000348
5VPCD15D513001326	5VPCD15D513002766	5VPCD15D513002007	5VPCB15L013001568
5VPCD15D513001844	5VPCD15D613002680	5VPCD15D613001013	5VPCS15L813002791

5VPCD15D513002069	5VPCD15DX13001306	5VPCD15D913001037	5VPCS15L113002793
5VPCD15D513001097	5VPCD15D813001997	5VPCB15D013000879	5VPCD15LX13001183
5VPCD15DX13002763	5VPCD15D813002342	5VPCB15D013002485	5VPCD15L913000414
5VPCB15D313001525	5VPCB15D013001854	5VPCB15D113001023	5VPCD15L813001179
5VPCB15D413002862	5VPCB15D513000473	5VPCD15D013001508	5VPCD15L713001187
5VPCD15D613002307	5VPCB15D713002385	5VPCD15D113001629	5VPCD15L613001374
5VPCD15D713002140	5VPCB15D813002623	5VPCD15D313001535	5VPCD15L613001178
5VPCD15DX13002178	5VPCD15D213002336	5VPCD15D513002685	5VPCD15L513001382
5VPCD15DX13002228	5VPCD15D313002300	5VPCD15D613001710	5VPCD15L313001171
5VPCB15D613001003	5VPCD15D313002457	5VPCD15D613002162	5VPCD15L213001162
5VPCB15D813001522	5VPCD15DX13001046	5VPCD15D713002509	5VPCD15L113001184
5VPCB15D913000864	5VPCD15DX13002293	5VPCD15D813001711	5VPCD15L013000429
5VPCD15D013002092	5VPCS15DX13001456	5VPCD15D913001409	5VPCB15LX13001576
5VPCD15D213001929	5VPCB15D213002701	5VPCD15DX13002813	5VPCB15L713001194
5VPCD15D213002269	5VPCB15D413002408	5VPCS15D113001538	5VPCB15L513000996
5VPCD15D313002488	5VPCB15D513002465	5VPCS15D913001464	5VPCB15L213001569
5VPCD15D713001697	5VPCB15D913000704	5VPCB15D613002409	5VPCB15L113000378
5VPCD15D913002706	5VPCB15DX13002462	5VPCB15D713000992	5VPCD15L513002855
5VPCD15DX13000852	5VPCD15D413002290	5VPCB15D813000869	5VPCS15L713000367
5VPCB15D213002598	5VPCD15DX13000981	5VPCB15D813001715	5VPCD15L913001188
5VPCB15D313002870	5VPCD15DX13002455	5VPCB15D913000668	5VPCD15L913001174
5VPCB15D513000456	5VPCB15D013000977	5VPCD15D113001209	5VPCD15L713000413
5VPCB15D613002748	5VPCB15D213000673	5VPCD15D113001663	5VPCD15L413001163
5VPCB15D613002829	5VPCB15D213000818	5VPCD15D313001664	5VPCD15L113001380
5VPCB15D913001609	5VPCB15D513000876	5VPCD15D813000963	5VPCB15LX13000377
5VPCB15DX13001554	5VPCD15D013000794	5VPCD15D813001059	5VPCD15L913002857
5VPCD15D113002005	5VPCD15D013000973	5VPCD15D913000860	5VPCS15L813001978
5VPCD15D513001696	5VPCD15D613000945	5VPCD15D613002324	5VPCB15L713001017
5VPCD15D513001701	5VPCD15D613002811	5VPCD15D313001650	5VPCD15L613000385
5VPCD15D513001942	5VPCD15D913001085	5VPCB15D213002424	5VPCB15L113000347
5VPCD15D713002817	5VPCB15D213000821	5VPCB15D313000441	5VPCB15L113000929
5VPCB15D713000734	5VPCB15D413001680	5VPCB15D413002442	5VPCB15L113000994
5VPCD15D713001652	5VPCB15D813000743	5VPCB15D513000439	5VPCB15L313001130
5VPCB15D113002544	5VPCD15D713002302	5VPCB15D613000742	5VPCB15L413001007
5VPCD15D013000844	5VPCB15D113002866	5VPCB15D713000703	5VPCB15L513001596
5VPCD15D413002161	5VPCB15D213000494	5VPCB15DX13002414	5VPCB15L913000998
5VPCD15D013002562	5VPCB15D313000875	5VPCD15D013000715	5VPCD15L213001758
5VPCD15D213000831	5VPCB15D413000464	5VPCD15D213000960	5VPCD15L213001825
5VPCD15D213001798	5VPCB15D413002831	5VPCD15D213001414	5VPCD15L413001860
5VPCD15D413000572	5VPCB15D513002434	5VPCD15D313000661	5VPCD15L513002824
5VPCB15D013000607	5VPCB15D513002482	5VPCD15D413002371	5VPCD15L613001181
5VPCB15D013000719	5VPCB15D613000644	5VPCD15D513000788	5VPCD15L713001822
5VPCB15D113000440	5VPCB15D713000488	5VPCD15D513002458	5VPCD15LX13001796
5VPCB15D613002913	5VPCD15D013000777	5VPCD15D613000508	5VPCB15L313001192
5VPCB15D713001737	5VPCD15D113002148	5VPCD15D613000749	5VPCB15L513001193
5VPCD15D013002111	5VPCD15D213001509	5VPCD15D613000847	5VPCB15L513001579
5VPCD15D113001050	5VPCD15D413001348	5VPCD15D613002453	5VPCB15L913001018
5VPCD15D313000577	5VPCD15D513001343	5VPCD15D713000520	5VPCB15L913001570
5VPCD15D913002060	5VPCD15D613000962	5VPCD15D813001045	5VPCD15L313001185
5VPCD15D913002303	5VPCD15D613001092	5VPCD15DX13000656	5VPCD15L313001378

5VPCD15DX13000575	5VPCD15D713001635	5VPCS15D113001460	5VPCD15L813001165
5VPCD15DX13002374	5VPCD15D713002011	5VPCS15D413000545	5VPCD15L913001384
5VPCS15D413001470	5VPCD15D813000512	5VPCD15D213002126	5VPCB15L213000356
5VPCB15D513001820	5VPCD15D813002552	5VPCD15D313002118	5VPCB15L313000995
5VPCD15D213001932	5VPCD15D913001801	5VPCD15D413002001	5VPCB15L313001578
5VPCD15D213002725	5VPCD15D913002026	5VPCB15D013001966	5VPCB15L713000997
5VPCB15D013001787	5VPCD15D913002818	5VPCB15D313001718	5VPCB15L813001575
5VPCB15D613000448	5VPCD15DX13001726	5VPCB15D813000645	5VPCB15L913001004
5VPCB15D913001562	5VPCD15DX13002553	5VPCD15D313001342	5VPCD15L313001381
5VPCB15D913002873	5VPCS15D313000391	5VPCD15D413001138	5VPCD15L413001826
5VPCD15D113001761	5VPCS15D713001592	5VPCD15D513000550	5VPCD15L513001169
5VPCD15D813002020	5VPCB15D013000915	5VPCD15D713001053	5VPCD15L513001821
5VPCD15DX13001760	5VPCB15D113000597	5VPCD15D813000803	5VPCD15L713000380
5VPCS15D413001582	5VPCB15D313001850	5VPCD15D913002124	5VPCS15L613000375
5VPCB15D913002601	5VPCB15D713001849	5VPCB15D113002446	5VPCS15L613001977
5VPCD15D113002697	5VPCD15D113001792	5VPCB15D413000674	5VPCS15L813000376
5VPCD15D513002556	5VPCD15D313002653	5VPCB15D513000599	5VPCB15L513001128
5VPCB15D513001428	5VPCD15D413002550	5VPCB15D613000482	5VPCB15L813000426
5VPCD15D313001647	5VPCD15D513002296	5VPCB15DX13000887	5VPCD15L013001158
5VPCD15D913000809	5VPCD15D613002551	5VPCD15D013001346	5VPCD15L113001170
5VPCB15D513001235	5VPCB15D213002827	5VPCD15D113001047	5VPCD15L113001377
5VPCB15D513001784	5VPCB15D313000472	5VPCD15D313000630	5VPCD15L413001177
5VPCB15D713002886	5VPCB15D413000481	5VPCD15D313001812	5VPCB15L513001131
5VPCB15D813000919	5VPCD15D013002027	5VPCD15D413001060	5VPCB15L113001580
5VPCB15DX13002428	5VPCD15D213001252	5VPCD15D513002251	5VPCB15L713001597
5VPCD15D113001694	5VPCD15D413001723	5VPCD15D613001061	5VPCB15L913001567
5VPCD15D813001305	5VPCD15D613001996	5VPCD15D813000574	5VPCD15L013001161
5VPCD15D813002096	5VPCD15D913000549	5VPCD15D813002163	5VPCD15L013001175
5VPCD15D813002292	5VPCB15D113001684	5VPCD15D813002180	5VPCD15L313001168
5VPCD15D813002812	5VPCB15D613001602	5VPCD15D913001118	5VPCD15L413001759
5VPCD15D913002270	5VPCD15D013002142	5VPCD15D913002284	5VPCD15L813001764
5VPCD15DX13001791	5VPCD15D013002397	5VPCB15D013002728	5VPCD15LX13001829
5VPCD15D413001947	5VPCD15D113001937	5VPCB15D013002888	5VPCB15L013000999
5VPCD15DX13001810	5VPCD15D213002305	5VPCB15D113001703	5VPCB15L113001000
5VPCB15D713001785	5VPCD15D213002367	5VPCB15D213002438	5VPCB15L113001191
5VPCD15D313000949	5VPCD15D313001440	5VPCB15D313002867	5VPCB15L213001006
5VPCB15D013001420	5VPCD15D613002341	5VPCB15D413002599	5VPCB15L313001127
5VPCB15D013001515	5VPCD15D713002154	5VPCB15D513001560	5VPCB15L713001129
5VPCB15D113000695	5VPCD15DX13001502	5VPCB15D513002739	5VPCB15LX13000914
5VPCB15D113000891	5VPCS15D513000392	5VPCB15D513002885	5VPCD15L513001379
5VPCB15D213002567	5VPCB15D313001816	5VPCB15D713001480	5VPCD15L813001182
5VPCB15D313002044	5VPCB15D413000447	5VPCB15D813001956	5VPCD15L813001859
5VPCB15D413002604	5VPCB15D413002439	5VPCB15D913002467	5VPCB15L013001005
5VPCB15D613002569	5VPCB15D813002881	5VPCB15D913002565	5VPCB15L413000343
5VPCB15D713001706	5VPCB15DX13001974	5VPCD15D713001232	5VPCB15L613000926
5VPCB15D913000699	5VPCD15D013001766	5VPCD15D813000851	5VPCB15LX13001125
5VPCB15D913001397	5VPCD15D013002318	5VPCB15D813001391	5VPCD15L113001167
5VPCB15D913001559	5VPCD15D513000564	5VPCD15D413001933	5VPCD15L213001159
5VPCB15DX13002686	5VPCD15D913001250	5VPCD15D713001411	5VPCD15L413001180
5VPCD15D113001226	5VPCD15DX13002584	5VPCB15D713000765	5VPCD15L513001186

5VPCD15D113002389	5VPCS15D613001471	5VPCD15D113001078	5VPCD15L613001861
5VPCD15D313002586	5VPCB15D413002859	5VPCD15D413000846	5VPCD15L713000427
5VPCD15D313002684	5VPCB15D513001963	5VPCS15D813000533	5VPCD15L813001375
5VPCD15D413001284	5VPCB15D813002847	5VPCB15D513000862	5VPCD15L913001823
5VPCD15D413001334	5VPCB15DX13000467	5VPCD15D413002760	5VPCB15L013001571
5VPCD15D513001228	5VPCB15DX13000680	5VPCD15D913001295	5VPCB15L113001594
5VPCD15D513002122	5VPCD15D213001073	5VPCD15DX13000933	5VPCB15L413001573
5VPCD15D513002802	5VPCD15D213002398	5VPCB15D013001613	5VPCB15L513001016
5VPCD15D613001416	5VPCD15D513002217	5VPCB15D113000616	5VPCB15L913001598
5VPCD15D613001531	5VPCD15D713002235	5VPCB15D213001516	5VPCB15LX13000993
5VPCD15D613002016	5VPCD15D013001301	5VPCB15D413001422	5VPCD15L713000430
5VPCD15D713000839	5VPCD15D213001770	5VPCD15D413002208	5VPCD15L713001383
5VPCD15D913002074	5VPCD15D813000753	5VPCD15D513001231	5VPCD15L713002825
5VPCD15D913002379	5VPCD15D813002390	5VPCD15D613001304	5VPCD15L813001828
5VPCD15DX13000754	5VPCD15D013000861	5VPCD15DX13000768	5VPCD15L913002826
5VPCD15DX13001984	5VPCD15D013001329	5VPCS15D413001467	5VPCS15L513000366
5VPCS15D213001550	5VPCB15D613002703	5VPCB15D213001242	5VPCS15LX13002792
5VPCS15D313001461	5VPCB15D913001819	5VPCB15D213002861	5VPCB15L613000344
5VPCS15D613001583	5VPCD15D513001794	5VPCB15D613002622	5VPCB15L213001572
5VPCB15D113002429	5VPCD15D613002176	5VPCB15D713001074	5VPCB15L613001574
5VPCB15DX13002915	5VPCD15D813000526	5VPCD15D113000772	5VPCB15L713001020
5VPCD15D813002311	5VPCB15D213000897	5VPCD15D213002112	5VPCB15LX13001593
5VPCD15D813002762	5VPCD15D213002272	5VPCD15D313000966	5VPCD15L013001189
5VPCB15D113001944	5VPCD15D513002265	5VPCB15D213001774	5VPCD15L013001824
5VPCB15D113002687	5VPCD15D713002705	5VPCB15D713001771	5VPCD15L113002853
5VPCB15D413001971	5VPCD15D813001286	5VPCD15D313002085	5VPCD15L313002854
5VPCB15D513002448	5VPCD15DX13001239	5VPCD15D313002393	5VPCD15L613001827
5VPCB15D613001423	5VPCB15D813002735	5VPCD15D413000751	5VPCD15L713002856
5VPCB15D713000877	5VPCB15D913000816	5VPCD15D413002516	5VPCD15L813002851
5VPCB15D813001908	5VPCD15DX13002696	5VPCD15D813000932	5VPCS15U713001270
5VPCD15D013001296	5VPCB15D013000462	5VPCD15D913000647	5VPCS15U913001271
5VPCD15D013002769	5VPCB15D013001028	5VPCD15D913002382	5VPCS15U313001265
5VPCD15D213001090	5VPCB15D013001675	5VPCD15DX13001208	5VPCB15UX13001103
5VPCD15D313002149	5VPCB15D113000499	5VPCD15DX13001418	5VPCB15UX13001750
5VPCD15D413002144	5VPCB15D113001717	5VPCB15D013001773	5VPCB15U113001197
5VPCD15D413002158	5VPCB15D213001564	5VPCB15D613001244	5VPCD15U713001201
5VPCD15D513002170	5VPCB15D213002603	5VPCD15D113002280	5VPCD15U713001148
5VPCD15D513002654	5VPCB15D313001427	5VPCD15D413001527	5VPCS15UX13001277
5VPCD15D613002002	5VPCB15D413000867	5VPCB15D013000445	5VPCS15UX13001263
5VPCD15D613002260	5VPCB15D413001002	5VPCB15D013000624	5VPCS15U813001276
5VPCD15D813002325	5VPCB15D513000621	5VPCB15D113000437	5VPCS15U613001275
5VPCD15D913002480	5VPCB15D613002426	5VPCB15D113002592	5VPCS15U613001261
5VPCD15DX13000835	5VPCB15D613002720	5VPCB15D213001483	5VPCS15U513001266
5VPCD15D213001011	5VPCB15D813000905	5VPCB15D513002675	5VPCS15U413001274
5VPCD15D213002210	5VPCB15D813001732	5VPCB15D713000748	5VPCS15U413001212
5VPCD15D913001071	5VPCB15D813002752	5VPCD15D013002304	5VPCS15U313001217
5VPCB15D313002898	5VPCB15D913000718	5VPCD15D113000836	5VPCS15U113001264
5VPCB15D513002868	5VPCB15DX13000677	5VPCD15D113002084	5VPCS15U913001268
5VPCD15D213000795	5VPCB15DX13001733	5VPCD15D213001283	5VPCS15U713001267
5VPCD15D313000806	5VPCD15D013000505	5VPCD15D313001230	5VPCS15U413001260

5VPCD15D313001132	5VPCD15D013000584	5VPCD15D313002555	5VPCS15U013001272
5VPCD15D513002380	5VPCD15D113000562	5VPCD15D413001642	5VPCS15U013001269
5VPCD15D713001134	5VPCD15D113001730	5VPCD15D413001916	5VPCS15U813001214
5VPCB15D713002774	5VPCD15D413001687	5VPCD15DX13000950	5VPCS15U313001220
5VPCD15D913002561	5VPCD15D413001995	5VPCD15DX13001757	5VPCS15U213001273
5VPCD15D913002575	5VPCD15D413002189	5VPCS15D313002786	5VPCS15U113001216
5VPCB15D613002863	5VPCD15D413002256	5VPCS15D513000537	5VPCB15U513001834
5VPCB15D813000452	5VPCD15D513000791	5VPCS15D813001469	5VPCS15UX13001215
5VPCB15D913000329	5VPCD15D513002010	5VPCD15D013002013	5VPCD15U213001199
5VPCB15DX13000727	5VPCD15D513002377	5VPCB15D713000474	5VPCB15U113001104
5VPCB15DX13001814	5VPCD15D613000525	5VPCD15D113000657	5VPCD15U413001155
5VPCD15D013002061	5VPCD15D813002454	5VPCD15D113002182	5VPCB15U813001830
5VPCD15D113000934	5VPCD15D913001099	5VPCD15D513001648	5VPCB15UX13001196
5VPCD15D413001804	5VPCD15DX13000513	5VPCD15D513001763	5VPCB15U313001752
5VPCD15D113001968	5VPCD15DX13000530	5VPCB15D313002481	5VPCD15U513001147
5VPCD15D213001526	5VPCD15DX13002004	5VPCB15D913000461	5VPCD15U013001198
5VPCB15D513000974	5VPCD15DX13002360	5VPCB15DX13000906	5VPCD15U513001200
5VPCB15D713001513	5VPCD15D313002006	5VPCD15D513001987	5VPCB15UX13001831
5VPCD15D313001406	5VPCD15D713002249	5VPCD15D613001223	5VPCB15U413001744