

BMW Group

December 15, 2005

Mr. Michael Lee
Office of Defects Investigation
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, DC 20590

Re: PE05-053

Dear Mr. Lee:


As noted in our November 28, 2005 response to PE05-053, specifically, Question 10, we would be providing exemplar sample parts under separate cover.

Accordingly, this letter responds to Question 10(c), specifically, "...any kits that have been released, or developed, by BMW for use in service repairs to the subject component/assembly which relate, or may relate, to the alleged defect in the subject vehicles."

Enclosed with this letter are wiring harness repair cable kit part number 6 937 521, and part number 6 937 522, pertaining to the side air bag wiring harness, and the safety-belt pretensioner wiring harness, respectively. As requested, two of each part number are provided.

Should you have any questions, please contact Martin Rapaport of my staff at (201) 573-7708.

Sincerely,



Thomas C. Baloga
General Manager
Safety Engineering & Intelligent Transportation Systems

Enclosures:

Part Number 6 937 521 - Quantity - 2
Part Number 6 937 522 - Quantity - 2

Cc:

T. Cooper, NHTSA (Office of Defects Investigation) - Letter only

Company
BMW of North America, LLC

BMW Group Company

Mailing address
PO Box 1227
Westwood, NJ
07675-1227

Office address
300 Chestnut Ridge Road
Woodcliff Lake, NJ
07677-7731

Telephone
(201) 307-4000

Fax
(201) 782-0764

Website
bmwusa.com

OFFICE OF DEFECTS INVESTIGATION
NHTSA
2005 DEC 19 P 1:37

RECEIVED
MVS-710

