

Approximate Change Production Incorporation Date	Description of Change	Reason for Change	Part Number of Original Component	Part Numbers of Modified Component	Was Original Component Withdrawn from Sale	Date modified Component Available for Service	Parts Interchangeable
09/23/02	Add to control plan a 2mm allowable clearance between the adjacent coil and the lower spring seat flange when compressed to full jounce	Minimize contact between spring and spring seat flange	YF1C 5310 AA YF1C 5310 BA YF1C 5310 CA YF1C 5310 DA	YF1C 5310 AA YF1C 5310 BA YF1C 5310 CA YF1C 5310 DA	No	N/A	Yes
09/30/03	Add dual coat corrosion protection	Improve corrosion performance	YF1C 5310 AA YF1C 5310 BA YF1C 5310 CA YF1C 5310 DA	4F13 5310 AA 4F13 5310 BA 4F13 5310 CA 4F13 5310 DA	No-Exhaust Service Parts	9/30/03	No-One Way Interchangeability in C11466402
12/03-1/04	Resource coil springs to China Spring Factory	Resource to global emerging market supplier	4F13 5310 AA 4F13 5310 BA 4F13 5310 CA 4F13 5310 DA	4F13 5310 AA 4F13 5310 BA 4F13 5310 CA 4F13 5310 DA	No	12/03-1/04	N/A - Changed supplier, but did not advance part number