Highland, MI

Reference No.: 10730485

V.I.N.: 3B7HF13Z31G7

Dear

This will further acknowledge contact with DaimlerChrysler Motors Corporation regarding your 2001 Dodge Ram 1500 Pickup Quad Cab.

naturally, we were sorry to learn of the incident described to us during the initial contact. However, we have had the opportunity to review the inspection report, and must inform you that we are not led to believe that the incident was due to a manufacturing responsibility. Therefore, we must respectfully decline any responsibility associated with this incident.

Based on this information, we can only suggest that you refer this matter to your insurance carrier. Should they feel a manufacturing responsibility exists, they have full subrogation rights under the terms of your policy.

Thank you for allowing us the opportunity to review this matter with you.

Sincerely,

A. Williams Special Investigations (248) 944-7056

sh

E. Lewis



28635 Mound Road Warren, Michigan 48092-3499 (586) 753-3326 FAX (586) 753-3335

# Facsimile Cover Sheet DaimlerChrysler Vehicle Investigation

Owner:			•	
Project No. DAIM-0001		CAIR N	CAIR No.: 10730485	
!				
TO: Eric Lev	<u>wis</u>			
;	FROM: Tina Martin			
•	,	Date Se	nt: <u>12-10-02</u>	
		DUE DA	TE: <u>12-13-02</u>	
*PLEASE ACKNOWLEDGE PROMPTLY BY FAX OR EMAIL				
*Receipt of CAIR and Accepting case for investigation? Yes \(\subseteq\) No				
<u> </u>	Date:			
Coversheet for DaimlerChrysler (Service Associate Use Only) (Also fax or email to EAA for closure)				
*Closure Date: 12-13-02 DaimlerChrysler Fax No.: 248-512-8748				
☐ Bennis	(248) 944-7036	☐ Martell	(248) 944-7038	
<b>⊠</b> Bott	(248) 944-7056	☐ Susalla	(248) 944-7149	
☐ Gilbert	(248) 944-7037	□ Porterfiel	d (248) 944-7134	
Comments:	Photos up hordred	,	)	
			$\checkmark$	



IF YES, ENCLOSE COPIES OF REPAIR ORDERS

Zip 48383 PHONE

### PART B - EXTERIOR/INTERIOR VEHICLE DAMAGE

- WINDSHIELD
- ALL AREAS OF DAMAGE MARKINGS ON INTERIOR AND EXTERIOR
- CLOSE UPS OF STAINS, SKIN, HAIR, CLOTH
- EXTERIOR AND INTERIOR DAMAGE INCLUDING **UNDERCARRIAGE**

#### **INFORMATION:**

- DESCRIBE ANY INJURIES TO DRIVER AND/OR OTHER **OCCUPANTS**
- SEE SEAT BELT/SEATS SECTION IF APPLICABLE

REQUIRED PHOTOGRAPHS: Damage is to the hood, hood hinges, grill and top rear area of both front fenders. Secondary hood latch is bent in the rearward and upward position preventing it from locking. Unable to determain cause of bent scondary latch assembly. An emergency lighting system switch mounted next to the hood release lever interferes with the hood release operation. Prevents the releasee from returning to the lock position - have to push the release lever to the lock position.

Next

cairnumber :10730485

### PART - C AIRBAG(S) NOT APPLICABLE

# PART - D SEATS/SHOULDER BELTS NOT APPLICABLE PART - E TRANSMISSION NOT APPLICABLE

Previous

Next

### PART - F UNINTENDED ACCELERATION NOT APPLICABLE

### **PART - G BRAKES NOT APPLICABLE**

## PART - H STEERING/SUSPENSION/TIRES NOT APPLICABLE

### PART - I AXLE/DIFFERENTIAL NOT APPLICABLE

PART J - ADDITIONAL COMMENTS (DO NOT DRAW ANY CONCLUSIONS)

Previous