



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE09-052
Date Opened: 11/06/2009
Principal Investigator: Robert Young
Subject: Motorcycle Stalling
Date Closed: 01/04/2010

Manufacturer: BMW of North America, LLC
Products: 2009 BMW K1300S & K1300 GT
Population: 2,019

Problem Description: Motorcycle stalls while underway.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	45	35	80
Crashes/Fires:	1	0	1
Injury Incidents:	1	0	1
# Injuries:	1	0	1
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other:	1	0	1

Description of Other: Web discussion boards.

Action: Recall 09V-471 – Close this PE.

Engineer: Bob Young
Div. Chief: Richard Boyd
Office Dir.: Kathleen C. DeMeter

Date: 01/04/2010
Date: 01/04/2010
Date: 01/04/2010

Summary:

The subject motorcycles may stall due to restricted airflow within the air intake system during low rpm engine operation, typically while shifting and/or decelerating.

BMW is recalling the subject motorcycles (09V-471) to update the engine management software. Additionally, BMW will include Model Year 2010 K300S/GT models. With that recall, submitted in lieu of responding to our information request, this PE is closed.