

VIN	CLAIM	MILES	KM	FINDINGS
2G1WB55K569	Hole in return hose	7395		Parts will be send to supplier to be analyzed
2G1WT58N969	Hole in return hose		710	Parts will be send to supplier to be analyzed
2G1WU581269	Hole in return hose		2395	Parts will be send to supplier to be analyzed
2G1WT58N769	Hole in return hose		2388	Parts will be send to supplier to be analyzed
2G1WB58K369	Hole in return hose	436		Parts will be send to supplier to be analyzed
2G1WU581969	Hole in return hose		5068	Parts will be send to supplier to be analyzed
2G1WB58N869	Hole in return hose		1356	Parts will be send to supplier to be analyzed
2G1WB58N669	Hole in return hose		2348	Parts will be send to supplier to be analyzed

VIN	CLAIM	MILES	KM	FINDINGS
2G1WC581869	Loose Clamp	429		CT-Clamps tested ok
2G1WT58K069	Loose Clamp	700		Complete Assembly Tested-Leak and burt- Found OK
2G1WB58K469	Loose Clamp	1070		CT-Clamps tested ok
2G1WB58K469	Loose Clamp	8		CT-Clamps tested ok
2G1WU581469	Loose Clamp		9165	CT-Clamps tested ok
2G1WT58KX69	Loose Clamp	1500		Complete Assembly Tested-Leak and burt- Found OK
2G1WC581969	Loose Clamp	245		CT-Clamps tested ok
2G1WB58K469	Loose Clamp	21		CT-Clamps tested ok
2G1WB58K069	Loose Clamp	4081		CT-Clamps tested ok
2G1WU581769	Loose Clamp		4608	CT-Clamps tested ok
2G1WB58K369	Loose Clamp	267		CT-Clamps tested ok
2G1WT58K669	Loose Clamp	2		CT-Clamps tested ok
2G1WB58K269	Loose Clamp	3967		CT-Clamps tested ok
2G1WU581269	Loose Clamp		536	CT-Clamps tested ok

Note: Distorted clamps impossible to reproduce failure.