



Automotive Safety Office
Environmental and Safety Engineering

Fairlane Plaza South
330 Town Center Drive
Dearborn, MI 48126-2738 USA

August 27, 2009

Kyle Bowker
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E. W48-312
Washington, D.C. 20590

Dear Mr. Bowker:

Subject: RQ09-002:NVS-213kmb additional information

As you requested in an August 26, 2009, telephone conversation, attached is a CD containing photographs of vehicles related to Ford's Field Service Action (FSA) 07S51, referenced in Ford's August 24, 2009, response to your August 12, 2009, request for additional information. The photographs were obtained from dealers who were repairing vehicles that had previously received the "inspection and grease" portion of the FSA. The filename describes the particular concern with the prior repair.

If you have any questions concerning this response, please feel free to contact me.

Sincerely,

A handwritten signature in black ink that reads "R. A. Nevi".

R. A. Nevi
Assistant Director
Global Automotive Safety Compliance

Attachment

