

November 10, 2010

Mr. Scott Yon, Chief
Vehicle Integrity Division
Office of Defects Investigation
U.S. DEPARTMENT OF TRANSPORTATION
National Highway Traffic Safety Administration
1200 New Jersey Ave., SE
Washington, DC 20590

Re: **PE10-037**
2007-08 Honda Fit
Low beam headlight failure

Dear Mr. Yon:

Please find our response to Q10 for supplier name information.

10. State the number of each of the following that Honda has sold that may be used in subject vehicles by component name, part number (both service and engineering/production), model and model year of the vehicle in which it is used and month/year of sale (*including the cut-off date for sales, if applicable*):
- a) Subject component(s); and
 - b) Any kits that have been released, or developed, by Honda for use in service repairs to the subject component(s)/assemblies.

For each component part number, provide the supplier's name, address, and appropriate point of contact (name, title, and telephone number). Also identify by make, model and model year, any other vehicles of which Honda is aware that contain the identical component(s), whether installed in production or in service, and state the applicable dates of production or service usage.

Response:

Supplier Contact Information

Supplier: Yazaki Parts Co., Ltd
Part name/part number: Instrument wire harness (32117-SLN)
Engine room wire harness (32200-SLN)
Address: 500 Tsukinami Nasukarasuyama Tochigi 321-0593 Japan
TEL: 0287-88-7173
Name: Humihiro Kitamura
Title: Quality Control Div. General Manager

Supplier: Toyo Denso Co., Ltd
Part name/part number: Lighting & turn switch (35255-S5A-A02, 35255-S5K-F12)
Factory: Kameyama Factory
Address: 6-1 Nobono-cho Kameyama Mie 519-0212 Japan
TEL: 0595-85-1151
Name: Atsushi Kinoshita
Title: Quality Control Section Manager

Factory: Shanghai Toyo Denso Co., Ltd
Address: 1988 Rongle East Road, Song-jiang, Shanghai 201613, CHINA
TEL: 021-5774-1132
Name: Noriharu Takeshita
Title: Factory Manager


Supplier: Panasonic Corporation
Part name/part number: Power relay (39794-S04-014)
Address: Omori Bellport E-building 10F
6-22-7 Minamioi Shinagawa-ku Tokyo 140-0013 Japan
TEL: 03-5767-9082
Name: Ken Tanaka
Title: Director

Supplier: Mitsuba Corporation
Part name/part number: Power relay (39794-S04-003)
Address: 1-2681 Hirosawa-Cho Kiryu Gunma 376-8555 Japan
TEL: 0277-52-0246
Name: Hideo Imai
Title: Quality Assurance Div. General Manager

Supplier: Iwata Bolt Co., Ltd
Part name/part number: BOLTEARTH (6x16 Zn) (90148-SE0-003)
Address: 917-1 Kawarada-cho Fujishi Yokkaichi Mie 510-0874 Japan
TEL: 059-347-1941
Name: Takehiro Kato
Title: Deputy Manager

Sincerely,

AMERICAN HONDA MOTOR CO., INC.



Jay Joseph
Senior Manager
Product Regulatory Office

JWJ:nis