



March 25, 2015

To: Cynthia Glass.

Dear Cynthia, I am responding to a request for information regarding EQ 15-003.

As of 3/25/15 Rosenbauer Motors LLC has had no reported incidences of this type of problem in any of our trucks. I have searched our reporting data base and have found no problems with our heater hoses or there components being damaged by over pressurization as described in the Blue Bird documents that we received.

Rosenbauer's system is designed so that there are no exposed heater hoses anywhere within the passenger compartment of our trucks.

Please let me know if you need anything else in regards to this issue.

Respectfully,

Bradley D. Johnson

Warranty and Service Manager

Rosenbauer Motors LLC

[www.rosenbaueramerica.com](http://www.rosenbaueramerica.com)

[info@rosenbaueramerica.com](mailto:info@rosenbaueramerica.com)

ROSENBAUER SOUTH DAKOTA, LLC.  
100 THIRD STREET  
LYONS, SOUTH DAKOTA 57041  
P: 605.543.5591

ROSENBAUER MINNESOTA, LLC.  
5181 260TH STREET  
P.O. BOX 549  
WYOMING, MINNESOTA 55092  
P: 651.462.1000

ROSENBAUER MOTORS, LLC.  
5190 260TH STREET  
P.O. BOX 549  
WYOMING, MINNESOTA 55092  
P: 651.462.1000

ROSENBAUER AERIALS, LLC.  
870 SOUTH BROAD STREET  
FREMONT, NEBRASKA 68025  
P: 402.721.7622