

Occasional Fuel Odor And/Or Fuel Leak

447: GP 47.25

CAUSE / EXPLANATION:

Low pressure Fuel Feed Line to the High Pressure Pump may leak during cold ambient temperatures and a cold engine start. As the engine heats up the line will expand and potentially weep / leak fuel.

CORRECTION:

Replace the fuel feed line with part number; A274 070 01 81.

- A new vendor is supplying the hoses for production and spare parts
- The physical part number of the old and new hose is the same
- PDCs scrapped the old parts stock and made new parts stock available as of 11/1/2016
- New hose will be implemented into production in early January 2017