

Information Case



Customer states the vehicle is leaking fuel

INFORMATION REDACTED
PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C.
552(B)(6)

Case no.
Creation date
Last Edit By

2016-01-07 12.49.18

Vehicle

Vehicle Model	UR1/MB-M1PV126
FIN	
Mileage	0000611
Registration Date	2015-10-23
Engine No.	
Transmission NO.	
Production Date.	2015-08-28
Repair Attempts	0
Total Days Down	2

Dealer

Dealer Data		Contact Person	
Dealer Code	14316	Name	
Name	MERCEDES-BENZ OF TAMPA	Email	
Address	4400 NORTH DALE MABRY HIGHWAY	Phone No	
	FL 33614 TAMPA	Fax No	
	United States	Mobile No	

Attachments

Attached Date	File Name	Descr
2016-01-07	Metris fuel leak.jpeg	Photo of loose fuel line

Symptom

>Power generation>Fuel system>Fuel system leaks>Line leaks

Measures Taken

Date:2018-04-24 11.26
Name:BRABENS Status:Informational
Date:2017-02-24 15.52
Name:GHBAHOU Status:Informational

Date:2016-08-18 10.51
Name:GHBAHOU Status:Informational
Date:2016-04-07 13.32
Name:GHBAHOU Status:Informational
Date:2016-01-07 12.52
Name:D7EHANDL Status:Informational Measures Performed / Technical Question(s): Found fuel line clamp loose (not closed) for connection to the pipe with test port. Parts Replaced: Fuel line clamp
Date:2016-01-07 12.49
Name:D7EHANDL Status:Draft Workshop Findings: Fuel leaking under the vehicle's engine compartment. R&R encapsulation panel and found the Fuel line clamp was never closed for connection to pipe with fuel test connection.

Workshop Findings
Date:2016-01-07 12.49
Name:D7EHANDL Status:Draft Workshop Findings: Fuel leaking under the vehicle's engine compartment. R&R encapsulation panel and found the Fuel line clamp was never closed for connection to pipe with fuel test connection.

Case History
Date:2018-04-24 11.26
Name:BRABENS Status:Informational
Date:2017-02-24 15.52
Name:GHBAHOU Status:Informational
Date:2016-08-18 10.51
Name:GHBAHOU Status:Informational
Date:2016-04-07 13.32
Name:GHBAHOU Status:Informational
Date:2016-01-07 12.52
Name:D7EHANDL Status:Informational Measures Performed / Technical Question(s): Found fuel line clamp loose (not closed) for connection to the pipe with test port. Parts Replaced: Fuel line clamp
Date:2016-01-07 12:52
Name:D7EHANDL Status:Informational Quality Rating: Not Prepared

Date:2016-01-07 12.49

Name:D7EHANDL Status:Draft

Workshop Findings:

Fuel leaking under the vehicle's engine compartment. R&R encapsulation panel and found the Fuel line clamp was never closed for connection to pipe with fuel test connection.

Control Unit/Fault Code

Control Unit	Fault C0de	Description	Part Number	HW Version	SW Version	Diagnostic Variant
--------------	------------	-------------	-------------	------------	------------	--------------------

Group/SubGroup

Group	Sub Group
(47)Fuel system	(25)Lines, hoses

Hand Off

First Contact Attempt	Appointment Date	On Site Date	Confirmed With	Hand off Rating	Hand Off Comment