

Information Case



Mercedes-Benz

Strong odor of gas on cold start.

INFORMATION REDACTED
PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C.
552(B)(6)

Case no.	000089067
Creation date	2016-11-18 13.30.02
Last Edit By	Brandin Benson

Vehicle

Vehicle Model	UR1/MB-M1PV126
FIN	
Mileage	0030542
Registration Date	2016-01-28
Engine No.	
Transmission NO.	
Production Date.	2015-09-29
Repair Attempts	0
Total Days Down	9

Dealer

Dealer Data		Contact Person	
Dealer Code	62133	Name	
Name	MERCEDES-BENZ OF WEST CHESTER	Email	
Address	5897 MUHLHAUSER ROAD	Phone No	
	OH 45069 WEST CHESTER	Fax No	
	United States	Mobile No	

Attachments

Attached Date	File Name	Description
2016-11-18	20161118 131808.jpeg	Location of fuel leak

Symptom

>Power generation>Fuel system>Leakage>Line leaks

Measures Taken

Date:2018-04-24 14.23
Name:BRABENS Status:Informational
Date:2016-12-08 13.34
Name:TBREEDE Status:Informational

Date:2016-11-18 13.55
Name:TBREEDE Status:Informational
Date:2016-11-18 13.30
Name:R6213300 Status:Draft
Workshop Findings:
Rubber fuel hose to high pressure fuel pump leaks/sweats. Only occurs at cooler ambient temperatures (about 45\u00C2\u00B0F and below). Leak goes away after engine warms up. Will not leak at warmer ambient temperatures.
Measures Performed / Technical Question(s):
Have had two vehicles in the shop with this same issue (VIN's: [REDACTED] miles, [REDACTED]
Parts Replaced:
Rubber fuel hose and clamps replaced.

Workshop Findings
Date:2016-11-18 13.30
Name:R6213300 Status:Draft
Workshop Findings:
Rubber fuel hose to high pressure fuel pump leaks/sweats. Only occurs at cooler ambient temperatures (about 45\u00C2\u00B0F and below). Leak goes away after engine warms up. Will not leak at warmer ambient temperatures.

Case History
Date:2018-04-24 14.23
Name:BRABENS Status:Informational
Date:2016-12-08 13.34
Name:TBREEDE Status:Informational
Date:2016-11-18 13.55
Name:TBREEDE Status:Informational
Date:2016-11-18 13.53
Name:TBREEDE Status:Researching
Date:2016-11-18 13.30
Name:R6213300 Status:Draft
Workshop Findings:
Rubber fuel hose to high pressure fuel pump leaks/sweats. Only occurs at cooler ambient temperatures (about 45\u00C2\u00B0F and below). Leak goes away after engine warms up. Will not leak at warmer ambient temperatures.
Measures Performed / Technical Question(s):
Have had two vehicles in the shop with this same issue (VIN's: [REDACTED] miles, [REDACTED]
Parts Replaced:
Rubber fuel hose and clamps replaced.

Condition Data
When:
Intermittent

Cold

Control Unit/Fault Code						
Control Unit	Fault C0de	Description	Part Number	HW Version	SW Version	Diagnostic Variant

Group/SubGroup	
Group	Sub Group
(07)Mixture formation	(03)Injection jets, Injection valves, Lines

Hand Off					
First Contact Attempt	Appointment Date	On Site Date	Confirmed With	Hand off Rating	Hand Off Comment