

**Quality Monitoring Report**

<b>QMR Id</b> QMR1-[REDACTED]	<b>Created By</b> bro1	<b>Report Date</b> 09/28/2017	<b>Last Updated</b> 09/28/2017	<b>Reg-Zn-Dst</b> [REDACTED]	<b>Dealer</b> 040238
<b>Section</b> Electrical	<b>Sub Section</b> SRS Airbag & Pretentioners				
<b>VIN</b> JF2SJAEC7H-[REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 11846		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 09/28/2017	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> N		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					
<b>DTC Code(s)</b> B1650					
<b>Reporter Name</b> Brent Roberts	<b>Reporter Email</b> bro1@subaru.com	<b>Reporter Phone Number</b> 2562806906			

**Customer's Description of Complaint**

C/S airbag light is on.

**Technician's Findings and Repair**

FSE was asked to assist with QRA with supplier and NASI. On inspection the B1650 code was in history and not an active code. An inspection revealed no fault. FSE and NASI test drove vehicle for between 5 and 10 miles to determine if the DTC would return. No codes were set. No further action being taken at this time. A TR will be issued.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJAEC7H-[REDACTED]	<b>Warranty Start Date</b> 08/19/2016	<b>Production Date</b> 05/17/2016	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2017	<b>Model Code</b> HFF
<b>Color</b> CBS	<b>Options</b> 13	<b>Emission Spec</b> C	<b>Turbo</b> N
<b>Engine Size</b>	<b>Original Trans #</b> [REDACTED]		

2.5

---