

Quality Monitoring Report



QMR Id QMR1- [REDACTED]	Created By jsha	Report Date 12/14/2017	Last Updated 12/14/2017	Reg- Zn-Dst [REDACTED]	Dealer 040731
Section Body	Sub Section Front Seat				
VIN JF2SJAJC8HH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 9370		
Failure Code [REDACTED]	Failure Date 12/02/2017	Failed Part # 64139SG160LL	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650					

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number [REDACTED]
------------------------------------	---	--

Customer's Description of Complaint

Air bag light on

Technician's Findings and Repair

During FSE visit FSE found this part in the parts department. FSE interviewed technician and verified he knows of the new bulletin 07-108-16R. Technician will follow the bulletin before replacing the seat bottom.

Attachments

No Attachments Found

VIN Remainder JF2SJAJC8HH [REDACTED]	Warranty Start Date 11/28/2016	Production Date 09/09/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFI
Color QBP	Options 21	Emission Spec C	Turbo N
Engine Size	Original Trans # [REDACTED]		

2.5
