

Quality Monitoring Report



QMR Id QMR1- [REDACTED]	Created By ahil5705	Report Date 09/11/2018	Last Updated 09/11/2018	Reg- Zn-Dst [REDACTED]	Dealer 020234
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN JF2SJALC8H [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 34113		
Failure Code [REDACTED]	Failure Date 09/11/2018	Failed Part # --	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					

DTC Code(s)
B1650

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --
------------------------------------	-------------------------------------	------------------------------------

Customer's Description of Complaint

Customer states Airbag warning light is on.

Technician's Findings and Repair

Found TSB 07/108-16R. Perform Pinpoint test as per TSB. Check connector for poor contact. None found. Checked Air Bag harness with Test harness1AG with 6AG. Pin number 9 and pin 1. At 6AG pin 11 and pin 2 found 5 ohms. Test OK. Check 6AG harness pins 9 -11 to chassis ground 1.8M ohms. Test OK. Test harness 2AP pin 3 and chassis ground 12.4 V. OK. Checked Battery voltage OK 12.5. Cleared Memory Recheck for codes. No codes found at this time.

Attachments

No Attachments Found

VIN Remainder JF2SJALC8HH [REDACTED]	Warranty Start Date 07/29/2016	Production Date 05/28/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFI
Color DGM	Options 22	Emission Spec C	Turbo N

Engine Size

Original Trans #

2.5

