

Very faint stain on
seat caused by
fluid spill

