

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

**Quality Monitoring Report**

<b>QMR Id</b> QMR1- [REDACTED]	<b>Created By</b> sdcjpyl	<b>Report Date</b> 10/26/2018	<b>Last Updated</b> 10/26/2018	<b>Reg- Zn-Dst</b> [REDACTED]	<b>Dealer</b> 020198
<b>Section</b> Electrical	<b>Sub Section</b> SRS Airbag & Pretentioners				
<b>VIN</b> JF2SJAEC4JH [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 17146		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 10/10/2018	<b>Failed Part #</b> 64139SG060LL	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					
<b>DTC Code(s)</b> B1650, B1760					

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --
------------------------------------	-------------------------------------	--

**Customer's Description of Complaint**

Customer states that the passenger airbag warning light intermittently comes on when someone is sitting in the passenger seat

**Technician's Findings and Repair**

Technician inspected and found that warning light would come on when sitting in passenger seat. SRS DTC B1650 and ODS B1760 were current. Technician confirmed seat cushion was dry and not exposed to high humidity. Passenger seat connections were inspected, and no poor contact was present. Retailer order seat cushion

**Attachments**

[REDACTED]

<b>VIN Remainder</b> JF2SJAEC4J [REDACTED]	<b>Warranty Start Date</b> 07/27/2017	<b>Production Date</b> 05/23/2017	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2018	<b>Model Code</b> JFF
<b>Color</b>	<b>Options</b>	<b>Emission Spec</b>	<b>Turbo</b>

JGM

13

C

N

**Engine Size**

**Original Trans #**

2.5

