

Quality Monitoring Report

QMR Id QMR1 [REDACTED]	Created By ostran	Report Date 02/19/2019	Last Updated 02/19/2019	Reg- Zn- Dst [REDACTED]	Dealer 401897
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN JF2SJAGCXJ [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 6592		
Failure Code [REDACTED]	Failure Date 01/15/2019	Failed Part # 64139SG060LL	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650, B1826					
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --			

Customer's Description of Complaint

Customer states the airbag light is illuminated.

Technician's Findings and Repair

Technician inspected vehicle and verified customer concern. Vehicle has current code for B1650 and B1826 in history. Service director informs FSE during retailer visit that this occurred after the vehicle had the cloth removed and leather installed. FSE advised retailer that this would not be a warrantable repair in which it was understood. Service director inquired about the lengthy backorder in which he was instructed to complete an URFCAs due to the backorder status.

Attachments

No Attachments Found

VIN Remainder JF2SJAGCXJH [REDACTED]	Warranty Start Date 08/30/2018	Production Date 06/26/2018	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2018	Model Code JFF
Color	Options	Emission Spec	Turbo

JGM

14

C

N

Engine Size

Original Trans #

2.5

