

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By rontko	Report Date 05/21/2019	Last Updated 05/21/2019	Reg- Zn- Dst [REDACTED]	Dealer 140668
Section Body	Sub Section Front Seat				
VIN JF2SJADC3 [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 40212		
Failure Code [REDACTED]	Failure Date 04/23/2019	Failed Part # 64139SG002VH	Technician [REDACTED]	Duplicated Condition? Y	
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
					Property Damage N

DTC Code(s)
B1650

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number [REDACTED]
------------------------------------	-------------------------------------	--

Customer's Description of Complaint

customer states airbag light is on

Technician's Findings and Repair

Code 1650 Followed TSB #07-108-16R Seat bottom and module need to be replaced. Replaced seat bottom. Airbag light went off. No codes.

Attachments

No Attachments Found

VIN Remainder JF2SJADC3GH [REDACTED]	Warranty Start Date 06/17/2016	Production Date 11/26/2015	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2016	Model Code GFF
Color BBM	Options 13	Emission Spec C	Turbo N
Engine Size	Original Trans #		

2.5

