

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By sdcjcol	Report Date 07/08/2019	Last Updated 07/08/2019	Reg- Zn- Dst [REDACTED]	Dealer 020165
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN JF2SJAWC6HH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 18994		
Failure Code [REDACTED]	Failure Date 06/28/2019	Failed Part # --	Technician Duplicated Condition? N		
R/O Number --	Rollover N	Fire N	Accident N	Injury N	Death N
[REDACTED]					Property Damage N
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number 8455218739			

Customer's Description of Complaint

Customer states air bag light is on again.

Technician's Findings and Repair

Airbag light not on when tech got to vehicle. Tech found DTC's B1650 and B1750 in history. Tech found debris under pass seat. Performed TSB 07-108-16r and found condition has returned to normal and no faults were found. SM has decided to replace pass seat bottom for customer satisfaction due to airbag light coming on twice.

Attachments

No Attachments Found

VIN Remainder JF2SJAWC6HH [REDACTED]	Warranty Start Date 06/14/2017	Production Date 04/19/2017	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFJ
Color SBM	Options 34	Emission Spec C	Turbo N

Engine Size

Original Trans #

2.5

