

CHEVROLET
 7300 S. 27th Street
 Lincoln, Nebraska 68512
 Phone: 402-420-3300
 Fax: 402-420-3399

DUTEAU
Driven by you.

SUBARU
 2750 Jamie Lane
 Lincoln, Nebraska 68516
 Phone: 402-420-4650
 Fax: 402-420-4679

RECOMMENDED SERVICES

OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL	OPERATION	OPERATION DESCRIPTION	MO/MI	TOTAL

SERVICE HISTORY

DATE	REPAIR ORDER	MILEAGE	ADVISOR	TECHNICIAN	TYPE	OPERATION	OPERATION DESCRIPTION
03/28/17	[REDACTED]	19306	1202	1135	W	26CVZ1DRIVE	DRIVEABILITY/CEL
02/02/17	[REDACTED]	18014	1195	1135	C	26CVZ1ELECTRIC	ELECTRICAL
				1135	C	26CVZ0INSPECT	INSPECTION & RECS
				1213	C	25CVZEXPSYNROT	5000 SYN MAINTENANCE
				1223	C	25CVZSESINSP	EXPRESS MPI
				1225	C	25CVXEXPCABINFI	REPLACE CABIN FILTER

SALESPERSON NO.

S E R V I C E

STATE REG# DDDDDD

TERMS	VEHICLE ID NO. JF2SJADC4G	YEAR/MAKE/MODEL 16/SUBARU/FORESTER/4DR 2.5I PREM AT	PRODUCTION DATE	STOCK NO.	LICENSE NO. TMI818
CASH <input type="checkbox"/>	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
CREDIT CARD <input type="checkbox"/>	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
CHCK <input type="checkbox"/>	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
PRIOR APPROVAL <input type="checkbox"/>	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
OTHER <input type="checkbox"/>	LINCOLN, NE [REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
CALL WHEN READY <input type="checkbox"/> YES <input type="checkbox"/> NO	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
SAVE REMOVED PARTS FOR CUSTOMER <input type="checkbox"/> YES <input type="checkbox"/> NO	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]
APPOINTMENT <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	04:31pm	05/02/17	06:15pm	PRIORITY	LABOR RATE 114.00

1 W*26CVZ1TRIM INT/EXT TRIM
 INSTALL PASSENGER SEAT BOTTOM PER PREVIOUS DIAGNOSIS.

1135 .2 913411
 .5 913417
 (17) YMA43

Z.I Loaner

ABS system erratic operation.

Replaced seat vented operation.


BIT60 code present and would reset.
 Nothing was found wet and all connectors tested ok. TSB 07-08-16 flow chart attached.

631349

Evidence of rust seen on the seat frame



B1760 FLOW CHART



IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.