

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By cber1564	Report Date 07/13/2017	Last Updated 07/13/2017	Reg-Zn-Dst [REDACTED]	Dealer 040950
Section Electrical	Sub Section Air Bag				
VIN JF2SJGEC6HH [REDACTED]	Engine # --	Trans # --	Mileage 7562		
Failure Code [REDACTED]	Failure Date 07/12/2017	Failed Part # --	Technician Duplicated Condition? N		
R/O Number [REDACTED]	Rollover N	Fire N	Accident Injury Death N N N	Property Damage N	
DTC Code(s) B1650					

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --
------------------------------------	-------------------------------------	------------------------------------

Customer's Description of Complaint

Air bag off light comes on with someone in the seat.

Technician's Findings and Repair

B1650 set 3rd time this code has set. The seat bottom was dry and all connections looked good to the seat bottom. Pin fitment was tight in SRS connectors to ODS. Replaced the seat bottom.

Attachments

No Attachments Found

VIN Remainder JF2SJGEC6HH [REDACTED]	Warranty Start Date 11/15/2016	Production Date 09/02/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFM
Color CBS	Options 16	Emission Spec C	Turbo Y
Engine Size	Original Trans # [REDACTED]		

