

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By ostran	Report Date 07/18/2017	Last Updated 07/18/2017	Reg-Zn-Dst [REDACTED]	Dealer 070283
Section Electrical	Sub Section Air Bag				
VIN JF2SJAEC2HH [REDACTED]	Engine # --	Trans # --	Mileage 152		
Failure Code [REDACTED]	Failure Date 04/24/2017	Failed Part # 64139SG060LL	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650, B1795					
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --			

Customer's Description of Complaint

Customer states air bag light is on. Customer states passenger side air bag always says off.

Technician's Findings and Repair

Note: Part was found during routine warranty 10 bin inspection. Technician verified concern. Technician found codes B1650 and B1795. Technician found TSB 07-108-16 and followed flow chart. Results were to replace seat bottom assembly. Technician removed and replaced seat bottom assembly, system is working as designed. No FF data captured, No TT results attached to RO. TR with part collection will be issued.

Attachments

No Attachments Found

VIN Remainder JF2SJAEC2HH [REDACTED]	Warranty Start Date 04/21/2017	Production Date 11/30/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFF
Color	Options	Emission Spec	Turbo

IS1

13

C

N

Engine Size

Original Trans #

2.5

