

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By dzwa	Report Date 08/21/2017	Last Updated 08/21/2017	Reg-Zn-Dst [REDACTED]	Dealer 040690
Section Electrical	Sub Section Air Bag				
VIN JF2SJAGC4GH [REDACTED]	Engine # --	Trans # --	Mileage 14230		
Failure Code [REDACTED]	Failure Date 08/01/2017	Failed Part # 64139SG002LL	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650, B1760					
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --			

Customer's Description of Complaint

C/S airbag light is on.

Technician's Findings and Repair

Tech verified the condition. Tech found DTC B1650, B1760 set. Tech followed TT and determined the seat cushion need to be replaced. Tech did not save DTC or TT results. FSE found this part during 10-bin inspection. There were no signs of liquid spilled on the seat cushion or signs of surface rust on the underside of the seat. Part is being collected and returned to the PCC. TR issued.

Attachments

[REDACTED]

VIN Remainder [REDACTED]	Warranty Start Date 02/20/2016	Production Date 12/15/2015	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2016	Model Code GFF
Color	Options	Emission Spec	Turbo

DGM

15

C

N

Engine Size

Original Trans #

2.5

