

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By ewalke	Report Date 08/31/2017	Last Updated 08/31/2017	Reg-Zn-Dst 050-01-04	Dealer [REDACTED]
Section Electrical	Sub Section Air Bag				
VIN JF2SJADCXG [REDACTED]	Engine # --	Trans # --	Mileage 32378		
Failure Code [REDACTED]	Failure Date 08/23/2017	Failed Part # 81502SG712	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident Injury N	Death N	Property Damage N
DTC Code(s) B1650					
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --			

Customer's Description of Complaint

Customer states that the Air bag Light was on but off now.

Technician's Findings and Repair

The Tech called me and told me he had a B1650 stored in a Forester. He asked what the issue was that I had covered on my conference call. I told him we were looking for Passenger Side Seat Cushions setting a B1650. He informed me the vehicle he was working on also had a B1650 but the Rear SRS harness resistance was Low. Instead of 1M Ohms his was .85M Ohms. Based on the vehicle concern I told him this was not the issue I was pursuing but thanked him for the information.

Attachments

[REDACTED]

VIN Remainder JF2SJADCXG [REDACTED]	Warranty Start Date 02/15/2016	Production Date 11/05/2015	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2016	Model Code GFF
Color ISM	Options 13	Emission Spec C	Turbo N

Engine Size

Original Trans #

2.5

