

Quality Monitoring Report



| | | | | | |
|--------------------------------------|-------------------------------------|------------------------------------|--|---------------------------------|-----------------------------|
| QMR Id QMR [REDACTED] | Created By rml13668 | Report Date 09/12/2017 | Last Updated 09/12/2017 | Reg-Zn-Dst [REDACTED] | Dealer 040103 |
| Section Electrical | Sub Section Air Bag | | | | |
| VIN JF2SJAGCXHH [REDACTED] | Engine # -- | Trans # -- | Mileage 20979 | | |
| Failure Code [REDACTED] | Failure Date 08/28/2017 | Failed Part # -- | Technician Duplicated Condition? N | | |
| R/O Number [REDACTED] | Rollover N | Fire N | Accident N | Injury N | Death N |
| | | | | | Property Damage N |
| DTC Code(s) B1650 | | | | | |
| Reporter Name [REDACTED] | Reporter Email [REDACTED] | Reporter Phone Number -- | | | |

Customer's Description of Complaint

customer states air bag was on but not on now

Technician's Findings and Repair

air bag light was on found code b1650 logged into history this code is generated by havin g, a electronic device chargingin passenger seat. The current generated by device charging triggers the fault code, will advise customer of this.

Attachments

No Attachments Found

| | | | |
|--|---|--------------------------------------|-----------------------------|
| VIN Remainder JF2SJAGCXHH [REDACTED] | Warranty Start Date 09/28/2016 | Production Date 08/02/2016 | Car Line Forester |
| Original Engine # [REDACTED] | Trans. Type Desc Continuously Variable Transmission | Model Year 2017 | Model Code HFF |
| Color DGM | Options 14 | Emission Spec C | Turbo N |
| Engine Size 2.5 | Original Trans # [REDACTED] | | |

