

Vehicle Information

VIN: [REDACTED] Model: CK15753-2015 SILVERADO 1500 DOUBLE CAB CAB 4WD
Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes
Order Type: 70 - RETAIL - STOCK
Field Actions: [Open](#) [REQUEST ANOTHER VIN](#)

Job Card Date: 12/02/2019 Job Card Number: [REDACTED] **Transaction Detail**

Repair Service Agent: [REDACTED] Odometer Reading: 57,226 MI
WINDY CHEVROLET INC. Authorization Code:
1008 CANYON RD
ELLENSBURG WA 98926-4107

Process Date:
12/02/2019
Transaction Type:
ZREG---Regular Vehicle
Transaction
Transaction Expense Category:
Special Policy
Customer Complaint Code:
0828-Interior - Seats (Fit and
Finish)

Job Card Line #: 1 Transaction Adjustment: Cause Code: 6017-Module/Component -
Broken

Labour Op 9900530-18128 - Replace Front Seat Belt Anchor Plate Tensioner and Cushion Outer Finish Cover
(Includes Ined
Causal Part Number 00000000019356262-TENSIONER KIT,D/SEAT BELT (RETR SI)
→See other Parts and/or Nel Items Line Total: USD 299.68

Parts Return Status

Project ID: [REDACTED] Request Nbr: [REDACTED]

Complaint/Cause/Correction
Complaint: 0828 - Interior - Seats (Fit and Finish)

CUSTOMER STATES THE LEFT SEAT BELT IS BROKEN, S.O.P IS HERE

Cause: 6017 - Module/Component - Broken

BODY ELECT CONCERN

Correction:

R&R DRIVER SIDE SEAT BELT PRETENSIONER AND COVER. LOP 9900529 .60
SPECIAL COVERAGE #18128