

# Repair Order Detail - Internal Copy

RO Number

RO Status: CLOSED

Customer:

Phone(s):

Vehicle:

Main:

2016 CHU613

[Click to View Cust Copy](#)

Cell:

Mileage: 322,034

Service advisor: 11

Tag number:

Payment type: CHG

Promised date: 11/17/2018

Waiter: No

Estimate: 0.00

Customer Comments: No

## A FULL SERVICE, CHECK LIGHTS, GEAR BOXES, AIR FILTER & GREASE CHASSIS

|    |    |                                                                     |      |        |
|----|----|---------------------------------------------------------------------|------|--------|
| FS | CM | FULL SERVICE, CHECK LIGHTS, GEAR BOXES, AIR FILTER & GREASE CHASSIS | 1.50 | 149.25 |
|----|----|---------------------------------------------------------------------|------|--------|

Tech(s): 38

B76

2 FILTER

11.18

B7409

1 FILTER

12.70

BF7943

1 FILTER

10.32

PF7930

1 FILTER

13.28

DL-15W40

40 OIL, QT

108.80

DL-GREASE

2 MULTI PURPOSE EP2 LB

7.16

21882786

1 AIR CLEANER

10.48

RS4634

1 FILTER

39.27

Pts: 213.19 Lbr: 149.25 Other: 0.00 Total Line A: 362.44

## B PLUG INTO TRUCK AND CHECK CODES

|      |    |                    |      |       |
|------|----|--------------------|------|-------|
| DIAG | CM | GENERAL DIAGNOSTIC | 0.50 | 49.75 |
|------|----|--------------------|------|-------|

Tech(s): 38

SDF

SOFTWARE DIAG FEE

75.00

22327069

1 SOLENOID

419.03

Pts: 419.03 Lbr: 49.75 Other: 75.00 Total Line B: 543.78

Story: 322034 PLUGGED INTO TRUCK READ CODES HAD CLUTCH CODE FOR SLOW ENGAGEMENT DID GUIDED DIAGNOSTICS ON CODE SAID REPLACE OUTSIDE CONTROL FOR CLUTCH. REPLACED CONTROL VALVE.

RECALIBRATE CLUTCH, DROVE AROUND BUILDING, LIGHT CAME BACK ON TRUCK DOES NOT PUSH THROUGH BRAKES ANYMORE. ITS JUST SLOW GOING INTO GEAR AND SLOW GEAR CHANGES.

## C CHECK CAUSE FOR AIR LEAK

|    |    |                 |      |        |
|----|----|-----------------|------|--------|
| GR | CM | GENERAL REPAIRS | 2.40 | 238.80 |
|----|----|-----------------|------|--------|

Tech(s): 38

8116\*91234\*

2 3/8T X 3/8P

24.04

PRESTOMATIC A

Pts: 24.04 Lbr: 238.80 Other: 0.00 Total Line C: 262.84

Story: 322034 FOUND 2 AIR FITTINGS ON FIRE WALL LEAKING AIR REPLACED BOTH FITTINGS.

Customer Pay

Labor

437.80

Parts

656.26

Lube

0.00

Sublet

0.00

# Repair Order Detail - Internal Copy

|                           |          |
|---------------------------|----------|
| Miscellaneous/Shop Charge | 105.65   |
| Deductible                | 0.00     |
| Total Charges             | 1,199.71 |
| Less Insurance/Adjustment | 0.00     |
| Sales Tax                 | 83.99    |
| Total                     | 1,283.70 |