

SS 3497 Cascadia Windshield Leaks

See SB 60-144

If a windshield leak is detected, use the attached document as a guide for determining the proper repair procedure.

Refer to Service Solution 3495 for information about identifying potential leak locations.

If any one of these repairs are completed in conjunction with the FL545 Recall, the required parts and materials, and up to the below listed amount of T-time may be included on the claim, using SRT code 996-0000T. Only one of these procedures may be included on your claim.

1. Remove and replace lockstrip: 0.2 hours.
2. Spot repair windshield seal bond and R&R lockstrip: 0.3 hours.
3. Remove and replace windshield seal: 2.5 hours.

If leak repairs are performed and included on your FL545 claim, be prepared to provide a detailed description of the repairs, if requested.

Solution ID: 3497