



Engine Support



CA503 : VEHICLE SERVICES | Wednesday, May 25, 2022

DANIEL LEE | Logout

[Help](#) | [Contacts](#) | [Dealer List](#) | [Site Map](#)

1-866-4-DEALER (1-866-433-2537)

[SALES](#)[SERVICE](#)[PARTS](#)[TRAINING](#)[RESOURCES](#)

Search this site...

[HMA Dealer Portal](#) ▶ [Message View](#)[Back](#)**Service Campaign T3G: Theta GDI Engine DTC P1326 – Engine Inspection/Replacement REVISION****Posted Date:** 11/03/2021 | **Dept:** All Departments

- [21-01-066H - Theta Engine P1326 Campagn T3G REVISION.pdf](#)
- [21-01-067H - Op Code-Part Number Reference T3G REVISION_FINAL.pdf](#)
- [21-EM-004H-1 - Bearing Clearance Test Service Procedure \(Enhanced\).pdf](#)
- [T3G Claim Submission Process Training 11.3.2021.pdf](#)
- [T3G Dealer Best Practice 11.3.2021.pdf](#)

Hello all,

Great news! – HMA is pleased to announce an increase in labor times associated with the T3G Theta Engine TSB where a BCT test has been performed for the following situations:

- Additional op time of **0.3 M/H** has been added to applicable labor operations where a BCT Test has been completed & the result is 'NO PASS'.
- Additional op time of **0.6 M/H** has been added to applicable labor operations where a BCT Test has been performed (but could not completed) and the result is 'NO BCT'.
- Additional op time of **0.6 M/H** has been added to applicable labor operations where a BCT Test has been completed, the result is 'PASS', and Abnormal Engine Noise is heard (engine knocks).

Please see attached documents:

- [Updated Dealer Best Practice](#)
- [Claim Submission Process Training](#)
- [Updated T3G TSB](#)
- [Updated T3G Op Code/ Parts Number TSB](#)
- [BCT Clearing Procedure Enhanced TSB](#)

Thank you,
Service Process Team