

This report is also valid for:

LJ8T-14K147-AB (36-487)

NZ6T-14K147-AA (36-490, not launch MY-21)

Regards,



Óscar Omar Estrada Lazcano

Mechanical Design Engineer
Stoneridge, Inc.

stoneridge.com



Tap to call in from a mobile device (attendees only)

[+1-313-248-3668](tel:+13132483668) FordNet 248-3668 / Toll

[+1-888-628-3668](tel:+18886283668) US Toll Free Number

[Global call-in numbers](#) | [Toll-free calling restrictions](#)

Join from a video system or application

Dial 710386007@ford.webex.com

You can also dial 173.243.2.68 and enter your meeting number.

If you are a host, [go here](#) to view host information.

NOTICE: *This meeting may include the option for video. The recording of meetings is prohibited. For company policies on using video:* [click here](#)

For additional help with WebEx, Ford users can click on the Digital Worker link: [WebEx Support](#)

Can't join the meeting? [Contact support.](#)

T32MC04



Flipper Switches - New Tool Replacement for Bases

Stoneridge

Thank you!





Óscar Omar Estrada Lazcano

*Mechanical Design Engineer
Stoneridge, Inc.*

stoneridge.com



Meeting number (access code): 710 386 007

Join by phone

Tap to call in from a mobile device (attendees only)

[+1-313-248-3668](tel:+13132483668) FordNet 248-3668 / Toll

[+1-888-628-3668](tel:+18886283668) US Toll Free Number

[Global call-in numbers](#) | [Toll-free calling restrictions](#)

Join from a video system or application

Dial [710386007](tel:710386007)@ford.webex.com

You can also dial 173.243.2.68 and enter your meeting number.

If you are a host, [go here](#) to view host information.

NOTICE: This meeting may include the option for video. The recording of meetings is prohibited. For company policies on using video: [click here](#)

For additional help with WebEx, Ford users can click on the Digital Worker link: [WebEx Support](#)

Can't join the meeting? [Contact support](#).

T32MC04



Flipper Switches - New Tool Replacement for Bases

Stoneridge

Thank you!



11