

One Pager – Safety Recall 211/009G: Seat Belt Pretensioner**2021 Hyundai Elantra/Elantra HEV, 2021 Hyundai Venue****2021 Genesis GV70/GV80****1. Executive Summary:**

Hyundai is initiating recall campaign 211/009G, a safety recall to repair a condition involving the driver's side seat belt pretensioner in certain Hyundai/Genesis vehicles in the U.S. and Canada. Hyundai is conducting this action to ensure the safety of its vehicles for Hyundai/Genesis customers.

2. Condition:

The driver's side seat belt pretensioners in the subject vehicles were installed from a suspect production lot containing pyrotechnic-type pretensioners that may deploy abnormally during a crash. An abnormal pyrotechnic pretensioner deployment could cause metal fragments to enter the vehicle occupant compartment, which may result in injury to vehicle occupants. At the time of this filing, the cause of the abnormal deployment is unknown. Hyundai is recalling vehicles equipped with pretensioners produced within the same production lot to conduct a detailed part return analysis. The part inspections and investigation will actively continue to determine if a specific root cause and defect trend exists.

3. Affected Number of Vehicles:

Approximately 978 total vehicles produced for sale in the U.S. are affected including:

- 323 model year 2021 Hyundai Elantra/Elantra HEV vehicles;
- 208 model year 2021 Hyundai Venue vehicles;
- 195 model year 2021 Genesis GV80 vehicles;
- 252 model year 2021 Genesis GV70 vehicles;

Affected vehicles in the Canadian market is still being determined.

4. Crashes/Injuries/Fires:

Hyundai is aware of one (1) related injury from one (1) crash event in the U.S.

5. Date of Determination:

October 6, 2021

6. Target Date for 573 Notification:

October 13, 2021

7. Stop Sale?

A "stop sale" will be issued in accordance with federal regulation for affected vehicles unsold at dealers. The stop sale will commence with the filing of the 573 to NHTSA.

8. Media Information

No, however Hyundai will have a statement prepared for any media inquiries.

9. Remedy Information:

All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Hyundai dealer to have the seat belt pretensioner replaced. This remedy will be offered at no cost for all affected customers. All returned pretensioners will be collected for further analysis into root cause.