
One Pager – Safety Recall 220: Seat Belt Pretensioner
2022 Hyundai Elantra/Elantra HEV**1. Executive Summary:**

Hyundai is initiating recall campaign 220, a safety recall to repair a condition involving the driver's side seat belt pretensioner in certain Hyundai vehicles in the U.S. and Canada. Hyundai is conducting this action to ensure the safety of its vehicles for Hyundai customers.

2. Condition:

The front passenger-side seat belt pretensioners in the subject vehicles were installed from a suspect production lot containing pyrotechnic-type pretensioners that may deploy abnormally during a crash. An abnormal pyrotechnic pretensioner deployment could cause metal fragments to enter the vehicle occupant compartment, which may result in injury to vehicle occupants. At the time of this filing, the cause of the abnormal deployment is unknown. Hyundai is recalling vehicles equipped with pretensioners produced within a certain production lot to conduct a detailed part return analysis. The part inspections and investigation will actively continue to determine if a specific root cause and defect trend exists.

3. Affected Number of Vehicles:

Approximately 140 total vehicles produced for sale in the U.S. are affected including:

- 129 model year 2022 Hyundai Elantra vehicles;
- 11 model year 2022 Hyundai Elantra HEV vehicles;

Approximately 278 total vehicles produced for sale in Canada are affected including:

- 223 model year 2022 Hyundai Elantra vehicles;
- 56 model year 2022 Hyundai Elantra HEV vehicles;

4. Crashes/Injuries/Fires:

Hyundai is aware of one (1) related injury from one (1) crash event in Singapore involving a vehicle equipped with pretensioners from the suspect production lot.

5. Date of Determination:

February 24, 2022

6. Target Date for 573 Notification:

March 3, 2022

7. Stop Sale?

A "stop sale" will be issued in accordance with federal regulation for affected vehicles unsold at dealers. The stop sale will commence with the filing of the 573 to NHTSA.

8. Media Information

No, however Hyundai will have a statement prepared for any media inquiries.

9. Remedy Information:

All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Hyundai dealer to have the seat belt pretensioner replaced. This remedy will be offered at no cost for all affected customers. All returned pretensioners will be collected for further analysis into root cause.