

Article Number: 49200
Article Type: S
Author: DSMITH48
Global Concern Number: E05-2019-0006

Market(s):

Area Code	Geo Sales Area	Date of Activation	Date of Deactivation
NA	***	09/23/2020	04/07/2021
WD	ABW	09/23/2020	04/07/2021
WD	AIA	09/23/2020	04/07/2021
WD	ANT	09/23/2020	04/07/2021
WD	ATG	09/23/2020	04/07/2021
WD	BHS	09/23/2020	04/07/2021
WD	BLZ	09/23/2020	04/07/2021
WD	BMU	09/23/2020	04/07/2021
WD	BRB	09/23/2020	04/07/2021
WD	CRI	09/23/2020	04/07/2021
WD	CUB	09/23/2020	04/07/2021
WD	CYM	09/23/2020	04/07/2021
WD	DMA	09/23/2020	04/07/2021
WD	DOM	09/23/2020	04/07/2021
WD	GRD	09/23/2020	04/07/2021
WD	GTM	09/23/2020	04/07/2021
WD	HND	09/23/2020	04/07/2021
WD	HTI	09/23/2020	04/07/2021
WD	JAM	09/23/2020	04/07/2021
WD	KNA	09/23/2020	04/07/2021
WD	LCA	09/23/2020	04/07/2021
WD	MSR	09/23/2020	04/07/2021
WD	MTQ	09/23/2020	04/07/2021
WD	NIC	09/23/2020	04/07/2021
WD	PAN	09/23/2020	04/07/2021
WD	PRI	09/23/2020	04/07/2021
WD	SLV	09/23/2020	04/07/2021
WD	SPM	09/23/2020	04/07/2021
WD	TCA	09/23/2020	04/07/2021
WD	TTO	09/23/2020	04/07/2021
WD	UMI	09/23/2020	04/07/2021
WD	VCT	09/23/2020	04/07/2021
WD	VGB	09/23/2020	04/07/2021
WD	VIR	09/23/2020	04/07/2021

Title:

2018-2019 EcoSport - 1.0L EcoBoost Engine Built On Or Before 3-Apr-2019 - 6F15 - Illuminated Engine Oil Warning Lamp With Loss Of Engine Oil Pressure

Text:

Some 2018-2019 EcoSport vehicles equipped with a 1.0L EcoBoost with an engine build date on or before 3-Apr-2019 and a 6F15 automatic transmission may exhibit an illuminated oil pressure warning lamp with a loss of engine oil pressure. This may be due to an engine oil pump belt tensioner which leads to a loss of engine oil pressure. Due to the nature of this failure, an engine replacement may be required. Engines built after 3-Apr-2019 should not be affected.

Vehicles:

2018-2019 EcoSport B515 India (BW)

Symptom Code:

Global Customer Symptom Codes:

Category	Q1	Q2	Q3	Full Code
Start/Run/Move				4*****
Start/Run/Move	Starting			440***
Start/Run/Move	Starting	No Crank		4401**
Start/Run/Move	Starting	No Crank		440100
Start/Run/Move	Starting	Cranks Wont Start		4403**
Start/Run/Move	Starting	Cranks Wont Start		440300
Start/Run/Move	Starting	Cranks Wont Start	Always	440302
Start/Run/Move	Starting	Cranks Wont Start	Intermittent	440339
Start/Run/Move	Starting	Hard Start/Long Crank		4407**
Start/Run/Move	Starting	Hard Start/Long Crank		440700
Start/Run/Move	Starting	Hard Start/Long Crank	Always	440702
Start/Run/Move	Starting	Not Listed		440Z**
Start/Run/Move	Starting	Not Listed		440Z00
Start/Run/Move	Running			441***
Start/Run/Move	Running			4410**
Start/Run/Move	Running			441000
Start/Run/Move	Noise			448***
Start/Run/Move	Noise			4480**
Start/Run/Move	Noise			448000
Start/Run/Move	Noise	Moving/Driving		4482**
Start/Run/Move	Noise	Moving/Driving	Always	448202
Driving Performance				5*****
Driving Performance	Runs Rough			550***
Driving Performance	Runs Rough			5500**
Driving Performance	Runs Rough			550000
Driving Performance	Runs Rough	All Running Modes		550A**
Driving Performance	Runs Rough	All Running Modes	Always	550A02
Driving Performance	Stalls/Quits			552***
Driving Performance	Stalls/Quits			5520**
Driving Performance	Stalls/Quits			552000
Driving Performance	Lack/Loss of Power			554***
Driving Performance	Lack/Loss of Power			5540**
Driving Performance	Lack/Loss of Power			554000
Driving Performance	Lack/Loss of Power	Not Listed		554Z**
Driving Performance	Lack/Loss of Power	Not Listed		554Z00

Audit Comments:

Area Code	Geo Sales Area	Comment	Old Date of Deactivation	New Date of Deactivation	CDSID
NA	***	GSMITH LOADED MESSAGE:067-2020-3444::ADD	01/01/1900	09/22/2024	GSMITH
NA	***	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH
WD	ABW	GSMITH LOADED MESSAGE:067-2020-3444::ADD	01/01/1900	09/22/2024	GSMITH
WD	ABW	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH
WD	AIA	GSMITH LOADED MESSAGE:067-2020-3444::ADD	01/01/1900	09/22/2024	GSMITH
WD	AIA	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH
WD	ANT	GSMITH LOADED MESSAGE:067-2020-3444::ADD	01/01/1900	09/22/2024	GSMITH
WD	ANT	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH
WD	ATG	GSMITH LOADED MESSAGE:067-2020-3444::ADD	01/01/1900	09/22/2024	GSMITH
WD	ATG	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH

[illegible]

WD	UMI	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH
WD	VCT	GSMITH LOADED MESSAGE:067-2020-3444::ADD	01/01/1900	09/22/2024	GSMITH
WD	VCT	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH
WD	VGB	GSMITH LOADED MESSAGE:067-2020-3444::ADD	01/01/1900	09/22/2024	GSMITH
WD	VGB	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH
WD	VIR	GSMITH LOADED MESSAGE:067-2020-3444::ADD	01/01/1900	09/22/2024	GSMITH
WD	VIR	THIS MESSAGE WAS SUPERCEDED BY 49726	09/22/2024	04/07/2021	GSMITH