



Close Window

## View Field Action Details



This screen allows IVH users to view the detail information for the selected VIN on Filed Action.

### Vehicle Information

VIN: [REDACTED] Model: 1RF68-2017 VOLT  
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes  
 Order Type: 70 - RETAIL - STOCK  
 Field Actions: [0 Open](#)

### Field Action Details

Type	Number	Description	Release Date
Service Update Bulletins	2043940	Brake Transmission Shift Interlock (BTSI) Transmission Won't Shift Out of Park	06/24/2016
Status:	Closed		
Group:			
Sub-Group:	83440		
Expires:	06/30/2017		
Original Number:	43940		
Labour Ops:	9102296 2043940 - Inspect Brake Transmission Shift Interlock Function		
Government Agency #:			
Field Action Description:	Certain 2016 model year Chevrolet Malibu and 2016-2017 Chevrolet Volt vehicles may have a condition where a burr may be present on the spring end which is part of the shifter assembly. This may result in an intermittent condition where the vehicle will not shift out of "Park."		
Safety Risk Description:	Transmission Won't Shift Out of Park		
Repair Description:	Inspect and replace the shifter assembly if required.		