



780 Serramonte Boulevard
Colma, California 94014
Phone: (650) 994-2400
www.stewartcars.com



B.A.R. # ARD 183919

E.P.A. # CAD 981980998

NO [REDACTED] IMPORTANT WARRANTY AND ADDITIONAL INFORMATION ON BACK.

CELL [REDACTED]

CUSTOMER NO	[REDACTED]	NAME	DARRYN TYSON	622	TAG NO.	446B	INVOICE DATE	10/14/22
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]	MILEAGE	55,748	COLOR	NIGHTFALL G
[REDACTED]	[REDACTED]	YEAR / MAKE / MODEL	17/CHEVROLET/VOLT/5DR HB LT					
[REDACTED]	[REDACTED]	DELIVERY DATE	[REDACTED]					
[REDACTED]	[REDACTED]	SELLING DEALER NO	[REDACTED]					
[REDACTED]	[REDACTED]	F.T.E. NO	[REDACTED]					
[REDACTED]	[REDACTED]	P.O. NO	[REDACTED]					
[REDACTED]	[REDACTED]	R.O. DATE	09/15/22					
[REDACTED]	[REDACTED]	REPRINT#	1					
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO: 55751					

LABOR & PARTS
J# 1 18CVZID **DIAGNOSIS/INSPECTION HOURS:** **TECH(S):546** **WARRANTY**
 CUSTOMER STATES CHECK ENGINE LIGHT ON DASH; PROPULSION POWER IS REDUCED MESSAGE CAME ON AND WENT OFF. VEHICLE SHOWED ERROR MESSAGE UNABLE TO CHARGE BUT STILL ABLE TO CHARGE CHECK AND ADVISE
 TURN CAR ON. UNABLE TO MOVE CAR. CONNECTED GDS AND FOUND DTC U2603, U2619, U2620, U2621, U2622, U2623 U2624 CURRENT FOUND TSB #18-NA-261 T O REPLACE BECM.
 REPLACED BECM AFTER LOWERING BATTERY PACK. SMOKE TEST BATTERY PACK PASS NO LEAKS. REINSTALLED BATTERY PACK ON TO CAR AND PROGRAM BECM VIA SPS [REDACTED]
 NOTE BECM PLASTIC COVER CAME CRACKED BUT NO IMPACT DAMAGE TO MODULE. MODULE IS NOT A SEAL SYSTEM. INSTALLED AN NO CODES SET

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 1	1	24296900	MODULE 2.210 Y		WARRANTY
		SPAC C00473913			
JOB # 1	4	11517042	BOLT 8.906 Y		WARRANTY
JOB # 1	1	12378390	DEXCOOL 5 8.800 N		WARRANTY
JOB # 1	-1	24296900	CORE RETURN		WARRANTY
				JOB # 1 TOTAL PARTS	0.00
				JOB # 1 TOTAL LABOR & PARTS	0.00

J# 2 68CVZ ***Goodwrench VEH INSP HOURS:** **TECH(S):546** **INTERNAL**
 Goodwrench MULTI-POINT VEHICLE INSPECTION as per attached Inspection Sheet.
 ..Brake Inspection (in some cases) may only be a visual estimate and not a true measurement depending on the complexity of the Brake System inspection process..
 PERFORM A TIRE INFLATION SERVICE AND DOCUMENT TIRE PRESSURE Preemptive Preventative Maintenance Inspection Completed Multi-Point Vehicle Inspection ... See Notes:
 SET ALL TIRE PRESSURES AS DOCUMENTED BELOW
 SET TIRE PRESSURES 36PSI
 FRONT BRAKE LINING REMAINING 7MM
 REAR BRAKE LINING REMAINING 7MM
 FRONT TIRE TREAD REMAINING 7/32
 REAR TIRE TREAD REMAINING 4/32

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
				JOB # 2 TOTAL PARTS	0.00
				JOB # 2 TOTAL LABOR & PARTS	0.00

J# 3 69CVZ **DECLINED REPAIRS HOURS:** **0.00** **TECH(S):480** **INTERNAL**
 CUSTOMER DECLINED REPAIR AT THIS TIME
 MAINTENANCE
 DECLINED REPAIRS
 NO REPAIRS PERFORMED / CUSTOMER DECLINED

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
-------	-----	-----------	-------------	------------

The Reynolds and Reynolds Company, EPHAMTSHHE, GC0516739 Q, (03/21)



780 Serramonte Boulevard
 Colma, California 94014
 Phone: (650) 994-2400
 www.stewartcars.com
 E.P.A. # CAD 981980998



NOT

WARRANTY AND ADDITIONAL INFORMATION ON BACK.

CUSTOMER NO.	DARRYN TYSON	622	TAG NO. 446B	INVOICE DATE 10/14/22	CELL
			MILEAGE 55,748	VEHICLE NIGHTFALL G	
SAN FRANCISCO, CA	17/CHEVROLET/VOLT/5DR HB LT			DELIVERY DATE	DELIVERY MILES
				SELLING DEALER NO.	PRODUCTION DATE
				R.O. DATE 09/15/22	REPRINT# 1
RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	MO: 55751		

JOB # 3 TOTAL PARTS 0.00
 JOB # 3 TOTAL LABOR & PARTS 0.00

MISC-----CODE-----DESCRIPTION-----CONTROL NO-----		
JOB # 2	65D Advertising Discount Labor	427207
		INTERNAL
	TOTAL - MISC	0.00

ESTIMATE-----
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
 ORIGINAL ESTIMATE OF \$500.00 (+TAX)

COMMENTS-----
 called 9/29 @ 1018AM NO ANSWER NO VOICEMAIL SET UP
 CALLED 10/14 1154AM NO ANSWER NO VOICEMAIL SET UP

RECOMMENDATIONS-----
 NOTE: NO IN-HOUSE SERVICE HISTORY
 RECOMMEND MAINTENANCE 1/ANNUAL SERVICE
 RECOMMEND BRAKE FLUID EXCHANGE, 2 YEAR OR 30000 MILES
 RECOMMEND WHEEL ALIGNMENT, 1 YEAR/12,000 MILES
 RECOMMEND TRANSMISSION FLUID EXCHANGE, 3 YEAR OR 45,000 MILES
 RECOMMEND COOLANT FLUID EXCHANGE, 5 YEARS OR 150,000 MILES
 RECOMMEND INDUCTION SERVICE, 2 YEARS OR 30000 MILES
 RECOMMEND REPLACE ENGINE AIR FILTER, 2 YEARS OR 30000 MILES
 RECOMMEND REPLACE CABIN AIR FILTER, 2 YEARS OR 30000 MILES

TOTALS-----

*****	TOTAL LABOR...	0.00
	TOTAL PARTS...	0.00
	TOTAL SUBLET...	0.00
	TOTAL G.O.G....	0.00
	TOTAL MISC CHG.	0.00
	TOTAL MISC DISC	0.00
	TOTAL TAX.....	0.00
	TOTAL INVOICE \$	0.00

A MESSAGE TO ALL OUR VALUED CUSTOMERS.
 We would like to take this opportunity to THANK YOU for your business and continued loyalty. We also want to ensure we provide you with the QUALITY SERVICE & repairs you deserve. If you do not feel "Completely Satisfied" with your service experience, please contact Joe Cassisi, Service Manager Stewart Chevrolet at (650)994-2400 X101
 We appreciate your comments and any concerns you may have.
 Stewart Automotive Group SERVICE DEPARTMENT HOURS
 Monday-Friday 7:30am to 6:00pm
 Saturday 8:00am to 4:30pm

CUSTOMER SIGNATURE

The Reynolds and Reynolds Company, EPRINTSH4E, G0516739 Q (03/21)