


CUSTOMER #: [REDACTED]

STEVINSON



CHEVROLET

15000 W. Colfax Ave. · Lakewood, CO 80401
Service (303) 302-3330
www.stevinsonchevrolet.com

INVOICE

PAGE 1

golden, CO
HOME [REDACTED]
BUS: [REDACTED]

SERVICE ADVISOR: 610514 Kirk Heydman

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
OTHER	17	CHEVROLET Volt	[REDACTED]		37508/37516	T4303	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
07OCT22 DD			17:00 21JUN23		0.00	CASH	19SEP23
R.O. OPENED	BOOKED	OPTIONS: DLR:10822					
13:48 21JUN23	13:12 19SEP23						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUSTOMER STATES THAT THE REDUCED ENGINE PROPULSION MESSAGE CAME ON CHECK ENGINE LIGHT WAS ON VEHICLE HAD NO POWER. RECENT BATTERY INSTALLED HERE ADVISE
 CAUSE: MISC MAINTENANCE REPAIRS
 5031700 HIGH VOLTAGE SECTION BATTERY REPLACEMENT
 610503 Clark, Bruce LIC#: 21
 W (N/C)
 1 23348948 F-(S) SENSOR (N/C)
 1 FR Freight (N/C)
 4 11517042 (S) BOLT (N/C)
 1 12378390 COOLANT (N/C)

37516 BATTERY SECTION #2 CELL #58 BAD 5031700 6.80 D/T (HAD 0.8L MAX WAS 0.3L) SCAN TESTED HAD CODE P1E65.00 SET. CELL #58 HAS A FAULT. NEEDS BATTERY SECTION #2 PER TAC CASE [REDACTED] 09/14/2023, R&R HIGH VOLTAGE BATTERY & COVER. REPLACE BATTERY SECTION #2. 1 SENSOR ON BATTERY HAD 1 EAR BROKEN WHEN I GOT IT OUT OF OLD BATTERY. REPLACE HIGH VOLTAGE SENSOR THERMISTOR #4. ADD: BALANCED NEW BATTERY SECTION WARRANTY CODE [REDACTED] PRESSURE CHECK COOLING SYSTEM IN BATTERY, NO LEAKS. AFTER COVER INSTALLED REPLACED BOLTS TO MANUAL SERVICE PORT. ADD: SMOKE TESTED, OK. TOPPED OFF COOLANT & BLEED AIR. CLEAR CODES & R/T, OK. FAILURE CODE #9090.

 B PERFORM STEVINSON MULTI POINT VEHICLE INSPECTION
 INSP PERFORM STEVINSON MULTI POINT VEHICLE INSPECTION
 610503 Clark, Bruce LIC#: 21
 CPC 0.00 0.00
 37508 0.00 MULTI-POINT INSPECTION COMPLETED.

INFORMATION REDACTED
 PURSUANT TO THE FREEDOM OF
 INFORMATION ACT (FOIA), 5 U.S.C.
 552(B)(6)

AS IS: The only warranties applying to this repair are those which may be offered by the parts manufacturer. STEVINSON HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, IF ANY, EITHER EXPRESS OR IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this part(s) and/or service. Customer shall not be entitled to recover from Stevinson any consequential damages, damages to property, damages for loss of use, loss of time, loss of profits, or income, or any other incidental damages. Customer acknowledges and agrees to the additional terms on the reverse side of this invoice. NO PARTS OR LABOR WARRANTY WHEN USED PARTS ARE INSTALLED. X _____ CUSTOMER SIGNATURE	DESCRIPTION	TOTALS
	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES / SHOP SUPPLIES	
	TOTAL CHARGES	
	LESS INSURANCE / DISCOUNT	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES RETAILERS TO COLLECT A WASTE TIRE FEE OF \$1.25 SET BY THE SOLID AND HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR VEHICLE TIRE AND EACH NEW TRAILER TIRE.