

Herb Chambers Chevrolet of Danvers



90 Andover Street, Rte. 114
Danvers, MA 01923
978-774-2000
www.herbchambers.com

INFORMATION REDACTED
PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C.
552(B)(6)

SERVICE ADVISOR 78383 ERIO R PEREZ		TAG NO. T045	INVOICE DATE 08 Dec 2021
HOURLY RATE 0.00	LICENSE NO.	PO NO.	COLOR 35810
YEAR/MAKE/MODEL 17 CHEVROLET VOLT		MILEAGE IN 35810	MILEAGE OUT 35810
DANVERS, MA		DELIVERY DATE 01 Jan 2017	IN SERVICE DATE
CELL PHONE	SALES PERSON	R.O. DATE 06 Nov 2021	WAR EXP.
COMMENTS 1			

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	C/S						
WAS DRIVING AND THE SCREEN POPPED UP SHIFT TO PARK. AND THE LOST POWER.							
CAUSE: DRIVE MOTOR B INSIDE TRANSMISSION SHORTED CAUSING LOSS OF ISOLATION							
	8464670						
							(N/C)
	1	24293729	F-TRANSAXLE				(N/C)
			CORE CHARGE W				(N/C)
	-1	24293729	CORE RETURN				(N/C)
	3	12378390	COOLANT				(N/C)
	6	88862155	FLUID				(N/C)
FC: PART#: 24293729 COUNT: 1							
CLAIM TYPE: ZREG							
AUTH CODE:							

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

CHECKED FOR DTCS. P1AF6, P1AEF, P1AEE, P1AF0, P1AF2, P1B0B, P1B43, P1AF4, P1E1E, P1E22, P1E1C, P2797 AND P19FA STORED. LOSS OF ISOLATION CODES. DISABLE HIGH VOLTAGE SYSTEM. CHECK FOR ISOLATION ON HIGH VOLTAGE BATTERY CABLES, A/C COMPRESSOR, COOLANT HEATER, AND BATTERY CHARGER MODULE. ALL OK. DISASSEMBLE TOP OF TRANSMISSION AND REMOVED POWER INVERTER MODULE. CHECKED FOR LOSS OF ISOLATION ON POWER INVERTER MODULE, TRANSMISSION FLUID PUMP. DRIVE MOTOR A AND DRIVE MOTOR B. FOUND LOSS OF ISOLATION WITH DRIVE MOTOR B DUE TO SHORTED MOTOR. STARTED CASE WITH TECH ASSIST. WAS ADVISED TO REPLACE THE TRANSMISSION DUE TO INTERNAL FAILURE AND THE CODES THAT WERE SET. REFERENCE BULLETIN # PIC6244D. TAC CASE# [REDACTED] REPLACED TRANSMISSION ASSEMBLY. PROGRAMMED POWER INVERTER MODULE AND IMMOBILIZER. WARRANTY CLAIM CODES: 17YN93840348 AND 0SYN93853009. FILLED TRANSMISSION, FILL AND BLEED COOLING SYSTEMS FOR BATTERY, ELECTRONICS AND ENGINE. ROADTEST. OK

B PERFORM MULTIPOINT INSPECTION
MPI PERFORM MULTIPOINT INSPECTION
23637 CPM

0.00 0.00

CASH CHECK CK NO. []
 VISA MASTERCARD
 AMEX CHARGE OTHER

THANK YOU FOR CHOOSING
HERB CHAMBERS CHEVROLET OF DANVERS

Customer Signature

Environmental Compliance

and state laws require that all hazardous waste (oil, solvents, anti-freeze, etc.) must be disposed of by a licensed contractor in an environmentally sound manner. Any charges for environmental compliance reflect our conformity to federal and state law in addition to our concern for the preservation of the environment.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS	
GAS, OIL, LUBE	
SUBLET REPAIRS	
MISCELLANEOUS CHARGES	
TOTAL CHARGES	
LESS DISCOUNT/INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	