

Parts Change Log

NHTSA Inquiry RQ24-015

Front Passenger Seatbelt Retractor - Design Changes								Service Parts - Disposition							
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production (Start of production at Vehicle Operations)	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Engineering Part Number(s) (including color variants)	Service Part Number(s) (includes color variants)	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2018	JL1B-C699D64-AAW	8/28/2017	7/21/2019	2018 MY Expedition - initial release	Initial engineering release or part	Expedition 2018 - 2021 MY	JL1B-C699D64-AA3DJ9 JL1B-C699D64-AA3JA6 JL1B-C699D64-AA31TB	JL1Z-78611B08-AC JL1Z-78611B08-AD JL1Z-78611B08-AE	9/25/2017	none	1/18/2022	Y (two-way interchangeability)	Consume	None
2	2019	JL1B-C699D64-ABW	7/22/2019	2/7/2021	ADD PIECE OF TAPE TO THE CONNECTOR HOUSING AND BASE	FRONT SEAT PRETENSIONER CONNECTOR HOUSING TAB IS EASILY DISLODGED CAUSING BENT PINS. ADD PIECE OF TAPE TO PREVENT INADVERTENT REMOVAL.	Expedition 2018 - 2021 MY	JL1B-C699D64-AB3DJ9 JL1B-C699D64-AB3JA6 JL1B-C699D64-AB31TB	JL1Z-78611B08-AC JL1Z-78611B08-AD JL1Z-78611B08-AE	9/25/2017	none	1/18/2022	Y (two-way interchangeability)	Consume	None
3	2022	JL1B-C699D64-ACW	2/8/2021	3/7/2021	DYNAMIC LOCKING TONGUE (DLT) CHANGE DLT 1 to DLT LBA	Content change for MCA for performance improvement requested by Ford	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
4	2022	JL1B-C699D64-ADW	3/8/2021	NA	ADD DAMPER ON RETRACTOR PRETENSIONER Change from 1 damper to 2 dampers	TO IMPROVE PRETENSIONING CONSISTENCY	Expedition 2022 - 2024 MY	JL1B-C699D64-AB3EL6 JL1B-C699D64-AD3GU3 JL1B-C699D64-AD3JA6 JL1B-C699D64-AD3EL6	JL1Z-78611B08-AF JL1Z-78611B08-AJ JL1Z-78611B08-AK JL1Z-78611B08-AL	1/18/2022	none	n/a	N (No interchangeability)	Consume	None
5	2022	JL1B-C699D64-ADW	2/16/2022	NA	MATERIAL CHANGE TO MGG PROPELLANT FROM IMR TO CS0400	Force majeure material shortage									

Front Driver Seatbelt Retractor - Design Changes								Service Parts - Disposition							
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production (Start of production at Vehicle Operations)	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Engineering Part Number(s) (including color variants)	Service Part Number(s) (includes color variants)	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2018	JL1B-C699D65-AAW	8/28/2017	2/11/2018	2018 MY Expedition - initial release	Initial engineering release or part	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
2	2019	JL1B-C699D65-ABW	2/12/2018	7/21/2019	ADD LONGER DAMPER ON RETRACTOR PRETENSIONER	TO IMPROVE PRETENSIONING CONSISTENCY	Expedition 2018 - 2021 MY	JL1B-C699D65-AB3DJ9 JL1B-C699D65-AB3JA6 JL1B-C699D65-AB31TB	JL1Z-78611B09-AF JL1Z-78611B09-AG JL1Z-78611B09-AH	9/25/2017	none	1/18/2022	Y (two-way interchangeability)	Consume	None
3	2022	JL1B-C699D65-ACW	7/22/2019	1/31/2021	ADD PIECE OF TAPE TO THE CONNECTOR HOUSING AND BASE	PRETENSIONER CONNECTOR HOUSING TAB IS EASILY DISLODGED CAUSING BENT PINS. ADD PIECE OF TAPE TO PREVENT INADVERTENT REMOVAL.	Expedition 2018 - 2021 MY	JL1B-C699D65-AC3DJ9 JL1B-C699D65-AC3JA6 JL1B-C699D65-AC31TB	JL1Z-78611B09-AF JL1Z-78611B09-AG JL1Z-78611B09-AH	9/25/2017	none	1/18/2022	Y (two-way interchangeability)	Consume	None
4	2022	JL1B-C699D65-ADW	2/1/2021	NA	LH FRONT ROW SEATBELT DLL CHANGE New DLL scarf design	Request from Ford to adjust LL levels	Expedition 2022 - 2024 MY	JL1B-C699D65-AD3EL6 JL1B-C699D65-AD3GU3 JL1B-C699D65-AD3JA6 JL1B-C699D65-AD3LU2	JL1Z-78611B09-AJ JL1Z-78611B09-AK JL1Z-78611B09-AL JL1Z-78611B09-AM	1/18/2022	none	n/a	N (No interchangeability)	Consume	None
5	2022	JL1B-C699D65-ADW	2/16/2022	NA	MATERIAL CHANGE TO MGG PROPELLANT FROM IMR TO CS0400	Force majeure material shortage									