

Field Product Report

Engine locked up
2021 GMC Sierra



GENERAL MOTORS
CUSTOMER CARE AND AFTERSALES



L87 – 6.2L Gas engine

- **Check engine light on engine locked up**
- **Found bearing spun, causing internal engine damage**
- **Replace engine**



