

CUSTOMER # [REDACTED]

CENTRAL GMC, INC.



INVOICE

70 Providence Hwy. (Rte.1)
Norwood, MA 02062
Telephone: (781) 762-2202
www.central.us

PAGE 1

STOUGHTON, MA

HOME: [REDACTED]
BUS: [REDACTED]

CONT: [REDACTED]
CELL: [REDACTED] .COM

SERVICE ADVISOR: 3585 WILLIAM DEVINE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
BLACK	21	GMC YUKON	[REDACTED]	[REDACTED]	55359/55359	T1912
IN SVC. DATE	PROD. DATE	WARR. EXP.	PROMIS	PO NO.	RATE	PAYMENT
31OCT20 DD						INV. DATE
R.O. OPENED	READY	19:00 03JUL25	OPTIONS: DLR:263719 ENG:6.2_Liter		CASH	23JUL25
14:59 03JUL25	17:04 23JUL25					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	C/S	CUSTOMER STATES CHECK ENGINE LIGHT COMES ON IN MORNING ENGINE STARTS RUNNING ROUGH THEN CLEARS UP DURING THE DAY					

CAUSE: .
WDIAG WARRANTY DIAGNOSTIC
2705 WGM
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: (N/C) 0.00

B MULTI-POINT VEHICLE INSPECTION
27PT 27PT
2705 CPGM
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00 0.00

C** CUSTOMER STATES CHECK ENGINE LIGHT IS ON CYLINDER #5 MISFIRE
CAUSE: FAULTY #5 FUEL INJECTOR, REPLACED LEFT BANK FUEL INJECTORS (1, 3, 5, 7)
4021200 FUEL INJECTOR REPLACEMENT - BANK 1
2705 WGM
4 12742701 (S) INJECTOR KIT (N/C)
1 12677002 (S) PIPE (N/C)
1 12703596 (S) PIPE (N/C)
1 12679463 (S) PIPE (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: (N/C) 0.00

.....55359 Codes p0300 and p050d were present these lead to the injectors. A injector balance test was performed and it was determined that the bank 1 injectors were running rich cylinder 5 was the worst which makes sense with the p050d present and the most history misfires on cylinder 5. Upon inspection there was a burning fuel smell on from the rail on bank 1 so they were removed and inspected and were determined to be sticking open causing the problem. So it was recommended all of the injectors on that bank to be replaced. After replacement fuel trim was reset and codes were cleared and no misfire appeared and codes came back and the injectors were now doing what they should be doing. So the car was test driven while monitoring fuel trim and misfire data and everything responded fine and is now functioning

THANK YOU FOR BRINGING YOUR VEHICLE TO CENTRAL GMC, INC.

DISCLAIMER OF WARRANTIES

All warranties on these parts are the manufacturer's. The Seller, Central Kia, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and Central Kia, neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of these parts. This disclaimer by the seller, Central Kia, in no way affects the terms of the manufacturer's warranty. Buyer shall not be entitled to recover from the selling dealer any consequential damages, damages to property, damages for loss of use, loss of time, loss of profit, or income, or any other incidental damages.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC./ENVIRONMENTAL	
TOTAL CHARGES	
LESS	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER SIGNATURE

COMPLETE BODYSHOP AND PAINT FACILITY
CALL CENTRAL COLLISION CENTER (781) 762-8444

DISPOSAL OF HAZARDOUS WASTE

The State of Massachusetts requires that all hazardous waste (Oil, Solvents, Anti-Freeze, etc.) must be disposed of by a licensed contractor in an environmentally safe manner. Any charges for disposal of hazardous waste reflects our conformity to state law in addition to our concern for the preservation of the environment.

CUSTOMER COPY