



Service Programming System (SPS) - Special Function

1.87 Picoscope Test

Test incomplete: retest required.

Irregular noise found within Picoscope data, please turn vehicle off, recheck all Picoscope connections and retest. If issue continues please contact TCSC for additional assistance.

INFORMATION REDACTED
PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C.
552(B)(6)

< Back

Next >

Cancel

Search

F2 F3 F4 F5 F6 F7 F8 F9 F10 F11 F12 Home End Insert
@ # \$ % ^ & * () _ +