



19h ago

ATTENTION:This email originated from outside of GM.



In regards to [REDACTED] the vehicle was towed into the dealership on 3-21-2025. The RO was not opened on the vehicle until 06/09/2025 do to the thought the L87 Engine was bad. At the time the Engine was placed on order to insure we had a fix for said problem. When we received the engine the vehicle was brought in and RO created. Upon engine disassembly it was determined that the engine had not failed, and was in need of attached repair.

Thanks You,
Josh Eveatt
Service Manager
Perkins La Junta
(719)384-4401 ext.2390