

REPAIR ORDER DETAIL

INFORMATION REDACTED
PURSUANT TO THE FREEDOM OF
INFORMATION ACT (FOIA), 5 U.S.C.
552(B)(6)

Repair Order Information

VIN: [REDACTED]

Repair Order Number: [REDACTED]

Service Order Open Date: Nov 11, 2024

Dealer BAC: [REDACTED]

Repair Order Type: Service

Service Order Closed Date: Dec 10, 2024

Customer Information

First Name: [REDACTED]

Home Phone: [REDACTED]

Address: [REDACTED]

Last Name: [REDACTED]

Work Phone: ---

City: [REDACTED]

Account: ---

Cell Phone: [REDACTED]

State: [REDACTED]

Customer Number: [REDACTED]

Email Address: [REDACTED]

Zip Code: [REDACTED]

Service Contact

Advisor ID: 302

Advisor Full Name: [REDACTED]

Vehicle Information

Year: 2021

Make: GMC

Model: 1500 Sierra

Merchandise Model Code: --

Odometer: 53601

Delivery Date: Dec 31, 1899

Payment Information

Customer Pay Amount Subtotal: 0.0

Warranty Amount Subtotal: 0.0

Internal Amount Subtotal: 314.28

Repair Order Amount Subtotal: 314.28

DMS Reported Customer Pay Subtotal: 0.0

DMS Reported Warranty Amount Subtotal: 0.0

DMS Reported Internal Subtotal: 314.28

DMS Reported Repair Order Amount Total: 314.28

Labor Information

Filter Results:

| Invoice Line Item | Department Type | Event Repair Labor Type 3 | DMS Operation Code | DMS Operation Description | Standard Operation Code | Labor Amount |
|-------------------|-----------------|---------------------------|--------------------|---------------------------|-------------------------|--------------|
| 1 | Service | Internal pay | 10CVZ | DRIVEABILITY | 3400 | 33.0 |
| 2 | --- | Internal pay | 10CVZ | DRIVEABILITY | 3400 | 84.0 |

Parts Information

Filter Results:

| Invoice Line Item | Event Repair Labor Type 2 | Part Number (DMS Value) | Part Description (DMS Value) | Part Unit Cost | Parts Amount | Parts Quantity |
|-------------------|---------------------------|-------------------------|------------------------------|----------------|--------------|----------------|
| 1 | Internal pay | 12711681 | SL-N-SENSOR (03682-BCKT) | 45.17 | 97.57 | 1 |
| 1 | Internal pay | 12714453 | SL-N-SENSOR (03682-BCKT) | 46.16 | 99.71 | 1 |