

KEYS AUTO CENTER
KEY WEST CHRYSLER DODGE JEEP RAM
KEY WEST FORD
KEY WEST TOYOTA

1618 N. ROOSEVELT BLVD.
KEY WEST, FL 33040
PHONE: (305) 294-5126
FAX: (305) 294-4536
www.keysautocenter.com

MONDAY - FRIDAY 7:30 AM - 6:00 PM
SATURDAY & SUNDAY CLOSED

CUSTOMER #:

ACCOUNTING



PAGE 1

MARATHON, FL
HOME:
BUS:

Repair Shop Registration Number: MV97879

SERVICE ADVISOR: 511364 CHARLES MICHAEL WI

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
WHITE	21	CADILLAC ESCALADE			63234/63234		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	FLAT RATE	PAYMENT	INV. DATE
01JAN21 DD			17:00 26SEP25			MC	30SEP25
R.O. OPENED	READY	OPTIONS:					
17:13 04SEP25	15:21 30SEP25						

LINE	OPCODE	TECH	TYPE	A/HRS	S/HRS	LIST	NET	TOTAL
A CUSTOMER STATES - JUST HAD SHORT BLOCK REPLACED AT ED MORRIS CADILLAC - DRIVING BACK ENGINE SHUT DOWN - STARTED SHAKING MAKING WHISTLING SOUNDS AND ALL WARNING LIGHTS CAME ON								
CS CUSTOMER STATES - JUST HAD SHORT BLOCK REPLACED AT ED MORRIS CADILLAC - DRIVING BACK ENGINE SHUT DOWN - STARTED SHAKING MAKING WHISTLING SOUNDS AND ALL WARNING LIGHTS CAME ON								
511323	CCA			4.72	1.00	6500 20900	209.00	209.00
8	12626354	(S)	GASKET			1800 9904 0 12.38	12.38	99.04
1	12720120	(S)	INJECTOR KIT			9288 20434 0 204.34	204.34	204.34
1	12677002	(S)	PIPE			4564 11410 0 114.10	114.10	114.10
1	12679463	(S)	PIPE			1182 4137 0 41.37	41.37	41.37
REP HARNESS INSPECTION AND REPAIR								
511323	CCA			0.00	6.00	39000 125400	1254.00	1254.00
REP CYLINDER #4 INJECTOR CRACKED ELECTRICAL CONNECTOR AND SHORTING TO GROUND								
511323	CCA			0.00	4.60	29900 96140	961.40	961.40
VERSION 1 (EMP# 511323, 30SEP25 09:21): 63234 HARNESS REPAIR, REROUTING AND CYLINDER #4 INJECTOR REPLACEMENT 10.60 SCANNED P124B 00 CYLINDER #4 FUEL INJECTOR CONTROL CKT SHORT AND P0356 00 IGNITION COIL #6 CONTROL CIRCUIT. MONITORED ECM MISFIRE DATA AND FOUND CYLINDER #4 AND #6 TO BE MISFIRING. REMOVED INTAKE AND FOUND ENGINE HARNESS PINCHED BETWEEN FUEL LINE BRACKET AND BELLHOUSING CAUSING SHAFING ON FUEL INJECTOR CIRCUIT #4804 AND IGNITION COIL CIRCUIT #2126. REPAIRED AND REROUTED HARNESS, REINSTALLED INTAKE, CLEARED DTCS. AND VEH STILL MISFIRING ON CYLINDER #4, REMOVED INTAKE AND PERFORMED CIRCUIT TEST AND FOUND #4 INJECTOR SHORTED TO GROUND DUE TO BEING CRACKED. REPLACED #4								

WARRANTY DISCLAIMER ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PERFORMED BY THE DEALERSHIP AS IS. THE DEALERSHIP HEREBY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR ACCESSORIES OR SERVICE OR REPAIRS PERFORMED TO THE VEHICLE. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR SERVICE OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY SPECIAL DAMAGES, CONSEQUENTIAL DAMAGES, INDIRECT DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, PUNITIVE DAMAGES, ATTORNEYS' FEES AND/OR COSTS, OR ANY OTHER INCIDENTAL DAMAGES.

*** SHOP SUPPLY COSTS:** We have added a charge equal to 10% of the total cost of labor and parts, not to exceed \$50.00, to the Repair Order. This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies and waste disposal. The State of Florida requires a \$1.00 fee to be collected for each new tire sold in the state [s.403.718], and a \$1.50 fee to be collected for each new or remanufactured lead-acid battery sold in the state [s.403.7185].

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

Section 501.98, Florida Statutes, requires that, at least 30 days before bringing any claim against a motor vehicle dealer for an unfair or deceptive trade practice, a consumer must provide the dealer with a written demand letter stating the name, address, and telephone number of the consumer; the name and address of the dealer; a description of the facts that serve as the basis for the claim; the amount of damages; and copies of any documents in the possession of the consumer which relate to the claim. Such notice must be delivered by the United States Postal Service or by a nationally recognized carrier, return receipt requested, to the address where the subject vehicle was purchased or leased or where the subject transaction occurred, or an address at which the dealer regularly conducts business.

Customer X _____ Customer X _____

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.