

Parts Change Log

NHTSA Inquiry PE25-007

Part Changes Flex Front RH B-Pillar Trim Panel										Service Parts - Disposition						
Version	Model Year	Engineering Part Number		CR	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2010	BA83-7420554-AAW	RH	C12281024	11/30/2009	End of Production	Update Pre-Job2 applique part numbers to include new keypad with old connector for service		Yes 2009 Flex	BA8Z-7420554-AA	11/30/2009 Service part number release date and service stock availability date may differ.	N/A	Still Avialable	Yes	N/A	None
2	All	BA83-7420554-AAW	RH	C12426835	N/A Color only	N/A Color only	Color Blanket	Blanket CR/notice for color updates	N/A							

Part Changes Flex Front LH B-Pillar Trim Panel										Service Parts - Disposition						
Version	Model Year	Engineering Part Number		CR	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2010	BA83-7420555-ABW	LH	C12302458	~April 2010	8/23/2011	Add mesh sleeve to protect keypad wires	Keypad harness getting cut during installation	Yes 2010 Flex	BA8Z-7420555-AA	11/30/2009 Service part number release date and service stock availability date may differ.	N/A	4/27/2017 Service part number release date and service stock availability date may differ.	No	Consume	None
2	2012	BA83-7420555-ACW	LH	C12411225	8/23/2011	3/11/2013	Keypad programming change		Yes 2010-2011 Flex							
3	2014	BA83-7420555-ADW	LH	C12645007	3/11/2013	4/30/2015	Change keypad capacitor C4 value	Better keypad response during initialization	Yes 2010-2013 Flex							
4	2016	BA83-7420555-AEW	LH	C12886218	4/30/2015	4/27/2017	Change integrated circuit (IC) to current production Gen2 IC - change driven by electrical team (Windsor Mold not involved in change decision)		Yes 2010-2015 Flex							
5	2017	BA83-7420555-AFW	LH	C13289717	4/27/2017	6/20/2017	New EESE atmel chip for keypad	Quality improvement	Yes 2010-2016 Flex	BA8Z-7420555-AB	4/27/2017 Service part number release date and service stock availability date may differ.	N/A	6/20/2017 Service part number release date and service stock availability date may differ.	Yes	Consume	None
6	2017	BA83-7420555-AGW	LH	C13340146	6/20/2017	End of Production	Redesign the 2-way locator to improve the robustness/fit. Move the 2 way locator 2.0mm rearward to improve the margin fit to the rear door B-pillar applique and belt molding	Poor fit, applique contacting rear door	Yes 2010-2016 Flex	BA8Z-7420555-AC	6/20/2017 Service part number release date and service stock availability date may differ.	N/A	Still in production	Yes	Consume	None
7	2019			C13994052			Blanket CR for Job Last Update									

Part Changes Flex Rear RH B-Pillar Trim Panel										Service Parts - Disposition						
Version	Model Year	Engineering Part Number		CR	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2010	BA83-74255A34-AAW	RH	C12281024	11/30/2009	End of Production	Update Pre-Job2 applique part numbers to include new keypad with old connector for service		Yes 2009 Flex	BA8Z-74255A34-A	11/30/2009 Service part number release date and service stock availability date may differ.	N/A	Still in production	Yes	N/A	None

Part Changes Flex Rear LH B-Pillar Trim Panel										Service Parts - Disposition						
Version	Model Year	Engineering Part Number		CR	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2010	BA83-74255A35-AAW	RH	C12281024	11/30/2009	End of Production	Update Pre-Job2 applique part numbers to include new keypad with old connector for service		Yes 2009 Flex	BA8Z-74255A35-A	11/30/2009 Service part number release date and service stock availability date may differ.	N/A	Still in production	Yes	N/A	None