



Service Parts Operations

Campaign Parts Bulletin

CPB#

DISTRIBUTION:	
<input type="checkbox"/> DEALER PRINCIPAL	<input type="checkbox"/> USED CAR SALES
<input type="checkbox"/> PARTS MANAGER	<input type="checkbox"/> BODY SHOP MANAGER
<input type="checkbox"/> SERVICE MANAGER	<input type="checkbox"/> BUSINESS/GENERAL
<input type="checkbox"/> NEW CAR SALES	<input type="checkbox"/> OTHER
PLEASE INITIAL AND RETURN TO PARTS MANAGER FOR PERMANENT FILE	

TO: ALL DEALERS

DATE: 12-22-00

FROM: J. M. STONE, RECALL CAMPAIGNS

00V-228.003

SUBJECT: 00067 - CERTAIN 2000 'U-VAN AND W-CAR MODEL VEHICLES, AND CERTAIN 2000-01 S/T TRUCK MODEL VEHICLES

ATTN: PARTS MANAGER

**E/CMVSS NON-COMPLIANCE CAMPAIGN BULLETIN #00067 -
DECEMBER 20, 2000**

DESCRIPTION:

- **Condition:** General Motors has decided that certain 2000-01 U-Van, 2000-01 W-Car, and 2000-01 S/T Truck model vehicles fail to conform to Federal/Canada Motor Vehicle Safety Standard 209, "Seat Belt Assemblies". The seat belt buckles in certain, specific seating locations in these vehicles do not meet the pull test requirement. In a crash, the seat belt buckle may release and the occupant may receive more severe injuries.
- Dealers are to replace suspect seat belt buckle assemblies. In certain seating locations, dealers will inspect for a suspect date code and replace seat belt buckle assemblies having the suspect date codes.
- Refer to the Product Campaign Bulletin for further information.

EFFECTIVE DATE:

Owner mailing is scheduled to begin December 27, 2000.

GENERAL INFORMATION:

- The Parts list follows:

PARTS INFORMATION

Parts required to complete this campaign are to be obtained from General Motors Service Parts Operations (GMSPO). Please refer to your "Involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Part Number	Position and Description	Quantity/ Vehicle
12457479	U-Van Front RH - BELT KIT,D/SEAT(BKL SI)(W/PRETENSIONER)(GRAY)	As reqd.
12457483	U-Van Front RH - BELT KIT,P/SEAT(BKL SI)(W/PRETENSIONER)(GRAY)	As reqd.
12457486	U-Van Front RH - BELT KIT,P/SEAT(BKL SI)(W/PRETENSIONER)(SABLE)	As reqd.
12459820	U-Van Rear Center - BELT KIT,R/SEAT CTR(BKL SI)(#2)(INCLS CTR BELT COMPL & LH/RH BKL)(SABLE)	As reqd.
12531160	U-Van Rear Center - BELT KIT,R/SEAT(BKL SI)(GRAY)	As reqd.
88894663	U-Van Rear Center - BELT KIT,R/SEAT CTR(BKL SI)(INCLS CTR BELT COMPL & LH/RH BKL)(GRAY)	As reqd.
88894664	U-Van Rear Center - BELT KIT,R/SEAT CTR(BKL SI)(INCLS CTR BELT COMPL & LH/RH BKL)(NEUTRAL)	As reqd.
88894671	U-Van Rear Center - BELT KIT,R/SEAT(BKL SI)(BEIGE)	As reqd.
88895093	U-Van Rear Center - BELT KIT,R/SEAT(BKL SI)(60%)(GRAY)	As reqd.
88895094	U-Van Rear Seat Bench - BELT KIT,R/SEAT(BKL SI)(60%)(NEUTRAL)	As reqd.
88896096	U-Van Rear Seat Bench - BELT KIT,R/SEAT(BKL SI)(60%)(SABLE)	As reqd.
12369754	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(7 PANEL WEBBING)(NEUTRAL)	As reqd.
12453442	W-Car Front Center - BELT KIT,F/SEAT CTR(BLUE)	As reqd.

12458469	W-Car Front LH - BELT KIT,D/SEAT(BKL SI)(12 PANEL WEBBING)(GRAY)	As reqd.
12458899	W-Car Front Center - BELT KIT,F/SEAT CTR(PEWTER)	As reqd.
12459815	W-Car Rear RH - BELT KIT,R/SEAT CTR(LAT SI)(PEWTER)	As reqd.
12459816	W-Car Rear RH - BELT KIT,R/SEAT CTR(LAT SI)(OAK)	As reqd.
12459833	W-Car Front LH - BELT KIT,D/SEAT(BKL SI)(OAK)	As reqd.
88893317	W-Car Front LH - BELT KIT,D/SEAT(BKL SI)(EBONY)	As reqd.
88893318	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(PEWTER)	As reqd.
88893319	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(OAK)	As reqd.
88893320	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(BLUE)	As reqd.
88893321	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(EBONY)	As reqd.
88893325	W-Car Rear RH - BELT KIT,R/SEAT CTR & OTR ST BKL(PEWTER)	As reqd.
88893353	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(OAK)	As reqd.
88893354	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(EBONY)	As reqd.
88893355	W-Car Rear LH - BELT KIT,R/SEAT CTR & OTR ST BKL(PEWTER)	As reqd.
88893356	W-Car Rear RH - BELT KIT,R/SEAT CTR & OTR ST BKL(OAK)	As reqd.
88894557	W-Car Front Center - BELT KIT,F/SEAT CTR(NEUTRAL)	As reqd.
88894558	W-Car Front Center - BELT KIT,F/SEAT CTR(PEWTER)	As reqd.
88894560	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(PEWTER)	As reqd.
88894561	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(GRAY)	As reqd.
88894562	W-Car Rear Center - BELT KIT,R/SEAT CTR &	As reqd.

	OTR ST BKL(BLUE)	
88894563	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(GRAPHITE)	As reqd.
88894565	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(GRAY)	As reqd.
88894566	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(7-PANEL WEBBING)(NEUTRAL)	As reqd.
88895099	W-Car Front LH - BELT,D/SEAT(BKL SI)(NEUTRAL)	As reqd.
88895102	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(NEUTRAL)	As reqd.
88895103	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(GRAY)	As reqd.
88895104	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(BLUE)	As reqd.
88895105	W-Car Front Center - BELT KIT,F/SEAT CTR(NEUTRAL)	As reqd.
88895106	W-Car Front Center - BELT KIT,F/SEAT CTR(GRAY)	As reqd.
88896426	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(NEUTRAL)	As reqd.
88896427	W-Car Rear Center - BELT KIT,R/SEAT CTR & OTR ST BKL(NEUTRAL)	As reqd.
88896429	W-Car Front LH - BELT KIT,D/SEAT(BKL SI)(GRAPHITE)	As reqd.
88896430	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(7 PANEL WEBBING)(GRAPHITE)	As reqd.
88896432	W-Car Front RH - BELT,P/SEAT(BKL SI)(GRAY)	As reqd.
88896434	W-Car Front RH - BELT KIT,P/SEAT(BKL SI)(NEUTRAL)	As reqd.
12474640	S/T Front RH - BELT KIT,P/SEAT(BKL SI)(GRAPHITE)	As reqd.
12474641	S/T Front LH - BELT KIT,D/SEAT(BKL SI)(BEIGE)	As reqd.
12474643	S/T Front LH - BELT KIT,D/SEAT(BKL SI)(PEWTER)	As reqd.
12474644	S/T Front RH - BELT KIT,P/SEAT(BKL SI)(PEWTER)	As reqd.

12477768	S/T Front RH - BELT KIT,F/SEAT CTR(LAT SI)(INCLS OTR BKL)(GRAPHITE)	As reqd.
12477769	S/T Front RH - BELT KIT,F/SEAT CTR(LAT SI)(INCLS OTR BKL)(BEIGE)	As reqd.
12477774	S/T Split Bench Center - BELT KIT,F/SEAT CTR(BKL SI)(GRAPHITE)	As reqd.
12477776	S/T Split Bench Center - BELT KIT,F/SEAT CTR(BKL SI)(PEWTER)	As reqd.

End of bulletin.

Dana E. Evansoff/US/GM/GMC © GM

**GM SERVICE OPERATIONS
DCS669**

URGENT - DISTRIBUTE IMMEDIATELY

DATE: January 30, 2001

SUBJECT: 00067 - Product Safety Campaign
Seat Belt Buckle
Corrections and Clarification

MODELS: Certain 2000-01 'U' Van and
'W' Car Model Vehicles
Certain 2000-01 'S/T' Truck
Model Vehicles

TO: All Buick, Chevrolet, GMC,
Oldsmobile, and Pontiac Dealers

ATTN: Service Manager, Parts Manager,
and Warranty Administrator

00Y-228.003

Corrections:

Please note the following corrections to campaign bulletin 00067:

General: Some seat belt buckle assemblies have been found to have incorrect instructions included with the kit. Do not depend on the instructions included with the kits to determine part usage or installation procedures.

PAGE 8, fourth (4th) grouping
(Pontiac, Grand Prix, Neutral, 52I)

...Replace incorrect beginning VIN YF302181 with YF301133.

...Replace incorrect ending VIN YP318654 with YF302181.

PAGE 8, sixth (6th) grouping
(Pontiac, Grand Prix, Graphite/Charcoal, 12I/17I)

...Replace incorrect beginning VIN YF302181 with YF301133.

...Replace incorrect ending VIN YP318654 with YF302181.

PAGE 13, third (3rd) grouping
(Chev/GMC/Olds, S/T, Graphite, 12I)

...First Position (P/N 12474640):

Replace Frt Passenger (Bucket or Bench Seat) with Frt RH Passenger (Bkt or AMS Split Bench).

...Second Position (P/N 12477768):

Replace Frt Passenger (Bench Seat Only) with Frt RH Passenger (A52 Bench Only - includes latch plate for center position).

CLARIFICATIONS:

** There have been questions regarding missing wiring/connectors for heated seats (RPO KA1) on replacement seat belt buckles for front passenger bucket seats due to incomplete information in the campaign bulletin.

...For S/T Utility with graphite interior (RPO 12I) and bucket seats, no passenger bucket seat belt buckles for heated seats (RPO KA1) are included in this campaign.

...For S/T Utility with pewter interior (RPO 92I) and bucket seats, passenger seat belt buckles with and without heated seats (RPO KA1) are included in this campaign. The P/N for the pewter (92I) passenger seat belt buckle with heated seats is 12474643 (same as driver's seat belt buckle). The P/N for the pewter (92I) passenger seat belt buckle without heated seats is 12474644.

...For S/T Utility with beige interior (RPO 64I), only driver seat belt buckles are included in this campaign.

** For U-Vans, no seat belt buckles for modular bucket seats (RPO AR9) are involved. Modular bucket seats do not have armrests, and may be moved to different locations, unlike captains chairs or split bench seats.

** The Service Parts Assistance Center (SPAC) and Technical Assistance Center (TAC) have received inquiries regarding part numbers and/or seating positions not included in the parts information table.

...The service procedures that begin on page 13 of the bulletin provide step-by-step instructions for inspection and/or replacement of seat belt buckles at each seating position in each vehicle that MAY need to be inspected and/or replaced.

...Only certain seating positions in certain vehicles need to have the seat belt buckles inspected and/or replaced. For any vehicle included in this campaign, the table beginning on page 5 of the bulletin must be checked to determine which seating positions require inspection and/or replacement of one or more seat belt buckles. Do not use the service procedures beginning on page 15 to determine which buckles require inspection and/or replacement in any vehicle. Please review the following example for clarification:

EXAMPLE

Year/Model: 2000 Chevrolet Impala
Interior Color: Pewter (92I)
VIN Last 8: Y9365791

Front Seating: AR9 Reclining Front Bucket Seats

Refer to the table on page 7 of the bulletin.

1. There are two groupings that match the model and interior color, but only the lower grouping includes the VIN of the example vehicle.
2. This grouping indicates that the front passenger, front center, and rear seating positions require inspection and/or replacement.
3. The driver seating position is not included, and does not require any inspection/replacement.
4. Since this vehicle has front bucket seats, there is no front center passenger seating position or seat belt buckle to inspect or replace.
5. The rear seat belt buckles are to be inspected for suspect date codes and replaced if necessary.
6. The front passenger seat belt buckle assembly cannot be inspected and should be replaced with P/N 88893318.
7. To replace the front RH passenger seat belt buckle, follow the service procedure that begins in the middle of page 13. This service procedure includes steps for replacing the seat belt buckles for both front seating positions, but on this specific vehicle, only the front passenger seat belt buckle requires replacement.
8. The LH rear seat belt buckle assembly (LH rear and center rear are a single assembly) requires inspection for suspect date codes. If either of the date codes is 146002, 146003, 146004, 153002, or 161003, the buckle should be replaced with P/N 88893355. If there is no date code match with any of the five listed date codes, do not replace this seat belt buckle assembly.
9. The RH rear seat buckle assembly requires inspection of the date code. If the date code is 153002, 154001, 154003, or 161002, the buckle should be replaced with P/N 12459815. If the date code does not match any of the four listed date codes, do not replace this seat belt buckle assembly.
10. To replace either of the rear seat belt buckle assemblies, follow the service procedure that begins near the bottom of page 15. This service procedure includes steps for replacing the seat belt buckles at all three seating positions, if necessary.

Campaign bulletin 00067 is being revised and will be re-published.

END OF MESSAGE

GM SERVICE OPERATIONS

GM SERVICE OPERATIONS
DCS737
URGENT - DISTRIBUTE IMMEDIATELY

DATE: May 11, 2001

SUBJECT: 00067B - NONCOMPLIANCE CAMPAIGN

MODELS: CERTAIN 2000-01 'U'-VAN AND 'W'-CAR MODEL VEHICLES
CERTAIN 2000-01 'S/T' TRUCK MODEL VEHICLES

TO: ALL BUICK, CHEVROLET, OLDSMOBILE, PONTIAC,
AND GMC DEALERS

ATTN: SERVICE MANAGER, PARTS MANAGER,
AND WARRANTY ADMINISTRATOR

A BULLETIN SUPPLEMENT IS BEING ISSUED IN ORDER TO:

- * PROVIDE INFORMATION REGARDING SOME VEHICLES THAT WERE ERRONEOUSLY INCLUDED IN THE CAMPAIGN POPULATION
- * PROVIDE AN IMPROVED VEHICLE SEATING POSITION DECISION TABLE

THE BULLETIN SUPPLEMENT SHOULD BE FILED WITH CAMPAIGN BULLETIN 00067A, ISSUED FEBRUARY 19, 2001.

VEHICLES INVOLVED

A small number of 2000 Chevrolet S-10 and GMC Sonoma model vehicles were erroneously included in this campaign. These vehicles were built at the Linden Plant and are equipped with pewter interior (RPO 921) and full bench seats (RPO A52).

These vehicles have been removed from GNVIS (GM Vehicle Inquiry System) or GM Access Screen (Canada only) or DCS Screen 445 (IPC only) and involved owners will be notified of this error.

There is no change to the vehicles involved table from bulletin 00067A.

MAILING INFORMATION

Dealer Mailing is scheduled to begin May 11, 2001.

Owner Mailing is scheduled to begin May 18, 2001.

END OF MESSAGE

GM SERVICE OPERATIONS

00V-228.003

DCS772
URGENT - DISTRIBUTE IMMEDIATELY

DATE: July 19, 2001

SUBJECT: 00067B - F/CMVSS NONCOMPLIANCE CAMPAIGN
SEAT BELT BUCKLE EXCLUSION OF CERTAIN VEHICLES

MODELS: Certain 2000-01 'U' Van and 'W' Car Model
Vehicles Certain 2000-01 'S/T' Truck Model Vehicles

TO: All Buick, Chevrolet, GMC, Oldsmobile, and
Pontiac Dealers

ATTN: Service Manager, Parts Manager, and
Warranty Administrator

00V-228,003

A small number of 2000 Chevrolet, GMC, and Oldsmobile utility model vehicles were erroneously included in this campaign. These vehicles were built at the Linden and Moraine plants and are equipped with heated seat (RPO KA1) and graphite interior (RPO 12I).

These vehicles will be removed from GMVIS (GM Vehicle Inquiry System) or GM Access Screen (Canada only) or DCS Screen 445 (IPC only) and involved owners will be notified of this error (sample letter attached).

There is no change to the vehicles involved table from bulletin 00067B.

Sample Owner Letter:

Dear General Motors Customer:

General Motors recently notified you regarding a campaign involving the inspection and possible replacement of seat belt buckles on your vehicle. Upon further investigation, we have determined that your vehicle was not built with any suspect part(s), and does not need to be included in this campaign.

If you have already had your vehicle serviced under this campaign, we apologize for any inconvenience our error may have caused you.

If you have not yet had your vehicle serviced for this campaign, no further action is necessary. We apologize if this error has caused you any concern regarding the integrity of the safety belts in your vehicle.

If you have any questions regarding this matter, please contact your

(Division)dealer or the (Division) Customer Assistance Center at
1-800-###-####. Deaf, hearing impaired or speech impaired call 1-800-###-####
(Utilizes Telecommunication Devices for the Deaf/Text Telephones TDD/TTY).

General Motors Corporation

This owner mailing began on July 18, 2001.

END OF MESSAGE

GM SERVICE OPERATIONS



NISSAN NORTH AMERICA, INC.

December 15, 2000

Mr. Jonathan D. White
Chief, Recall Analysis Division
Office of Defects Investigation
Safety Assurance
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Ref: 00V-228,005/00V-338

Dear Mr. White:

The enclosed communication is being provided pursuant to 49 CFR Part 573.5(c)(9).

Very truly,

Frank D. Slaveter
Corporate Manager
Technical Compliance

Encl.

RECEIVED
OFFICE
DEFECTS INVESTIGATION
DEC 19 PM 12:26

The following Nissan net message is being sent to all Nissan dealers this evening, December 11, 2000.

NISSAN NET BROADCAST MESSAGE

SUBJECT: 2001 QUEST SEAT BELT BUCKLE REPLACEMENT VOLUNTARY SAFETY RECALL CAMPAIGN

ATTENTION - DEALER PRINCIPALS, SALES, PARTS AND SERVICE MANAGERS

THERE MAY BE SOME PARTS ORDERING CONFUSION DUE TO THE FACT THAT THERE ARE TWO SEPARATE BULLETINS FOR THIS ISSUE (NTB00-089 FOR 01MY AND NTB00-087 FOR 00MY). THE PARTS IN THESE BULLETINS ARE NOT INTERCHANGEABLE. PLEASE REFER TO THE CORRECT BULLETIN WHEN PLACING PARTS ORDERS FOR THESE CAMPAIGNS.

SINCE A VERY LOW NUMBER OF VEHICLES ARE AFFECTED BY THE 01MY CAMPAIGN, THE PART NUMBERS WILL BE PLACED ON CUSTOMER CARE STATUS. USE THE CSC PROCESS TO ORDER PARTS FOR SPECIFIC VEHICLES REQUIRING REPAIR. VIN NUMBERS FOR THE CSC ORDERS WILL BE VERIFIED. ORDERS WITH VIN NUMBERS THAT DO NOT APPLY TO THIS CAMPAIGN WILL BE CANCELED.

YOUR CONTINUED SUPPORT OF THE SAFETY AND CUSTOMER SATISFACTION OF NISSAN QUEST OWNERS IS APPRECIATED.

NISSAN PARTS AND SERVICE OPERATIONS
12/11/2000