

00028

(Sample Of Notification Used)

April, 2000

Dear General Motors Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Reason For This Recall: General Motors has decided that a defect which relates to motor vehicle safety exists in certain 1999-2000 Chevrolet Express and GMC Savana vans equipped with a brake warning indicator. Some of these vehicles have a power steering cooler hose that can separate from the power brake booster fluid flow switch assembly. If this occurs, power steering fluid could flow onto hot engine parts and an engine compartment fire could occur.

What Will Be Done: To prevent the possibility of this condition occurring, your GM dealer will inspect the power steering hose joints for spring clamps. If spring clamps are found, they will be replaced with three new screw clamps. This service will be performed for you at no charge.

How Long Will The Repair Take? The length of time required to perform this inspection and service correction, if necessary, is approximately 15-25 minutes. Additional time may be required to schedule and process your vehicle. If your dealer has a large number of vehicles awaiting service, this additional time may be significant. Please ask your dealer if you wish to know how much additional time will be needed to schedule, process and repair your vehicle.

Contacting Your Dealer: Please contact your Chevrolet/GMC dealer as soon as possible to arrange a service date. Parts are available and instructions for making this correction have been sent to your dealer. Your Chevrolet/GMC dealer is best equipped to obtain parts and provide services to correct your vehicle as promptly as possible. Should your dealer be unable to schedule a service date within a reasonable time, you should contact the appropriate Customer Assistance Center at the listed number below:

Division	Number	Deaf, Hearing Impaired or Speech Impaired *
Chevrolet	1-800-222-1020	1-800-833-2438
GMC	1-800-462-8782	1-800-462-8583

* Utilizes Telecommunication Devices for the Deaf/Text Telephones (TDD/TTY)

If, after contacting the appropriate Customer Assistance Center, you are still not satisfied that we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590 or call 1-800-424-9393 (Washington, DC residents use 202-366-0123).

Customer Reply Card: The attached customer reply card identifies your vehicle. Presentation of this card to your dealer will assist in making the necessary correction in the shortest possible time. If you no longer own this vehicle, please let us know by completing the attached and mailing it in the postage paid envelope.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

**Chevrolet/Pontiac-GMC Division
General Motors Corporation**

Enclosure